

Aviation Accident Review



FY02


Department of the Interior Aviation Accident Review

Robert Galloway

Larry Brosnan

Steve Rauch

Office of Aircraft Services



Ground Rules




The National Transportation Safety Board

- ◆ **NTSB 831.13** Flow and dissemination of accident or incident information.

(b) ... Parties to the investigation may relay to their respective organizations information necessary for purposes of prevention or remedial action.

... However, no (release of) information... without prior consultation and approval of the NTSB.




Ground Rules



The National Transportation Safety Board

- ◆ Avoid discussion of “Probable Cause”, unless determined and published by the NTSB
- ◆ This presentation is provided for accident prevention purposes only




Ground Rules

Each accident is unique

Although the results may be very similar the causal factors leading up to an accident are seldom exactly alike.

Therefore it is unlikely that any two sets of findings, recommendations, or presentations will ever be the same.

It is imperative that you focus your attention on the underlying "root" causes for each unique accident and avoid comparing one investigation or presentation against another.



“The PROCESS”

Accident Investigation
involves asking three questions

What happened?

(gather facts)


Why did it happen?

(causal analysis)

What can we do to prevent it?


(develop recommendations)

The 3W's of accident investigation



Aviation Accident Review





Houma, LA

October 3, 2001

Cessna 185
Amphibian

Mission

Repositioning
flight

Damage

Substantial

Injuries

None


Procurement

Fleet

NTSB ID

FTW02LA007





Houma, LA

October 3, 2001


The amphibian configured aircraft was inbound for landing at the Houma-Terrebonne Airport, LA, when the pilot "flared too high and made a hard landing."

The commercial pilot, who was the sole occupant, was not injured.


Inspection revealed one of the fuselage bulkheads sustained substantial damage.



Bulkhead Crack




Indentation in Skin



Landing Gear Bolts



Sheared Bolts



Bent Bolts

Necking down at bend

Bent Brake Disk(s)





NTSB Probable Cause ***Houma, LA, Oct 3, 2001***



The National Transportation Safety Board

The National Transportation Safety Board determined that the probable cause of this accident was ...

Probable Cause

“The pilot's high flare, which resulted in a hard landing”





OAS Observations

Houma, LA, October 3, 2001

Issue

Pilot flared too high

Discussion

- Would landing in a level attitude (pitch) with power be a more appropriate procedure for landing an amphibian configured aircraft on hard surfaced runways ?





OAS Observations

Houma, LA, October 3, 2001

Issue

***Preflight inspections
are important***

Discussion

- What do you check on your aircraft before each flight to ensure that there is no structural damage ?





OAS Observations

Houma, LA, October 3, 2001


Issue

Emergency Locator Transmitter

Discussion

- Do you know how to check the emergency locator transmitter (ELT) in the aircraft you're flying in ?





Bethel, AK

October 5, 2001

Cessna 185

Mission

Wildlife
tracking

Damage

Substantial

Injuries

None


Procurement

Fleet

NTSB ID

ANC02TA001





Bethel, AK

October 5, 2001

During approach to a large paved runway, the pilot did not adequately compensate for the crosswind and lost directional control of the aircraft.

There were no noted mechanical deficiencies and the environmental conditions were not excessive.

The aircraft's left wing, left elevator, and left wheel were damaged.








Yukon Delta 
NATIONAL WILDLIFE REFUGE
 U.S. Fish and Wildlife Service
Department of the Interior

Hangar Facility







NTSB Probable Cause Bethel, AK, October 5, 2001



The National Transportation Safety Board

The National Transportation Safety Board determined that the probable cause of this accident was ...

Probable Cause

"The pilot's inadequate compensation for wind conditions.

Factors associated in the accident were a crosswind, and a worn tailwheel steering horn."





OAS Observations ***Bethel, AK, October 5, 2001***

Issue

Pilot proficiency in aircraft configuration (tires vs. floats)




Discussion

Did the pilot take an unnecessary risk when he chose to take an aircraft that had just been reconfigured from floats to wheels on an operational mission (with passengers) without first having taken the aircraft on a re-familiarization flight ?

Could he have reduced the risk by landing to the gravel runway instead of the paved runway ?

Would using the Bureau's Mentor Pilot Program help pilots avoid hazards such as this ?



Richland, WA

April 11, 2002

Hughes 369C (MD500D)

Mission

Wildlife
capture

Damage

Substantial

Injuries

None


Procurement

End-Product
Contract (improper)

NTSB ID

SEA02TA067





Richland, WA

April 11, 2002

While using a net gun on an elk capture mission one of the net's weights struck the red main rotor blade causing substantial damage.

The pilot landed immediately.

There were no injuries and no further damage to the aircraft.




Top of Rotor Blade



**Leading edge
and spar**

Rotor Blade


Leading edge damage



Spanwise
damage

Chordwise
damage


Net Weight with Lanyard and Net



Note two points of failure

Proper Firing Position





NTSB Probable Cause ***Richland, WA, April 11, 2001***



The National Transportation Safety Board

The National Transportation Safety Board determined that the probable cause of this accident was ...

Probable Cause

“Failure of the netting material securing a net weight while maneuvering.

The net weight was a factor.”





OAS Observations

Richland, WA, April 11, 2001

Issue

Risk Management strengths

Discussion

- Very experienced crew
- Pilot flew as conservative a profile as possible
- Very good crew coordination





OAS Observations

Richland, WA, April 11, 2001


Issue

Risk Management weaknesses

Discussion

- Lack of standards for gunner training
- Gunners are not carded
- Last minute mission request and lack of understanding resulted in the flight being conducted as a flight services contract rather than an end-product contract (they *assumed operational control*)





Cantwell, AK

May 16, 2002

Robinson R-44

Mission

Wildlife
tracking

Damage

Substantial

Injuries

None


Procurement

ARA

NTSB ID

ANC02TA035





Cantwell, AK

May 16, 2002

While herding caribou out of an area of trees the low rotor annunciator sounded. The pilot said he did not have sufficient power available to climb away from his position and the helicopter settled into low bushes.

After an additional loss of rotor RPM the pilot was able to regain enough rotor RPM to fly to a nearby river bed.


After landing the pilot found damage to both main rotor blades.








NEVER PULL DOWN
PUSH UP OPPOSITE BLADE





NEVER



NTSB Probable Cause Cantwell, AK, May 16, 2002



The National Transportation Safety Board

The National Transportation Safety Board determined that the probable cause of this accident was ...

Probable Cause

“A failure of the pilot-in-command to maintain adequate main rotor rpm during an out-of-ground-effect hover.





OAS Observations ***Cantwell, AK, May 16, 2002***


Issue

Performance planning
(Gross Weight)

Discussion

- Maximum gross weight of the R-44 is 2,400 lbs.
- Planned operating weight was 2,396.35 lbs. (3.65 lbs. to spare)
- Are we accepting necessary (or unnecessary) risk when we chose to operate this close to the limit?





OAS Observations ***Cantwell, AK, May 16, 2002***


Issue

***Performance planning
(Power Required)***



Discussion

- In the operating environment (2000' PA / 10°C) the maximum continuous power was limited to 23.4" Hg.
- Power check indicated 24.1" Hg. required for HOGE.
- Pilot chose to use the max T/O power limitation (5 min limit) by adding 1.6" Hg. for a total of 25" Hg.
- Are we accepting necessary (or unnecessary) risk when we choose to operate this close to the limit...**once again?**



Swan River, Manitoba, Can.

May 27, 2002

Cessna 206
Amphibian

**TSB Investigation On-Going
Preliminary Information**

Mission

Waterfowl
Survey

Damage

Destroyed

Injuries

1 Minor

Procurement

Fleet


TSB ID

A02C0105

NTSB ID

WAS02WA044





Swan River, Manitoba, Can.

May 27, 2002

Shortly after takeoff the pilot felt a vibration and noticed the manifold pressure slowly and progressively decreasing.


The pilot turned downwind to return to the airport but was unable to maintain altitude and performed a forced landing.

The aircraft was destroyed in a post-crash fire.

The pilot received minor injuries and the passenger was not injured.



Swan River, Manitoba, Can.



Winnipeg

WINNIPEG

Reported Flight Path

Runway

Accident site



Float impact





Prop impact



Cessna U206F Amphibian POH Supplement



1986 Stationair 6

Information Manual

Takeoff on Land...

9. Landing Gear . . . RETRACT

Emergency Landing on Land without Engine Power


2. Landing Gear . . .

DOWN . . for Smooth Terrain

UP for Rough Terrain

FAA Pamphlet

FAA-P-8740 - 44
AFO-800-1283



accident prevention program

Impossible Turn



U.S. Department of Transportation
Federal Aviation Administration
Washington, D.C.

FAA Accident Prevention FAA-P-8740-44

If you suffer a loss of power on takeoff, any maneuvering (i.e. returning to the runway) sacrifices airspeed and altitude.

FAA recommends not returning to the airport, but rather choosing a landing area within 60° of your flight path.



OAS Observations

Swan River, Manitoba Can., May 27, 2002

Issue

Crew Resource Management

Discussion

- Why didn't the pilot request assistance during the emergency ?
- Why didn't the passenger offer assistance to the pilot during the emergency ?





OAS Observations

Swan River, Manitoba Can., May 27, 2002

Issue

Situational awareness

Discussion

- Runway 20 - 4130 feet
- Aircraft took off in the first 1/3 of the runway.
- With more than one half mile of runway plus another 1000 feet of pasture available to the pilot, why did the pilot attempt to return to the airport ?





OAS Observations

Swan River, Manitoba Can., May 27, 2002

Issue

Pilot and passenger were not wearing personal protective equipment.

Discussion

- Pilot was not wearing a flight helmet or gloves and suffered first-degree burns on his hand during the egress.
- Why did the pilots choose to not use available PPE ? (helmets and gloves were stowed in the back of the aircraft)





OAS Observations

Swan River, Manitoba Can., May 27, 2002

Issue

***Critical checklist items
were not completed***

Discussion

- Why did the pilot fail to retract the landing gear in accordance with the Takeoff and the Emergency Landing checklists ?





OAS Observations

Swan River, Manitoba Can., May 27, 2002


Issue

OAS accident reporting hotline number was improperly used as the flight plan point-of-contact number

Discussion

- OPM 02-02 requires flight plans and flight following.
- The 1-888-4MISHAP number is an Interagency Aviation Accident Reporting Hotline and not to be used for flight following.
- The 888 number would not have worked in Canada anyway.





Kaktovik, AK

June 7, 2002

Cessna 185
(Wheel-Ski)

Mission

Point-to-Point

Damage

Substantial

Injuries

None


Procurement

Fleet

NTSB ID

ANC02TA045





Kaktovik, AK


June 7, 2002

The airplane received substantial damage during the landing roll on a remote, ice covered lake, about 45 miles southwest of Kaktovik, Alaska.

The airplane was being operated as a visual flight rules (VFR) local area public use flight. Visual meteorological conditions prevailed. The pilot reported landing to the west with a 5-7 knot tailwind.

The pilot and sole passenger were not injured.






A photograph of a red aircraft wing section, likely a leading edge, with a significant portion covered in silver duct tape. The tape is applied in several overlapping strips, showing signs of wear and being partially torn at the edges. The background shows a workshop environment with wooden beams and metal supports.


**Field repair
to leading edge
of right wing**

**Damage to leading edge
of right wing
(duct tape removed)**









NTSB Probable Cause ***Houma, LA, Oct 3, 2001***



The National Transportation Safety Board

The National Transportation Safety Board determined that the probable cause of this accident was ...

Probable Cause

“The pilot's inadequate evaluation of the weather conditions during landing at a remote lake, resulting in a downwind landing.

Factors contributing to the accident were the presence of a tailwind, and an icy lake surface.





OAS Observations ***Kaktovik, AK, June 7, 2002***

Issue

Aircraft damage was repaired and the aircraft was moved to Fairbanks in violation of 49 CFR 830.10

Discussion

Title 49 CFR 830.10

- "The operator of an aircraft involved in an accident...is responsible for preserving to the extent possible any wreckage, cargo, and mail aboard the aircraft and all records...until the Board takes custody thereof or a release is granted pursuant to 831.12b of this chapter."**





OAS Observations ***Kaktovik, AK, June 7, 2002***

Issue

The pilot landed to the west with a 5-7 knot tailwind

Discussion

- The pilot mistakenly thought he was landing into the wind which had been out of the west during earlier takeoff and landings.
- A subsequent change in wind direction was not detected by the pilot resulting in a downwind landing.





OAS Observations ***Kaktovik, AK, June 7, 2002***

Issue

***The pilot configured
the aircraft for
landing using skis***

Discussion

- Would a wheel landing have been a better choice... which would have allowed the pilot to use brakes to slow the aircraft ?





OAS Observations ***Kaktovik, AK, June 7, 2002***


Issue

Once the pilot realized he was not going to be able to stop he elected not to execute a go-around.

Discussion

- Would planning for, and executing, a go-around have prevented this accident ?





Yosemite NP, CA

June 13, 2002

Navy UH-1N
(Bell 212)

Navy and OAS Investigations On-Going
Preliminary Information

Mission

Hoist Rescue

Damage

Minor

Injuries

1 Fatal

1 Serious


Procurement

MOU with Navy

Operational Control

US Navy





Yosemite NP, CA

June 13, 2002

While using their rescue hoist to evacuate a seriously injured climber from the Cathedral Spires Gully the aircraft experienced a decay in main rotor RPM with a resulting loss of heading control and altitude.

As the crew worked to control the aircraft the hoist cable struck a tree and separated.

The rescue corpsman and climber were retained by the belay line.




Pre-Mission Coordination




Pre-Mission Coordination



Cathedral Spires Gully




Hoist Location




Tree Impacts














Main Rotor Damage



Main Rotor Damage





OAS Observations

Yosemite NP, CA, June 13, 2002

Issue

***Risk Management
strengths***

Discussion

- Comprehensive training program and aviation plan
- Weighed the risks of ground vs. air evacuation
- Lessons learned were rapidly implemented within the Region
- Excellent post-accident response and reporting
- Excellent post-accident involvement by all levels of Park leadership





OAS Observations

Yosemite NP, CA, June 13, 2002

Issue

***Risk Management
weaknesses***

Navy SAR Operations



Discussion

- Navy SAR pilots are not normally qualified in SAR operations or the aircraft (Bell 212) until assignment to a SAR detachment.

- How can we minimize the risks when working with Navy SAR ?

have no school that teaches mountain-flying techniques

- Navy policy requires a large crew thus increasing the aircraft's gross weight.
(and we don't require a load calc)



OAS Observations

Yosemite NP, CA, June 13, 2002

Issue

***Risk Management
weaknesses***

Navy SAR Operations



Discussion

- How can we:
 - ✓ Improve the interface between Park and Navy SAR (or other) personnel prior to actual rescue missions ?
 - ✓ Improve identification of key personnel ?
 - ✓ Increase or improve training opportunities ?
 - ✓ Identify and correct communication problems ?



OAS Observations

Yosemite NP, CA, June 13, 2002

Issue


Risk Management weaknesses

Navy pilot performance

Discussion

- Would a high recon of the site have allowed the pilot to:
 - ✓ Identify hazards (terrain and obstructions) ?
 - ✓ Identify winds and turbulence ?
 - ✓ Confirm power required vs. power available ?





Mount Rainier, WA

June 25, 2002

Bell 206B-III

Mission

Personnel
Transport

Damage

Destroyed

Injuries

None


Procurement

ARA

NTSB ID

SEA02TA110






Mount Rainier, WA

June 25, 2002


While landing on a glacier to insert two personnel to support a rescue operation the aircraft pitched nose up, the pilot attempted to correct with forward cyclic, and a knocking/banging was heard.

The pilot rapidly increased collective to come back to a hover but the aircraft began an uncontrolled rapid yaw to the right. The pilot lowered the collective and the aircraft impacted and remained upright.

There were no injuries.



Mount Rainier (North Face)












HOVER CEILING OUT OF GROUND EFFECT TAKEOFF POWER 0° TO 46°C

GENERATOR 22.3 AMPS
 SKID HEIGHT 40 FT (12.2 METERS)
 WITH ANTI-ICE ON GROSS WEIGHT IS 260 LBS (117.9 Kg) LESS
 PARTICLE SEPARATOR WITH CARGO HOOK

ANTI-ICE OFF
 N2 ENGINE RPM 100%



**Load Calc
by OAS**

DA ~ 10,800'




Figure 4-5. Critical relative wind azimuth area

The Hover Ceiling In Ground Effect charts (figure 4-3) and Hover Ceiling Out of Ground Effect charts (figure 4-4) present hover performance (allowable gross weight) for conditions of pressure altitude and OAT. The charts are divided into two areas.

AREA A (White area) as shown on the hover ceiling charts presents hover performance for which controllability has been demonstrated in sideward and rearward relative wind conditions up to 20 MPH (17 knots).



ENGINE TOT WILL RISE NOTICEABLY WHEN HOVERING DOWNWIND. AVOID HOVERING DOWNWIND WHEN OPERATING NEAR TOT LIMITS.

AREA B (Shaded area) as shown on Hover Ceiling charts presents hover performance that can be realized in CALM WINDS or winds outside the CRITICAL RELATIVE WIND AZIMUTH AREA in figure 4-5.

U.S. DEPARTMENT OF THE INTERIOR
HELICOPTER LOAD CALCULATION


HELICOPTER MODEL Bell 206 BIII
NO. 874

Pilot	Project	Date		
	<u>SAR</u>	<u>6-25-02</u>		
		Time		
		<u>1445</u>		
1. Departure Base	<u>Kauntz</u>	Pressure ALT	<u>2385</u>	
		Temperature	<u>2.5°</u>	
2. Destination Base	<u>Upper Carbon Gul</u>	Pressure ALT	<u>9800</u>	
		Temperature	<u>10</u>	
3. Helicopter Equipped Weight			<u>1850</u>	
4. Flight Crew Weight			<u>180</u>	
5. Fuel (Gals. <u>40 X 7</u> lbs.)			<u>280</u>	
6. Operating Weight			<u>2310</u>	
		IGE	OGE	
7. Computed Gross Weight		<u>3200</u>	<u>2950</u>	
8. Fixed Weight Reduction		<u>130</u>	<u>130</u>	
9. Adjusted Weight (7 Minus 8)		<u>3070</u>	<u>2820</u>	
10. Takeoff/Landing Limits (Handbook Limitation Section)		<u>3200</u>		
11. Selected Weight (Lowest of 9 or 10 for Nonjettisonable)		<u>3070</u>	<u>2820</u>	
12. Operating Weight (Line 6)		<u>2310</u>	<u>2310</u>	
13. Allowable Payload		<u>760</u>	<u>510</u>	
14. Passengers and/or Cargo		<u>245</u>		
Names		<u>225</u>		
Weight	<u>62 pack</u>	<u>20</u>		
15. Actual Payload		<u>490</u>		
16. Actual Gross Weight (12 Plus 15) (Must Not Exceed Line 11)		<u>2800</u>		

U.S. DEPARTMENT OF THE INTERIOR
HELICOPTER LOAD CALCULATION

HELICOPTER MODEL Bell 206B3
NO. _____

Pilot	Project	Date		
		Time		
		Pressure ALT		
		Temperature		
		Pressure ALT	<u>8800/13°C</u>	
		Temperature		
		1830	1850	
		<u>180</u>		
		<u>280</u>		
		<u>2290</u>		
			OGE	
7. Computed Gross Weight			<u>2,625</u>	
8. Fixed Weight Reduction			<u>130</u>	
			<u>2,495</u>	
			<u>3,200 (internal)</u>	
11. Selected Weight (Lowest of 9 or 10 for Nonjettisonable)			<u>2,495</u>	
12. Operating Weight (Line 6)			<u>2,290</u>	
13. Allowable Payload			<u>205</u>	
14. Passengers and/or Cargo				
Names				
Weight	<u>Passenger #1</u>		<u>245</u>	
	<u>Passenger #2</u>		<u>225</u>	
	<u>Oxygen Bottle</u>		<u>20</u>	
			<u>490</u>	
15. Actual Payload			<u>490</u>	
16. Actual Gross Weight (12 Plus 15) (Must Not Exceed Line 11)			<u>2800</u>	



Allowable Load
205 lbs

Actual Load
490 lbs

U.S. DEPARTMENT OF THE INTERIOR
HELICOPTER LOAD CALCULATION


HELICOPTER MODEL Bell 206 BIII
NO. 874

Pilot	Project	Date		
	<u>SAR</u>	<u>6-25-02</u>		
		Time		
		<u>1445</u>		
1. Departure Base	<u>Kauntz</u>	Pressure ALT	<u>2385</u>	
		Temperature	<u>2.5°</u>	
2. Destination Base	<u>Upper Carbon Gul</u>	Pressure ALT	<u>9800</u>	
		Temperature	<u>10</u>	
3. Helicopter Equipped Weight			<u>1850</u>	
4. Flight Crew Weight			<u>180</u>	
5. Fuel (Gals. <u>40 X 7</u> lbs.)			<u>280</u>	
6. Operating Weight			<u>2310</u>	
		IGE	OGE	
7. Computed Gross Weight		<u>3200</u>	<u>2950</u>	
8. Fixed Weight Reduction		<u>130</u>	<u>130</u>	
9. Adjusted Weight (7 Minus 8)		<u>3070</u>	<u>2820</u>	
10. Takeoff/Landing Limits (Handbook Limitation Section)		<u>3200</u>		
11. Selected Weight (Lowest of 9 or 10 for Nonjettisonable)		<u>3070</u>	<u>2820</u>	
12. Operating Weight (Line 6)		<u>2310</u>	<u>2310</u>	
13. Allowable Payload		<u>760</u>	<u>510</u>	
14. Passengers and/or Cargo		<u>245</u>		
Names		<u>2.25</u>		
Weight	<u>62 pack</u>	<u>20</u>		
15. Actual Payload		<u>490</u>		
16. Actual Gross Weight (12 Plus 15) (Must Not Exceed Line 11)		<u>2800</u>		

U.S. DEPARTMENT OF THE INTERIOR
HELICOPTER LOAD CALCULATION

HELICOPTER MODEL Bell 206B3
NO. _____

Pilot	Project	Date		
		Time		
		Pressure ALT		
		Temperature		
		Pressure ALT	<u>8800/13°C</u>	
		Temperature		
		1830	1850	
		<u>180</u>		
		<u>280</u>		
		<u>2290</u>		
		IGE	OGE	
7. Computed Gross Weight			<u>2,850</u>	
8. Fixed Weight Reduction			<u>130</u>	
			<u>2,720</u>	
			<u>3,200 (internal)</u>	
11. Selected Weight (Lowest of 9 or 10 for Nonjettisonable)			<u>2,720</u>	
12. Operating Weight (Line 6)			<u>2,290</u>	
13. Allowable Payload			<u>430</u>	
14. Passengers and/or Cargo				
Names				
Weight	<u>Passenger #1</u>		<u>245</u>	
	<u>Passenger #2</u>		<u>225</u>	
	<u>Oxygen Bottle</u>		<u>20</u>	
15. Actual Payload			<u>490</u>	
16. Actual Gross Weight (12 Plus 15) (Must Not Exceed Line 11)			<u>490</u>	



Allowable Load
430 lbs

Actual Load
490 lbs



X



komon



NTSB Probable Cause ***Mount Rainier, WA, June 25, 2002***



The National Transportation Safety Board

The National Transportation Safety Board determined that the probable cause of this accident was ...

Probable Cause

“The pilot's failure to maintain aircraft control while trying to land.

Rough/uneven terrain, inaccurate performance data calculations, inadequate in-flight planning and lack of familiarity with the geographic area were factors.





OAS Observations

Mount Rainier, WA, June 25, 2002

Issue

Risk Management strengths

Discussion

- Involved Park leadership
- Weighed the risks of ground vs. air evacuation
- Appropriate sense of urgency
- Pro-active training program
- Excellent post-accident response actions and recovery planning





OAS Observations

Mount Rainier, WA, June 25, 2002

Issue

***Risk Management
weaknesses***

***Pilot qualification and
experience***

Discussion

- Pilot qualification
 - ✓ Why was a pilot who was not carded to fly for the vendor not identified by the HEMG, the pilot, or the vendor ?
 - ✓ Did the lack of a standard definition for "deep snow" operations contribute to this accident ?
 - ✓ Was this mission too complex for a pilot's first flight to Mount Rainier ?





OAS Observations

Mount Rainier, WA, June 25, 2002

Issue

Risk Management weaknesses

Crew qualification and experience

Discussion

- Crew qualification
 - ✓ Would periodic joint training between vendor pilots, vendor guides, and Park employees have precluded communication and Crew Resource Management failures ?
 - ✓ Should DOI require vendor climbing guides to receive aviation training (i.e. Basic Aviation Safety Training B3) ?





OAS Observations

Mount Rainier, WA, June 25, 2002

Issue

***Risk Management
weaknesses***

Culture of risk acceptance



Discussion

- Was the mishap pilot pressured into accepting the mission because the company's other two pilots routinely performed this type of mission ?
- Why did Helibase Management not act on the warnings offered by the Army helicopter crew ?
- Why did senior Park managers believe landing a Bell 206B-III on the Glacier was less risky than hoisting with a CH-47 ?



OAS Observations

Mount Rainier, WA, June 25, 2002

Issue

***Risk Management
weaknesses***

Discussion

- How can we ensure that passengers wear proper personal protective equipment (PPE) or have a waiver to the PPE requirements?
- Was the passenger briefing adequate ?
- How can we manage/minimize the risks to local aviation operations when key aviation personnel are resourced to fire / law enforcement assignments ?





OAS Observations

Mount Rainier, WA, June 25, 2002


Issue

Risk Management weaknesses

Discussion

- How can we ensure that passengers and crew who have been involved in an aircraft accident are medically cleared before returning to duty?
- How could this site have been secured without placing the guards at risk ?





Fillmore, UT

July 7, 2002

PZL M-18
(Dromader)

Mission

Aerial
Suppression

Damage

Destroyed

Injuries

None


Procurement

CWN

NTSB ID

DEN02TA069





Fillmore, UT


July 7, 2002

After takeoff the aircraft climbed to 400 feet and turned crosswind.

The pilot noted the manifold pressure was less than desired and that the aircraft was slowly descending. As the pilot attempted to stop the descent he failed to release the retardant and the aircraft impacted the terrain with the right wing and came to rest 180° from touchdown heading.

The pilot was not injured.






















Date: MTDC Lot Acceptance/Quality Assurance Analysis

Subject: LAQA Results
To: Mark Bickham, National Interagency Fire Center

Thank you for submitting your sample under the lot acceptance and quality assurance program. Results of laboratory tests are within the acceptable range (refractometer=13.0-15.0) for **Fire-Trol LCA-R**.

The sample received by our lab was LCA-R concentrate. The refractometer and density are both indicators of salt content. The viscosity and density are within the parameters that we expect to see in an unmixed sample of LCA. Typically, an LC concentrate is mixed with water in our lab to get the refractometer reading. The refractometer results are within acceptable parameters for the mixed product.

These results indicate that no water was added to this sample before it was received at our lab. Fire-Trol LCA-R has a specific weight of 9.12 lb/gal and 12.10 lb/gal, respectively, for mixed retardant and liquid concentrate. We would expect to see a density of 1.090-1.105 g/mL for a mixed product (water added). In an 800 gallon tank at 1.105 g/mL, the weight should be about 7296 lbs. A density of 1.466 g/mL equates to 12.2 lb/gal. of LCA-R, which translates to 9760 lbs.

Quality control values obtained in our laboratory are shown below.

Sample Number	Base Identification	Viscosity (centipoise)	Refractometer Reading	Density (g/mL)
422-LAQA-02	Accident exhibit 7/8	1400	14.5	1.466

We have moved to a new building. Please send future samples to this address:

5785 Hwy 10 W.

Missoula, MT 59808

Phone number will remain the same.

If you have any questions concerning the results of these tests or the LA/QA program, please contact me at (406) 329-4859, or email szylstra@fs.fed.us.

Shirley Zylstra

SHIRLEY ZYLSTRA

Wildland Fire Chemical Systems

These results indicate that no water was added to this sample before it was received at our lab...

...Fire-Trol LCA-R has a specific weight of 9.12 lb/gal and 12.10 lb/gal, respectively, for mixed retardant and liquid concentrate.

...A density of 1.466 g/mL equates to 12.2 lb/gal. of LCA-R...

Aircraft ID:
N5189Y

M-18A Dromader load vs. weight calculation

(Input a/c empty weight for particular N#)

A/C empty weight (lbs)	6387
A/C gross weight (lbs)	11700
A/C useful load (lbs)	5313

(Input pilot weight)

A/C Pilot Weight (lbs)	200
A/C Fuel Weight-AVGAS (lbs)	846
A/C Fuel Weight-JET (lbs)	0

(For A/C Fuel Weight, Enter Amount of Correct Type Fuel Below)

*For Radial Engine M18, Enter U.S. Gallons of Aviation Gasoline here:	141
Aviation Gasoline (AVGAS) Weight per gallon in lbs:	6.0
*For Turbine Engine M18, Enter U.S. Gallons of Aviation Jet Fuel here:	
Aviation Jet Fuel (JET) Weight per gallon in lbs:	7.0

(Caution: Enter gallons for only one fuel type. Jet or Avgas)

Note: M18	Extended usable fuel capacity:	188 gallons
	Standard usable fuel capacity:	106 gallons

Hopper Load in gallons	Material Weight in lbs/gallon			Hopper Load in gallons	*Aircraft actual weight w/load condition with pilot, fuel, & hopper load A, B, or C		
	A= water 8.3	B=slurry/mix 9.12	C=straight LC 12.2		8.3	9.12	12.2
	Hopper wt. A	Hopper wt. B	Hopper wt. C		Load A	Load B	Load C
100	830	912	1220	100	8263	8345	8653
150	1245	1368	1830	150	8678	8801	9263
200	1660	1824	2440	200	9093	9257	9873
250	2075	2280	3050	250	9508	9713	10483
300	2490	2736	3660	300	9923	10169	11093
350	2905	3192	4270	350	10338	10625	11703
400	3320	3648	4880	400	10753	11081	12313
450	3735	4104	5490				
500	4150	4560	6100				
550	4565	5016	6710	550	11998	12449	14143
600	4980	5472	7320	600	12413	12905	14753

(Max. Hopper Wt. 3300 lbs. Std. Aircraft)
Note: Hopper Limit is not applicable when
in compliance with STC SA01276AT.

(*Max. Aircraft Gross Weight 11700 lbs)
*When in compliance with STC SA01276AT
Weights in red exceed max. A/C gross weight!

Max gross 11,700 lbs.
Over gross by 613 lbs.

Various aircraft load calculations may be quickly determine

Cells highlighted in green may be changed to reflect a parti

NOTE: (Pilots are responsible to insure that the aircraft does not exceed the maximum approved operational weight!)



1203

AVGAS 100LL
NO SMOKING




MISCO
PRODUCTS
DIVISION


10440 0-30°
HAND REFRACTOMETER
AUTOMATICALLY TEMPERATURE
COMPENSATED

3401 Virginia Rd
Cleveland, OH
44122
216-831-1000
MADE IN U.S.A.

Straight LC Concentrate



Acceptable Mixture 13-15





NTSB Probable Cause ***Fillmore, UT, July 7, 2002***



The National Transportation Safety Board


The National Transportation Safety Board determined that the probable cause of this accident was ...

Probable Cause

“The pilot's failure to follow proper procedures / directives, and the airplane's inability to climb while maneuvering after takeoff.

Factors contributing to the accident were improperly mixed aerial application materials (fire retardant slurry), the high aircraft weight and balance, and the pilot's diverted attention.





OAS Observations

Fillmore, UT, July 7, 2002

Issue

Risk Management strengths

Discussion

- Excellent post-accident involvement by all levels of Bureau leadership
- Immediate, fleet-wide corrective actions
- Pro-active training program by National SEAT Program Manager
- Excellent post-accident response and reporting





OAS Observations ***Fillmore, UT, July 7, 2002***

Issue

***Risk Management
weaknesses***

Discussion

- SEAT manager (SEMG)
 - ✓ How can we improve training and information dissemination for seasonal employees ?
 - ✓ Do SEMGs recognize that changes, or situations not covered in the contract must be approved by the Contracting Officer ?
 - ✓ Why did the SEMG accept the responsibility to train the vendor crew?





OAS Observations ***Fillmore, UT, July 7, 2002***

Issue

***Risk Management
weaknesses***

Discussion

- SEAT manager (SEMG)
 - ✓ Why did the SEMG fail to comply with the manufacturer's recommendation for recirculating the retardant and for using the refractometer ?
 - ✓ How did the SEMG fail to notice the water valve was closed ?





OAS Observations

Fillmore, UT, July 7, 2002

Issue

***Risk Management
weaknesses***

Discussion

- Vendor responsibilities
 - ✓ How can we ensure vendors adequately train their personnel ?
 - ✓ How should we react when vendor personnel are not adequately trained ?
 - ✓ Should loaders be evaluated and carded since their actions directly affect aviation safety ?





OAS Observations ***Fillmore, UT, July 7, 2002***

Issue

***Risk Management
weaknesses***

Discussion

- Pilot performance
 - ✓ Was this pilot adequately trained?
 - ✓ Should performance planning similar to helicopter load calcs be required for SEAT ops ?
 - ✓ Why did the pilot fail to release all, or part, of his load ?
 - ✓ How did the pilot fail to notice the water valve was closed ?





OAS Observations ***Fillmore, UT, July 7, 2002***

Issue

***Risk Management
weaknesses***

Discussion

- Aircraft issues
 - ✓ How can we be assured of adequate aircraft performance when the Pilot Operating Handbook's performance charts do not cover the temperatures we operate in ?
 - ✓ Does the variation in cockpit design and switch location create increased risk (negative habit transfer) ?



