

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent hydraulic fluid leakage into the auxiliary power unit (APU) inlet due to fatigue vibration and cracking in the flared radius of a hydraulic pipe in the aft fuselage, which could result in smoke and odors in the passenger cabin or cockpit; accomplish the following:

#### Installation a Pipe Support and Clamps

(a) For Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87) series airplanes, as listed in McDonnell Douglas Service Bulletin

MD80-29-056, dated June 18, 1996: Within 18 months after the effective date of this AD, install a pipe support and clamps on the hydraulic lines in the aft fuselage in accordance with the service bulletin.

#### Replacement of the Hydraulic Pipe Assembly

(b) For Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87) series airplanes, and Model MD-88 airplanes, as listed McDonnell Douglas Service Bulletin MD80-29-062, Revision 01, dated August 3, 1999: Within 18 months after the effective date of this AD, replace the hydraulic pipe assembly in the aft fuselage with a new pipe assembly having a greater wall thickness, in accordance with the service bulletin. Except for Model MD-88 airplanes that have been modified in accordance with McDonnell Douglas MD-80 Service Bulletin 29-54, dated February 2, 1993, or Revision 2, dated December 17, 1993, the requirements of this paragraph must be accomplished concurrently with the requirements of paragraph (a) of this AD

#### Installation of Drain Tube Assemblies and Diverter Assemblies

(c) For Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87) series airplanes, as listed in McDonnell Douglas Service Bulletin MD80-53-286, dated September 3, 1999; and Model MD-9-30 series airplanes, as listed in McDonnell Douglas Service Bulletin MD90-53-018, dated September 3, 1999: Within 18 months after the effective date of this AD, install drain tube assemblies and diverter assemblies in the area of the APU inlet, in accordance with the applicable service bulletin.

#### Spares

(d) As of the effective date of this AD, no person shall install a hydraulic pipe assembly, part number 7936907-603, on any airplane.

#### Alternative Methods of Compliance

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate.

Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

#### Special Flight Permits

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on January 11, 2000.

**Donald L. Riggin,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 00-1118 Filed 1-14-00; 8:45 am]

**BILLING CODE 4910-13-U**

---

## DEPARTMENT OF THE INTERIOR

### Minerals Management Service

#### 30 CFR Part 206

RIN 1010-AC24

#### Public Workshop on Proposed Rule—Establishing Oil Value for Royalty Due on Indian Leases

**AGENCY:** Minerals Management Service, Interior.

**ACTION:** Notice of Public Workshop.

**SUMMARY:** The Minerals Management Service (MMS) is giving notice of a public workshop concerning the supplementary proposed Indian oil value rule published in the **Federal Register** on January 5, 2000, (65 FR 403). The proposed rule would amend the royalty valuation regulations for crude oil produced from Indian leases.

**DATES:** The public workshop will be held in Lakewood, Colorado, on February 8, 2000, beginning at 9 a.m. and ending at 3 p.m., Mountain time.

**ADDRESSES:** The workshop will be held at the Minerals Management Service, Royalty Management Program, Denver

Federal Center, Auditorium, Building 85, Kipling Street (between 6th Avenue and Alameda Pkwy), Lakewood, CO 80215, telephone number (303) 231-3585.

**FOR FURTHER INFORMATION CONTACT:** Mr. Peter Christnacht, Royalty Valuation Division, Royalty Management Program, Minerals Management Service, P.O. Box 25165, MS 3151, Denver, Colorado, 80225-0165, telephone number (303) 275-7252; or, Mr. David S. Guzy, Chief, Rules and Publications Staff, Royalty Management Program, Minerals Management Service, P.O. Box 25165, MS 3021, Denver, Colorado 80225-0165, telephone number (303) 231-3432, fax number (303) 231-3385, e-mail David.Guzy@mms.gov.

**SUPPLEMENTARY INFORMATION:** The workshop will be open to the public in order to discuss the supplementary proposed rule and gather comments. We encourage members of the public to attend this meeting. Those wishing to make formal presentations should sign up upon arrival. The sign-up sheet will determine the order of speakers. For building security measures, each person will be required to sign in and may be required to present a picture identification to gain entry to the meeting.

Dated: January 11, 2000.

**Lucy Querques Denett,**

*Associate Director for Royalty Management.*

[FR Doc. 00-1099 Filed 1-14-00; 8:45 am]

**BILLING CODE 4310-MR-P**

---

## ENVIRONMENTAL PROTECTION AGENCY

#### 40 CFR Part 52

[CA 181-0199; FRL-6525-6]

#### Disapproval of Implementation Plans; California State Implementation Plan Revision, South Coast Air Quality Management District

**AGENCY:** Environmental Protection Agency (EPA).

**ACTION:** Proposed rule.

**SUMMARY:** The EPA is proposing to disapprove Rule 1623 of the South Coast Air Quality Management District (SCAQMD) which has been submitted as a revision to the State Implementation Plan (SIP). Rule 1623—Credits for Lawn and Garden Equipment provides a mechanism for issuing mobile source emission reduction credits (MSERCs) to entities who voluntarily either sell or replace old engine-powered lawn and garden