

Bill Bihner, 10:51 AM 1/28/2003 -0500, Fwd: STS-107 Flight Day 12 Report

X-Sender: wbihner@mail.hq.nasa.gov  
X-Mailer: QUALCOMM Windows Eudora Version 4.3.2  
Date: Tue, 28 Jan 2003 10:51:25 -0500  
To: "Bryan O'connor" <boconnor@hq.nasa.gov>  
From: Bill Bihner <wbihner@hq.nasa.gov>  
Subject: Fwd: STS-107 Flight Day 12 Report  
Cc: Pete Rutledge <prutledg@hq.nasa.gov>, James Lloyd <jlloyd@hq.nasa.gov>, Mark Kowaleski <mkowales@hq.nasa.gov>, Pepper Phillips <pPhillip@mail.hq.nasa.gov>

Bryan,

A new "assessment" on the potential for orbiter damage from ET foam loss. Bottom line is some orbiter structural damage predicted but no safety of flight issue based on this report. Will keep you posted.

Bill

From: SR&QA MER Console <SRQAMer@ems.jsc.nasa.gov>  
To: "srqa-mer listserver" <SRQA-MER@vesuvius.jsc.nasa.gov>  
Subject: STS-107 Flight Day 12 Report  
Date: Tue, 28 Jan 2003 09:38:59 -0600  
X-Mailer: Internet Mail Service (5.5.2653.19)

STS-107 Flight Day 12 Report  
GMT 028:15:30

Shift Leads: David Witwer, Brandon Dick, Mike Etchells  
Mission Engineer: Dan Zalit (OJT)

The STS-107 mission continues nominally in a 154 x 140 nm orbit with all Orbiter subsystems performing satisfactorily. No new Orbiter issues or anomalies have been reported in the previous 24 hours.

Our MER Manager released the following update on the debris hit on the left wing last during ascent. "Systems integration personnel performed a debris trajectory analysis to estimate the debris impact conditions and locations. This analysis was performed utilizing the reported observations from the ascent video and film. It was assumed that the debris was foam from the external tank. Based on the results of the trajectory analysis, an impact analysis was performed to assess the potential damage to the tile and reinforced carbon carbon (RCC). The impact analysis indicates the potential for a large damage area to the tile. Damage to the RCC should be limited to coating only and have no mission impact. Additionally, thermal analyses were performed for different locations and damage conditions. The damage conditions included one tile missing down to the densified layer of the tile and multiple tiles missing over an area of about 7 in by 30 in. These thermal analyses indicate possible localized structural damage but no burn-through, and no safety of flight issue."

Previous flight day reports discuss the eight MER anomalies listed below.

MER Anomalies:

- MER-01 AC2 Phase B Sluggish Current Signature
- MER-02 No ICOM B in Spacehab
- MER-03 O2 Tank 7 Heater A Failed Off in Manual Mode (ORB)
- MER-04 70MM Hasselblad Camera Motor Drive Binds/Jams (GFE)
- MER-05 Suspect Fuel Cell Monitoring System (FCMS) Data Cable (GFE)
- MER-06 Loss of DR20 Tape Recording and Playback (GFE)
- MER-07 LH2 Prevalve Open B Indicator Failed Off
- MER-07A MDM FA4 CD-08 CH-00 Has Intermittent Data Hits (ORB)
- MER-08 70 mm Hasselblad Camera S/N 1012 Motor Drive Binds/Jams (GFE)

CAMPBELL, CARLISLE C., JR (JSC-ES2) (NASA), 09:06 AM 1/31/2003 -0600, RE: FW: STS-107 Wir

From: "CAMPBELL, CARLISLE C., JR (JSC-ES2) (NASA)"  
<carlisle.c.campbell@nasa.gov>  
To: "boconnor" <boconnor@hq.nasa.gov>  
Subject: RE: FW: STS-107 Wing Debris Impact on Ascent: Final analysis case  
completed  
Date: Fri, 31 Jan 2003 09:06:08 -0600  
X-Mailer: Internet Mail Service (5.5.2653.19)

We are doing great, but it's not like the good old days.

The LaRC Center Director plans to offer their help on this debris impact concern through Bill Readdy, I have heard. We don't have much time left if there is another issue

CCC.

-----Original Message-----

From: boconnor [mailto:boconnor@hq.nasa.gov]  
Sent: Friday, January 31, 2003 5:30 AM  
To: CAMPBELL, CARLISLE C., JR (JSC-ES2) (NASA)  
Subject: Re: FW: STS-107 Wing Debris Impact on Ascent: Final analysis case completed

Carlisle,

Thanks for the info. I had heard a little bit of this, but I did not realize so much analysis was required.

How are you doing?

Best,

At 08:53 AM 1/30/2003 -0600, you wrote:

>Bryan,

>

>This is confidential, but I just wanted to be sure that you were aware of  
>the potential landing gear door damage.

>

>Carlisle

>

>> -----Original Message-----

>> From: ROCHA, ALAN R. (RODNEY) (JSC-ES2) (NASA)  
>> Sent: Sunday, January 26, 2003 7:45 PM  
>> To: SHACK, PAUL E. (JSC-EA42) (NASA); MCCORMACK, DONALD L. (DON)  
>> (JSC-MV6) (NASA); OUELLETTE, FRED A. (JSC-MV6) (NASA)  
>> Cc: ROGERS, JOSEPH E. (JOE) (JSC-ES2) (NASA); GALBREATH, GREGORY F.  
>> (GREG) (JSC-ES2) (NASA); JACOBS, JEREMY B. (JSC-ES4) (NASA);  
>> SERIALE-GRUSH, JOYCE M. (JSC-EA) (NASA); KRAMER, JULIE A. (JSC-EA4)  
>> (NASA); CURRY, DONALD M. (JSC-ES3) (NASA); KOWAL, T. J. (JOHN) (JSC-ES3)  
>> (NASA); RICKMAN, STEVEN L. (JSC-ES3) (NASA); SCHOMBURG, CALVIN (JSC-EA)  
>> (NASA); CAMPBELL, CARLISLE C., JR (JSC-ES2) (NASA)

>> Subject: STS-107 Wing Debris Impact on Ascent: Final analysis case  
>> completed  
>>  
>> As you recall from Friday's briefing to the MER, there remained open work  
>> to assess analytically predicted impact damage to the wing underside in  
>> the region of the main landing gear door. This area was considered a low  
>> probability hit area by the image analysis teams, but they admitted a  
>> debris strike here could not be ruled out.  
>>  
>> As with the other analyses performed and reported on Friday, this  
>> assessment by the Boeing multi-technical discipline engineering teams also  
>> employed the system integration's dispersed trajectories followed by  
>> serial results from the Crater damage prediction tool, thermal analysis,  
>> and stress analysis. It was reviewed and accepted by the ES-DCE (R. Rocha)  
>> by Sunday morning, Jan. 26. The case is defined by a large area gouge  
>> about 7 inch wide and about 30 inch long with sloped sides like a crater,  
>> and reaching down to the densified layer of the TPS.  
>>  
>> SUMMARY: Though this case predicted some higher temperatures at the outer  
>> layer of the honeycomb aluminum face sheet and subsequent debonding of the  
>> sheet, there is no predicted burn-through of the door, no breaching of the  
>> thermal and gas seals, nor is there door structural deformation or thermal  
>> warpage to open the seal to hot plasma intrusion. Though degradation of  
>> the TPS and door structure is likely (if the impact occurred here), there  
>> is no safety of flight (entry, descent, landing) issue.  
>>  
>> Note to Don M. and Fred O.: On Friday I believe the MER was thoroughly  
>> briefed and it was clear that open work remained (viz., the case  
>> summarized above), the message of open work was not clearly given, in my  
>> opinion, to Linda Ham at the MMT. I believe we left her the impression  
>> that engineering assessments and cases were all finished and we could  
>> state with finality no safety of flight issues or questions remaining.  
>> This very serious case could not be ruled out and it was a very good thing  
>> we carried it through to a finish.  
>>  
>>  
>> Rodney Rocha (ES2) x38889  
>> \* Division Shuttle Chief Engineer (DCE), ES-Structural Engineering

CAMPBELL, CARLISLE C., JR (JSC-ES2) (NASA), 09:06 AM 1/31/2003 -0600, RE: FW: STS-107 Wir

>> Division  
>> \* Chair, Space Shuttle Loads & Dynamics Panel  
>>  
>>

O'C

Bryan O'Connor  
Associate Administrator  
Office of Safety and Mission Assurance

Mark Kowaleski, 09:10 AM 2/4/2003 -0500, If you need help...

---

X-Sender: mkowales@mail.hq.nasa.gov  
X-Mailer: QUALCOMM Windows Eudora Version 4.3.2  
Date: Tue, 04 Feb 2003 09:10:10 -0500  
To: boconnor@mail.hq.nasa.gov  
From: Mark Kowaleski <mkowales@hq.nasa.gov>  
Subject: If you need help...

Bryan,

I just wanted to let you know that if you needed someone to be by your side to assist you during your investigation that I am willing and able.

After Jim mentioned you were asking for a bunch of info I figured you could probably use somebody with you to get clutter off your radar screen. I can work in any capacity, even if it is just taking care of your logistics, taking notes, making up charts for you, whatever.

Yesterday at the SMA telecon we got into heated discussion about crew escape. Some of the Boeing escape concepts showed descent effectivity as high 210K feet, but I really had to argue to get most folks to even consider the possibility of crew escape. I replayed in my mind the not-so-warm response I got from the Shuttle Program after I gave the crew escape and M/OD repair capability pitch at the SLEP Kick-off meeting. It bothered me so much I shed a tear over it.

As the Board's plans unfold, count me in if you need/want my support. I need to contribute to this.

I hope all is well for you during this difficult time.

Sincerely,

Mark

X-Sender: a.h.phillips@pop.larc.nasa.gov  
Date: Fri, 14 Feb 2003 12:51:21 -0500  
To: "Pamela F. Richardson" <Pamela.Richardson@hq.nasa.gov>  
From: "Alan H. Phillips" <a.h.phillips@larc.nasa.gov>  
Subject: Fwd: Euler solutions-Section 6 Removed  
Cc: "Peter J. Rutledge" <prutledg@mail.hq.nasa.gov>, Jim Lloyd <Jlloyd@hq.nasa.gov>

Some CFD results that LaRC is performing in support of JSC investigation activities.

Alan

Date: Thu, 13 Feb 2003 08:26:24 -0500  
To: jose.m.caram@nasa.gov, charles.h.campbell@jsc.nasa.gov  
From: Charles Miller <c.g.miller@larc.nasa.gov>  
Subject: Euler solutions-Section 6 Removed  
Cc: "SAUNDERS, MARK P" <M.P.SAUNDERS@larc.nasa.gov>, "PHILLIPS, ALAN H" <A.H.PHILLIPS@larc.nasa.gov>

Joe and Chuck

The attachment contains Euler solutions performed by Karen Bibb in support of the aerodynamic effort, but may be of keen interest to the aerothermodynamic folks as well. These predictions will be discussed along with Tom Horvath's material which will be sent to you shortly.

Thanks

Charles



FELISA-aeroThermo-2003-02-1.ppt

\*\*\*\*\*  
Alan H. Phillips  
Director, Office of Safety and Mission Assurance  
NASA Langley Research Center  
5A Hunsaker Loop  
Building 1162, Room 112C  
Mail Stop 421  
Hampton, VA 23681

(757)864-3361 Voice

(757)864-6327 Fax

\*\*\*\*\*




# Wing Leading Edge Damage Inviscid CFD

February 13, 2003

LaRC Aero Team

# Analysis Scenario


- Utilize existing computational model of shuttle
- Simulate damage by “removing” panel 6
- Looking for **qualitative** aerodynamic effect and flowfield characteristics



# Geometry, Meshes, and CFD Methods


- Baseline Geometry
  - Built on LAURA structured mesh, via GridTool
  - Based on geometry from JSC 1999
  - Simplified wing tip, base region
  - No control deflections
- "panel 6" geometry
  - Planform coordinates approximate, taken from estimate of location from recent public viewgraphs
  - Lines projected vertically down onto geometry, and removed.
- Mesh
  - Unstructured triangular/tetrahedral
  - GridEx - FELISA for mesh generation
  - 1.7 M points
- FELISA
  - **Inviscid**, Unstructured CFD
    - Issue with how well complex flow is handled
  - Equilibrium Air Chemistry
- 2 conditions, alpha = 40 deg.
  - from Gnoffo, et. al., JSR '94
  - Mach 23.68, STS-1
  - Mach 18.07, STS-2

# Baseline Orbiter, Cp contours



2/14/2003  
K. Bibb

# Orbiter with panel 6 removed, Cp Contours



2/14/2003

K. Bibb

# Streamlines – frontal view


20 deg  
Wach 23,68  
blue – baseline orbiter  
red – panel 6 removed

Streamlines for damaged vehicle track inboard of baseline

Inboard streamlines similar

Windside streamlines on baseline stay on windside


Blue – Baseline Orbiter  
Red – Panel 6 removed



# Streamlines – Side View

Blue – Baseline Orbiter  
Red – Panel 6 removed

Mach 2.5,  $\alpha = 10.0$  deg  
FELISA model of D. Equilibrium V. Geometry  
Trajectory point from STS-120, 0.5 sec



2/14/2003  
K. Bibb

# Streamlines – Top View



Blue – Baseline Orbiter  
Red – Panel 6 removed

2/14/2003  
K. Bibb



# Observations

- Missing section of wing leading edge has significant effect on flow over leeside
- Limitations to analysis
  - Preliminary mesh. Was 'grid converged' for Mach 10 case (Prabhu '01), (Mach 15 also?). Leeside is fairly coarse to resolve the features.
  - Euler, so separation/recirculation not accurately captured.


# Summary

- Missing section of wing leading edge potentially has significant effect on flow over leeside.
- Work in progress
  - Force and Moment Analysis – delta aero to match Aero Team's approach
  - Visualization for Mach 18 cases
- Planned for near term
  - Additional trajectory points to match STS-107
  - Refined mesh. Expect sharper shocks, but not significant change in integrated loads.
  - Other damage scenarios
    - Panel 9 removal, to assess how fuselage shock moves
    - Wheel well door missing, gear down scenarios

# Backup slides

# Planform coordinates

- Line 1: (189.8, 1036)  
to (202.9, 1024.1)
- Line 2:  
(196.7, 1046.6) to  
(210.6, 1037.3)
- Line 3: (189.8, 1036)  
to (196.7, 1046.6)



Alan H. Phillips, 12:51 PM 2/14/2003 -0500, Fwd: Euler solutions-Section 6 Removed

X-Sender: a.h.phillips@pop.larc.nasa.gov  
Date: Fri, 14 Feb 2003 12:51:24 -0500  
To: "Pamela F. Richardson" <Pamela.Richardson@hq.nasa.gov>  
From: "Alan H. Phillips" <a.h.phillips@larc.nasa.gov>  
Subject: Fwd: Euler solutions-Section 6 Removed  
Cc: "Peter J. Rutledge" <prutledg@mail.hq.nasa.gov>, Jim Lloyd <Jlloyd@hq.nasa.gov>

Some CFD results that LaRC is performing in support of JSC investigation activities.

Alan

Date: Thu, 13 Feb 2003 08:26:24 -0500  
To: jose.m.caram@nasa.gov, charles.h.campbell@jsc.nasa.gov  
From: Charles Miller <c.g.miller@larc.nasa.gov>  
Subject: Euler solutions-Section 6 Removed  
Cc: "SAUNDERS, MARK P" <M.P.SAUNDERS@larc.nasa.gov>, "PHILLIPS, ALAN H" <A.H.PHILLIPS@larc.nasa.gov>

Joe and Chuck

The attachment contains Euler solutions performed by Karen Bibb in support of the aerodynamic effort, but may be of keen interest to the aerothermodynamic folks as well. These predictions will be discussed along with Tom Horvath's material which will be sent to you shortly.

Thanks

Charles

 FELISA-aeroThermo-2003-02-1.ppt

\*\*\*\*\*  
Alan H. Phillips  
Director, Office of Safety and Mission Assurance  
NASA Langley Research Center  
5A Hunsaker Loop  
Building 1162, Room 112C  
Mail Stop 421  
Hampton, VA 23681

Alan H. Phillips, 12:51 PM 2/14/2003 -0500, Fwd: Euler solutions-Section 6 Removed

---

(757)864-3361 Voice

(757)864-6327 Fax

\*\*\*\*\*


# Wing Leading Edge Damage Inviscid CFD

February 13, 2003

LaRC Aero Team

# Analysis Scenario

- Utilize existing computational model of shuttle
- Simulate damage by “removing” panel 6
- Looking for *qualitative* aerodynamic effect and flowfield characteristics






# Geometry, Meshes, and CFD Methods


- Baseline Geometry
  - Built on LAURA structured mesh, via GridTool
  - Based on geometry from JSC 1999
  - Simplified wing tip, base region
  - No control deflections
- "panel 6" geometry
  - Planform coordinates approximate, taken from estimate of location from recent public viewgraphs
  - Lines projected vertically down onto geometry, and removed.
- Mesh
  - Unstructured triangular/tetrahedral
  - GridEx - FELISA for mesh generation
  - 1.7 M points
- FELISA
  - **Inviscid**, Unstructured CFD
    - Issue with how well complex flow is handled
  - Equilibrium Air Chemistry
- 2 conditions, alpha = 40 deg.
  - from Gnoffo, et. al., JSR '94
  - Mach 23.68, STS-1
  - Mach 18.07, STS-2

# Baseline Orbiter, Cp contours




2/14/2003  
K. Bibb

# Orbiter with panel 6 removed, Cp Contours



2/14/2003  
K. Bibb

# Streamlines – frontal view





Blue – Baseline Orbiter  
 Red – Panel 6 removed

2/14/2003  
 K. Bibb

# Streamlines – Side View

Blue – Baseline Orbiter  
Red – Panel 6 removed


Mach 23.68, alpha=40.0 deg  
FELISA Physical CFD Equilibrium Air Chemistry  
Trajectory point from STS-1, gnomib JSR 91 analysis



2/14/2003  
K. Bibb

# Streamlines – Top View

March 23 08, alpha=40.0 deg  
FELISA inviscid CFD Equilibria  
trajectory point from SFS-1, ghaifa JSR '04 analysis



blue – baseline orbiter  
red – panel 6 removed

Blue – Baseline Orbiter  
Red – Panel 6 removed

2/14/2003  
K. Bibb

# Observations

- Missing section of wing leading edge has significant effect on flow over leeside
- Limitations to analysis
  - Preliminary mesh. Was 'grid converged' for Mach 10 case (Prabhu '01), (Mach 15 also?). Leeside is fairly coarse to resolve the features.
  - Euler, so separation/recirculation not accurately captured.

# Summary

- Missing section of wing leading edge potentially has significant effect on flow over leeside.
- Work in progress
  - Force and Moment Analysis – delta aero to match Aero Team's approach
  - Visualization for Mach 18 cases
- Planned for near term
  - Additional trajectory points to match STS-107
  - Refined mesh. Expect sharper shocks, but not significant change in integrated loads.
  - Other damage scenarios
    - Panel 9 removal, to assess how fuselage shock moves
    - Wheel well door missing, gear down scenarios




# Backup slides

2/14/2003  
K. Bibb

# Platform coordinates

- Line 1: (189.8, 1036)  
to (202.9, 1024.1)
- Line 2:  
(196.7, 1046.6) to  
(210.6, 1037.3)
- Line 3: (189.8, 1036)  
to (196.7, 1046.6)



2/14/2003  
K. Bibb

X-Sender: mkowales@mail.hq.nasa.gov

X-Mailer: QUALCOMM Windows Eudora Version 4.3.2

Date: Fri, 24 Jan 2003 12:49:46 -0500

To: prutledg@mail.hq.nasa.gov, jlloyd@mail.hq.nasa.gov,  
mgreenfi@mail.hq.nasa.gov, boconnor@mail.hq.nasa.gov,  
wbihner@mail.hq.nasa.gov, gwhite1@mail.hq.nasa.gov,  
rpatrican@hq.nasa.gov, mcard@hq.nasa.gov, prichardson@hq.nasa.gov,  
fchandle@mail.hq.nasa.gov

From: Mark Kowaleski <mkowales@hq.nasa.gov>

Subject: STS-107 Status Report for January 24

The STS-107 mission continues to go well. Research activities in the SpaceHab module, comprising 80+ experiments are going well. Consumables margins continue to exceed predictions and will contribute to a higher than expected landing weight.

Analysis of the landing weight determined that it may be very close to the 233,000-pound certification limit (expected to be near 233,600 lbs). Ground controllers and the Mission Evaluation Room (MER) engineers will continue to monitor cryo consumption to better estimate end-of-mission landing weight.

At the MMT today they discussed the analysis that is taking place:

-Payload interfaces (OK) -Landing gear and tires (OK) -Steering (OK) -Thermal at bondline (TBD but expected to be OK) -Reentry trajectory (OK) -Main engine nozzle loading (TBD but expected to be OK) - also, consumables during landing phase is being reassessed.

Prior history of high landing weights:

STS-90 was right at 233K

STS-87 at 233,090

STS-83 at 235,286 (early mission termination due to fuel cell problem)

Evaluation of the debris seen in the video and film review determined that there may be significant tile damage; however, not to the extent that would result in burnthrough or catastrophic failure. The evaluation also determined that there should be no adverse effect to the RCC panels due to the angle (glancing) of potential impact predicted.

My thoughts: If the damage was any worse, we could have been looking at a real serious problem (rekindles the "on-orbit repair capability" discussion). We won't know the real extent of the damage until the orbiter comes back and we unload the detailed photographs. Leading theory is that the foam originated from the bipod ramp vicinity (this was issue for STS-112 and discussed at length at STS-113 FRR). If from bipod area, then this is 4th instance of major foam from that area (STS-112, 32, and 50). Build paper is being reviewed for the last few and next few tanks - nothing out-of-family has turned up with regard to foam application.

Mark

From: "ERMINGER, MARK D. (JSC-NC) (NASA)" <mark.d.erminger@nasa.gov>

To:

Subject: Shuttle Standup Notes 1/23/03

Date: Thu, 23 Jan 2003 08:21:00 -0600

X-Mailer: Internet Mail Service (5.5.2653.19)

STS-114 (OV-104) 3/1/03

- \* Payload Bay Doors closed
- \* Aft close-outs complete
- \* VAB rollout Wednesday morning

STS-115 (OV-105) 5/23/03

- \* FRCS installation complete
- \* OMS Crossfeed drain
- \* Preps for pod removal
- \* RMS removal in work
- \* MPS feedline inspections

VAB

- \* STS-114 stack close-outs

Stennis

- \* Battleship flowliner 520 second test completed
- \* Will boroscope strain gauges and then run another test on Monday
- \* Gen Kostelnick, Art Stevenson, STS-113 crew, and John Young observed the test

SSME

- \* All Stennis test data on the engine was nominal

USA Booster

- \* Post flight reviews look good so far
- \*
- \* Motor
- \* Post flight review is going well
- \* Test firing 1 PM MST today
- \*
- \* ET
- \* Gen Kostelnick visited MAF yesterday
- \* Are working the debris issue
- \* We know generally where the debris came from
- \* We will have to wait until the Orbiter gets back
- \*
- \* USA Orbiter
- \* Vehicle is doing well on orbit
- \* Working debris analysis
- \* BSTRATIM next week at MSFC
- \* Will focus on plans for OV-103
- \* Are developing a tool to inspect the 12" lines

Vehicle Engineering

- \* OMM Review next week

USA Integration

- \* Debris analysis completed a couple of runs looking at 20x10x6 and 20x16x6
- \* Provided input area, velocity, and impact to Orbiter

EVA

- \* 6 Hr 51 Min EVA on Station last week

Upgrades

- \* SLEP Summit kicked off last week

Hale

- \* STS-114 Orbiter Rollout Review Tuesday

Ham

- \* Flight is going well
- \* Working end of mission weight because of extra cryo
- \* Are controlling Spacehab temperature and humidity with the Orbiter
- \* MMT tomorrow, Monday and Thursday
- \* Landing is Saturday 7:49 AM CST

Other info after the meeting

- \* The STS-114/ULF-1 FRR may slip to 2/19 or 2/20

From: "ERMINGER, MARK D. (JSC-NC) (NASA)" <mark.d.erminger@nasa.gov>

To:

Subject: Shuttle Standup Notes 1/30/03

Date: Thu, 30 Jan 2003 08:11:18 -0600

X-Mailer: Internet Mail Service (5.5.2653.19)

STS-114 (OV-104) 3/1/03

- \* Rollout to OPF
- \* In the process of Orbiter to ET Mate
- \* Rolling to the pad on Wed 0700
- \* Potential of heavy weather Wed afternoon and may roll earlier

STS-115 (OV-105) 5/23/03

- \* Fuel Cell 1 R/R
- \* Preps for right OMS pod removal

OV-103

- \* OMM

Stennis

- \* 580 second test on Engine 0526
- \* 11th start of Pratt 11
- \* Another test today

SSME

- \* Data looked good on the last test

USA Booster

- \* Continuing to gather test on the ETA Ring
- \* ESD is working FOD Awareness
- \* They found some potential FOD in the bottom of a motor on the liner (paint and wood chip)

- \* ET
- \* Nothing new on TPS issue

USA Orbiter

- \* The vehicle is working great
- \* Ready for landing on Saturday
- \* OMM Review today

Vehicle Engineering

- \* BSTR review at MSFC today
- \* 12" tool development is more challenging
- \* Cockpit review at Owego next week

Segert

- \* Successfully launched Delta 2
- \* That was one of the flights in our way

Ham

- \* Working hard to get the cameras out on the runway to process for foam loss review
- \* Weather looking good for landing Saturday 8:15 CST

X-Sender: wbihner@mail.hq.nasa.gov  
X-Mailer: QUALCOMM Windows Eudora Version 4.3.2  
Date: Mon, 13 Jan 2003 08:57:28 -0500  
To: "Bryan O'Connor" <boconnor@hq.nasa.gov>  
From: Bill Bihner <wbihner@hq.nasa.gov>  
Subject: Weather Outlook for STS-107  
Cc: Michael Greenfield <mgreenfi@hq.nasa.gov>,  
Pete Rutledge <prutledg@hq.nasa.gov>,  
Mark Kowaleski <mkowales@hq.nasa.gov>

The CCAFS weather folks are saying 95% go for weater for launch on Thursday. The SMG forecasts for RTLS and TAL weather are also forecast "Go"

Bill



X-Sender: wbihner@mail.hq.nasa.gov  
X-Mailer: QUALCOMM Windows Eudora Version 4.3.2  
Date: Fri, 17 Jan 2003 09:47:10 -0500  
To: "Bryan O'Connor" <boconnor@hq.nasa.gov>  
From: Bill Bihner <wbihner@hq.nasa.gov>  
Subject: STS-107 Mission Status  
Cc: Pete Rutledge <prutledg@hq.nasa.gov>,  
Mark Kowaleski <mkowales@hq.nasa.gov>

The STS-107 mission is going very well.

SRB reported that the SRBs were slightly hotter than normal and that the forward skirt buckled on water impact. SRBs will be back to the port today and open assessment will start Monday.

Launch pad damage was nominal.

The crew is on the timeline for sleep periods and payload activity. The MER reported two issues/funnies that they are working and neither have mission impact so far:

During the pre-launch/post-insertion time period, AC2 phase B exhibited sluggish current increase during motor operation on three motors. The first occurrence of the sluggish performance was noted at T-31 seconds, and the second and third occurrences were noted during the post-insertion activities. AC2 phases A and C would increase to their expected values, but phase B would increase only to about half of expected value, then recover to the expected value within about a second. The affected motors are: vent doors 8 and 9, Ku-band deploy motor 2, and port payload bay door open motor 2. There was no impact to motor drive times. There is no common circuit breaker/motor control assembly. All other motor signatures analyzed were nominal, some of which are powered from the same circuit breaker/motor control assemblies as the affected motors.

During Spacehab activation, the crew reported that transmissions from the Orbiter on the intercommunications (ICOM) B loop were not being heard in the Spacehab module. Communications on the ICOM A loop were satisfactory. This loss of redundancy should not affect the continuing mission operations.

The next MMT will be on Tuesday, January 21.

Bill

X-Sender: wbihner@mail.hq.nasa.gov

X-Mailer: QUALCOMM Windows Eudora Version 4.3.2

Date: Fri, 31 Jan 2003 08:38:41 -0500

To: "Bryan O'Connor" <boconnor@hq.nasa.gov>

From: Bill Bihner <wbihner@hq.nasa.gov>

Subject: STS-107 Mission Status

Cc: Jim Lloyd <jlloyd@hq.nasa.gov>, Pete Rutledge <prutledg@hq.nasa.gov>, Mark Kowaleski <mkowales@hq.nasa.gov>, Richard Patrican <rpatrica@hq.nasa.gov>, Gil White <gwhite1@hq.nasa.gov>

Bryan,

The item below was also discussed at yesterday's MMT meeting. The bottom line is that after early problems with pump 1, they switched to pump 2 and cooling in the Hab became a non-issue. Yesterday they reported a nearly doubling in the blockage with the pump 2 system over the last 48 hours and were concerned that they might need to shut pump 2 down and go back to pump 1. If we can't control cooling in the Hab, then we will definitely lose science. So, although we have consumables enough to support landing through Wed, Feb 5, if this becomes an issue, they may want to land earlier, even if it means an EDW landing. Right now its not an issue and landing first opportunity is still scheduled for Saturday around 0915 EST and weather looks favorable. Will keep you posted.

Bill

NEW: MER-009 (Spacehab Water Loop Flow Degradation ORB). The payload heat exchanger and total flow rates for the Spacehab water loop have been steadily decreasing throughout the mission; the Spacehab water pump outlet pressure is also decreasing; pump 2 was initially run but the switch to pump 1 was made early in the mission; t/s post-landing to determine if Orbiter hardware is the cause of the problem or has in any way been impacted by the problem; the hardware consists of the payload heat exchanger and the water lines leading to and from the interface panel.

X-Sender: wbihner@mail.hq.nasa.gov  
X-Mailer: QUALCOMM Windows Eudora Version 4.3.2  
Date: Wed, 22 Jan 2003 11:25:13 -0500  
To: "Bryan O'connor" <boconnor@hq.nasa.gov>  
From: Bill Bihner <wbihner@hq.nasa.gov>  
Subject: STS-107 cooling problems information  
Cc: Pete Rutledge <prutledg@hq.nasa.gov>,  
Mark Kowaleski <mkowales@hq.nasa.gov>,  
Richard Patrican <rpatrica@hq.nasa.gov>

Bryan,

Here's how the Press is characterizing the STS-107 payload cooling system problem.

Bill

Article from Florida Today, Jan 21, 11:13 PM:

Shuttle cooling system fails

By Chris Kridler

FLORIDA TODAY

CAPE CANAVERAL -- The crew of Columbia is a little warmer after multiple cooling system malfunctions on the shuttle Tuesday. A day's worth of data was lost on one of about 80 experiments on board, but the crew's scientific research should not be endangered by the problem, said Phil Engelauf of mission control in Houston. "We don't believe there's going to be a loss of science by the end of mission," he said. "We think we'll have recovered everything." The cooling equipment for Spacehab, the research module in the shuttle's payload bay, creates condensation, much as a house's air conditioner does. Because there's no gravity, the water can't just flow into the tank. The equipment that diverts the water flooded, possibly because of a blockage, and malfunctioned. An alternate system was crippled by an apparent electrical short. The orbiter now is supplying cool air for both the shuttle and Spacehab, Engelauf said, and the crew is comfortable. The experiments, however, could use more cooling. The astronauts will adjust valves on lines under Spacehab's floor to try to increase the flow of cooling water to the experiments. The temperature on the shuttle is usually about 72 degrees, but it peaked at 84 before falling back to about 76, Engelauf said. The crew reaches Spacehab through a tunnel that leads from the orbiter's middeck. The experiment that lost data Tuesday is designed to evaporate urine to filter out impurities and create drinking water. It needs a lot of cooling. It's a test for a system planned for the International Space Station. In an unrelated problem, a tray jammed on an experiment examining growth of bacteria and fungi in microgravity. Specimens on that tray were lost, mission scientist John Charles said. The experiment's five remaining trays are intact. Mission controllers also are working around frequent crashes of a ground system processing some of the data from

Spacehab. The scientific data can be recorded when there's a crash, Engelauf said, so there's no loss of information. "It's largely an inconvenience at this point, but it isn't costing us any science," he said. Despite the problems, the crew is doing well, Engelauf said. "They all seem to be very happy with the conduct of the science, with the interaction between the crew and the ground," he said.

X-Sender: wbihner@mail.hq.nasa.gov  
X-Mailer: QUALCOMM Windows Eudora Version 4.3.2  
Date: Wed, 22 Jan 2003 10:02:42 -0500  
To: "Bryan O'connor" <boconnor@hq.nasa.gov>  
From: Bill Bihner <wbihner@hq.nasa.gov>  
Subject: Fwd: STS-107 FD06 Report  
Cc: Pete Rutledge <prutledg@hq.nasa.gov>,  
Mark Kowaleski <mkowales@hq.nasa.gov>,  
Richard Patrican <rpatrica@hq.nasa.gov>,  
James Lloyd <jlloyd@hq.nasa.gov>

## STS-107 Flight Day 06 Report

Shift Leads: Doug McMullen, Richard Foster, Denise Londrigran  
Mission Engineer: Dan Zalit (OJT)

The STS-107 mission is progressing nominally and all Orbiter subsystems are performing satisfactorily. The Orbiter consumables remaining are above the levels required for completion of the planned mission.

One item currently under investigation is the Space Shuttle Main Engine (SSME) 3 liquid hydrogen (LH2) pre valve (PV6) open indicator "A" that initially failed to the off state at 016:17:25 GMT (00:01:46 MET). Four additional data dropouts of this same measurement have been observed in the last five days. The measurement in question is provided to the general purpose computer (GPC) via multiplexer/demultiplexer (MDM) flight aft (FA) 4 Card 08 Channel 00. Review of all measurements routed through the same MDM card and channel revealed four liquid oxygen (LO2) Pogo Valve Open indications that had also failed to the off state. Of the nine measurements that indicated a failed off state, only one LO2 and one LH2 indication occurred at the exact same time. The investigation of the cause of these indications is underway.

Shuttle held two meetings to address the SpaceHab Humidity/Water Separator Assembly (WSA) problems. Shuttle and Payload safety attended. There were two issues that the flight director wanted to address, (1) water loop valve modulation to reduce the temperature/humidity, and (2) an IFM to remove water and possible debris from RS#1, and an electrical troubleshooting. After the Valve Modulation didn't yield expected results the Program has decided to go ahead with the WSA IFM, which will repair one of the failed water separators, it is currently being modified to suit the current situation. A copy of the most current rev is at the console. The crew will continue to try and attain better results using the Valve Modulation, but the program will probably look more to trying to recover one of the water separators if possible. The IFM will require MT approval before proceeding. Execution of the IFM at this time is TBD.

There is one new MER anomaly

MER Anomalies:

- MER-01 AC2 Phase B Sluggish Current Signature
- MER-02 No ICOMB in Spacehab
- MER-03 O2 Tank 7 Heater A Failed Off in Manual Mode (ORB)
- MER-04 70MM Hasselblad Camera Motor Drive Binds/Jams (GFE)
- MER-05 Suspect Fuel Cell Monitoring System (FCMS) Data Cable (GFE)
- MER-06 Loss of DR20 Tape Recording and Playback (GFE)
- MER-07 LH2 Prevalve Open B Indicator Failed Off

X-Sender: mkowales@mail.hq.nasa.gov  
X-Mailer: QUALCOMM Windows Eudora Version 4.3.2  
Date: Sat, 08 Feb 2003 09:54:57 -0500  
To: James Lloyd <jlloyd@hq.nasa.gov>, boconnor <boconnor@hq.nasa.gov>  
From: Mark Kowaleski <mkowales@hq.nasa.gov>  
Subject: Re: Space Shuttle Columbia Tragedy  
Cc: prichard@hq.nasa.gov, prutledg@hq.nasa.gov, jlemke <jlemke@hq.nasa.gov>, mark Kowaleski <mkowales@hq.nasa.gov>, michael Greenfield <michael.greenfield@hq.nasa.gov>

Not sure if Michael Greenfield approved yet, but it is in the Columbia Action Center's (CAC) database, at least in this draft form.

At 09:12 AM 2/8/2003 -0500, James Lloyd wrote:

Bryan,

Some interesting information that you will probably be interested in reading. Mark K. sent it to me and it came from (approved by?) the Columbia Action Center led by Michael G.

"Safety is priority one" is embedded in this and I am not going to spend any time explaining the foible of that statement, i. e. it isn't a trade point - it's a fundamental value. The paragraph includes some anecdotal observations to underscore the statement. The paper, I am sure, was written by a budgeteer. I feel like we are constantly tilting at that wind mill and too no avail. If people are even listening they still are not understanding the distinction. Sorry for the rant but it's a minor frustration that I can't seem to communicate this so it's understood.

Jim

X-Sender: mkowales@mail.hq.nasa.gov  
X-Mailer: QUALCOMM Windows Eudora Version 4.3.2  
Date: Mon, 10 Feb 2003 08:18:32 -0500  
To: linda.j.ham@nasa.gov  
From: Mark Kowaleski <mkowales@hq.nasa.gov>  
Subject: Fwd: stress/thermal analysis request  
Cc: stuart.l.mcclung@nasa.gov, boconnor@mail.hq.nasa.gov,  
jloyd@mail.hq.nasa.gov, pruttedg@mail.hq.nasa.gov,  
mark.d.erminger1@jsc.nasa.gov, yolanda.y.marshall@nasa.gov

Hello Linda,

I work for Bryan O'Connor as the HQ Shuttle Safety Manger in Code Q. Stuart McClung said that I needed to request the STS-107 TPS Multi-Tile Loss Thermal Analysis data package from you (see note below). I have been trying to get this document for over a week and no one seems to either want to part with it or locate it.

We have the Foam Transport Assessment and the TPS Damage Assessment from Boeing. The requested analysis is referenced in the conclusion of the Boeing Orbiter TPS Assessment, dated 1-23-03.

Would you please get me a copy of the thermal analysis? We need it for the NASA Administrator's talking points for his testimony on Wednesday.

Mark

From: "MCCLUNG, STUART L. (JSC-MV6) (NASA)" <stuart.l.mcclung@nasa.gov>  
To: "mkowales@mail.hq.nasa.gov" <mkowales@mail.hq.nasa.gov>  
Subject: stress/thermal analysis request  
Date: Sat, 8 Feb 2003 17:41:18 -0600  
X-Mailer: Internet Mail Service (5.5.2653.19)

Mark, cut and pasted the note I sent to Linda, and the guys on the affected team.

stu

We provided HQ/Mark Kowaleski with copies of the 1/23 and 1/24 presentations on the debris impact and Orbiter assessment. They have requested the thermal analysis that is referenced on the last page in the conclusion. I've talked with McCormack and Rodney and they walked me thru the review of the analysis, and noted that we do not have copies of the actual analysis that Mike and his team performed. Normal routine, actually.

HQ has requested copies of the analysis, and in my opinion, more for completeness than any of their own review. Fred told me that as of today, these type of requests need to go thru the MRT, so I'm going to direct Mark



to make the request thru that route, but I'd suggest that Mike and co., be ready for the request.

From: "ERMINGER, MARK D. (JSC-NC) (NASA)" <mark.d.erminger@nasa.gov>  
To:  
Subject: Shuttle Standup Notes 2/10/03  
Date: Mon, 10 Feb 2003 14:14:17 -0600  
X-Mailer: Internet Mail Service (5.5.2653.19)

Dittmore

- \* Met with CAIB for a couple of days last week
- \* They will be here Mon and Tuesday, KSC Wednesday, then MSFC and MAF
- \* We are making progress. We are getting a lot of data from the field
- \* We are working hard on the fault trees and testing plans
- \* Visited Barksdale yesterday

Ham

- \* On Saturday the MRT talked about processes

STS-114 (OV-104)

- \* In a maintenance mode

STS-115 (OV-105)

- \* Fuel Cell #1 installed
- \* Removing Right OMS pod tomorrow for structural inspections
- \* MPS system testing

OV-103

- \* Very busy with OMM Activity
- \*
- \* VAB
- \* Booster buildup for STS-117

Stennis

- \* Finished post test inspections on Engine 0526

USA Booster

- \* Supporting Independent team at MSFC
- \*
- \* Motor
- \* Working Group in Utah looking at nozzles and paper
- \* Flex Boot tear problem in work
- \*
- \* ET
- \* Have 5 test proposals
- \* Looked at areas at MAF that we would like to re-open
- \*
- \* USA Orbiter
- \* Working to get Palmdale team populated early this week

Vehicle Engineering

- \* CAU Team was in Owego all week

- \* Have some hardware technical issues
- \* Have plans and schedules to solve those problems
- \* Significant Finds - ET Sep Camera from umbilical well
- \* Upper atmosphere scientists in over the weekend
- \* Are pushing Fault Tree out in front to drive testing

#### Systems Integration

- \* Will have a draft schedule for the MRT tomorrow
- \* Integration Management Review here Thursday

#### HQ

- \* In a press to put together answers to the questions from O'Keefe  
Congressional testimony on Wednesday

#### Kostelnick

- \* We can defer CAU Review if it gets in the way

#### Hale

- \* Expect 3 trucks on Wednesday for the Reconstruction Team
- \* The Salvation Army has been feeding our people in Lufkin 3 meals per day

#### Ham

- \* Have an Org Chart to show how we report to the CAIB
- \* All data from working groups must go through the MRT before it goes to the CAIB

#### Galvez.ISS

- \* ISS decision point is 2/13 on whether they want to launch 2 or 3 crew members on the next Soyuz flight to ISS
- \* The next Station mission will be ULF-1

ERMINGER, MARK D. (JSC-NC) (NASA), 09:21 AM 2/6/2003 -0600, Shuttle Standup Notes 2/6/03

From: "ERMINGER, MARK D. (JSC-NC) (NASA)" <mark.d.erminger@nasa.gov>

To:

Subject: Shuttle Standup Notes 2/6/03

Date: Thu, 6 Feb 2003 09:21:07 -0600

X-Mailer: Internet Mail Service (5.5.2653.19)

Dittemore

- \* Meeting with the Columbia Accident Investigation Board (CAIB) today at 8 AM
- \* As of today, the MRT and MIT will be under the CAIB
- \* Task Force led by Frank Buzzard will be the Admin arm of the CAIB

Ham

- \* MRT will be at 10 AM today
- \* Hope to move to Bld 1 on Monday
- \* Will start asking for formal charts
- \* Requests for interviews from the press need to go through Ron

Dittemore

- \* FOIA requests need to go through Linda Ham and the CSR

Dittemore

- \* Have pre-approved certain people to be able to talk to the media about background info
- \* The investigation will not involve every single person and he understands their desire to participate
- \* Managers need to keep the program going and not conflict with the investigation
- \* Infrastructure revitalization, SLEP, Training, and other things would be good things to work on

MSFC

\*

STS-114 (OV-104)

- \* Finished Orbiter ET Mate and Shuttle Interface Test

STS-115 (OV-105)

- \* Fuel Cell installed

OV-103

- \* Mods and inspections

\*

SSME

- \* One more test at Stennis on the flowliner

USA Booster

- \* SRB IA Team looking at hardware and paperwork
- \* Will start processing flight hardware today

\*

- \* Motor
- \* RSRM IA Team is at KSC this week and Utah next week
- \* USA Orbiter
- \* Engineering team is looking at OV-104 in VAB Payload Bay Moisture requirement
- \* Working the design of the BSTRA tool

#### Vehicle Engineering

- \* Deep into data review
- \* Data request go through the MER

#### USA Integration

- \* Integration Management Review next week in Houston

#### KSC

- \* Memorial Service at KSC on Friday

#### USA Flight Ops

- \* All MCC and Training systems back on line

#### MOD

- \* ISS support continues
- \* Will start training again next week

#### Upgrades

- \* Direction from HQ on SLEP Summit to maintain dates in March
- \* Support for each of the panels varies
- \* Will decide for sure next week

#### HQ

- \* Memorial at the National Cathedral at 10 EST today

#### USA

- \* Working optimum use of vehicles to support the manifest

#### Dittemore

- \* Asked the manifest people to work options assuming 4/1 or 6/1 resumption of flights

**Alan H. Phillips, 04:43 PM 2/27/2003 -0500, LaRC Wind Tunnel Testing Results**

---

X-Sender: a.h.phillips@pop.larc.nasa.gov  
Date: Thu, 27 Feb 2003 16:43:19 -0500  
To: "Pamela F. Richardson" <Pamela.Richardson@hq.nasa.gov>  
From: "Alan H. Phillips" <a.h.phillips@larc.nasa.gov>  
Subject: LaRC Wind Tunnel Testing Results  
Cc: "Peter J. Rutledge" <prutledg@mail.hq.nasa.gov>, Jim Lloyd <Jlloyd@hq.nasa.gov>

Pam/Jim/Pete:

Attached is a report that summarizes work that the LaRC aerothermal guys have performed working with the Ralph Roe team at JSC. It is my understanding that these results have been briefed to the folks at JSC.

Alan

 [Horvath.pdf](#)

\*\*\*\*\*  
Alan H. Phillips  
Director, Office of Safety and Mission Assurance  
NASA Langley Research Center  
5A Hunsaker Loop  
Building 1162, Room 112C  
Mail Stop 421  
Hampton, VA 23681

(757)864-3361 Voice  
(757)864-6327 Fax  
\*\*\*\*\*

# **LaRC Wind Tunnel Testing in Support of Orbiter External Aerothermodynamics**


Status Report  
February 13, 2003

Thomas J. Horvath  
Aerothermodynamics Branch  
NASA Langley Research Center

# LaRC Near Term Experimental Aerothermodynamic Support

## Objective

- Provide rapid assessment of localized OML shape changes on Orbiter aerothermodynamics and aerodynamics



## Motivation

- Most failure scenarios involve leading edge/acreage TPS damage

## Approach

- Closely coupled aerodynamic and heat-transfer ground based testing

## Simulated surface discontinuity

Protuberance

Asymm b.l.  
transition

## Aero

Laminar/turb  
heating augmentation

## MLG wheel well

## Fuselage

Heating  
augmentation

Cavity


Asymm b.l.  
transition

Laminar/turb  
heating augmentation

Heating  
augmentation



# Orbiter L.E. Sensitivity Study



IR camera

0.0075 scale  
ceramic  
heating  
model

Trip full scale

Height 0.47-in  
Size 13 x 13-in

$M_e \approx 2.3 @ x/l = 0.6 CL$

Run = 10  
 $Re_{\infty, L} = 1.74 \times 10^6$   
 $Re_{2, L} = 0.30 \times 10^6$   
 $M_{\infty} = 6$

$M_e \approx 2.3 @ x/l = 0.6 CL$

Run = 7  
 $Re_{\infty, L} = 2.43 \times 10^6$   
 $Re_{2, L} = 0.42 \times 10^6$   
 $M_{\infty} = 6$

For STS-28 Early Transition  $M_{\infty} = 17.9$


$Re_{\infty, L} \approx 2.4 \times 10^6$   
 $Re_{2, L} \approx 0.4 \times 10^6$   
 $M_e \approx 3 @ x/l = 0.6 CL$

Bouslog  
 OEX Aerothermo Sym  
 1995

# Shuttle Orbiter Surface Streamlines

LAURA Inviscid  $M_\infty = 6$ ,  $\alpha = 40$  deg

Attachment Line





Proximity of LE "disturbance"  
to attachment line impacts the  
acreeage of TPS affected by  
boundary layer transition...

# Effect of L.E. Roughness on Orbiter Windward Thermal Mapping


## NASA LaRC 20-Inch Mach 6 Air

$\alpha = 40$  deg    Baseline    0.0075 Scale

Model	FS
Trip height (in)	0.0035    0.47
Trip size (in)	0.1x0.1    13x13




Run = 2  
 $Re_{\infty, L} = 1.75 \times 10^6$



Run = 5  
 $Re_{\infty, L} = 2.42 \times 10^6$

NASA Langley  
 Aerothermodynamics Branch




Run = 6  
 $Re_{\infty, L} = 3.31 \times 10^6$

Bow/wing shock  
 interaction induced transition

# Wing Leading Edge OML Sensitivity Study


- Tunnel occupancy to date (2-12-03) : 4 days
- Facility: NASA LaRC 20-Inch Mach 6
- Deliverables: Global surface temperature mappings to infer b.l. transition.  
Global heating to determine augmentation levels above laminar levels.

**Leading edge protuberance  
RCC panel #6**



**Orbiter windward  
surface temperatures**

**Leading edge panel cutout  
RCC panel #6**



**Orbiter side fuselage heating**

# Effect of L.E. Roughness on Orbiter Windward Thermal Mapping




## NASA LaRC 20-Inch Mach 6 Air

$\alpha = 40$  deg Panel # 1 0.0075 Scale


Model FS

Trip height (in) 0.0035 0.47

Trip size (in) 0.1x0.1 13x13



NASA Langley  
 Aerothermodynamics Branch







# Effect of L.E. Roughness on Orbiter Windward Thermal Mapping

NASA LaRC 20-Inch Mach 6 Air

$\alpha = 40$  deg Panel # 6 0.0075 Scale

Model FS  
 Trip height (in) 0.0035 0.47  
 Trip size (in) 0.1x0.1 13x13







NASA Langley  
 Aerothermodynamics Branch

# Effect of L.E. Roughness on Orbiter Windward Thermal Mapping

NASA LaRC 20-Inch Mach 6 Air

$\alpha = 40$  deg Panel # 9 0.0075 Scale

Model FS  
 Trip height (in) 0.0035 0.47  
 Trip size (in) 0.1x0.1 13x13





# Effect of L.E. Roughness on Orbiter Windward Thermal Mapping


NASA LaRC 20-Inch Mach 6 Air

$\alpha = 40 \text{ deg}$  Panel # 12 0.0075 Scale

	Model	FS
Trip height (in)	0.0035	0.747
Trip size (in)	0.1x0.1	13x13




Run = 21  
 $Re_{\infty, L} = 1.73 \times 10^6$



Run = 22  
 $Re_{\infty, L} = 2.43 \times 10^6$

NASA Langley  
 Aerothermodynamics Branch



Run = 23  
 $Re_{\infty, L} = 3.24 \times 10^6$





# Effect of L.E. Roughness on Orbiter Windward Thermal Mapping


NASA LaRC 20-Inch Mach 6 Air

$\alpha = 40 \text{ deg}$  Panel # 16 0.0075 Scale

	Model	FS
Trip height (in)	0.0035	0.47
Trip size (in)	0.1x0.1	13x13




Run = 28  
 $Re_{\infty, L} = 1.7 \times 10^6$



Run = 29  
 $Re_{\infty, L} = 2.38 \times 10^6$

NASA Langley  
 Aerothermodynamics Branch



Run = 30  
 $Re_{\infty, L} = 3.36 \times 10^6$



Bow/wing shock  
 interaction induced transition

# Effect of Roughness on Orbiter Windward Thermal Mapping


NASA LaRC 20-Inch Mach 6 Air

$\alpha = 40$  deg    Inboard LGMD    0.0075 Scale

	Model	FS
Trip height (in)	0.0035	0.47
Trip size (in)	0.05x0.05	7x7




Run = 32  
 $Re_{\infty, L} = 1.71 \times 10^6$



Run = 33  
 $Re_{\infty, L} = 2.4 \times 10^6$

NASA Langley  
 Aerothermodynamics Branch



Run = 34  
 $Re_{\infty, L} = 3.33 \times 10^6$


Bow/wing shock  
 interaction induced transition

# Effect of Roughness on Orbiter Windward Thermal Mapping


NASA LaRC 20-Inch Mach 6 Air

$\alpha = 40$  deg    Outboard LGMD    0.0075 Scale


	Model	FS
Trip height (in)	0.0035	0.47
Trip size (in)	0.05x0.05	7x7



LGMD




Run = 36  
 $Re_{\infty, L} = 1.72 \times 10^6$



Run = 37  
 $Re_{\infty, L} = 2.43 \times 10^6$

NASA Langley  
 Aerothermodynamics Branch



Run = 38  
 $Re_{\infty, L} = 3.35 \times 10^6$



Bow/wing shock  
 interaction induced transition

# Effect of Roughness on Orbiter Windward Thermal Mapping


NASA LaRC 20-Inch Mach 6 Air

$\alpha = 40 \text{ deg}$  0.0075 Scale


Model	FS
Trip height (in)	0.0035
Trip size (in)	0.05x0.05 7x7



Run = 41  
 $Re_{\infty, L} = 1.72 \times 10^6$



Run = 42  
 $Re_{\infty, L} = 2.43 \times 10^6$



Run = 43  
 $Re_{\infty, L} = 3.35 \times 10^6$   
Bow/wing shock  
interaction induced transition

# Effect of L.E. Roughness on Orbiter Windward Nondimensional Heating



NASA LaRC 20-Inch Mach 6 Air

$\alpha = 40$  deg    Baseline    0.0075 Scale


Model    FS  
 Trip height (in)    0.0035    0.47  
 Trip size (in)    0.1x0.1    13x13



$h/h_{ref}$




Run = 2  
 $Re_{\infty, L} = 1.75 \times 10^6$



Run = 5  
 $Re_{\infty, L} = 2.42 \times 10^6$

NASA Langley  
 Aerothermodynamics Branch



Run = 6  
 $Re_{\infty, L} = 3.31 \times 10^6$




Bow/wing shock  
 interaction induced transition

# Effect of L.E. Roughness on Orbiter Windward Nondimensional Heating



## NASA LaRC 20-Inch Mach 6 Air

$\alpha = 40 \text{ deg}$  Panel # 1 0.0075 Scale

	Model	FS
Trip height (in)	0.0035	0.47
Trip size (in)	0.1x0.1	13x13



NASA Langley  
 Aerothermodynamics Branch







# Effect of L.E. Roughness on Orbiter Windward Nondimensional Heating

NASA LaRC 20-Inch Mach 6 Air

$\alpha = 40$  deg    Panel # 6    0.0075 Scale

Model FS  
 Trip height (in) 0.0035 0.47  
 Trip size (in) 0.1x0.1 13x13




NASA Langley  
 Aerothermodynamics Branch

# Effect of L.E. Roughness on Orbiter Windward Nondimensional Heating


NASA LaRC 20-Inch Mach 6 Air

$\alpha = 40$  deg Panel # 9 0.0075 Scale


Model FS  
 Trip height (in) 0.0035 0.47  
 Trip size (in) 0.1x0.1 13x13



$h/h_{ref}$




Run = 13  
 $Re_{\infty, L} = 1.74 \times 10^6$



Run = 14  
 $Re_{\infty, L} = 2.46 \times 10^6$

NASA Langley  
 Aerothermodynamics Branch



Run = 15  
 $Re_{\infty, L} = 3.37 \times 10^6$

Bow/wing shock interaction induced transition







# Effect of L.E. Roughness on Orbiter Windward Nondimensional Heating

NASA LaRC 20-Inch Mach 6 Air

$\alpha = 40$  deg

Panel # 12    0.0075 Scale

Model	FS
Trip height (in)	0.0035    0.47
Trip size (in)	0.1x0.1    13x13






# Effect of L.E. Roughness on Orbiter Windward Nondimensional Heating


NASA LaRC 20-Inch Mach 6 Air

$\alpha = 40$  deg Panel # 16 0.0075 Scale

	Model	FS
Trip height (in)	0.0035	0.47
Trip size (in)	0.1x0.1	13x13



NASA Langley  
Aerothermodynamics Branch



# Effect of Roughness on Orbiter Windward Nondimensional Heating

NASA LaRC 20-Inch Mach 6 Air



$\alpha = 40$  deg    Inboard LGMD    0.0075 Scale

Model	FS
Trip height (in)	0.0035
Trip size (in)	0.05x0.05
	7x7




Trip


$h/h_{ref}$



Run = 32  
 $Re_{\infty, L} = 1.71 \times 10^6$



Run = 33  
 $Re_{\infty, L} = 2.4 \times 10^6$



Run = 34  
 $Re_{\infty, L} = 3.33 \times 10^6$   
 Bow/wing shock  
 interaction induced transition

# Effect of Roughness on Orbiter Windward Nondimensional Heating



NASA LaRC 20-Inch Mach 6 Air

$\alpha = 40$  deg    Outboard LGMD    0.0075 Scale


Model	FS
Trip height (in)	0.0035
Trip size (in)	0.05x0.05
	7x7



$h/h_{ref}$     Trip




Run = 36  
 $Re_{\infty, L} = 1.72 \times 10^6$



Run = 37  
 $Re_{\infty, L} = 2.43 \times 10^6$

NASA Langley  
 Aerothermodynamics Branch



Run = 38  
 $Re_{\infty, L} = 3.35 \times 10^6$

Bow/wing shock  
 interaction induced transition

# Effect of Roughness on Orbiter Windward Nondimensional Heating

NASA LaRC 20-Inch Mach 6 Air



$\alpha = 40$  deg    0.0075 Scale

Trip height (in)	Model	FS
0.0035	0.05x0.05	0.47
0.05x0.05	7x7	7x7




Trip

$h/h_{ref}$




Run = 41  
 $Re_{\infty, L} = 1.72 \times 10^6$



Run = 42  
 $Re_{\infty, L} = 2.43 \times 10^6$

Trip




Run = 43  
 $Re_{\infty, L} = 3.35 \times 10^6$

Trip


Bow/wing shock  
 interaction induced transition

**Effect of RCC Panel #6 L.E. Cavity on Orbiter Fuselage  
Nondimensional Heating**




NASA LaRC 20-Inch Mach 6 Air  
 $\alpha = 40 \text{ deg}$     0.0075 Scale



**Baseline Smooth LE**



**Semi-circular notch RCC Panel #6**



## Summary

- OML shape changes along wing LE and in vicinity of MLG produce by-pass boundary layer transition near freestream flight length Reynolds number
- Wing heating augmentation a factor of 2 to 3 above laminar values
  - "Healthy" TPS tiles should provide adequate temperature margins
  - Adequate margins for damage/compromised TPS?
- Surface cavity at RCC panel #6 produced externally driven heating augmentation on Orbiter fuselage

## Future Plans

- Aerodynamic increments on ceramic heat-transfer model/metallic aero model
  - Asymmetric transition via cavities/protuberances
  
- Aerothermal/transition tests in LaRC 20-Inch Mach 13-18 Simulator
  - Location of wing/bow shock interaction more appropriate to flight
  - Low Reynolds number more appropriate to flight
  
- Correlation of roughness induced transition along wing LE and MLG using  $Re_k$ ,  $Re_{\theta}/M_e$ . Comparison with existing Orbiter correlations (Berry, Bouslog, Reda etc).
  
- Reproduce "early transition" event associated with STS-28 and STS-73 in wind tunnel to provide insight into extrapolation to flight
  
- Cavity flows [missing tile(s)]