Office of Marine Safety









National Transportation Safety Board Meeting

Sinking of the Small Passenger Vessel Panther

Everglades National Park

December 30, 2002





Launch Team

Two investigators

- IIC/OPS
- Survival Factors



Party Members





Everglades
National Park
Boat Tours



Office of Marine Safety

- Explosion of tank barge Bouchard 125
- Boiler Explosion on the cruise ship *Norway*
- Capsizing of the charter fishing vessel *Taki-Tooo*
- Allision of the Staten Island ferry Andrew J. Barberi
- Capsizing of the water taxi Lady D
- Grounding of small passenger vessel Safari Spirit
- Fire on passenger vessel Columbia



U.S. Small
Passenger
Vessel
Panther





Panther





Everglades National Park





Everglades National Park Boat Tours




Panther II



























"Red Rock"





"Red Rock"









Hoosier Daddy




National Park Service Boat




















Stern













Salvage Operation






































National Transportation Safety Board


December 2002

- Grounded first week of December
- Returned to marina twice with low freeboard
- December 29 returned with starboard list













Speed Increased






Passengers shifted aft















Operator's Console

















Safety Issues

- Vessel Maintenance
- Company Operations
- Lifejacket Stowage



Office of Research and Engineering



Bilge Pump

Dual Alarm


Strut Blocks



Bilge Pump










National Transportation Safety Board






Laboratory finding:

That the bilge pump did not operate during laboratory testing and may not have been functioning at the time of the accident.



Dual Alarm








Laboratory finding:


That the dual alarm, part of the bilge high-water level warning system, was functional, but it is likely that it was not connected to the system at the time of the accident.



Strut Blocks






























National Transportation Safety Board













Laboratory finding:

That decayed wood was repaired, not replaced.



Maintenance Issues

- No Maintenance Records
- Temporary vs. Permanent Repairs
- No Post-Casualty Procedures



Marine Casualty

- groundings
- loss of life or injury
- collisions
- fires
- explosions
- other damage impairing seaworthiness



National Park Service Concessionaire Requirements

Took immediate action for Everglades National Park



Proposed Safety Recommendation



Require that concessionaire companies operating passenger vessels in your jurisdictions develop and implement a preventive maintenance program for all systems affecting the safe operation of their vessels, including the hull and mechanical and electrical systems.



Port Imperial Manhattan





Port Imperial Manhattan







Safety Recommendation M-02-05

Require that companies operating domestic passenger vessels develop and implement a preventive maintenance program for all systems affecting the safe operation of their vessels, including the hull and mechanical and electrical systems.



Operational Procedures

- Failure to report casualty
- Failure to carry required deckhand



Operational Procedures

Masters operating outside channel

Masters not aware of High-Level Bilge Alarm



Lifejacket Stowage





Lifejacket Locker






Coast Guard Regulations

- Convenient stowage
- Distributed throughout accommodation spaces
- If practicable, float free
- Readily available



Port Imperial Manhattan Lifejacket Locker





Safety Recommendation M-02-13



Issue a directive to small

"Closed-

Acceptable Action"

segregateu.



Bayside Blaster





Safety Recommendation M-02-28

Evaluate inspection that small applicable for lifeja manning.

"ClosedAcceptable
Action"

safety ensure ce with ements s and



Child-Sized Lifejackets





Advance Safety Recommendation M-03-01

Establish of regular bath who operate an approprion board.

"Open-Acceptable Response"

y, on a onaires n carry child

