400 Seventh Street, S.W.
Washington, D.C. 20590

U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

*** *** ***

U.S. Department of Transportation
National Highway Traffic Safety Administration

CASE SUMMARY

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

PSU 49 CASE NO. 120A TYPE OF ACCIDENT _____

A. DESCRIPTION OF THE ACCIDENT SEQUENCE AND ACCIDENT PECULIARITIES

(Provide a summary of the accident sequence as well as any particular event of the accident that is noteworthy. Injury mechanism and vehicle crashworthiness is the focus, not driver culpability. Do not include any personal identifiers.)

See Attachment.

B. VEHICLE PROFILE(S)

Vehicle No.	Class of Vehicle	Year/Make/Model	Most Severe Damage Based on Vehicle Inspection		Component Failure
			Damage Plane	Severity Description	

DO NOT SANITIZE THIS FORM

C. PERSON PROFILE(S)

Vehicle No.	Person Role	Seat Position	Restraint Use	Most Severe Injury (TO BE COMPLETED BY ZONE CENTER)			
				Body Region	Injury Type	AIS	Injury Source

Body Region

Abdomen
Ankle—foot
Arm (upper)
Back-thoracolumbar spine
Brain
Chest
Ears
Eye
Elbow
Face
Forearm
Head—skull
Heart
Kidneys
Knee
Leg (lower)
Liver
Lower limbs(s) (whole or unknown part)
Mouth
Neck—cervical spine
Nose
Pelvic—hip
Pulmonary—lungs
Shoulder
Spleen
Thigh
Thyroid, other endocrine gland
Upper limb(s) (whole or unknown part)
Vertebrae
Whole body
Wrist—hand

Injury Type

Abrasion
Amputation
Avulsion
Burn
Concussion
Contusion
Crush
Detachment, separation
Dislocation
Fracture
Fracture and dislocation
Laceration
Other
Perforation, puncture
Rupture
Sprain
Strain
Total severance, transection
Unknown

Abbreviated Injury Scale

(1) Minor injury
(2) Moderate injury
(3) Serious injury
(4) Severe injury
(5) Critical injury
(6) Maximum (untreatable)
(7) Injured, unknown severity

DO NOT SANITIZE THIS FORM

PSU49 1995 Case Summary Form
CASE 120A
TYPE OF ACCIDENT: CAR/VAN/CAR - RIGHT ANGLE

A. DESCRIPTION OF THE ACCIDENT SEQUENCE AND ACCIDENT PECULIARITIES

Vehicle 1 was traveling north approaching an intersection. Vehicle 2 was traveling east and vehicle 3 was traveling west. At the intersection, the front of vehicle 2 impacted the left side of vehicle 1. Vehicle 1 continued and impacted the left front to the left front of vehicle 3. The LR tire and wheel from vehicle 1 seperated from the vehicle and impacted the left side of vehicle 3. Then the LR hub of vehicle 1 impacted a curb on the northeast corner of the intersection and came to rest. Vehicles 1 & 2 were towed andvehicle 3 was driven. The driver of vehicle 1 was fatally injured.
01

PSU49 1995 Case Summary Form
CASE 120A
TYPE OF ACCIDENT: CAR/VAN/CAR - RIGHT ANGLE

B. VEHICLE PROFILE(S)

Veh. No	Class of Vehicle	Year/Make/ Model	Damage Plane	Severity Descr.	Component Failure
01	Compact	1992/Chevrolet/Camaro	Left	Severe	None
02	Large Van	1995/Ford/Econoline	Front	Unk	None
03	Compact	1987/Pontiac/Sunbird	Left	Minor	None

01

PSU49 1995 Case Summary Form
CASE 120A
TYPE OF ACCIDENT: CAR/VAN/CAR - RIGHT ANGLE

C. PERSON PROFILE(S)

Veh. No	Person Role	Seat Positon	Restraint Use	Body Region	Injury Type	AIS	Injury Source
01	Driver	LF	L&S air bag	Aorta	Transection	6	Door surface
02	Driver	LF	L&S air bag		None		
	Pass	RF	L&S		None		
03	Non-tow						

O

U.S. Department of Transportation
National Highway Traffic Safety Administration

ACCIDENT COLLISION DIAGRAM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

PSU No. 49 Case Number—Stratum 1 2 0 A

Indicate North



HS Form 431B (1/95)

Scale: 1 centimeter = 2.5 meters

U.S. Department of Transportation
National Highway Traffic Safety Administration

ACCIDENT COLLISION DIAGRAM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

PSU No. 49 Case Number—Stratum 120A Indicate North



HS Form 431B (1/95)

Scale: 1 centimeter = _____ meters

U.S. Department of Transportation
National Highway Traffic Safety Administration

ACCIDENT COLLISION MEASUREMENT TABLE

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Primary Sampling Unit Number 49 | Case Number—Stratum 1 2 0 A

ACCIDENT COLLISION DIAGRAM

Document the physical plant:

- all road/roadway delineation (e.g., curbs/edge lines, lane markings, median markings, pavement markings, parked vehicles, poles, signs, etc.)
- all traffic controls (e.g., speed limit)
- north arrow placed on diagram
- roadway surface type and condition of applicable roadways
- grade measurements for all applicable roadways and at location of rollover initiation
- roadway curvature

Document vehicle dynamics including:

- reference point and reference line relative to physical features present at the scene
- scaled documentation of all accident induced physical evidence
- scaled documentation of all roadside objects contacted
- scaled representations of the vehicle(s) at pre-impact, impact, and final rest based upon either:
  - a) physical evidence, or
  - b) reconstructed accident dynamics

CRASH DATA

	VEH. #1	VEH. #2	VEH. #3
Heading Angle	350°	90°	270°
Surface Type	CONCRETE		
Surface Condition	DRY		
Coefficient of Friction	.65		
Grade (v/h) Measurement (between impact and final rest)	–	–	–
Grade (v/h) Measurement (at location of rollover initiation)	–	–	–
Pre-impact Grade:	–	–	–

Reference Point: SIGNAL LIGHT POLE ON SE CORNER

Reference line: SOUTH EDGE OF EAST BOUND [redacted]

Item	Distance and Direction from Reference Point	Distance and Direction from Reference Line
RP	0	.9
BEGIN SCRAPE LR V_1	13.6 W	4.5 N
END SCRAPE LR V_1	12.9 W	5.1 N
V_2 FLUID SPILL	6.5 W	7.5 N
ISLAND CURB IMPACT	10.0 W	17.7 N
EASTERN POINT OF IMPACTED ISLAND	8.6 W	7.7 N

HS Form 431A (1/95)

Item	Distance and Direction from Reference Point	Distance and Direction from Reference Line

U.S. Department of Transportation
National Highway Traffic Safety Administration

ACCIDENT FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 49
2. Case Number - Stratum: 120A

IDENTIFICATION

3. Number of General Vehicle Forms Submitted: 03
4. Date of Accident (Month,Day,Year): [redacted] 95
5. Time of Accident: 0741

Code reported military time of accident.

NOTE: Midnight = 2400
Unknown = 9999

SPECIAL STUDIES - INDICATORS

Check (✓) each special study (SS15-SS18 below) that has been completed; code 1 for the checked special studies and 0 for the special studies not checked.

6. ___ SS15 Administrative Use: 0
7. ___ SS16 Pedestrian Crash Data Study: 0
(Data for this special study available in a separate file.)
8. ___ SS17 Impact Fires: 0
9. ___ SS18 Unsafe Driver Actions: 0
10. ___ SS19 _____: 0

NUMBER OF EVENTS

11. Number of Recorded Events in This Accident: 04

Code the number of events which occurred in this accident.

ACCIDENT EVENTS

For each event that occurred in the accident, code the lowest numbered vehicle in the left columns and the other involved vehicle or object in the right columnns.

Accident Event Sequence Number	Vehicle Number	Class Of Vehicle	General Area of Damage	Vehicle Number or Object Contacted	Class Of Vehicle	General Area of Damage
12. 01	13. 01	14. 02	15. L	16. 02	17. 21	18. F
19. 02	20. 01	21. 02	22. L	23. 03	24. 02	25. L
26. 03	27. 03	28. 02	29. L	30. ~~RR~~ 79	31. 00	32. 0
33. 04	34. 01	35. 02	36. L	37. 63	38. 00	39. 0
40. 05	41. ___	42. ___	43. ___	44. ___	45. ___	46. ___

IF GREATER THAN FIVE EVENTS, CONTINUE CODING ON THE ACCIDENT EVENT SUPPLEMENT

CODES FOR CLASS OF VEHICLE

(00) Not a motor vehicle
(01) Subcompact/mini (wheelbase < 254 cm)
(02) Compact (wheelbase ≥ 254 but < 265 cm)
(03) Intermediate (wheelbase ≥ 265 but < 278 cm)
(04) Full size (wheelbase ≥ 278 but < 291 cm)
(05) Largest (wheelbase ≥ 291 cm)
(09) Unknown passenger car size
(14) Compact utility vehicle
(15) Large utility vehicle (≤ 4,500 kgs GVWR)
(16) Utility station wagon (≤ 4,500 kgs GVWR)
(19) Unknown utility type
(20) Minivan (≤ 4,500 kgs GVWR)
(21) Large van (≤ 4,500 kgs GVWR)
(24) Van Based school bus (≤ 4,500 kgs GVWR)
(28) Other van type (≤ 4,500 kgs GVWR)
(29) Unknown van type (≤ 4,500 kgs GVWR)
(30) Compact pickup truck (≤ 4,500 kgs GVWR)
(31) Large pickup truck (≤ 4,500 kgs GVWR)
(38) Other pickup truck (≤ 4,500 kgs GVWR)
(39) Unknown pickup truck type (≤ 4,500 kgs GVWR
(45) Other light truck (≤ 4,500 kgs GVWR)
(48) Unknown light truck type (≤ 4,500 kgs GVWR)
(49) Unknown light vehicle type
(50) School bus (excludes van based)(> 4,500 kgs GVWR)
(58) Other bus (> 4,500 kgs GVWR)
(59) Unknown bus type
(60) Truck (> 4,500 kgs GVWR)
(67) Tractor without trailer
(68) Tractor-trailer(s)
(78) Unknown medium/heavy truck type
(79) Unknown light/medium/heavy truck type
(80) Motored cycle
(90) Other vehicle
(99) Unknown

CODES FOR GENERAL AREA OF DAMAGE (GAD)

CDS APPLICABLE AND OTHER VEHICLES
(0) Not a motor vehicle
(N) Noncollision
(F) Front
(R) Right side
(L) Left side
(B) Back
(T) Top
(U) Undercarriage
(9) Unknown

TDC APPLICABLE VEHICLES
(0) Not a motor vehicle
(N) Noncollision
(F) Front
(R) Right side
(L) Left side
(B) Back of unit with cargo area (rear of trailer or straight truck)
(D) Back (rear of tractor)
(C) Rear of cab
(V) Front of cargo area
(T) Top
(U) Undercarriage
(9) Unknown

CODES FOR VEHICLE NUMBER OR OBJECT CONTACTED

(01-30) — Vehicle Number

Noncollision
(31) Overturn — rollover (excludes end-over-end)
(32) Rollover — end-over-end
(33) Fire or explosion
(34) Jackknife
(35) Other intraunit damage (specify): _____
(36) Noncollision injury
(38) Other noncollision (specify): _____
(39) Noncollision — details unknown

Collision With Fixed Object
(41) Tree (≤ 10 cm in diameter)
(42) Tree (> 10 cm in diameter)
(43) Shrubbery or bush
(44) Embankment
(45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
(50) Pole or post (≤ 10 cm in diameter)
(51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
(52) Pole or post (> 30 cm in diameter)
(53) Pole or post (diameter unknown)
(54) Concrete traffic barrier
(55) Impact attenuator
(56) Other traffic barrier (includes guardrail) (specify): _____
(57) Fence
(58) Wall
(59) Building
(60) Ditch or culvert
(61) Ground
(62) Fire hydrant
(63) Curb
(64) Bridge
(68) Other fixed object (specify): _____
(69) Unknown fixed object

Collision with Nonfixed Object
(70) Passenger car, light truck, van, or other vehicle not in-transport
(71) Medium/heavy truck or bus not in-transport
(72) Pedestrian
(73) Cyclist or cycle
(74) Other nonmotorist or conveyance _____
(75) Vehicle occupant
(76) Animal
(77) Train
(78) Trailer, disconnected in transport
(79) Object fell from vehicle in-transport
(88) Other nonfixed object (specify): LR TIRE + WHEEL FROM V1
(89) Unknown nonfixed object

(98) Other event (specify): _____
(99) Unknown event or object

PSU 49-120A
V-01

PRECRASH ENVIRONMENTAL DATA

19. Relation To Interchange Or Junction — 2
(0) Non-interchange area and non-junction
(1) Interchange area related

Non-Interchange junctions
(2) Intersection related
(3) Driveway, alley access related
(4) Other junction (specify)
_____
(5) Unknown type of junction

(9) Unknown

20. Trafficway Flow — 1
(0) Not physically divided (two way traffic)
(1) Divided trafficway-median strip without positive barrier
(2) Divided trafficway-median strip with positive barrier
(3) One way traffic
(9) Unknown

21. Number Of Travel Lanes — 3
(1) One
(2) Two
(3) Three
(4) Four
(5) Five
(6) Six
(7) Seven or more
(9) Unknown

22. Roadway Alignment — 2
(1) Straight
(2) Curve right
(3) Curve left
(9) Unknown

23. Roadway Profile — 1
(1) Level
(2) Uphill grade (>2%)
(3) Hill crest
(4) Downhill grade (>2%)
(5) Sag
(9) Unknown

24. Roadway Surface Type — 1
(1) Concrete
(2) Bituminous (asphalt)
(3) Brick or block
(4) Slag, gravel, or stone
(5) Dirt
(8) Other (specify): _____
(9) Unknown

25. Roadway Surface Condition — 1
(1) Dry
(2) Wet
(3) Snow or slush
(4) Ice
(5) Sand, dirt, or oil
(8) Other (specify): _____
(9) Unknown

26. Light Conditions — 1
(1) Daylight
(2) Dark
(3) Dark, but lighted
(4) Dawn
(5) Dusk
(9) Unknown

27. Atmospheric Conditions — 0
(0) No adverse atmospheric-related driving conditions
(1) Rain
(2) Sleet/hail
(3) Snow
(4) Fog
(5) Rain and fog
(6) Sleet and fog
(7) Other (e.g., smog, smoke, blowing sand or dust, etc.) (specify):
_____
(9) Unknown

28. Traffic Control Device — 1
(0) No traffic control(s)
(1) Traffic control signal (not RR crossing)

Regulatory
(2) Stop sign
(3) Yield sign
(4) School zone sign
(5) Other regulatory sign (specify):
_____
(6) Warning sign (not RR crossing)
(7) Unknown sign
(8) Miscellaneous/other controls including RR controls (specify):
_____
(9) Unknown

29. Traffic Control Device Functioning — 2
(0) No traffic control device
(1) Traffic control device not functioning (specify):_____
(2) Traffic control device functioning properly
(9) Unknown

PSU 49-120A
V-01

OCCUPANT RELATED

37. Driver Presence in Vehicle: 1
(0) Driver not present
(1) Driver present
(9) Unknown

38. Number of Occupants This Vehicle: 01
(00-96) Code actual number of occupants for this vehicle
(97) 97 or more
(99) Unknown

39. Number of Occupant Forms Submitted: 01

AIR BAG RELATED

40. Is this an AOPS Vehicle? 1
(0) No (includes unknown)
(1) Yes - researcher determined
(2) VIN determined air bag system
(3) VIN determined automatic (passive) belts
(4) VIN determined air bag and automatic (passive) belts

41. Air Bag(s) Deployment, First Seat Frontal: 2
(0) Not equipped or not available
(1) No air bags deployed

Single Air Bag Vehicle
(2) Driver air bag deployed
(3) Driver air bag, unknown if deployed

Multiple Air Bag Vehicle
(4) Driver side only deployed
(5) Passenger side only deployed
(6) Driver and passenger side deployed
(7) Driver and passenger side unknown if deployed
(8) Air bag(s) deployed, details unknown
(9) Unknown

42. Air Bag(s) Deployment, Other Than First Seat Frontal: 0
(0) Not equipped with an "other" air bag
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, details unknown
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

Specify type of "other" air bag present: _____

VEHICLE WEIGHT ITEMS

43. Vehicle Curb Weight: 1,41 0
____ Code weight to nearest 10 kilograms.
(045) Less than 450 kilograms
(610) 6,100 kilograms or more
(999) Unknown
3,103 lbs X .4536 = 1,408 kgs
Source: [redacted]

44. Vehicle Cargo Weight: 0,000 0
____ Code weight to nearest 10 kilograms.
(000) Less than 5 kilograms
(450) 4,500 kilograms or more
(999) Unknown
__,___ lbs X .4536 = __,___ kgs
Source: [redacted]

ROLLOVER DATA

45. Rollover: 00
(00) No rollover (no overturning)

Rollover (primarily about the longitudinal axis)
(01-16) Code the number of quarter turns
(17) Rollover, 17 or more quarter turns (specify): _____
(98) Rollover--end-over-end (i.e., primarily about the lateral axis)
(99) Rollover (overturn), details unknown

46. Rollover Initiation Type: 00
(00) No rollover
(01) Trip-over
(02) Flip-over
(03) Turn-over
(04) Climb-over
(05) Fall-over
(06) Bounce-over
(07) Collision with another vehicle
(08) Other rollover initiation type specify): _____
(98) Rollover--end-over-end
(99) Unknown rollover initiation type

47. Location of Rollover Initiation: 0
(0) No rollover
(1) On roadway
(2) On shoulder—paved
(3) On shoulder—unpaved
(4) On roadside or divided trafficway median
(8) Rollover--end-over-end
(9) Unknown

48. Rollover Initiation Object Contacted: 00
(Note: Applicable codes on back of page)

49. Location on Vehicle Where Initial Principal Tripping Force Is Applied: 0
(0) No rollover
(1) Wheels/tires
(2) Side plane
(3) End plane
(4) Undercarriage
(5) Other location on vehicle (specify): _____
(6) Non-contact rollover forces (specify): _____
(8) Rollover--end-over-end
(9) Unknown

50. Direction of Initial Roll: 0
(0) No rollover
(1) Roll right - primarily about the longitudinal axis
(2) Roll left - primarily about the longitudinal axis
(8) Rollover--end-over-end
(9) Unknown roll direction

PSU 49-120A
V-01

CODES FOR ROLLOVER INITIATION OBJECT CONTACTED

(00) No rollover
(01-30) — Vehicle Number

Noncollision
(31) Turn-over — fall-over
(32) No rollover impact initiation (end-over-end)
(34) Jackknife

Collision With Fixed Object
(41) Tree (≤ 10 cm in diameter)
(42) Tree (> 10 cm in diameter)
(43) Shrubbery or bush
(44) Embankment

(45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
(50) Pole or post (≤ 10 cm in diameter)
(51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
(52) Pole or post (> 30 cm in diameter)
(53) Pole or post (diameter unknown)

(54) Concrete traffic barrier
(55) Impact attenuator
(56) Other traffic barrier (includes guardrail) (specify):_____

(57) Fence
(58) Wall
(59) Building
(60) Ditch or culvert
(61) Ground
(62) Fire hydrant
(63) Curb
(64) Bridge
(68) Other fixed object (specify):

(69) Unknown fixed object

Collision with Nonfixed Object
(70) Passenger car, light truck, van, or other vehicle not in-transport
(71) Medium/heavy truck or bus not in-transport
(76) Animal
(77) Train
(78) Trailer, disconnected in transport
(79) Object fell from vehicle in-transport
(88) Other nonfixed object (specify):

(89) Unknown nonfixed object

(98) Other event (specify):

(99) Unknown event or object

U.S. Department of Transportation
National Highway Traffic Safety Administration

EXTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 49
2. Case Number - Stratum: 120A
3. Vehicle Number: 01

VEHICLE IDENTIFICATION

VIN: 1G1FP23TXNL[redacted] Model Year: 92

Vehicle Make (specify): CHEVROLET Vehicle Model (specify): CAMARO

LOCATOR

Locate the end of the damage with respect to the vehicle longitudinal center line or bumper corner for end impacts or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L	Location of Max Crush
1	BEGINS 30cm BACK LF AXLE	BEGINS 21cm BACK LF AXLE	207cm BACK LF AXLE
2	BEGINS 43cm FORWARD LF AXLE	BEGINS 31cm FORWARD LF AXLE	69cm FORWAR LF AXLE

CRUSH PROFILE IN CENTIMETERS

NOTES: Identify the plane at which the C-measurements are taken (e.g., at bumper, above bumper, at sill, above sill, etc.) and label adjustments (e.g., free space).

Measure C1 to C6 from driver to passenger side in front or rear impacts and rear to front in side impacts.

Free space value is defined as the distance between the baseline and the original body contour taken at the individual C locations. This may include the following: bumper lead, bumper taper, side protrusion, side taper, etc. Record the value for each C-measurement and maximum crush.

Use as many lines/columns as necessary to describe each damage profile.

Specific Impact Number	Plane of Impact C-Measurements	Direct Damage Width (CDC)	Direct Damage Max Crush	Field L	C_1	C_2	C_3	C_4	C_5	C_6	±D
1	LEFT	283	C3	292	8	28	56	48	38	6	-42
	FREE SPACE				2	2	2	2	2	2	
	RESULTANT				6	26	54	46	36	4	
					* C4	PROJECTED DUE TO		DOOR	BEING		
					PULLED	OUT	BY	EXTRICATION			
2	LEFT (FRONT)	51	C4	64	4	10	15	19	13	19	+199
	FREESPACE				2	2	2	2	2	6	
	RESULTANT				2	8	13	17	11	13	

ORIGINAL SPECIFICATIONS WORK SHEET

Wheelbase	101.0	inches	x	2.54	=	257 cm
Overall Length	192.6	inches	x	2.54	=	489 cm
Maximum Width	72.4	inches	x	2.54	=	184 cm
Curb Weight	3,103	pounds	x	.4536	=	1,408 kg
Average Track	60.5	inches	x	2.54	=	154 cm
Front Overhang	___.___	inches	x	2.54	=	___ cm
Rear Overhang	___.___	inches	x	2.54	=	___ cm
Undeformed End Width	___.___	inches	x	2.54	=	___ cm
Engine Size: cyl./displ.	____	cc	x	.001	=	___.___ L
	___	CID	x	.0164	=	___.___ L

VEHICLE DAMAGE SKETCH

TIRE—WHEEL DAMAGE

a. Rotation physically restricted

RF 2
LF 2
RR 2
LR 1 - OFF

b. Tire deflated

RF 2
LF 2
RR 2
LR 1

(1) Yes (2) No (8) NA (9) Unk.

TYPE OF TRANSMISSION

☒ Manual ☐ Automatic

END SHIFT ≥ 10 CM
☐ Yes ☒ No

ORIGINAL SPECIFICATIONS

Wheelbase	257	cm
Overall Length	489	cm
Maximum Width	184	cm
Curb Weight	1,408	kg
Average Track	154	cm
Front Overhang	114	cm
Rear Overhang	118	cm
Undeformed End Width	162	cm
Engine Size: cyl./displ.	V6/3.1	L

WHEEL STEER ANGLES

(For locked front wheels or displaced rear axles only)

RF ± — — °
LF ± — — °
RR ± — — °
LR ± 0 0 °

Within ± 5 degrees

DRIVE WHEELS

☐ FWD ☒ RWD ☐ 4WD

Approximate Cargo Weight 0 kg

MEASUREMENTS IN CENTIMETERS



SCRAPE ON BUMPER FROM PAVEMENT - PLASTIC BUMPER FOLDED UNDER FRONT AT TIME OF LF IMPACT WITH V2

Original Bumper height 22









NOTES: Sketch new perimeter and cross hatch direct damage and single hatch induced damage on all views. Annotate observations which might be useful in reconstructing the accident (e.g., grass in tire bead, direction of striations, scuff on sidewalls, etc.). If pulling trailer, sketch type of trailer and damage received on the back of this page.

Annotate any damage caused by extrication such as component removal by torching, prying, or hydraulic shears.

CDC WORKSHEET

CODES FOR OBJECT CONTACTED

(01-30) — Vehicle Number

Noncollision
- (31) Overturn — rollover (excludes end-over-end)
- (32) Rollover—end-over-end
- (33) Fire or explosion
- (34) Jackknife
- (35) Other intraunit damage (specify): _____
- (36) Noncollision injury
- (38) Other noncollision (specify): _____
- (39) Noncollision — details unknown

Collision With Fixed Object
- (41) Tree (≤ 10 cm in diameter)
- (42) Tree (> 10 cm in diameter)
- (43) Shrubbery or bush
- (44) Embankment
- (45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
- (50) Pole or post (≤ 10 cm in diameter)
- (51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
- (52) Pole or post (> 30 cm in diameter)
- (53) Pole or post (diameter unknown)
- (54) Concrete traffic barrier
- (55) Impact attenuator
- (56) Other traffic barrier (includes guardrail) (specify): _____
- (57) Fence
- (58) Wall
- (59) Building
- (60) Ditch or culvert
- (61) Ground
- (62) Fire hydrant
- (63) Curb
- (64) Bridge
- (68) Other fixed object (specify): _____
- (69) Unknown fixed object

Collision with Nonfixed Object
- (70) Passenger car, light truck, van, or other vehicle not in-transport
- (71) Medium/heavy truck or bus not in-transport
- (72) Pedestrian
- (73) Cyclist or cycle
- (74) Other nonmotorist or conveyance _____
- (75) Vehicle occupant
- (76) Animal
- (77) Train
- (78) Trailer, disconnected in transport
- (79) Object fell from vehicle in-transport
- (88) Other nonfixed object (specify): _____
- (89) Unknown nonfixed object
- (98) Other event (specify): _____
- (99) Unknown event or object

DEFORMATION CLASSIFICATION BY EVENT NUMBER

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force (degrees)	Incremental Value of Shift	(3) Deformation Location	(4) Specific Longitudinal or Lateral Location	(5) Specific Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
01	02	320	00	L	D	A	W	04
02	03	300	00	L	F	E	W	02
04	63	270	00	L	B	W	N	01

COLLISION DEFORMATION CLASSIFICATION

HIGHEST DELTA "V"

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force	(3) Deformation Location	(4) Longitudinal or Lateral Location	(5) Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
4. 01	5. 02	6. 11	7. L	8. D	9. A	10. W	11. 04

Second Highest Delta "V"

12. 02	13. 03	14. 10	15. L	16. F	17. E	18. W	19. 02

CRUSH PROFILE IN CENTIMETERS

The crush profile for the damage described in the CDC(s) above should be documented in the appropriate space below. (ALL MEASUREMENTS ARE IN CENTIMETERS.)

HIGHEST DELTA "V"

20. L	21. C_1	C_2	C_3	C_4	C_5	C_6	22. ±D
292	006	026	054	046	036	004	+0042

Second Highest Delta "V"

23. L	24. C_1	C_2	C_3	C_4	C_5	C_6	25. ±D
064	002	008	013	017	011	013	+199

26. Undeformed End Width (Coded when highest severity impact is an end plane impact.) 998
- ____ Code to the nearest centimeter
- (250) 250 centimeters or more
- (998) No highest severity end plane impact
- (999) Unknown

27. Direct Damage Width (For highest severity impact) 250
- ____ Code to the nearest centimeter
- (250) 250 centimeters or more
- (999) Unknown

28. Original Wheelbase 257
- ____ Code to the nearest centimeter
- (650) 650 centimeters or more
- (999) Unknown

101.0 inches X 2.54 = 257 centimeters

29. Original Average Track Width 154
- ____ Code to the nearest centimter
- (185) 185 centimeters or more
- (999) Unknown

60.5 inches X 2.54 = 154 centimeters

30. Are CDCs Documented but Not Coded on The Automated File? 1
(0) No
(1) Yes

31. Researcher's Assessment of Vehicle Disposition 1
(0) Not towed due to vehicle damage
(1) Towed due to vehicle damage
(9) Unknown

32. Is This A Multi-Stage Manufactured Vehicle And/Or A Certified Altered Vehicle? 0
(0) No post manufacturer modifications
(1) Yes - post manufacturer modifications (specify): _____
_____
_____
(Include photograph of CERTIFICATION PLACARD in case report)
(9) Unknown if vehicle is modified

FIRE OCCURRENCE

33. Fire Occurrence 0
(0) No fire

Yes, fire occurred
(1) Minor
(2) Major
(9) Unknown

34. Origin of Fire 0
(0) No fire
(1) Vehicle exterior (front, side, back, top)
(2) Exhaust system
(3) Fuel tank (and other fuel retention system parts)
(4) Engine compartment
(5) Cargo/trunk compartment
(6) Instrument panel
(7) Passenger compartment area
(8) Other location (specify):
_____
(9) Unknown

FUEL SYSTEM

35. Location of Fuel Tank-1 Filler Cap 2

36. Location of Fuel Tank-2 Filler Cap 0
(0) No fuel tank
(1) On back plane
(2) Aft of center of the rear wheels (rear axle) on left side plane
(3) Aft of center of the rear wheels (rear axle) on right side plane
(4) Forward of center of the rear wheels (rear axle) on left side plane
(5) Forward of center of the rear wheels (rear axle) on right side plane
(6) Over the center of the rear wheels (rear axle) on left side plane
(7) Over the center of the rear wheels (rear axle) on right side plane
(8) Other (specify): _____
(9) Unknown

37. Type of Fuel Tank-1 1

38. Type of Fuel Tank-2 0
(0) No fuel tank (electrical vehicle)
(1) Metallic
(2) Non-metallic
(9) Unknown

39. Location of Fuel Tank-1 4

40. Location of Fuel Tank-2 0
(0) No fuel tank
(1) Aft of center of the rear wheels (rear axle) centered
(2) Aft of center of the rear wheels (rear axle) left side
(3) Aft of center of the rear wheels (rear axle) right side
(4) Forward of center of the rear wheels (rear axle) centered
(5) Forward of center of the rear wheels (rear axle) left side
(6) Forward of center of the rear wheels (rear axle) right side
(7) Over center of the rear wheels (rear axle)
(8) Other (specify): _____
(9) Unknown

41. Damage to Fuel Tank-1 8

42. Damage to Fuel Tank-2 0
(0) No fuel tank
(1) No damage to fuel tank
(2) Deformed, no seam failure
(3) Deformed, with a seam failure
(4) Punctured
(5) Lacerated (ripped)
(6) Abraded (scraped)
(7) Filler neck separation from the fuel tank
(8) Other damage (specify): FILLER NECK
(9) Unknown

PINCHED - UNABLE TO VIEW TANK

43. Leakage Location of Fuel System-1 1

44. Leakage Location of Fuel System-2 0
(0) No fuel tank
(1) No fuel leakage

Primary Area Of Leakage
(2) Tank
(3) Filler neck
(4) Cap
(5) Lines/pump/filter
(6) Vent/emission recovery
(8) Other (specify):_____
(9) Unknown

45. Fuel Type-1 01

46. Fuel Type-2 00

Single Fuel Type
(00) No fuel tank
(01) Gasoline
(02) Diesel
(03) CNG (Compressed Natural Gas)
(04) LPG (Liquid Petroleum Gas) also known as Propane
(05) LNG (Liquid Natural Gas)
(06) Methanol (M100 or M85)
(07) Ethanol (E100 or E85)
(08) Other (Hydrogen or others) (specify):
_____

Electric Powered or Electric/Solar Powered Vehicles
(10) Lead Acid Battery
(11) Nickel-Iron Battery
(12) Nickel-Cadmium Battery
(13) Sodium Metal Chloride Battery
(14) Sodium Sulfur Battery
(18) Other (Specify):_____

(98) Other Hybrid (specify):
_____

(99) Unknown fuel type

47. Is This Vehicle Equipped With More Than Two Fuel Tanks? 0
(0) No (one or two tanks only)

Yes - More Than Two Tanks
(1) Yes -- no damage to any tank or filler cap and no fuel system leakage
(2) Yes -- no damage to any tank or filler cap but there is fuel system leakage (specify leakage location):
_____
(3) Yes -- damage to an additional tank or filler cap and there is fuel system leakage (specify the following):
Type of tank _____
Tank location _____
Filler cap location _____
Tank damage _____
Location of leakage _____
Type of fuel _____
(9) Unknown if more than two tanks

COMMENTS

_____
_____
_____
_____
_____
_____
_____
_____
_____
_____
_____

*** STOP: IF THE CDS APPLICABLE VEHICLE WAS NOT TOWED ***

(GV10=0)

DO NOT COMPLETE THE INTERIOR VEHICLE FORM.

U.S. Department of Transportation
National Highway Traffic Safety Administration

INTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number 49
2. Case Number - Stratum 120A
3. Vehicle Number 01

INTEGRITY

4. Passenger Compartment Integrity 98
(00) No integrity loss

Yes, Integrity Was Lost Through
(01) Windshield
(02) Door (side)
(03) Door/hatch (back door)
(04) Roof
(05) Roof glass
(06) Side window
(07) Rear window (backlight)
(08) Roof and roof glass
(09) Windshield and door (side)
(10) Windshield and roof
(11) Side and rear window (side window and backlight)
(12) Windshield and side window
(13) Door and side window
(98) Other combination of above (specify): 03, 11
(99) Unknown

EXTRICATION

Door, Tailgate or Hatch Opening

5. LF 3 6. RF 1 7. LR 0 8. RR 0 9. TG/H 2

(0) No door/gate/hatch
(1) Door/gate/hatch remained closed and operational
(2) Door/gate/hatch came open during collision
(3) Door/gate/hatch jammed shut
(8) Other (specify):
(9) Unknown

Damage/Failure Associated with Door, Tailgate or Hatch Opening in Collision. If IV05-IV09 ≠ 2, Then code Ø

10. LF 0 11. RF 0 12. LR 0 13. RR 0 14. TG/H 2

(0) No door/gate/hatch or door not opened

Door, Tailgate or Hatch Came Open During Collision
(1) Door operational (no damage)
(2) Latch/striker failure due to damage
(3) Hinge failure due to damage
(4) Door structure failure due to damage
(5) Door support (i.e., pillar, sill, roof side rail, etc.) failure due to damage
(6) Latch/striker and hinge failure due to damage
(8) Other failure (specify):
(9) Unknown

GLAZING

Type of Window/Windshield Glazing

15. WS 1 16. LF 2 17. RF 2 18. LR 0 19. RR 0
20. BL 2 21. Roof 0 22. Other 0

(0) No glazing
(1) AS-1 – Laminated
(2) AS-2 – Tempered
(3) AS-3 – Tempered-tinted (original)
(4) AS-2 – Tempered-with after market tint
(5) AS-3 – Tempered-tinted (with additional after market tint)
(6) AS-14 – Glass/Plastic
(7) Glazing removed prior to accident
(8) Other (specify):
(9) Unknown

Window Precrash Glazing Status

23. WS 1 24. LF 2 25. RF 2 26. LR 0 27. RR 0
28. BL 1 29. Roof 0 30. Other 0

(0) No glazing
(1) Fixed
(2) Closed
(3) Partially opened
(4) Fully opened
(7) Glazing removed prior to accident
(9) Unknown

Glazing Damage from Impact Forces

31. WS 2 32. LF 6 33. RF 1 34. LR 0 35. RR 0
36. BL 6 37. Roof 0 38. Other 0

(0) No glazing
(1) No glazing damage from impact forces
(2) Glazing in place and cracked from impact forces
(3) Glazing in place and holed from impact forces
(4) Glazing out-of-place (cracked or not) and not holed from impact forces
(5) Glazing out-of-place and holed from impact forces
(6) Glazing disintegrated from impact forces
(7) Glazing removed prior to accident
(9) Unknown if damaged

Glazing Damage from Occupant Contact

39. WS 1 40. LF 1 41. RF 1 42. LR 0 43. RR 0
44. BL 1 45. Roof 0 46. Other 0

(0) No glazing
(1) No occupant contact to glazing
(2) Glazing contacted by occupant but no glazing damage
(3) Glazing in place and cracked by occupant contact
(4) Glazing in place and holed by occupant contact
(5) Glazing out-of-place (cracked or not) by occupant contact and not holed by occupant contact
(6) Glazing out-of-place by occupant contact and holed by occupant contact
(7) Glazing removed prior to accident
(8) Glazing disintegrated by occupant contact
(9) Unknown if contacted by occupant

INTRUSION WORKSHEET

Note: Sketch intruded areas

Row Width (cm)

135

135





LOCATION OF INTRUSION	INTRUDED COMPONENT	(All Measurements Are In Centimeters) COMPARISON VALUE	–	INTRUDED VALUE	=	INTRUSION	DOMINANT CRUSH DIRECTION	
11	DOOR	135	–	105	=	30	LAT	1
11	SILL	135	–	121	=	14	1	9
11	DASH	134	–	128	=	6	1	
11	A-PILLAR	126	–	111	=	15		8
11	ROOF SIDE RAIL	124	–	106	=	18		7
11	SEAT BACK	124	–	100	=	24		3
11	SEAT CUSHION	124	–	103	=	21		5
21	SIDE PANEL - REAR OF B-PILLAR	126	–	118	=	8		10
21	B-PILLAR	126	–	99	=	27	1	2
21	SEAT CUSHION	128	–	109	=	19		6
21	SEAT BACK	128	–	106	=	22		4
11	STEERING COLUMN	112	–	106	=	6		
			–		=			
			–		=			
			–		=			

Document no more than the 15 most severe intrusions

OCCUPANT AREA INTRUSION

Note: If no intrusions, leave variables IV47-IV86 blank.

	Location of Intrusion	Intruding Component	Magnitude of Intrusion	Dominant Crush Direction
1st	47. 11	48. 11	49. 4	50. 3
2nd	51. 21	52. 07	53. 3	54. 3
3rd	55. 11	56. 20	57. 3	58. 3
4th	59. 21	60. 21	61. 3	62. 3
5th	63. 11	64. 25	65. 3	66. 3
6th	67. 21	68. 25	69. 3	70. 3
7th	11	32	3	3
~~8th~~ OK	~~71. 11~~	~~72. 14~~	~~73. 3~~	~~74. 3~~
9th ~~8th~~	75. 11	76. 06	77. 3	78. 3
10th ~~8th~~	79. 11	80. 18	81. 2	82. 3
~~10th~~	~~83. 21~~	~~84. 12~~	~~85. 2~~	~~86. 3~~

LOCATION OF INTRUSION

Front Seat
- (11) Left
- (12) Middle
- (13) Right

Second Seat
- (21) Left
- (22) Middle
- (23) Right

Third Seat
- (31) Left
- (32) Middle
- (33) Right

Fourth Seat
- (41) Left
- (42) Middle
- (43) Right

- (97) Catastrophic
- (98) Other enclosed area (specify) _____
- (99) Unknown

INTRUDING COMPONENT

Interior Components
- (01) Steering assembly
- (02) Instrument panel left
- (03) Instrument panel center
- (04) Instrument panel right
- (05) Toe pan
- (06) A (A1/A2)-pillar
- (07) B-pillar
- (08) C-pillar
- (09) D-pillar
- (10) Side panel - forward of the A1/A2-pillar
- (11) Door panel (side)
- (12) Side panel - rear of the B-pillar
- (13) Roof (or convertible top)
- (14) Roof side rail
- (15) Windshield
- (16) Windshield header
- (17) Window frame
- (18) Floor pan (includes sill)
- (19) Backlight header
- (20) Front seat back
- (21) Second seat back
- (22) Third seat back
- (23) Fourth seat back
- (24) Fifth seat back
- (25) Seat cushion
- (26) Back door/panel (e.g., tailgate)
- (27) Other interior component (specify): _____

Exterior Components
- (30) Hood
- (31) Outside surface of this vehicle (specify): _____
- (32) Other exterior object in the environment (specify): _____
- (33) Unknown exterior object
- (97) Catastrophic
- (98) Intrusion of unlisted component(s) (specify): _____
- (99) Unknown

MAGNITUDE OF INTRUSION

- (1) ≥ 3 centimeters but < 8 centimeters
- (2) ≥ 8 centimeters but < 15 centimeters
- (3) ≥ 15 centimeters but < 30 centimeters
- (4) ≥ 30 centimeters but < 46 centimeters
- (5) ≥ 46 centimeters but < 61 centimeters
- (6) ≥ 61 centimeters
- (7) Catastrophic
- (9) Unknown

DOMINANT CRUSH DIRECTION

- (1) Vertical
- (2) Longitudinal
- (3) Lateral
- (7) Catastrophic
- (9) Unknown

STEERING RIM/SPOKE DEFORMATION

(All Measurements Are in Centimeters)

COMPARISON VALUE	–	DAMAGE VALUE	=	DEFORMATION
	–		=	
	–		=	
	–		=	
	–		=	

STEERING COLUMN

87. Steering Column Type 2
(1) Fixed column
(2) Tilt column
(3) Telescoping column
(4) Tilt and telescoping column
(8) Other column type (specify): _____
(9) Unknown

88. Tilt Steering Column Adjustment 9
(0) No tilt steering column
(1) Full up
(2) Between full up and center
(3) Center
(4) Between center and full down
(5) Full down
(9) Unknown

89. Telescoping Steering Column Adjustment 0
(0) No telescoping steering column
(1) Full back
(2) Between full back and midpoint
(3) Midpoint
(4) Between midpoint and full forward
(5) Full forward
(9) Unknown

90. Steering Rim/Spoke Deformation 00
____Code actual measured deformation to the nearest centimeter
(00) No steering rim deformation
(01-14) Actual measured value in centimeters
(15) 15 centimeters or more
(98) Observed deformation cannot be measured
(99) Unknown

91. Location of Steering Rim/Spoke Deformation 00
(00) No steering rim deformation

Quarter Sections
(01) Section A
(02) Section B
(03) Section C
(04) Section D



Half Sections
(05) Upper half of rim/spoke
(06) Lower half of rim/spoke
(07) Left half of rim/spoke
(08) Right half of rim/spoke

(09) Complete steering wheel collapse
(10) Undetermined location
(99) Unknown

INSTRUMENT PANEL

92. Odometer Reading 999,000
____ kilometers
Code to the nearest 1,000 kilometers
(000) No odometer
(001) Less than 1,500 kilometers
(500) 499,500 kilometers or more
(999) Unknown
___,___ miles X 1.6093 = ___,___ kilometers
Source: DASH DEFORMATION - UNABLE TO VIEW

93. Instrument Panel Damage from Occupant Contact? 9
(0) No
(1) Yes
(9) Unknown

94. Type of Knee Bolster Covering 1
(0) No knee bolster
(1) Padded
(2) Rigid plastic
(8) Other (specify): _____
(9) Unknown

95. Knee Bolsters Deformed from Occupant Contact? 9
(0) No knee bolster
(1) No deformation
(2) Yes - deformation
(9) Unknown

96. Did Glove Compartment Door Open During Collision(s)? 0
(0) No glove compartment door
(1) No - door did not open
(2) Yes - door opened
(9) Unknown

97. Adaptive (Assistive) Driving Equipment 0
(0) No adaptive driving equipment
(1) Adaptive driving equipment installed (Check all that apply.)
[ ] Hand controls for braking/acceleration
[ ] Steering control devices (attached to OEM steering wheel
[ ] Steering knob attached to steering wheel
[ ] Low effort power steering (unit or device)
[ ] Replacement steering wheel (i.e., reduced diameter)
[ ] Joy-stick steering controls
[ ] Wheelchair tie-downs
[ ] Modification to seat belts (specify): _____
[ ] Additional or relocated switches (specify): _____
[ ] Raised roof
[ ] Wall-mounted head rest (used behind wheelchair)
[ ] Other adaptive device (specify): _____
(9) Unknown

VEHICLE INTERIOR SKETCHES

Note area of ejection/entrapment





Sketch windshield contact(s) and the damaged area(s) on the instrument panel outline (e.g., radio, glove compartment, damage to instrument panel structure.
Cross hatch contact points, draw spider webs or use other annotation as may be appropriate.
Annotate the contacted area with a letter (begin with A) and list on the Points of Occupant Contact page.

POINTS OF OCCUPANT CONTACT

Contact	Interior Component Contacted	Occupant No. If Known	Body Region If Known	Supporting Physical Evidence	Confidence Level of Contact Point
A	170	01	unk	BAG DEPLOYED	1
B	052	01	unk	SCUFF	1
C	058	01	HEAD	HAIR	1
D	152	01	unk	WEBBING SCUFF - BELT CUT BY EXTRICATION	1
E					
F					
G					
H					
I					
J					
K					
L					
M					
N					

CODES FOR INTERIOR COMPONENTS

FRONT
- (001) Windshield
- (002) Mirror
- (003) Sunvisor
- (004) Steering wheel rim
- (005) Steering wheel hub/spoke
- (006) Steering wheel (combination of codes 004 and 005)
- (007) Steering column,transmission selector lever, other attachment
- (008) Cellular telephone or CB radio
- (009) Add on equipment(e.g., tape deck, air conditioner)
- (010) Left instrument panel and below
- (011) Center instrument panel and below
- (012) Right instrument panel and below
- (013) Glove compartment door
- (014) Knee bolster
- (015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
- (016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
- (017) Windshield reinforced by exterior object, (specify): _____
- (019) Other front object (specify): _____

LEFT SIDE
- (051) Left side interior surface, excluding hardware or armrests
- (052) Left side hardware or armrest
- (053) Left A (A1/A2)-pillar
- (054) Left B-pillar
- (055) Other left pillar (specify): _____
- (056) Left side window glass
- (057) Left side window frame
- (058) Left side window sill
- (059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (060) Other left side object (specify): _____

RIGHT SIDE
- (101) Right side interior surface, excluding hardware or armrests
- (102) Right side hardware or armrest
- (103) Right A (A1/A2)-pillar
- (104) Right B-pillar
- (105) Other right pillar (specify): _____
- (106) Right side window glass
- (107) Right side window frame
- (108) Right side window sill
- (109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (110) Other right side object (specify): _____

INTERIOR
- (151) Seat, back support
- (152) Belt restraint webbing/buckle
- (153) Belt restraint B-pillar or door frame attachment point
- (154) Other restraint system component (specify): _____
- (155) Head restraint system
- (160) Other occupants (specify): _____
- (161) Interior loose objects
- (162) Child safety seat (specify): _____
- (163) Other interior object (specify): _____

AIR BAG
- (170) Air bag-driver side
- (175) Air bag compartment cover-driver side
- (180) Air bag-passenger side
- (185) Air bag compartment cover-passenger side
- (190) Other air bag (specify) _____
- (195) Other air bag compartment cover (specify) _____

ROOF
- (201) Front header
- (202) Rear header
- (203) Roof left side rail
- (204) Roof right side rail
- (205) Roof or convertible top

FLOOR
- (251) Floor (including toe pan)
- (252) Floor or console mounted transmission lever, including console
- (253) Parking brake handle
- (254) Foot controls including parking brake

REAR
- (301) Backlight (rear window)
- (302) Backlight storage rack, door, etc.
- (303) Other rear object (specify): _____

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT
- (401) Hand controls for braking/acceleration
- (402) Steering control devices (attached to OEM steering wheel)
- (403) Steering knob attached to steering wheel
- (405) Replacement steering wheel (i.e., reduced diameter)
- (406) Joy stick steering controls
- (407) Wheelchair tie-downs
- (408) Modification to seat belts, (specify): _____
- (409) Additional or relocated switches, (specify): _____
- (410) Raised roof
- (411) Wall mounted head rest (used behind wheel chair)
- (412) Other adaptive device (specify): _____

CONFIDENCE LEVEL OF CONTACT POINT
- (1) Certain
- (2) Probable
- (3) Possible
- (9) Unknown

MANUAL RESTRAINTS

NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

If a Child safety seat is present, encode the data on the back of this page.

If the vehicle has automatic restraints available, encode the appropriate data on the back of the previous page.

		Left	Center	Right
FIRST	Availability	4	0	4
	Evidence of usage	04	00	04
	Used in this crash?	YES	0	-
	Proper Use	1	0	1
	Failure Modes	1	0	1
	Anchorage Adjustment	1	0	1
SECOND	Availability	4	0	4
	Evidence of usage	04	00	04
	Used in this crash?	-	0	-
	Proper Use	1	0	1
	Failure Modes	1	0	1
	Anchorage Adjustment	1	0	1
OTHER	Availability			
	Evidence of usage			
	Used in this crash?			
	Proper Use			
	Failure Modes			
	Anchorage Adjustment			

Manual (Active) Belt System Availability
- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available - type unknown

Integral Belt Partially Destroyed
- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)
- (8) Other belt (specify): _____
- (9) Unknown

Manual (Active) Belt System Use
- (00) None used, not available, or belt removed/destroyed
- (01) Inoperable (specify): _____
- (02) Shoulder belt
- (03) Lap belt
- (04) Lap and shoulder belt
- (05) Belt used - type unknown
- (08) Other belt used (specify): _____
- (12) Shoulder belt used with child safety seat
- (13) Lap belt used with child safety seat
- (14) Lap and shoulder belt used with child safety seat
- (15) Belt used with child safety seat - type unknown
- (18) Other belt used with child safety seat (specify): _____
- (99) Unknown if belt used

Proper Use of Manual (Active) Belts
- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly
- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____
- (8) Other improper use of manual belt system (specify): _____
- (9) Unknown

Manual (Active) Belt Failure Modes During Accident
- (0) No manual belt used or not available
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____
- (6) Broken retractor
- (7) Combination of above (specify): _____
- (8) Other manual belt failure (specify): _____
- (9) Unknown

Shoulder Belt Upper Anchorage Adjustment
- (0) No shoulder belt
- (1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage
- (2) In full up position
- (3) In mid position
- (4) In full down position
- (5) Position unknown
- (9) Unknown if position has adjustable upper anchorage adjustment

AUTOMATIC RESTRAINTS

NOTES: Encode the data for each applicable front seat position. The attribute for the variables may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

AIR BAGS

		Left Front	Right Front	Other
FIRST	Availability/Function			
	Deployment			
	Failure			

Air Bag System Availability/Function
(0) Not equipped/not available
(1) Air bag

Non-functional
(2) Air bag disconnected (specify): _____
(3) Air bag not reinstalled
(9) Unknown

Are There Indications of Air Bag System Failure? (This Occupant Position)
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(9) Unknown

Frontal Air Bag System Deployment (This Occupant Position)
(0) Not equipped/not available
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, accident sequence undetermined
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

Air Bag(s) Deployment, *Other* Than First Seat Frontal (This Occupant Position)
(0) Not equipped with an *"other"* air bag
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, details unknown
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

AUTOMATIC BELTS

		Left	Right
FIRST	Availability/Function		
	Use		
	Type		
	Proper Use		
	Failure Modes		

Automatic (Passive) Belt System Availability/Function
(0) Not equipped/not available
(1) 2 point automatic belts
(2) 3 point automatic belts
(3) Automatic belts - type unknown

Non-functional
(4) Automatic belts destroyed or rendered inoperative
(9) Unknown

Automatic (Passive) Belt System Use
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Automatic belt in use
(2) Automatic belt not in use (manually disconnected, motorized track inoperative)
(3) Automatic belt use unknown
(9) Unknown

Automatic (Passive) Belt System Type
(0) Not equipped/not available
(1) Non-motorized system
(2) Motorized system
(9) Unknown

Proper Use of Automatic (Passive) Belt System
(0) Not equipped/not available/not used
(1) Automatic belt used properly
(2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly
(3) Automatic shoulder belt worn under arm
(4) Automatic shoulder belt worn behind back
(5) Automatic belt worn around more than one person
(6) Lap portion of automatic belt worn on abdomen
(7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____
(8) Other improper use of automatic belt system (specify): _____
(9) Unknown

Automatic (Passive) Belt Failure Modes During Accident
(0) Not equipped/not available/not in use
(1) No automatic belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify): _____
(6) Broken retractor
(7) Combination of above (specify):
(8) Other automatic belt failure (specify): _____
(9) Unknown

FIRST SEAT FRONTAL AIR BAGS

NOTES: Encode the applicable data ***for the driver and first seat passenger*** in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

	Driver	Passenger
Type of air bag?	1	
Flaps open at tear points?	2	
Flaps damaged?	1	
Air bag damaged?	05	
Source of air bag damage	88	
Air bag tethered?	1	
Air bag have vent ports?	2	
Other occupant contact air bag?	1	
Occupant wearing eyewear?	1	

Type of Air Bag
- (0) Not equipped/not available
- (1) Original manufacturer installed system
- (2) Retrofitted air bag
- (3) Replacement air bag
- (8) Unknown type of air bag
- (9) Unknown

Did Air Bag Module Cover Flap(s) Open At Designated Tear Points?
- (0) Not equipped/not available
- (1) No
- (2) Yes
- (3) Deployed, unknown if flap(s) opened at designated tear points
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Were Air Bag Module Cover Flap(s) Damaged?
- (0) Not equipped/not available
- (1) No
- (2) Yes (specify): _____
- (3) Deployed, unknown if air bag module cover flap(s) damaged
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Was There Damage To The Air Bag?
- (00) Not equipped/not available
- (01) Not damaged

Yes - Air Bag Damage
- (02) Ruptured
- (03) Cut
- (04) Torn
- (05) Holed
- (06) Burned
- (07) Abraded
- (88) Other damage (specify): _____
- (95) Damaged, details unknown
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

Source of Air Bag Damage
- (00) Not equipped/not available
- (01) Not damaged
- (02) Object worn by occupant, (specify): _____
- (03) Object carried by occupant, (specify): _____
- (04) Adaptive/assistive controls, (specify): _____
- (05) Fire in vehicle
- (06) Thermal burns
- (07) Rescue or emergency efforts
- (88) Other damage source (specify): SHARP METEL- VEHICLE EXTERIOR
- (95) Damaged, unknown source
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

Was The Air Bag Tethered?
- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of tether straps): _____
- (3) Deployed, unknown if tethered
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Did The Air Bag Have Vent Ports?
- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of vent ports): 2
- (3) Deployed, unknown if vent ports present
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Was the Air Bag in this Occupant's Position Contacted by Another Occupant?
- (0) Not equipped/not available
- (1) No
- (2) Yes (specify): _____
- (3) Deployed, unknown if other occupant contact to air bag
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Was This Occupant Wearing Eye-wear?
- (0) Not equipped/not available
- (1) No
- (2) Eyeglasses/sunglasses
- (3) Contact lenses
- (4) Deployed, unknown if eyewear worn
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

DRIVER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Front)



2. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Back)



DRIVER AIR BAG SKETCHES (Cont'd)

3. DRIVER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

a. Upper Flap

width (W_U) 21

height (H_U) 7

b. Lower Flap

width (W_L) 21

height (H_L) 7



4. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

5. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

6. SKETCH LOCATION OF CIRCULAR AIR BAG VENT PORTS



PASSENGER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Front)



2. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Back)



PASSENGER AIR BAG SKETCHES (Cont'd)

3. PASSENGER AIR BAG MODULE COVER FLAP SIZE (SINGLE)

a. Flap

width (W) _____

height (H) _____



4. PASSENGER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

a. Upper Flap

width (W_U) _____

height (H_U) _____

b. Lower Flap

width (W_L) _____

height (H_L) _____



5. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

6. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

7. SKETCH LOCATION OF RECTANGULAR AIR BAG VENT PORTS



"OTHER" AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON *"OTHER"* AIR BAG (Front)

2. SKETCH DAMAGE AND CONTACT EVIDENCE ON *"OTHER"* AIR BAG (Back)

"OTHER" AIR BAG SKETCHES (Cont'd)

3. SKETCH AIR BAG MODULE FLAP AND SIZE OR OPENING FOR AIRBAG

4. SKETCH AIR BAG VENT PORTS

HEAD RESTRAINTS/SEAT EVALUATION

NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for these variables may be found at the bottom of the page. Head restraint type/damage and seat type/performance should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

		Left	Center	Right
FIRST	Head Restraint Type/Damage	1	0	1
	Seat Type	02	00	02
	Seat Performance	6	0	3
	Seat Orientation	1	0	1
	Seat Track Position	5	0	5
	Seat Back Incline Pre/Post Impact	23	0	22
SECOND	Head Restraint Type/Damage	0	0	0
	Seat Type	03	03	03
	Seat Performance	6	6	1
	Seat Orientation	1	1	1
	Seat Track Position	1	1	1
	Seat Back Incline Pre/Post Impact	01	01	01
THIRD	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
	Seat Track Position			
	Seat Back Incline Pre/Post Impact			
OTHER	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
	Seat Track Position			
	Seat Back Incline Pre/Post Impact			

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE

(I.E., UNUSUAL OCCUPANT CONTACT PATTERN)

HEAD RESTRAINTS/SEAT EVALUATION

Head Restraint Type/Damage by Occupant at This Occupant Position
(0) No head restraints
(1) Integral — no damage
(2) Integral — damaged during accident
(3) Adjustable — no damage
(4) Adjustable — damaged during accident
(5) Add-on — no damage
(6) Add-on — damaged during accident
(8) Other
Specify):_____
(9) Unknown

Seat Type (this Occupant Position)
(00) Occupant not seated or no seat
(01) Bucket
(02) Bucket with folding back
(03) Bench
(04) Bench with separate back cushions
(05) Bench with folding back(s)
(06) Split bench with separate back cushions
(07) Split bench with folding back(s)
(08) Pedestal (i.e., column supported)
(09) Other seat type (specify):
_____
(10) Box mounted seat (i.e., van type)
(99) Unknown

Seat Performance (this Occupant Position)
(0) Occupant not seated or no seat
(1) No seat performance failure(s)
(2) Seat adjusters failed
(3) Seat back folding locks or "seat back" failed (specify):
SEAT BACK IN RECLINED POSITION
(4) Seat tracks/anchors failed
(5) Deformed by impact of occupant
(6) Deformed by passenger compartment intrusion (specify): LT. DOOR & LT. REAR SIDE PANEL
(7) Combination of above (specify):
_____
(8) Other (specify):
_____
(9) Unknown

Seat Orientation (this Occupant Position)
(0) Occupant not seated or no seat
(1) Forward facing seat
(2) Rear facing seat
(3) Side facing seat (inward)
(4) Side facing seat (outward)
(8) Other (specify):
_____
(9) Unknown

Seat Track Adjusted Position Prior To Impact
(0) Occupant not seated or no seat
(1) Non-adjustable seat track

Adjustable Seat Track
(2) Seat at forward most track position
(3) Seat between forward most and middle track positions
(4) Seat at middle track position
(5) Seat between middle and rear most track positions
(6) Seat at rear most track position
(9) Unknown

Seat Back Incline Prior and Post Impact
(00) Occupant not seated or no seat
(01) Not adjustable

Upright prior to impact
(11) Moved to completely rearward position
(12) Moved to rearward midrange position
(13) Moved to slightly rearward position
(14) Retained pre-impact position
(15) Moved to slightly forward position
(16) Moved to forward midrange position
(17) Moved to completely forward position

Slightly reclined prior to impact
(21) Moved to completely rearward position
(22) Moved to rearward midrange position
(23) Retained pre-impact postion
(24) Moved to upright position
(25) Moved to slightly forward position
(26) Moved to forward midrange position
(27) Moved to completely forward position

Completely reclined prior to impact
(31) Retained pre-impact position
(32) Moved to rearward midrange position
(33) Moved to slightly rearward position
(34) Moved to upright position
(35) Moved to slightly forward position
(36) Moved to forward midrange position
(37) Moved to completely forward position

(99) Unknown



Coding diagrams for *Seat Back Incline Position Prior and Post Impact*

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE (I.E., UNUSUAL OCCUPANT CONTACT PATTERN)

CHILD SAFETY SEAT FIELD ASSESSMENT

When a child safety seat is present enter the occupant's number in the first row and complete the column below the occupant's number using the codes listed below. Complete a column for each child safety seat present.

Occupant Number						
1. Type of Child Safety Seat						
2. Child Safety Seat Orientation						
3. Child Safety Seat Harness Usage						
4. Child Safety Seat Shield Usage						
5. Child Safety Seat Tether Usage						
6. Child Safety Seat Make/Model	Specify Below for Each Child Safety Seat					

1. Type of Child Safety Seat

   (0) No child safety seat
   (1) Infant seat
   (2) Toddler seat
   (3) Convertible seat
   (4) Booster seat
   (7) Other type child safety seat (specify):

   _____

   (8) Unknown child safety seat type
   (9) Unknown if child safety seat used

2. Child Safety Seat Orientation

   (00) No child safety seat

   Designed for Rear Facing for This Age/Weight
   (01) Rear facing
   (02) Forward facing
   (08) Other orientation (specify):

   _____

   (09) Unknown orientation

   Designed for Forward Facing for This Age/Weight
   (11) Rear facing
   (12) Forward facing
   (18) Other orientation (specify):

   _____

   (19) Unknown orientation

   Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
   (21) Rear facing
   (22) Forward facing
   (28) Other orientation (specify):

   _____

   (29) Unknown orientation

   (99) Unknown if child safety seat used

3. Child Safety Seat Harness Usage

4. Child Safety Seat Shield Usage

5. Child Safety Seat Tether Usage
   Note: Options Below Are Used for Variables 3-5.

   (00) No child safety seat

   Not Designed with Harness/Shield/Tether
   (01) After market harness/shield/tether added, not used
   (02) After market harness/shield/tether used
   (03) Child safety seat used, but no after market harness/shield/tether added
   (09) Unknown if harness/shield/tether added or used

   Designed With Harness/Shield/Tether
   (11) Harness/shield/tether not used
   (12) Harness/shield/tether used
   (19) Unknown if harness/shield/tether used

   Unknown If Designed With Harness/Shield/Tether
   (21) Harness/shield/tether not used
   (22) Harness/shield/tether used
   (29) Unknown if harness/shield/tether used

   (99) Unknown if child safety seat used

6. Child Safety Seat Make/Model
   (Specify make/model and occupant number)

   _____

   _____

   _____

   _____

EJECTION/ENTRAPMENT DATA

Complete the following if the researcher has any indication that an occupant was either ejected from or entrapped in the vehicle. Code the appropriate data on the Occupant Assessment Form.

EJECTION No [ ] Yes [ ]

Describe indications of ejection and body parts involved in partial ejection(s):

Occupant Number						
Ejection						
(Note on Vehicle Interior Sketch) Ejection Area						
Ejection Medium						
Medium Status						

Ejection
(1) Complete ejection
(2) Partial ejection
(3) Ejection, Unknown degree
(9) Unknown

Ejection Area
(1) Windshield
(2) Left front
(3) Right front
(4) Left rear
(5) Right rear
(6) Rear
(7) Roof
(8) Other area (e.g., back of pickup, etc.) (specify): _____
(9) Unknown

Ejection Medium
(1) Door/hatch/tailgate
(2) Nonfixed roof structure
(3) Fixed glazing
(4) Nonfixed glazing (specify): _____
(5) Integral structure
(8) Other medium (specify): _____
(9) Unknown

Medium Status (Immediately Prior to Impact)
(1) Open
(2) Closed
(3) Integral structure
(9) Unknown

ENTRAPMENT No [ ] Yes [ ]

Describe entrapment mechanism: _____

Component(s): _____

(Note in vehicle interior diagram)

U.S. Department of Transportation
National Highway Traffic Safety Administration

OCCUPANT ASSESSMENT FORM

Form Approved
O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 49
2. Case Number - Stratum: 120 A
3. Vehicle Number: 01
4. Occupant Number: 01

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age: 31
Code actual age at time of accident.
(00) Less than one year old (specify by month): _____
(97) 97 years and older
(99) Unknown

6. Occupant's Sex: 2
(1) Male
(2) Female-not reported pregnant
(3) Female-pregnant-1st trimester(1st-3rd month)
(4) Female-pregnant-2nd trimester(4th-6th month)
(5) Female-pregnant-3rd trimester(7th-9th month)
(6) Female-pregnant-term unknown
(9) Unknown

7. Occupant's Height: 168 ~~163~~
Code actual height to the nearest centimeter.
(999) Unknown
~~64~~ ~~66~~ inches X 2.54 = 167.64 ~~1625~~ centimeters

8. Occupant's Weight: 077 ~~061~~
Code actual weight to the nearest kilogram.
(999) Unknown
~~170~~ ~~135~~ pounds X .4536 = 77.112 ~~61.2~~ kilograms

9. Occupant's Role: 1
(1) Driver
(2) Passenger
(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position: 11
Front Seat
(11) Left side
(12) Middle
(13) Right side
(14) Other (specify): _____
(15) On or in the lap of another occupant

Second Seat
(21) Left side
(22) Middle
(23) Right side
(24) Other (specify): _____
(25) On or in the lap of another occupant

Third Seat
(31) Left side
(32) Middle
(33) Right side
(34) Other (specify): _____
(35) On or in the lap of another occupant

Fourth Seat
(41) Left side
(42) Middle
(43) Right side
(44) Other (specify): _____
(45) On or in the lap of another occupant

(97) In or on unenclosed area
(98) Other seat (specify): _____
(99) Unknown

11. Occupant's Posture: 9
(0) Normal posture

Abnormal posture
(1) Kneeling or standing on seat
(2) Lying on or across seat
(3) Kneeling, standing or sitting in front of seat
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window
(5) Sitting on a console
(6) Lying back in a reclined seat position
(7) Bracing with feet or hands on a surface in front of seat
(8) Other abnormal posture (specify): _____
(9) Unknown

EJECTION/ENTRAPMENT

12. Ejection 0
    (0) No ejection
    (1) Complete ejection
    (2) Partial ejection
    (3) Ejection, unknown degree
    (9) Unknown

13. Ejection Area 0
    (0) No ejection
    (1) Windshield
    (2) Left front
    (3) Right front
    (4) Left rear
    (5) Right rear
    (6) Rear
    (7) Roof
    (8) Other area (e.g., back of pickup, etc.) (specify):_____
    (9) Unknown

14. Ejection Medium 0
    (0) No ejection
    (1) Door/hatch/tailgate
    (2) Nonfixed roof structure
    (3) Fixed glazing
    (4) Nonfixed glazing (specify):
    _____
    (5) Integral structure
    (8) Other medium (specify):
    _____
    (9) Unknown

15. Medium Status (Immediately Prior To Impact) 0
    (0) No ejection
    (1) Open
    (2) Closed
    (3) Integral structure
    (9) Unknown

16. Entrapment 9
    (0) Not entrapped/exit not inhibited
    (1) Entrapped/pinned - mechanically restrained
    (2) Could not exit vehicle due to jammed doors, fire, etc.
    (specify):_____
    _____
    (9) Unknown

17. Occupant Mobility 9
    (0) Occupant fatal before removed from vehicle
    (1) Removed from vehicle while unconscious or disoriented
    (2) Removed from vehicle due to injuries
    (3) Exited vehicle with some assistance
    (4) Exited vehicle under own power
    (5) Occupant fully ejected
    (9) Unknown

BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 4
(0) None available
(1) Belt removed/destroyed
(2) Shoulder belt
(3) Lap belt
(4) Lap and shoulder belt
(5) Belt available—type unknown

Integral Belt Partially Destroyed
(6) Shoulder belt (lap belt destroyed/removed)
(7) Lap belt (shoulder belt destroyed/removed)
(8) Other belt (specify):

(9) Unknown

19. Manual (Active) Belt System Use 04
(00) None used, not available, or belt removed/destroyed
(01) Inoperative (specify):

(02) Shoulder belt
(03) Lap belt
(04) Lap and shoulder belt
(05) Belt used—type unknown
(08) Other belt used (specify):

(12) Shoulder belt used with child safety seat
(13) Lap belt used with child safety seat
(14) Lap and shoulder belt used with child safety seat
(15) Belt used with child safety seat—type unknown
(18) Other belt used with child safety seat (specify):
(99) Unknown if belt used

20. Proper Use of Manual (Active) Belts 1
(0) None used or not available
(1) Belt used properly
(2) Belt used properly with child safety seat

Belt Used Improperly
(3) Shoulder belt worn under arm
(4) Shoulder belt worn behind back or seat
(5) Belt worn around more than one person
(6) Lap belt worn on abdomen
(7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of manual belt system (specify):

(9) Unknown

21. Manual (Active) Belt Failure Modes During Accident 1
(0) No manual belt used or not available
(1) No manual belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify):

(6) Broken retractor
(7) Combination of above (specify):

(8) Other manual belt failure (specify):

(9) Unknown

22. Shoulder Belt Upper Anchorage Adjustment 1
(0) No shoulder belt
(1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage
(2) In full up position
(3) In mid position
(4) In full down position
(5) Position unknown
(9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/ Function 0
(0) Not equipped/not available
(1) 2 point automatic belts
(2) 3 point automatic belts
(3) Automatic belts - type unknown

Non-functional
(4) Automatic belts destroyed or rendered inoperative
(9) Unknown

24. Automatic (Passive) Belt System Use 0
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Automatic belt in use
(2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify):
(3) Automatic belt use unknown
(9) Unknown

25. Automatic (Passive) Belt System Type 0
(0) Not equipped/not available
(1) Non-motorized system
(2) Motorized system
(9) Unknown

26. Proper Use of Automatic (Passive) Belt System 0
(0) Not equipped/not available/not used
(1) Automatic belt used properly
(2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly
(3) Automatic shoulder belt worn under arm
(4) Automatic shoulder belt worn behind back
(5) Automatic belt worn around more than one person
(6) Lap portion of automatic belt worn on abdomen
(7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of automatic belt system (specify):
(9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident 0
(0) Not equipped/not available/not in use
(1) No automatic belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify):

(6) Broken retractor
(7) Combination of above (specify):
(8) Other automatic belt failure (specify):

(9) Unknown

POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use 4
    (0) None used
    (1) Police did not indicate belt use
    (2) Shoulder belt
    (3) Lap belt
    (4) Lap and shoulder belt
    (5) Belt used, type not specified
    (6) Child safety seat
    (7) Automatic belt
    (8) Other type belt, (specify): _____
    (9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 2
    (0) No air bag available
    (1) Police did not indicate air bag availability/function
    (2) Deployed
    (3) Not deployed
    (4) Unknown if deployed
    (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

[ ] Not equipped/not available/destroyed or rendered inoperative
[ ] Vehicle inspection
[ ] Official injury data
[ ] Driver/occupant interview
[ ] Other (specify): _____
[ ] Unknown if belt used

AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System Availability/Function (This Occupant Position) 1
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

31. Frontal Air Bag System Deployment (This Occupant Position) 1
    (0) Not equipped/not available
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

32. Other Than First Seat Frontal Air Bag Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

    Specify type of "other" air bag present: _____

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) 0
    (0) Not equipped with an "other" air bag
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

34. Are There Indications of Air Bag System Failure? (This Occupant Position) 1
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify): _____
    (9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? 1
(0) Not equipped/not available
(1) No previous accidents

Yes
(2) Previous accident(s) without deployment(s)
(3) One previous accident with deployment
(4) More than one previous accident with at least one deployment
(8) Previous accidents, unknown deployment status
(9) Unknown

36. Type of Air Bag 1
(0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? 1
(0) Not equipped/not available
(1) No prior maintenance
(2) Yes, prior maintenance (specify):
_____
(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number 01
(00) Not equipped/not available
_____ Code the accident event sequence number that initiated the air bag deployment
(96) Deployed, unknown event
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

39. CDC For Air Bag Deployment Impact 1
(0) Not equipped/not available
(1) Highest delta V
(2) Second highest delta V
(3) Other non-coded delta V (specify):
_____
(6) Deployed, unknown event
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact +996 -059
(_000) Not equipped/not available
Code the value of the delta V for the impact that initiated the air bag deployment
(_996) Deployment, unknown longitudinal Delta V
(_997) Not deployed
(_998) Unknown if deployed
(_999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? 2
(0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? 1
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

43. Was There Damage To The Air Bag? 05 (04)
(00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage
(02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify):
_____
(95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION *continued*

44. Source of Air Bag Damage 88
(00) Not equipped/not available
(01) Not damaged
(02) Object worn by occupant, (specify):
(03) Object carried by occupant, (specify):
(04) Adaptive/assistive controls, (specify):
(05) Fire in vehicle
(06) Thermal burns
(07) Rescue or emergency efforts
(88) Other damage source (specify): SHARP METAL - VEHICLE EXTERIOR
(95) Damaged, unknown source
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

45. Was The Air Bag Tethered? 1
(0) Not equipped/not available
(1) No
(2) Yes (specify number of tether straps):
(3) Deployed, unknown if tethered
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

46. Did The Air Bag Have Vent Ports? 2
(0) Not equipped/not available
(1) No
(2) Yes (specify number of vent ports): 2
(3) Deployed, unknown if vent ports present
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? 1
(0) Not equipped/not available
(1) No
(2) Yes (specify):
(3) Deployed, unknown if other occupant contact to air bag
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

48. Was This Occupant Wearing Eye-wear? 1
(0) Not equipped/not available
(1) No
(2) Eyeglasses/sunglasses
(3) Contact lenses
(4) Deployed, unknown if eyewear worn
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION

49. Head Restraint Type/Damage by Occupant at This Occupant Position 1
(0) No head restraints
(1) Integral—no damage
(2) Integral—damaged during accident
(3) Adjustable—no damage
(4) Adjustable—damaged during accident
(5) Add-on—no damage
(6) Add-on—damaged during accident
(8) Other (specify):
(9) Unknown

50. Seat Type (this Occupant Position) 02
(00) Occupant not seated or no seat
(01) Bucket
(02) Bucket with folding back
(03) Bench
(04) Bench with separate back cushions
(05) Bench with folding back(s)
(06) Split bench with separate back cushions
(07) Split bench with folding back(s)
(08) Pedestal (i.e., column supported)
(09) Box mounted seat (i.e., van type)
(10) Other seat type (specify):
(99) Unknown

51. Seat Orientation (this Occupant Position) 1
(0) Occupant not seated or no seat
(1) Forward facing seat
(2) Rear facing seat
(3) Side facing seat (inward)
(4) Side facing seat (outward)
(8) Other (specify):
(9) Unknown

52. Seat Track Adjusted Position Prior To Impact 5
(0) Occupant not seated or no seat
(1) Non-adjustable seat track

Adjustable Seat Track
(2) Seat at forward most track position
(3) Seat between forward most and middle track positions
(4) Seat at middle track position
(5) Seat between middle and rear most track positions
(6) Seat at rear most track position
(9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*

53. Seat Back Incline Prior and Post Impact 2 3
(00) Occupant not seated or no seat
(01) Not adjustable

Upright prior to impact
(11) Moved to completely rearward position
(12) Moved to rearward midrange position
(13) Moved to slightly rearward position
(14) Retained pre-impact position
(15) Moved to slightly forward position
(16) Moved to forward midrange position
(17) Moved to completely forward position



Slightly reclined prior to impact
(21) Moved to completely rearward position
(22) Moved to rearward midrange position
(23) Retained pre-impact position
(24) Moved to upright position
(25) Moved to slightly forward position
(26) Moved to forward midrange position
(27) Moved to completely forward position



Completely reclined prior to impact
(31) Retained pre-impact position
(32) Moved to rearward midrange position
(33) Moved to slightly rearward position
(34) Moved to upright position
(35) Moved to slightly forward position
(36) Moved to forward midrange position
(37) Moved to completely forward position



(99) Unknown

54. Seat Performance (this Occupant Position) 6
(0) Occupant not seated or no seat
(1) No seat performance failure(s)
(2) Seat adjusters failed
(3) Seat back folding locks or "seat back" failed (specify):_____
(4) Seat track/anchors failed
(5) Deformed by impact of occupant
(6) Deformed by passenger compartment intrusion, (specify): LF DOOR PANEL
(7) Combination of above (specify):
(8) Other (specify): _____
(9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model 0 0 0
(000) No child safety seat
Applicable codes are found in your NASS CDS Data Collection, Coding and Editing
(950) Built-in child safety seat
(997) Other make/model (specify):
_____
(998) Unknown make/model
(999) Unknown if child safety seat used

56. Type of Child Safety Seat 0
(0) No child safety seat
(1) Infant seat
(2) Toddler seat
(3) Convertible seat
(4) Booster seat - with shield
(5) Booster seat - without shield
(7) Other type child safety seat (specify):
_____
(8) Unknown child safety seat type
(9) Unknown if child safety seat used

57. Child Safety Seat Orientation 0 0
(00) No child safety seat

Designed for Rear Facing for This Age/Weight
(01) Rear facing
(02) Forward facing
(08) Other orientation (specify):
_____
(09) Unknown orientation

Designed For Forward Facing for This Age/Weight
(11) Rear facing
(12) Forward facing
(18) Other orientation (specify):
_____
(19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
(21) Rear facing
(22) Forward facing
(28) Other orientation (specify):
_____
(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage 0 0

59. Child Safety Seat Shield Usage 0 0

60. Child Safety Seat Tether Usage 0 0

Note: Options below applicable to Variables OA58-OA60.
(00) No child safety seat

Not Designed With Harness/Shield/Tether
(01) After market harness/shield/tether added, not used
(02) After market harness/shield/tether used
(03) Child safety seat used, but no after market harness/shield/tether added
(09) Unknown if harness/shield/tether added or used

Designed With Harness/Shield/Tether
(11) Harness/shield/tether not used
(12) Harness/shield/tether used
(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether
(21) Harness/shield/tether not used
(22) Harness/shield/tether used
(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES

61. Injury Severity (Police Rating) 4

(0) O - No injury
(1) C - Possible injury
(2) B - Nonincapacitating injury
(3) A - Incapacitating injury
(4) K - Killed
(5) U - Injury, severity unknown
(6) Died prior to accident
(9) Unknown

62. Treatment - Mortality 1

(0) No treatment
(1) Fatal
(2) Fatal - ruled disease (specify):

_____

Nonfatal
(3) Hospitalization
(4) Transported and released
(5) Treatment at scene - nontransported
(6) Treatment later
(7) Treatment - other (specify):

_____

(8) Transported to a medical facility-unknown if treated
(9) Unknown

63. Type Of Medical Facility (for Initial Treatment) 1

(0) Not treated at a medical facility
(1) Trauma center
(2) Hospital
(3) Medical clinic
(4) Physician's office
(5) Treatment later at medical facility
(8) Other (specify):

_____

(9) Unknown

64. Hospital Stay 00

(00) Not Hospitalized
_____Code the number of days (up through 60) that the occupant stayed in hospital.
(61) 61 days or more
(99) Unknown

65. Working Days Lost 62

_____Code the number of days (up through 60) that the occupant lost from work due to the accident
(00) No working days lost
(61) 61 days or more
(62) Fatally injured
(97) Not working prior to accident
(99) Unknown

STOP WORK HERE

VARIABLES 66-74

TO BE CODED BY THE ZONE CENTER

TO BE CODED BY THE ZONE CENTER

INJURY CONSEQUENCES

66. Time to Death 01
_____Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 +n up through 30 days = 60)
(00) Not fatal
(96) Fatal - ruled disease
(99) Unknown

67. 1st Medically Reported Cause of Death 61

68. 2nd Medically Reported Cause of Death 00

69. 3rd Medically Reported Cause of Death 00
_____Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death
(00) Not fatal or no additional causes
(96) Mode of death given but specific injuries are not linked to cause of death. (specify):
_____
(97) Other result (includes fatal ruled disease) (specify):
_____
(99) Unknown

70. Number of Recorded Injuries for This Occupant 13
_____Code the actual number of injuries recorded for this occupant.
(00) No recorded injuries
(97) Injured, details unknown
(99) Unknown if injured

TRAUMA DATA

71. Glasgow Coma Scale (GCS) Score (at Medical Facility) 02
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured

72. Was the Occupant Given Blood? 9
(1) No - blood not given
(2) Yes - blood given
(specify units):_____
(9) Unknown if blood given

73. Arterial Blood Gases (ABG) – HCO_3 01
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported , HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

74. Primary Source of Belt Use Determination 1
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify):_____
(9) Unknown if belt used

U.S. Department of Transportation
National Highway Traffic Safety Administration

OCCUPANT INJURY FORM

Form Approved
O.M.B. No. 2127-0021
NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number	49	3. Vehicle Number	01
2. Case Number - Stratum	1204	4. Occupant Number	01

INJURY DATA-

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
1st	5. 1	6. 4	7. 2	8. 02	9. 18	10. 6	11. 4	12. 051	13. 2	14. 1	15. 01
2nd	16. 1	17. 4	18. 4	19. 14	20. 10	21. 4	22. 3	23. 051	24. 2	25. 1	26. 01
3rd	27. 1	28. 4	29. 5	30. 02	31. 52	32. 4	33. 2	34. 051	35. 2	36. 1	37. 01
4th	38. 1	39. 1	40. 9	41. 04	42. 02	43. 1	44. 2	45. 203	46. 2	47. 1	48. 08
5th	49. 1	50. 2	51. 9	52. 06	53. 02	54. 1	55. 7	56. 514	57. 2	58. 1	59. 00
6th	60. 1	61. 2	62. 9	63. 06	64. 02	65. 1	66. 2	67. 514	68. 2	69. 1	70. 00
7th	71. 1	72. 3	73. 9	74. 06	75. 02	76. 1	77. 2	78. 152	79. 2	80. 1	81. 00
8th	82. 1	83. 7	84. 9	85. 06	86. 02	87. 1	88. 2	89. 514	90. 2	91. 1	92. 00
9th	93. 1	94. 2	95. 9	96. 02	97. 02	98. 1	99. 1	100. 170	101. 1	102. 1	103. 00
10th	104. 1	105. 8	106. 9	107. 04	108. 02	109. 1	110. 2	111. 051	112. 1	113. 1	114. 01

OCCUPANT INJURY DATA

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
11th	1	8	9	02	02	1	2	010	1	1	00
12th	1	8	9	04	02	1	1	004	2	1	00
13th	1	8	9	02	02	1	2	051	1	1	01
14th											
15th											
16th											
17th											
18th											
19th											
20th											
21st											
22nd											
23rd											
24th											
25th											

OCCUPANT INJURY CLASSIFICATION

Body Region

(1) Head
(2) Face
(3) Neck
(4) Thorax
(5) Abdomen
(6) Spine
(7) Upper Extremity
(8) Lower Extremity
(9) Unspecified

Type of Anatomic Structure

(1) Whole Area
(2) Vessels
(3) Nerves
(4) Organs (includes Muscles/ligaments)
(5) Skeletal (includes joints)
(6) Head - LOC
(9) Skin

Specific Anatomic Structure

Vessels, Nerves, Organs. Bones, Joints are assigned consecutive two digit numbers beginning with 02.

The exceptions to this rule apply to:

Whole Area
(02) Skin - Abrasion
(04) Skin - Contusion
(06) Skin - Laceration
(08) Skin - Avulsion
(10) Amputation
(20) Burn
(30) Crush
(40) Degloving
(50) Injury - NFS
(90) Trauma, other than mechanical

Head - LOC
(02) Length of LOC

(04) Level
(06) of
(08) Consciousness

(10) Concussion

Spine
(02) Cervical
(04) Thoracic
(06) Lumbar

Level of Injury

Specific injuries are assigned consecutive two-digit numbers beginning with 02.

To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.

Abbreviated Injury Scale

(1) Minor Injury
(2) Moderate Injury
(3) Serious Injury
(4) Severe Injury
(5) Critical Injury
(6) Maximum (untreatable)
(7) Injured, unknown severity

Aspect

(1) Right
(2) Left
(3) Bilateral
(4) Central
(5) Anterior
(6) Posterior
(7) Superior
(8) Inferior
(9) Unknown
(0) Whole region

SOURCE OF INJURY DATA

OFFICIAL RECORDS
(1) Autopsy records with or without hospital/medical records
(2) Hospital/medical records other than emergency room (e.g., discharge summary)
(3) Emergency room records only (including associated X-rays or other lab reports)
(4) Private physician, walk-in or emergency clinic

UNOFFICIAL RECORDS
(5) Lay coroner report
(6) E.M.S. personnel
(7) Interviewee
(8) Other source (specify): _____
(9) Police

INJURY SOURCE CONFIDENCE LEVEL

(1) Certain
(2) Probable
(3) Possible
(9) Unknown

DIRECT/INDIRECT INJURY

(1) Direct contact injury
(2) Indirect contact injury
(3) Noncontact injury
(7) Injured, unknown source

INJURY SOURCES

FRONT
(001) Windshield
(002) Mirror
(003) Sunvisor
(004) Steering wheel rim
(005) Steering wheel hub/spoke
(006) Steering wheel (combination of codes 004 and 005)
(007) Steering column, transmission selector lever, other attachment
(008) Cellular telephone or CB radio
(009) Add on equipment (e.g., tape deck, air conditioner)
(010) Left instrument panel and below
(011) Center instrument panel and below
(012) Right instrument panel and below
(013) Glove compartment door
(014) Knee bolster
(015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
(016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
(017) Windshield reinforced by exterior object (specify)

_____

(019) Other front object (specify):

_____

LEFT SIDE
(051) Left side interior surface, excluding hardware or armrests
(052) Left side hardware or armrest
(053) Left A (A1/A2)-pillar
(054) Left B-pillar
(055) Other left pillar (specify):

_____

(056) Left side window glass
(057) Left side window frame
(058) Left side window sill
(059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(060) Other left side object (specify):

_____

RIGHT SIDE
(101) Right side interior surface, excluding hardware or armrests
(102) Right side hardware or armrest
(103) Right A (A1/A2)-pillar
(104) Right B-pillar
(105) Other right pillar (specify):

_____

(106) Right side window glass
(107) Right side window frame
(108) Right side window sill
(109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(110) Other right side object (specify):

_____

INTERIOR
(151) Seat, back support
(152) Belt restraint webbing/buckle
(153) Belt restraint B-pillar or door frame attachment point
(154) Other restraint system component (specify):

_____

(155) Head restraint system
(160) Other occupants (specify):

_____

(161) Interior loose objects
(162) Child safety seat (specify):

_____

(163) Other interior object (specify):

_____

AIR BAG
(170) Air bag-driver side
(171) Air bag-driver side and eyewear
(172) Air bag-driver side and jewelry
(173) Air bag-driver side and object held
(174) Air bag-driver side and object in mouth
(175) Air bag compartment cover-driver side
(176) Air bag compartment cover-driver side and eyewear
(177) Air bag compartment cover-driver side and jewelry
(178) Air bag compartment cover-driver side and object held
(179) Air bag compartment cover-driver side and object in mouth
(180) Air bag-passenger side
(181) Air bag-passenger side and eyewear
(182) Air bag-passenger side and jewelry
(183) Air bag-passenger side and object held
(184) Air bag-passenger side and object in mouth
(185) Air bag compartment cover-passenger side
(186) Air bag compartment cover-passenger side and eyewear
(187) Air bag compartment cover-passenger side and jewelry
(188) Air bag compartment cover-passenger side and object held
(189) Air bag compartment cover-passenger side and object in mouth
(190) Other air bag (specify)

_____

(195) Other air bag compartment cover (specify)

_____

ROOF
(201) Front header
(202) Rear header
(203) Roof left side rail
(204) Roof right side rail
(205) Roof or convertible top

FLOOR
(251) Floor (including toe pan)
(252) Floor or console mounted transmission lever, including console
(253) Parking brake handle
(254) Foot controls including parking brake

REAR
(301) Backlight (rear window)
(302) Backlight storage rack, door, etc.
(303) Other rear object (specify):

_____

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT
(401) Hand controls for braking/acceleration
(402) Steering control devices (attached to OEM steering wheel)
(403) Steering knob attached to steering wheel
(405) Replacement steering wheel (i.e., reduced diameter)
(406) Joy stick steering controls
(407) Wheelchair tie-downs
(408) Modification to seat belts, (specify): _____
(409) Additional or relocated switches, (specify):

_____

(410) Raised roof
(411) Wall mounted head rest (used behind wheel chair)
(412) Other adaptive device (specify):_____

_____

EXTERIOR of OCCUPANT'S VEHICLE
(451) Hood
(452) Outside hardware (e.g., outside mirror, antenna)
(453) Other exterior surface or tires (specify):

_____

_____

(454) Unknown exterior objects

EXTERIOR OF OTHER MOTOR VEHICLE
(501) Front bumper
(502) Hood edge
(503) Other front of vehicle (specify):

_____

(504) Hood
(505) Hood ornament
(506) Windshield, roof rail, A-pillar
(507) Side surface
(508) Side mirrors
(509) Other side protrusions (specify):

_____

(510) Rear surface
(511) Undercarriage
(512) Tires and wheels
(513) Other exterior of other motor vehicle (specify):

_____

_____

(514) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT
(551) Ground
(598) Other vehicle or object (specify):

_____

(599) Unknown vehicle or object

NONCONTACT INJURY
(601) Fire in vehicle
(602) Flying glass
(603) Other noncontact injury source (specify): _____
(604) Air bag exhaust gases
(697) Injured, unknown source

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



OFFICIAL INJURY DATA — SKELETAL INJURIES

Restrained?

___ No

___ Yes

Blood Alcohol Level (mg/dl)

BAL = 0

Glasgow Coma Scale Score

GCSS = N/A

Units of Blood Given

Units = 7

Arterial Blood Gases

pH = ___

PO_2 = ___

PCO_2 = ___

HCO_3 = ___

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



OFFICIAL INJURY DATA – INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



PSU 49-120A
V-02

PRECRASH ENVIRONMENTAL DATA

19. Relation To Interchange Or Junction — 2
(0) Non-interchange area and non-junction
(1) Interchange area related

Non-Interchange junctions
(2) Intersection related
(3) Driveway, alley access related
(4) Other junction (specify) _____
(5) Unknown type of junction
(9) Unknown

20. Trafficway Flow — 1
(0) Not physically divided (two way traffic)
(1) Divided trafficway-median strip without positive barrier
(2) Divided trafficway-median strip with positive barrier
(3) One way traffic
(9) Unknown

21. Number Of Travel Lanes — 3
(1) One
(2) Two
(3) Three
(4) Four
(5) Five
(6) Six
(7) Seven or more
(9) Unknown

22. Roadway Alignment — 1
(1) Straight
(2) Curve right
(3) Curve left
(9) Unknown

23. Roadway Profile — 1
(1) Level
(2) Uphill grade (>2%)
(3) Hill crest
(4) Downhill grade (>2%)
(5) Sag
(9) Unknown

24. Roadway Surface Type — 1
(1) Concrete
(2) Bituminous (asphalt)
(3) Brick or block
(4) Slag, gravel, or stone
(5) Dirt
(8) Other (specify): _____
(9) Unknown

25. Roadway Surface Condition — 1
(1) Dry
(2) Wet
(3) Snow or slush
(4) Ice
(5) Sand, dirt, or oil
(8) Other (specify): _____
(9) Unknown

26. Light Conditions — 1
(1) Daylight
(2) Dark
(3) Dark, but lighted
(4) Dawn
(5) Dusk
(9) Unknown

27. Atmospheric Conditions — 0
(0) No adverse atmospheric-related driving conditions
(1) Rain
(2) Sleet/hail
(3) Snow
(4) Fog
(5) Rain and fog
(6) Sleet and fog
(7) Other (e.g., smog, smoke, blowing sand or dust, etc.) (specify): _____
(9) Unknown

28. Traffic Control Device — 1
(0) No traffic control(s)
(1) Traffic control signal (not RR crossing)

Regulatory
(2) Stop sign
(3) Yield sign
(4) School zone sign
(5) Other regulatory sign (specify): _____
(6) Warning sign (not RR crossing)
(7) Unknown sign
(8) Miscellaneous/other controls including RR controls (specify): _____
(9) Unknown

29. Traffic Control Device Functioning — 2
(0) No traffic control device
(1) Traffic control device not functioning (specify): _____
(2) Traffic control device functioning properly
(9) Unknown

OCCUPANT RELATED

37. Driver Presence in Vehicle: 1
(0) Driver not present
(1) Driver present
(9) Unknown

38. Number of Occupants This Vehicle: 02
(00-96) Code actual number of occupants for this vehicle
(97) 97 or more
(99) Unknown

39. Number of Occupant Forms Submitted: 02

AIR BAG RELATED

40. Is this an AOPS Vehicle? 1
(0) No (includes unknown)
(1) Yes - researcher determined
(2) VIN determined air bag system
(3) VIN determined automatic (passive) belts
(4) VIN determined air bag and automatic (passive) belts

41. Air Bag(s) Deployment, First Seat Frontal 2
(0) Not equipped or not available
(1) No air bags deployed

Single Air Bag Vehicle
(2) Driver air bag deployed
(3) Driver air bag, unknown if deployed

Multiple Air Bag Vehicle
(4) Driver side only deployed
(5) Passenger side only deployed
(6) Driver and passenger side deployed
(7) Driver and passenger side unknown if deployed
(8) Air bag(s) deployed, details unknown
(9) Unknown

42. Air Bag(s) Deployment, Other Than First Seat Frontal 0
(0) Not equipped with an "other" air bag
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, details unknown
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

Specify type of "other" air bag present: _____

VEHICLE WEIGHT ITEMS

43. Vehicle Curb Weight 2,120
____ Code weight to nearest 10 kilograms.
(045) Less than 450 kilograms
(610) 6,100 kilograms or more
(999) Unknown
4,677 lbs X .4536 = 2,121 kgs
Source: [redacted]

44. Vehicle Cargo Weight 0,140
____ Code weight to nearest 10 kilograms.
(000) Less than 5 kilograms
(450) 4,500 kilograms or more
(999) Unknown
,300 lbs X .4536 = ,136 kgs
Source: [redacted]

ROLLOVER DATA

45. Rollover 00
(00) No rollover (no overturning)

Rollover (primarily about the longitudinal axis)
(01-16) Code the number of quarter turns
(17) Rollover, 17 or more quarter turns (specify): _____
(98) Rollover--end-over-end (i.e., primarily about the lateral axis)
(99) Rollover (overturn), details unknown

46. Rollover Initiation Type 00
(00) No rollover
(01) Trip-over
(02) Flip-over
(03) Turn-over
(04) Climb-over
(05) Fall-over
(06) Bounce-over
(07) Collision with another vehicle
(08) Other rollover initiation type specify): _____
(98) Rollover--end-over-end
(99) Unknown rollover initiation type

47. Location of Rollover Initiation 0
(0) No rollover
(1) On roadway
(2) On shoulder—paved
(3) On shoulder—unpaved
(4) On roadside or divided trafficway median
(8) Rollover--end-over-end
(9) Unknown

48. Rollover Initiation Object Contacted 00
(Note: Applicable codes on back of page)

49. Location on Vehicle Where Initial Principal Tripping Force Is Applied 0
(0) No rollover
(1) Wheels/tires
(2) Side plane
(3) End plane
(4) Undercarriage
(5) Other location on vehicle (specify): _____
(6) Non-contact rollover forces (specify): _____
(8) Rollover--end-over-end
(9) Unknown

50. Direction of Initial Roll 0
(0) No rollover
(1) Roll right - primarily about the longitudinal axis
(2) Roll left - primarily about the longitudinal axis
(8) Rollover--end-over-end
(9) Unknown roll direction

PSU 49-120A
V-02

CODES FOR ROLLOVER INITIATION OBJECT CONTACTED

(00) No rollover
(01-30) — Vehicle Number

Noncollision
(31) Turn-over — fall-over
(32) No rollover impact initiation (end-over-end)
(34) Jackknife

Collision With Fixed Object
(41) Tree (≤ 10 cm in diameter)
(42) Tree (> 10 cm in diameter)
(43) Shrubbery or bush
(44) Embankment

(45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
(50) Pole or post (≤ 10 cm in diameter)
(51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
(52) Pole or post (> 30 cm in diameter)
(53) Pole or post (diameter unknown)

(54) Concrete traffic barrier
(55) Impact attenuator
(56) Other traffic barrier (includes guardrail) (specify):_____

(57) Fence
(58) Wall
(59) Building
(60) Ditch or culvert
(61) Ground
(62) Fire hydrant
(63) Curb
(64) Bridge
(68) Other fixed object (specify):

_____

(69) Unknown fixed object

Collision with Nonfixed Object
(70) Passenger car, light truck, van, or other vehicle not in-transport
(71) Medium/heavy truck or bus not in-transport
(76) Animal
(77) Train
(78) Trailer, disconnected in transport
(79) Object fell from vehicle in-transport
(88) Other nonfixed object (specify):

_____

(89) Unknown nonfixed object

(98) Other event (specify):

_____

(99) Unknown event or object

U.S. Department of Transportation
National Highway Traffic Safety Administration

EXTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 49
2. Case Number - Stratum: 120A
3. Vehicle Number: 02

VEHICLE IDENTIFICATION

VIN 1FTEE14Y1SH[redacted] Model Year 95

Vehicle Make (specify): FORD Vehicle Model (specify): ECONOLINE 150

LOCATOR

Locate the end of the damage with respect to the vehicle longitudinal center line or bumper corner for end impacts or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L	Location of Max Crush
1	ENTIRE FRONTAL PLANE (PER BODY MAN)	SAME AS DIRECT	

CRUSH PROFILE IN CENTIMETERS

NOTES: Identify the plane at which the C-measurements are taken (e.g., at bumper, above bumper, at sill, above sill, etc.) and label adjustments (e.g., free space).

Measure C1 to C6 from driver to passenger side in front or rear impacts and rear to front in side impacts.

Free space value is defined as the distance between the baseline and the original body contour taken at the individual C locations. This may include the following: bumper lead, bumper taper, side protrusion, side taper, etc. Record the value for each C-measurement and maximum crush.

Use as many lines/columns as necessary to describe each damage profile.

Specific Impact Number	Plane of Impact C-Measurements	Direct Damage		Field L	C_1	C_2	C_3	C_4	C_5	C_6	±D
		Width (CDC)	Max Crush								
1	FRONT			VEHICLE		TAKEN		APART			

HS Form 435A (Rev. 1/95)

ORIGINAL SPECIFICATIONS WORK SHEET

Wheelbase	138.0	inches	x	2.54	=	351 cm
Overall Length	211.8	inches	x	2.54	=	538 cm
Maximum Width	79.5	inches	x	2.54	=	202 cm
Curb Weight	4,677	pounds	x	.4536	=	2,121 kg
Average Track	68.5	inches	x	2.54	=	174 cm
Front Overhang	___.___	inches	x	2.54	=	___ cm
Rear Overhang	___.___	inches	x	2.54	=	___ cm
Undeformed End Width	___.___	inches	x	2.54	=	___ cm
Engine Size: cyl./displ.	____	cc	x	.001	=	___.___ L
	___	CID	x	.0164	=	___.___ L

VEHICLE DAMAGE SKETCH

TIRE—WHEEL DAMAGE

a. Rotation physically restricted

RF 2
LF 1
RR 2
LR 2

b. Tire deflated

RF 2
LF 2
RR 2
LR 2

(1) Yes (2) No (8) NA (9) Unk.

TYPE OF TRANSMISSION

☐ Manual ☒ Automatic

END SHIFT ≥ 10 CM
☐ Yes ☐ No unk

ORIGINAL SPECIFICATIONS

Wheelbase	351	cm
Overall Length	538	cm
Maximum Width	202	cm
Curb Weight	2,121	kg
Average Track	174	cm
Front Overhang	70	cm
Rear Overhang	117	cm
Undeformed End Width	178	cm
Engine Size: cyl./displ.	I6/4.9	L

WHEEL STEER ANGLES

(For locked front wheels or displaced rear axles only)

RF ± — — °
LF ± 0 0 °
RR ± — — °
LR ± — — °

Within ± 5 degrees

DRIVE WHEELS

☐ FWD ☒ RWD ☐ 4WD

Approximate Cargo Weight 150 kg
TOOLS - PLUMING SUPPLIES

MEASUREMENTS IN CENTIMETERS









NOTES: Sketch new perimeter and cross hatch direct damage and single hatch induced damage on all views. Annotate observations which might be useful in reconstructing the accident (e.g., grass in tire bead, direction of striations, scuff on sidewalls, etc.). If pulling trailer, sketch type of trailer and damage received on the back of this page.

Annotate any damage caused by extrication such as component removal by torching, prying, or hydraulic shears.

CDC WORKSHEET

CODES FOR OBJECT CONTACTED

(01-30) — Vehicle Number

Noncollision
- (31) Overturn — rollover (excludes end-over-end)
- (32) Rollover—end-over-end
- (33) Fire or explosion
- (34) Jackknife
- (35) Other intraunit damage (specify): _____
- (36) Noncollision injury
- (38) Other noncollision (specify): _____
- (39) Noncollision — details unknown

Collision With Fixed Object
- (41) Tree (≤ 10 cm in diameter)
- (42) Tree (> 10 cm in diameter)
- (43) Shrubbery or bush
- (44) Embankment
- (45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
- (50) Pole or post (≤ 10 cm in diameter)
- (51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
- (52) Pole or post (> 30 cm in diameter)
- (53) Pole or post (diameter unknown)
- (54) Concrete traffic barrier
- (55) Impact attenuator
- (56) Other traffic barrier (includes guardrail) (specify): _____
- (57) Fence
- (58) Wall
- (59) Building
- (60) Ditch or culvert
- (61) Ground
- (62) Fire hydrant
- (63) Curb
- (64) Bridge
- (68) Other fixed object (specify): _____
- (69) Unknown fixed object

Collision with Nonfixed Object
- (70) Passenger car, light truck, van, or other vehicle not in-transport
- (71) Medium/heavy truck or bus not in-transport
- (72) Pedestrian
- (73) Cyclist or cycle
- (74) Other nonmotorist or conveyance
- (75) Vehicle occupant
- (76) Animal
- (77) Train
- (78) Trailer, disconnected in transport
- (79) Object fell from vehicle in-transport
- (88) Other nonfixed object (specify): _____
- (89) Unknown nonfixed object
- (98) Other event (specify): _____
- (99) Unknown event or object

DEFORMATION CLASSIFICATION BY EVENT NUMBER

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force (degrees)	Incremental Value of Shift	(3) Deformation Location	(4) Specific Longitudinal or Lateral Location	(5) Specific Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
01	01	040	00	F	D	E	W	01

COLLISION DEFORMATION CLASSIFICATION

HIGHEST DELTA "V"

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force	(3) Deformation Location	(4) Longitudinal or Lateral Location	(5) Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
4. 01	5. 01	6. 99	7. 9	8. 9	9. 9	10. 9	11. 99

Second Highest Delta "V"

12.	13.	14.	15.	16.	17.	18.	19.

CRUSH PROFILE IN CENTIMETERS

The crush profile for the damage described in the CDC(s) above should be documented in the appropriate space below. (ALL MEASUREMENTS ARE IN CENTIMETERS.)

HIGHEST DELTA "V"

20. L	21. C_1	C_2	C_3	C_4	C_5	C_6	22. ±D
							+ −

Second Highest Delta "V"

23. L	24. C_1	C_2	C_3	C_4	C_5	C_6	25. ±D
							+ −

26. Undeformed End Width (Coded when highest severity impact is an end plane impact.) 178
- ____ Code to the nearest centimeter
- (250) 250 centimeters or more
- (998) No highest severity end plane impact
- (999) Unknown

27. Direct Damage Width (For highest severity impact) 999
- ____ Code to the nearest centimeter
- (250) 250 centimeters or more
- (999) Unknown

28. Original Wheelbase 351
- ____ Code to the nearest centimeter
- (650) 650 centimeters or more
- (999) Unknown

138.0 inches X 2.54 = 351 centimeters

29. Original Average Track Width 174
- ____ Code to the nearest centimter
- (185) 185 centimeters or more
- (999) Unknown

68.5 inches X 2.54 = 174 centimeters

30. Are CDCs Documented but Not Coded on The Automated File? 0
(0) No
(1) Yes

31. Researcher's Assessment of Vehicle Disposition 1
(0) Not towed due to vehicle damage
(1) Towed due to vehicle damage
(9) Unknown

32. Is This A Multi-Stage Manufactured Vehicle And/Or A Certified Altered Vehicle? 1
(0) No post manufacturer modifications
(1) Yes - post manufacturer modifications (specify): CARGO VAN - TOOL BOXES - SAFETY CAGE
(Include photograph of CERTIFICATION PLACARD in case report)
(9) Unknown if vehicle is modified

FIRE OCCURRENCE

33. Fire Occurrence 0
(0) No fire

Yes, fire occurred
(1) Minor
(2) Major
(9) Unknown

34. Origin of Fire 0
(0) No fire
(1) Vehicle exterior (front, side, back, top)
(2) Exhaust system
(3) Fuel tank (and other fuel retention system parts)
(4) Engine compartment
(5) Cargo/trunk compartment
(6) Instrument panel
(7) Passenger compartment area
(8) Other location (specify): _____
(9) Unknown

FUEL SYSTEM

35. Location of Fuel Tank-1 Filler Cap 4

36. Location of Fuel Tank-2 Filler Cap 6
(0) No fuel tank
(1) On back plane
(2) Aft of center of the rear wheels (rear axle) on left side plane
(3) Aft of center of the rear wheels (rear axle) on right side plane
(4) Forward of center of the rear wheels (rear axle) on left side plane
(5) Forward of center of the rear wheels (rear axle) on right side plane
(6) Over the center of the rear wheels (rear axle) on left side plane
(7) Over the center of the rear wheels (rear axle) on right side plane
(8) Other (specify): _____
(9) Unknown

37. Type of Fuel Tank-1 1

38. Type of Fuel Tank-2 0
(0) No fuel tank (electrical vehicle)
(1) Metallic
(2) Non-metallic
(9) Unknown

39. Location of Fuel Tank-1 5

40. Location of Fuel Tank-2 0
(0) No fuel tank
(1) Aft of center of the rear wheels (rear axle) centered
(2) Aft of center of the rear wheels (rear axle) left side
(3) Aft of center of the rear wheels (rear axle) right side
(4) Forward of center of the rear wheels (rear axle) centered
(5) Forward of center of the rear wheels (rear axle) left side
(6) Forward of center of the rear wheels (rear axle) right side
(7) Over center of the rear wheels (rear axle)
(8) Other (specify): _____
(9) Unknown

41. Damage to Fuel Tank-1 1

42. Damage to Fuel Tank-2 0
(0) No fuel tank
(1) No damage to fuel tank
(2) Deformed, no seam failure
(3) Deformed, with a seam failure
(4) Punctured
(5) Lacerated (ripped)
(6) Abraded (scraped)
(7) Filler neck separation from the fuel tank
(8) Other damage (specify): _____
(9) Unknown

43. Leakage Location of Fuel System-1 1

44. Leakage Location of Fuel System-2 0
(0) No fuel tank
(1) No fuel leakage

Primary Area Of Leakage
(2) Tank
(3) Filler neck
(4) Cap
(5) Lines/pump/filter
(6) Vent/emission recovery
(8) Other (specify):_____
(9) Unknown

45. Fuel Type-1 01

46. Fuel Type-2 00

Single Fuel Type
(00) No fuel tank
(01) Gasoline
(02) Diesel
(03) CNG (Compressed Natural Gas)
(04) LPG (Liquid Petroleum Gas) also known as Propane
(05) LNG (Liquid Natural Gas)
(06) Methanol (M100 or M85)
(07) Ethanol (E100 or E85)
(08) Other (Hydrogen or others) (specify):
_____

Electric Powered or Electric/Solar Powered Vehicles
(10) Lead Acid Battery
(11) Nickel-Iron Battery
(12) Nickel-Cadmium Battery
(13) Sodium Metal Chloride Battery
(14) Sodium Sulfur Battery
(18) Other (Specify):_____

(98) Other Hybrid (specify):
_____

(99) Unknown fuel type

47. Is This Vehicle Equipped With More Than Two Fuel Tanks? 0
(0) No (one or two tanks only)

Yes - More Than Two Tanks
(1) Yes -- no damage to any tank or filler cap and no fuel system leakage
(2) Yes -- no damage to any tank or filler cap but there is fuel system leakage (specify leakage location):
_____
(3) Yes -- damage to an additional tank or filler cap and there is fuel system leakage (specify the following):
Type of tank _____
Tank location _____
Filler cap location _____
Tank damage _____
Location of leakage _____
Type of fuel _____
(9) Unknown if more than two tanks

COMMENTS

*** STOP: IF THE CDS APPLICABLE VEHICLE WAS NOT TOWED ***

(GV10=0)

DO NOT COMPLETE THE INTERIOR VEHICLE FORM.

U.S. Department of Transportation
National Highway Traffic Safety Administration

INTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 49
2. Case Number - Stratum: 120A
3. Vehicle Number: 02

INTEGRITY

4. Passenger Compartment Integrity: 00

(00) No integrity loss

Yes, Integrity Was Lost Through
(01) Windshield
(02) Door (side)
(03) Door/hatch (back door)
(04) Roof
(05) Roof glass
(06) Side window
(07) Rear window (backlight)
(08) Roof and roof glass
(09) Windshield and door (side)
(10) Windshield and roof
(11) Side and rear window (side window and backlight)
(12) Windshield and side window
(13) Door and side window
(98) Other combination of above (specify): _____
(99) Unknown

Door, Tailgate or Hatch Opening

5. LF 1 6. RF 1 7. LR 0 8. RR 1 9. TG/H 1

(0) No door/gate/hatch
(1) Door/gate/hatch remained closed and operational
(2) Door/gate/hatch came open during collision
(3) Door/gate/hatch jammed shut
(8) Other (specify): _____
(9) Unknown

Damage/Failure Associated with Door, Tailgate or Hatch Opening in Collision. If IV05-IV09 ≠ 2, Then code Ø

10. LF 0 11. RF 0 12. LR 0 13. RR 0 14. TG/H 0

(0) No door/gate/hatch or door not opened

Door, Tailgate or Hatch Came Open During Collision
(1) Door operational (no damage)
(2) Latch/striker failure due to damage
(3) Hinge failure due to damage
(4) Door structure failure due to damage
(5) Door support (i.e., pillar, sill, roof side rail, etc.) failure due to damage
(6) Latch/striker and hinge failure due to damage
(8) Other failure (specify): _____
(9) Unknown

GLAZING

Type of Window/Windshield Glazing

15. WS 1 16. LF 2 17. RF 2 18. LR 0 19. RR 2
20. BL 2 21. Roof 0 22. Other 2

(0) No glazing
(1) AS-1 — Laminated
(2) AS-2 — Tempered
(3) AS-3 — Tempered-tinted (original)
(4) AS-2 — Tempered-with after market tint
(5) AS-3 — Tempered-tinted (with additional after market tint)
(6) AS-14 — Glass/Plastic
(7) Glazing removed prior to accident
(8) Other (specify): _____
(9) Unknown

Window Precrash Glazing Status

23. WS 1 24. LF 4 25. RF 2 26. LR 0 27. RR 1
28. BL 1 29. Roof 0 30. Other 1

(0) No glazing
(1) Fixed
(2) Closed
(3) Partially opened
(4) Fully opened
(7) Glazing removed prior to accident
(9) Unknown

Glazing Damage from Impact Forces

31. WS 1 32. LF 1 33. RF 1 34. LR 0 35. RR 1
36. BL 1 37. Roof 0 38. Other 1

(0) No glazing
(1) No glazing damage from impact forces
(2) Glazing in place and cracked from impact forces
(3) Glazing in place and holed from impact forces
(4) Glazing out-of-place (cracked or not) and not holed from impact forces
(5) Glazing out-of-place and holed from impact forces
(6) Glazing disintegrated from impact forces
(7) Glazing removed prior to accident
(9) Unknown if damaged

Glazing Damage from Occupant Contact

39. WS 1 40. LF 1 41. RF 1 42. LR 0 43. RR 1
44. BL 1 45. Roof 0 46. Other 1

(0) No glazing
(1) No occupant contact to glazing
(2) Glazing contacted by occupant but no glazing damage
(3) Glazing in place and cracked by occupant contact
(4) Glazing in place and holed by occupant contact
(5) Glazing out-of-place (cracked or not) by occupant contact and not holed by occupant contact
(6) Glazing out-of-place by occupant contact and holed by occupant contact
(7) Glazing removed prior to accident
(8) Glazing disintegrated by occupant contact
(9) Unknown if contacted by occupant

INTRUSION WORKSHEET

Note: Sketch intruded areas



LOCATION OF INTRUSION	INTRUDED COMPONENT	(All Measurements Are In Centimeters) COMPARISON VALUE	—	INTRUDED VALUE	=	INTRUSION	DOMINANT CRUSH DIRECTION
			—		=		
			—		=		
			—		=		
			—		=		
			—		=		
			—		=		
			—		=		
			—		=		
			—		=		
			—		=		
			—		=		
			—		=		
			—		=		
			—		=		
			—		=		

Document no more than the 15 most severe intrusions

OCCUPANT AREA INTRUSION

Note: If no intrusions, leave variables IV47-IV86 blank.

	Location of Intrusion	Intruding Component	Magnitude of Intrusion	Dominant Crush Direction
1st	47.___ ___	48.___ ___	49.___	50.___
2nd	51.___ ___	52.___ ___	53.___	54.___
3rd	55.___ ___	56.___ ___	57.___	58.___
4th	59.___ ___	60.___ ___	61.___	62.___
5th	63.___ ___	64.___ ___	65.___	66.___
6th	67.___ ___	68.___ ___	69.___	70.___
7th	71.___ ___	72.___ ___	73.___	74.___
8th	75.___ ___	76.___ ___	77.___	78.___
9th	79.___ ___	80.___ ___	81.___	82.___
10th	83.___ ___	84.___ ___	85.___	86.___

LOCATION OF INTRUSION

Front Seat
- (11) Left
- (12) Middle
- (13) Right

Second Seat
- (21) Left
- (22) Middle
- (23) Right

Third Seat
- (31) Left
- (32) Middle
- (33) Right

Fourth Seat
- (41) Left
- (42) Middle
- (43) Right

- (97) Catastrophic
- (98) Other enclosed area (specify) _____
- (99) Unknown

INTRUDING COMPONENT

Interior Components
- (01) Steering assembly
- (02) Instrument panel left
- (03) Instrument panel center
- (04) Instrument panel right
- (05) Toe pan
- (06) A (A1/A2)-pillar
- (07) B-pillar
- (08) C-pillar
- (09) D-pillar
- (10) Side panel - forward of the A1/A2-pillar
- (11) Door panel (side)
- (12) Side panel - rear of the B-pillar
- (13) Roof (or convertible top)
- (14) Roof side rail
- (15) Windshield
- (16) Windshield header
- (17) Window frame
- (18) Floor pan (includes sill)
- (19) Backlight header
- (20) Front seat back
- (21) Second seat back
- (22) Third seat back
- (23) Fourth seat back
- (24) Fifth seat back
- (25) Seat cushion
- (26) Back door/panel (e.g., tailgate)
- (27) Other interior component (specify): _____

Exterior Components
- (30) Hood
- (31) Outside surface of this vehicle (specify): _____
- (32) Other exterior object in the environment (specify): _____
- (33) Unknown exterior object
- (97) Catastrophic
- (98) Intrusion of unlisted component(s) (specify): _____
- (99) Unknown

MAGNITUDE OF INTRUSION

- (1) ≥ 3 centimeters but < 8 centimeters
- (2) ≥ 8 centimeters but < 15 centimeters
- (3) ≥ 15 centimeters but < 30 centimeters
- (4) ≥ 30 centimeters but < 46 centimeters
- (5) ≥ 46 centimeters but < 61 centimeters
- (6) ≥ 61 centimeters
- (7) Catastrophic
- (9) Unknown

DOMINANT CRUSH DIRECTION

- (1) Vertical
- (2) Longitudinal
- (3) Lateral
- (7) Catastrophic
- (9) Unknown

STEERING RIM/SPOKE DEFORMATION

(All Measurements Are in Centimeters)

COMPARISON VALUE	—	DAMAGE VALUE	=	DEFORMATION
	—		=	
	—		=	
	—		=	
	—		=	

STEERING COLUMN

87. Steering Column Type 1
(1) Fixed column
(2) Tilt column
(3) Telescoping column
(4) Tilt and telescoping column
(8) Other column type (specify): _____
(9) Unknown

88. Tilt Steering Column Adjustment 0
(0) No tilt steering column
(1) Full up
(2) Between full up and center
(3) Center
(4) Between center and full down
(5) Full down
(9) Unknown

89. Telescoping Steering Column Adjustment 0
(0) No telescoping steering column
(1) Full back
(2) Between full back and midpoint
(3) Midpoint
(4) Between midpoint and full forward
(5) Full forward
(9) Unknown

90. Steering Rim/Spoke Deformation 0 0
____Code actual measured deformation to the nearest centimeter
(00) No steering rim deformation
(01-14) Actual measured value in centimeters
(15) 15 centimeters or more
(98) Observed deformation cannot be measured
(99) Unknown

91. Location of Steering Rim/Spoke Deformation 0 0
(00) No steering rim deformation

Quarter Sections
(01) Section A
(02) Section B
(03) Section C
(04) Section D



Half Sections
(05) Upper half of rim/spoke
(06) Lower half of rim/spoke
(07) Left half of rim/spoke
(08) Right half of rim/spoke

(09) Complete steering wheel collapse
(10) Undetermined location
(99) Unknown

INSTRUMENT PANEL

92. Odometer Reading 999,000
____ kilometers
Code to the nearest 1,000 kilometers
(000) No odometer
(001) Less than 1,500 kilometers
(500) 499,500 kilometers or more
(999) Unknown
___,___ miles X 1.6093 = ___,___ kilometers

Source: [redacted]

93. Instrument Panel Damage from Occupant Contact? 0
(0) No
(1) Yes
(9) Unknown

94. Type of Knee Bolster Covering 2
(0) No knee bolster
(1) Padded
(2) Rigid plastic
(8) Other (specify): _____
(9) Unknown

95. Knee Bolsters Deformed from Occupant Contact? 1
(0) No knee bolster
(1) No deformation
(2) Yes - deformation
(9) Unknown

96. Did Glove Compartment Door Open During Collision(s)? 0
(0) No glove compartment door
(1) No - door did not open
(2) Yes - door opened
(9) Unknown

97. Adaptive (Assistive) Driving Equipment 0
(0) No adaptive driving equipment
(1) Adaptive driving equipment installed (Check all that apply.)
[ ] Hand controls for braking/acceleration
[ ] Steering control devices (attached to OEM steering wheel
[ ] Steering knob attached to steering wheel
[ ] Low effort power steering (unit or device)
[ ] Replacement steering wheel (i.e., reduced diameter)
[ ] Joy-stick steering controls
[ ] Wheelchair tie-downs
[ ] Modification to seat belts (specify): _____
[ ] Additional or relocated switches (specify): _____
[ ] Raised roof
[ ] Wall-mounted head rest (used behind wheelchair)
[ ] Other adaptive device (specify): _____
(9) Unknown

VEHICLE INTERIOR SKETCHES

Note area of ejection/entrapment







NONE OBSERVED



Sketch windshield contact(s) and the damaged area(s) on the instrument panel outline (e.g., radio, glove compartment, damage to instrument panel structure.
Cross hatch contact points, draw spider webs or use other annotation as may be appropriate.
Annotate the contacted area with a letter (begin with A) and list on the Points of Occupant Contact page.

POINTS OF OCCUPANT CONTACT

Contact	Interior Component Contacted	Occupant No. If Known	Body Region If Known	Supporting Physical Evidence	Confidence Level of Contact Point
A					
B					
C					
D					
E					
F					
G					
H					
I					
J					
K					
L					
M					
N					

CODES FOR INTERIOR COMPONENTS

FRONT
(001) Windshield
(002) Mirror
(003) Sunvisor
(004) Steering wheel rim
(005) Steering wheel hub/spoke
(006) Steering wheel (combination of codes 004 and 005)
(007) Steering column,transmission selector lever, other attachment
(008) Cellular telephone or CB radio
(009) Add on equipment(e.g., tape deck, air conditioner)
(010) Left instrument panel and below
(011) Center instrument panel and below
(012) Right instrument panel and below
(013) Glove compartment door
(014) Knee bolster
(015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
(016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
(017) Windshield reinforced by exterior object, (specify): _____
(019) Other front object (specify): _____

LEFT SIDE
(051) Left side interior surface, excluding hardware or armrests
(052) Left side hardware or armrest
(053) Left A (A1/A2)-pillar
(054) Left B-pillar
(055) Other left pillar (specify): _____
(056) Left side window glass
(057) Left side window frame
(058) Left side window sill
(059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(060) Other left side object (specify): _____

RIGHT SIDE
(101) Right side interior surface, excluding hardware or armrests
(102) Right side hardware or armrest
(103) Right A (A1/A2)-pillar
(104) Right B-pillar
(105) Other right pillar (specify): _____
(106) Right side window glass
(107) Right side window frame
(108) Right side window sill
(109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(110) Other right side object (specify): _____

INTERIOR
(151) Seat, back support
(152) Belt restraint webbing/buckle
(153) Belt restraint B-pillar or door frame attachment point
(154) Other restraint system component (specify): _____
(155) Head restraint system
(160) Other occupants (specify): _____
(161) Interior loose objects
(162) Child safety seat (specify): _____
(163) Other interior object (specify): _____

AIR BAG
(170) Air bag-driver side
(175) Air bag compartment cover-driver side
(180) Air bag-passenger side
(185) Air bag compartment cover-passenger side
(190) Other air bag (specify) _____
(195) Other air bag compartment cover (specify) _____

ROOF
(201) Front header
(202) Rear header
(203) Roof left side rail
(204) Roof right side rail
(205) Roof or convertible top

FLOOR
(251) Floor (including toe pan)
(252) Floor or console mounted transmission lever, including console
(253) Parking brake handle
(254) Foot controls including parking brake

REAR
(301) Backlight (rear window)
(302) Backlight storage rack, door, etc.
(303) Other rear object (specify): _____

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT
(401) Hand controls for braking/acceleration
(402) Steering control devices (attached to OEM steering wheel)
(403) Steering knob attached to steering wheel
(405) Replacement steering wheel (i.e., reduced diameter)
(406) Joy stick steering controls
(407) Wheelchair tie-downs
(408) Modification to seat belts, (specify): _____
(409) Additional or relocated switches, (specify): _____
(410) Raised roof
(411) Wall mounted head rest (used behind wheel chair)
(412) Other adaptive device (specify): _____

CONFIDENCE LEVEL OF CONTACT POINT
(1) Certain
(2) Probable
(3) Possible
(9) Unknown

MANUAL RESTRAINTS

NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

If a Child safety seat is present, encode the data on the back of this page.

If the vehicle has automatic restraints available, encode the appropriate data on the back of the previous page.

		Left	Center	Right
FIRST	Availability	4	0	4
	Evidence of usage	04	00	04
	Used in this crash?	YES	0	YES
	Proper Use	1	0	1
	Failure Modes	1	0	1
	Anchorage Adjustment	1	0	1
SECOND	Availability			
	Evidence of usage			
	Used in this crash?			
	Proper Use			
	Failure Modes			
	Anchorage Adjustment			
OTHER	Availability			
	Evidence of usage			
	Used in this crash?			
	Proper Use			
	Failure Modes			
	Anchorage Adjustment			

Manual (Active) Belt System Availability

(0) None available
(1) Belt removed/destroyed
(2) Shoulder belt
(3) Lap belt
(4) Lap and shoulder belt
(5) Belt available - type unknown

Integral Belt Partially Destroyed

(6) Shoulder belt (lap belt destroyed/removed)
(7) Lap belt (shoulder belt destroyed/removed)
(8) Other belt (specify): _____
(9) Unknown

Manual (Active) Belt System Use

(00) None used, not available, or belt removed/destroyed
(01) Inoperable (specify): _____
(02) Shoulder belt
(03) Lap belt
(04) Lap and shoulder belt
(05) Belt used - type unknown
(08) Other belt used (specify): _____
(12) Shoulder belt used with child safety seat
(13) Lap belt used with child safety seat
(14) Lap and shoulder belt used with child safety seat
(15) Belt used with child safety seat - type unknown
(18) Other belt used with child safety seat (specify): _____
(99) Unknown if belt used

Proper Use of Manual (Active) Belts

(0) None used or not available
(1) Belt used properly
(2) Belt used properly with child safety seat

Belt Used Improperly

(3) Shoulder belt worn under arm
(4) Shoulder belt worn behind back or seat
(5) Belt worn around more than one person
(6) Lap belt worn on abdomen
(7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____
(8) Other improper use of manual belt system (specify): _____
(9) Unknown

Manual (Active) Belt Failure Modes During Accident

(0) No manual belt used or not available
(1) No manual belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify): _____
(6) Broken retractor
(7) Combination of above (specify): _____
(8) Other manual belt failure (specify): _____
(9) Unknown

Shoulder Belt Upper Anchorage Adjustment

(0) No shoulder belt
(1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage

(2) In full up position
(3) In mid position
(4) In full down position
(5) Position unknown
(9) Unknown if position has adjustable upper anchorage adjustment

AUTOMATIC RESTRAINTS

NOTES: Encode the data for each applicable front seat position. The attribute for the variables may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

AIR BAGS

		Left Front	Right Front	Other
FIRST	Availability/Function			
	Deployment			
	Failure			

Air Bag System Availability/Function
(0) Not equipped/not available
(1) Air bag

Non-functional
(2) Air bag disconnected (specify): _____
(3) Air bag not reinstalled
(9) Unknown

Are There Indications of Air Bag System Failure? (This Occupant Position)
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(9) Unknown

Frontal Air Bag System Deployment (This Occupant Position)
(0) Not equipped/not available
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, accident sequence undetermined
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

Air Bag(s) Deployment, *Other* Than First Seat Frontal (This Occupant Position)
(0) Not equipped with an *"other"* air bag
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, details unknown
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

AUTOMATIC BELTS

		Left	Right
FIRST	Availability/Function		
	Use		
	Type		
	Proper Use		
	Failure Modes		

Automatic (Passive) Belt System Availability/Function
(0) Not equipped/not available
(1) 2 point automatic belts
(2) 3 point automatic belts
(3) Automatic belts - type unknown

Non-functional
(4) Automatic belts destroyed or rendered inoperative
(9) Unknown

Automatic (Passive) Belt System Use
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Automatic belt in use
(2) Automatic belt not in use (manually disconnected, motorized track inoperative)
(3) Automatic belt use unknown
(9) Unknown

Automatic (Passive) Belt System Type
(0) Not equipped/not available
(1) Non-motorized system
(2) Motorized system
(9) Unknown

Proper Use of Automatic (Passive) Belt System
(0) Not equipped/not available/not used
(1) Automatic belt used properly
(2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly
(3) Automatic shoulder belt worn under arm
(4) Automatic shoulder belt worn behind back
(5) Automatic belt worn around more than one person
(6) Lap portion of automatic belt worn on abdomen
(7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____
(8) Other improper use of automatic belt system (specify): _____
(9) Unknown

Automatic (Passive) Belt Failure Modes During Accident
(0) Not equipped/not available/not in use
(1) No automatic belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify): _____
(6) Broken retractor
(7) Combination of above (specify):
(8) Other automatic belt failure (specify): _____
(9) Unknown

FIRST SEAT FRONTAL AIR BAGS

NOTES: Encode the applicable data ***for the driver and first seat passenger*** in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

	Driver	Passenger
Type of air bag?	1	
Flaps open at tear points?	2	
Flaps damaged?	1	
Air bag damaged?	01	
Source of air bag damage	01	
Air bag tethered?	2	
Air bag have vent ports?	2	
Other occupant contact air bag?	1	
Occupant wearing eyewear?	1	

Type of Air Bag
- (0) Not equipped/not available
- (1) Original manufacturer installed system
- (2) Retrofitted air bag
- (3) Replacement air bag
- (8) Unknown type of air bag
- (9) Unknown

Did Air Bag Module Cover Flap(s) Open At Designated Tear Points?
- (0) Not equipped/not available
- (1) No
- (2) Yes
- (3) Deployed, unknown if flap(s) opened at designated tear points
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Were Air Bag Module Cover Flap(s) Damaged?
- (0) Not equipped/not available
- (1) No
- (2) Yes (specify): _____
- (3) Deployed, unknown if air bag module cover flap(s) damaged
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Was There Damage To The Air Bag?
- (00) Not equipped/not available
- (01) Not damaged

Yes - Air Bag Damage
- (02) Ruptured
- (03) Cut
- (04) Torn
- (05) Holed
- (06) Burned
- (07) Abraded
- (88) Other damage (specify): _____
- (95) Damaged, details unknown
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

Source of Air Bag Damage
- (00) Not equipped/not available
- (01) Not damaged
- (02) Object worn by occupant, (specify): _____
- (03) Object carried by occupant, (specify): _____
- (04) Adaptive/assistive controls, (specify): _____
- (05) Fire in vehicle
- (06) Thermal burns
- (07) Rescue or emergency efforts
- (88) Other damage source (specify): _____
- (95) Damaged, unknown source
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

Was The Air Bag Tethered?
- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of tether straps): 2
- (3) Deployed, unknown if tethered
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Did The Air Bag Have Vent Ports?
- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of vent ports): 2
- (3) Deployed, unknown if vent ports present
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Was the Air Bag in this Occupant's Position Contacted by Another Occupant?
- (0) Not equipped/not available
- (1) No
- (2) Yes (specify): _____
- (3) Deployed, unknown if other occupant contact to air bag
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Was This Occupant Wearing Eye-wear?
- (0) Not equipped/not available
- (1) No
- (2) Eyeglasses/sunglasses
- (3) Contact lenses
- (4) Deployed, unknown if eyewear worn
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

DRIVER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Front)



2. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Back)



DRIVER AIR BAG SKETCHES (Cont'd)

3. DRIVER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

a. Upper Flap

width (W_U) 21

height (H_U) 13

b. Lower Flap

width (W_L) 21

height (H_L) 4



4. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

5. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

6. SKETCH LOCATION OF CIRCULAR AIR BAG VENT PORTS



PASSENGER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Front)



2. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Back)



PASSENGER AIR BAG SKETCHES (Cont'd)

3. PASSENGER AIR BAG MODULE COVER FLAP SIZE (SINGLE)

a. Flap

width (W) _____

height (H) _____



4. PASSENGER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

a. Upper Flap

width (W_U) _____

height (H_U) _____

b. Lower Flap

width (W_L) _____

height (H_L) _____



5. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

6. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

7. SKETCH LOCATION OF RECTANGULAR AIR BAG VENT PORTS



"OTHER" AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON *"OTHER"* AIR BAG (Front)

2. SKETCH DAMAGE AND CONTACT EVIDENCE ON *"OTHER"* AIR BAG (Back)

"OTHER" AIR BAG SKETCHES (Cont'd)

3. SKETCH AIR BAG MODULE FLAP AND SIZE OR OPENING FOR AIRBAG

4. SKETCH AIR BAG VENT PORTS

HEAD RESTRAINTS/SEAT EVALUATION

NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for these variables may be found at the bottom of the page. Head restraint type/damage and seat type/performance should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

		Left	Center	Right
FIRST	Head Restraint Type/Damage	1	0	1
	Seat Type	01	00	01
	Seat Performance	1	0	1
	Seat Orientation	1	0	1
	Seat Track Position	5	0	5
	Seat Back Incline Pre/Post Impact	23	0	23
SECOND	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
	Seat Track Position			
	Seat Back Incline Pre/Post Impact			
THIRD	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
	Seat Track Position			
	Seat Back Incline Pre/Post Impact			
OTHER	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
	Seat Track Position			
	Seat Back Incline Pre/Post Impact			

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE

(I.E., UNUSUAL OCCUPANT CONTACT PATTERN)

HEAD RESTRAINTS/SEAT EVALUATION

Head Restraint Type/Damage by Occupant at This Occupant Position
(0) No head restraints
(1) Integral — no damage
(2) Integral — damaged during accident
(3) Adjustable — no damage
(4) Adjustable — damaged during accident
(5) Add-on — no damage
(6) Add-on — damaged during accident
(8) Other
Specify):_____
(9) Unknown

Seat Type (this Occupant Position)
(00) Occupant not seated or no seat
(01) Bucket
(02) Bucket with folding back
(03) Bench
(04) Bench with separate back cushions
(05) Bench with folding back(s)
(06) Split bench with separate back cushions
(07) Split bench with folding back(s)
(08) Pedestal (i.e., column supported)
(09) Other seat type (specify):
_____
(10) Box mounted seat (i.e., van type)
(99) Unknown

Seat Performance (this Occupant Position)
(0) Occupant not seated or no seat
(1) No seat performance failure(s)
(2) Seat adjusters failed
(3) Seat back folding locks or "seat back" failed (specify):
_____
(4) Seat tracks/anchors failed
(5) Deformed by impact of occupant
(6) Deformed by passenger compartment intrusion (specify):_____
(7) Combination of above (specify):
_____
(8) Other (specify):
_____
(9) Unknown

Seat Orientation (this Occupant Position)
(0) Occupant not seated or no seat
(1) Forward facing seat
(2) Rear facing seat
(3) Side facing seat (inward)
(4) Side facing seat (outward)
(8) Other (specify):
_____
(9) Unknown

Seat Track Adjusted Position Prior To Impact
(0) Occupant not seated or no seat
(1) Non-adjustable seat track

Adjustable Seat Track
(2) Seat at forward most track position
(3) Seat between forward most and middle track positions
(4) Seat at middle track position
(5) Seat between middle and rear most track positions
(6) Seat at rear most track position
(9) Unknown

Seat Back Incline Prior and Post Impact
(00) Occupant not seated or no seat
(01) Not adjustable

Upright prior to impact
(11) Moved to completely rearward position
(12) Moved to rearward midrange position
(13) Moved to slightly rearward position
(14) Retained pre-impact position
(15) Moved to slightly forward position
(16) Moved to forward midrange position
(17) Moved to completely forward position

Slightly reclined prior to impact
(21) Moved to completely rearward position
(22) Moved to rearward midrange position
(23) Retained pre-impact postion
(24) Moved to upright position
(25) Moved to slightly forward position
(26) Moved to forward midrange position
(27) Moved to completely forward position

Completely reclined prior to impact
(31) Retained pre-impact position
(32) Moved to rearward midrange position
(33) Moved to slightly rearward position
(34) Moved to upright position
(35) Moved to slightly forward position
(36) Moved to forward midrange position
(37) Moved to completely forward position

(99) Unknown



Coding diagrams for *Seat Back Incline Position Prior and Post Impact*

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE (I.E., UNUSUAL OCCUPANT CONTACT PATTERN)

CHILD SAFETY SEAT FIELD ASSESSMENT

When a child safety seat is present enter the occupant's number in the first row and complete the column below the occupant's number using the codes listed below. Complete a column for each child safety seat present.

Occupant Number						
1. Type of Child Safety Seat						
2. Child Safety Seat Orientation						
3. Child Safety Seat Harness Usage						
4. Child Safety Seat Shield Usage						
5. Child Safety Seat Tether Usage						
6. Child Safety Seat Make/Model	Specify Below for Each Child Safety Seat					

1. Type of Child Safety Seat

   (0) No child safety seat
   (1) Infant seat
   (2) Toddler seat
   (3) Convertible seat
   (4) Booster seat
   (7) Other type child safety seat (specify):

   _____

   (8) Unknown child safety seat type
   (9) Unknown if child safety seat used

2. Child Safety Seat Orientation

   (00) No child safety seat

   Designed for Rear Facing for This Age/Weight
   (01) Rear facing
   (02) Forward facing
   (08) Other orientation (specify):

   _____

   (09) Unknown orientation

   Designed for Forward Facing for This Age/Weight
   (11) Rear facing
   (12) Forward facing
   (18) Other orientation (specify):

   _____

   (19) Unknown orientation

   Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
   (21) Rear facing
   (22) Forward facing
   (28) Other orientation (specify):

   _____

   (29) Unknown orientation

   (99) Unknown if child safety seat used

3. Child Safety Seat Harness Usage

4. Child Safety Seat Shield Usage

5. Child Safety Seat Tether Usage
   Note: Options Below Are Used for Variables 3-5.

   (00) No child safety seat

   Not Designed with Harness/Shield/Tether
   (01) After market harness/shield/tether added, not used
   (02) After market harness/shield/tether used
   (03) Child safety seat used, but no after market harness/shield/tether added
   (09) Unknown if harness/shield/tether added or used

   Designed With Harness/Shield/Tether
   (11) Harness/shield/tether not used
   (12) Harness/shield/tether used
   (19) Unknown if harness/shield/tether used

   Unknown If Designed With Harness/Shield/Tether
   (21) Harness/shield/tether not used
   (22) Harness/shield/tether used
   (29) Unknown if harness/shield/tether used

   (99) Unknown if child safety seat used

6. Child Safety Seat Make/Model
   (Specify make/model and occupant number)

   _____

   _____

   _____

   _____

EJECTION/ENTRAPMENT DATA

Complete the following if the researcher has any indication that an occupant was either ejected from or entrapped in the vehicle. Code the appropriate data on the Occupant Assessment Form.

EJECTION No [ ] Yes [ ]

Describe indications of ejection and body parts involved in partial ejection(s):

Occupant Number						
Ejection						
(Note on Vehicle Interior Sketch) Ejection Area						
Ejection Medium						
Medium Status						

Ejection
(1) Complete ejection
(2) Partial ejection
(3) Ejection, Unknown degree
(9) Unknown

Ejection Area
(1) Windshield
(2) Left front
(3) Right front
(4) Left rear
(5) Right rear
(6) Rear
(7) Roof
(8) Other area (e.g., back of pickup, etc.) (specify): _____
(9) Unknown

Ejection Medium
(1) Door/hatch/tailgate
(2) Nonfixed roof structure
(3) Fixed glazing
(4) Nonfixed glazing (specify): _____
(5) Integral structure
(8) Other medium (specify): _____
(9) Unknown

Medium Status (Immediately Prior to Impact)
(1) Open
(2) Closed
(3) Integral structure
(9) Unknown

ENTRAPMENT No [ ] Yes [ ]

Describe entrapment mechanism: _____

Component(s): _____

(Note in vehicle interior diagram)

U.S. Department of Transportation
National Highway Traffic Safety Administration

OCCUPANT ASSESSMENT FORM

Form Approved
O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 49
2. Case Number - Stratum: 120A
3. Vehicle Number: 02
4. Occupant Number: 01

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age: 18
Code actual age at time of accident.
(00) Less than one year old (specify by month): _____
(97) 97 years and older
(99) Unknown

6. Occupant's Sex: 1
(1) Male
(2) Female-not reported pregnant
(3) Female-pregnant-1st trimester(1st-3rd month)
(4) Female-pregnant-2nd trimester(4th-6th month)
(5) Female-pregnant-3rd trimester(7th-9th month)
(6) Female-pregnant-term unknown
(9) Unknown

7. Occupant's Height: 178
Code actual height to the nearest centimeter.
(999) Unknown

70 inches X 2.54 = 177.8 centimeters

8. Occupant's Weight: 082
Code actual weight to the nearest kilogram.
(999)Unknown

180 pounds X .4536 = 81.6 kilograms

9. Occupant's Role: 1
(1) Driver
(2) Passenger
(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position: 11
Front Seat
(11) Left side
(12) Middle
(13) Right side
(14) Other (specify): _____
(15) On or in the lap of another occupant

Second Seat
(21) Left side
(22) Middle
(23) Right side
(24) Other (specify): _____
(25) On or in the lap of another occupant

Third Seat
(31) Left side
(32) Middle
(33) Right side
(34) Other (specify): _____
(35) On or in the lap of another occupant

Fourth Seat
(41) Left side
(42) Middle
(43) Right side
(44) Other (specify): _____
(45) On or in the lap of another occupant

(97) In or on unenclosed area
(98) Other seat (specify): _____
(99) Unknown

11. Occupant's Posture: 0
(0) Normal posture

Abnormal posture
(1) Kneeling or standing on seat
(2) Lying on or across seat
(3) Kneeling, standing or sitting in front of seat
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window
(5) Sitting on a console
(6) Lying back in a reclined seat position
(7) Bracing with feet or hands on a surface in front of seat
(8) Other abnormal posture (specify): _____
(9) Unknown

EJECTION/ENTRAPMENT

12. Ejection 0
    (0) No ejection
    (1) Complete ejection
    (2) Partial ejection
    (3) Ejection, unknown degree
    (9) Unknown

13. Ejection Area 0
    (0) No ejection
    (1) Windshield
    (2) Left front
    (3) Right front
    (4) Left rear
    (5) Right rear
    (6) Rear
    (7) Roof
    (8) Other area (e.g., back of pickup, etc.)
    (specify):_____
    (9) Unknown

14. Ejection Medium 0
    (0) No ejection
    (1) Door/hatch/tailgate
    (2) Nonfixed roof structure
    (3) Fixed glazing
    (4) Nonfixed glazing (specify):
    _____
    (5) Integral structure
    (8) Other medium (specify):
    _____
    (9) Unknown

15. Medium Status (Immediately Prior To Impact) 0
    (0) No ejection
    (1) Open
    (2) Closed
    (3) Integral structure
    (9) Unknown

16. Entrapment 0
    (0) Not entrapped/exit not inhibited
    (1) Entrapped/pinned - mechanically restrained
    (2) Could not exit vehicle due to jammed doors, fire, etc.
    (specify):_____
    _____
    (9) Unknown

17. Occupant Mobility 4
    (0) Occupant fatal before removed from vehicle
    (1) Removed from vehicle while unconscious or disoriented
    (2) Removed from vehicle due to injuries
    (3) Exited vehicle with some assistance
    (4) Exited vehicle under own power
    (5) Occupant fully ejected
    (9) Unknown

BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 4
(0) None available
(1) Belt removed/destroyed
(2) Shoulder belt
(3) Lap belt
(4) Lap and shoulder belt
(5) Belt available—type unknown

Integral Belt Partially Destroyed
(6) Shoulder belt (lap belt destroyed/removed)
(7) Lap belt (shoulder belt destroyed/removed)
(8) Other belt (specify): _____
(9) Unknown

19. Manual (Active) Belt System Use 04
(00) None used, not available, or belt removed/destroyed
(01) Inoperative (specify): _____
(02) Shoulder belt
(03) Lap belt
(04) Lap and shoulder belt
(05) Belt used—type unknown
(08) Other belt used (specify): _____
(12) Shoulder belt used with child safety seat
(13) Lap belt used with child safety seat
(14) Lap and shoulder belt used with child safety seat
(15) Belt used with child safety seat—type unknown
(18) Other belt used with child safety seat (specify): _____
(99) Unknown if belt used

20. Proper Use of Manual (Active) Belts 1
(0) None used or not available
(1) Belt used properly
(2) Belt used properly with child safety seat

Belt Used Improperly
(3) Shoulder belt worn under arm
(4) Shoulder belt worn behind back or seat
(5) Belt worn around more than one person
(6) Lap belt worn on abdomen
(7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____
(8) Other improper use of manual belt system (specify): _____
(9) Unknown

21. Manual (Active) Belt Failure Modes During Accident 1
(0) No manual belt used or not available
(1) No manual belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify): _____
(6) Broken retractor
(7) Combination of above (specify): _____
(8) Other manual belt failure (specify): _____
(9) Unknown

22. Shoulder Belt Upper Anchorage Adjustment 1
(0) No shoulder belt
(1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage
(2) In full up position
(3) In mid position
(4) In full down position
(5) Position unknown
(9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/ Function 0
(0) Not equipped/not available
(1) 2 point automatic belts
(2) 3 point automatic belts
(3) Automatic belts - type unknown

Non-functional
(4) Automatic belts destroyed or rendered inoperative
(9) Unknown

24. Automatic (Passive) Belt System Use 0
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Automatic belt in use
(2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): _____
(3) Automatic belt use unknown
(9) Unknown

25. Automatic (Passive) Belt System Type 0
(0) Not equipped/not available
(1) Non-motorized system
(2) Motorized system
(9) Unknown

26. Proper Use of Automatic (Passive) Belt System 0
(0) Not equipped/not available/not used
(1) Automatic belt used properly
(2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly
(3) Automatic shoulder belt worn under arm
(4) Automatic shoulder belt worn behind back
(5) Automatic belt worn around more than one person
(6) Lap portion of automatic belt worn on abdomen
(7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____
(8) Other improper use of automatic belt system (specify): _____
(9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident 0
(0) Not equipped/not available/not in use
(1) No automatic belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify): _____
(6) Broken retractor
(7) Combination of above (specify):
(8) Other automatic belt failure (specify): _____
(9) Unknown

POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use 4
    (0) None used
    (1) Police did not indicate belt use
    (2) Shoulder belt
    (3) Lap belt
    (4) Lap and shoulder belt
    (5) Belt used, type not specified
    (6) Child safety seat
    (7) Automatic belt
    (8) Other type belt, (specify): _____
    (9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 1
    (0) No air bag available
    (1) Police did not indicate air bag availability/function
    (2) Deployed
    (3) Not deployed
    (4) Unknown if deployed
    (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

[ ] Not equipped/not available/destroyed or rendered inoperative
1 [✓] Vehicle inspection
[ ] Official injury data
2 [✓] Driver/occupant interview
[ ] Other (specify): _____
[ ] Unknown if belt used

AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System Availability/Function (This Occupant Position) 1
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

31. Frontal Air Bag System Deployment (This Occupant Position) 1
    (0) Not equipped/not available
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

32. Other Than First Seat Frontal Air Bag Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

    Specify type of "other" air bag present: _____

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) 0
    (0) Not equipped with an "other" air bag
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

34. Are There Indications of Air Bag System Failure? (This Occupant Position) 1
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify): _____
    (9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? 1
(0) Not equipped/not available
(1) No previous accidents

Yes
(2) Previous accident(s) without deployment(s)
(3) One previous accident with deployment
(4) More than one previous accident with at least one deployment
(8) Previous accidents, unknown deployment status
(9) Unknown

36. Type of Air Bag 1
(0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? 1
(0) Not equipped/not available
(1) No prior maintenance
(2) Yes, prior maintenance (specify):
_____
(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number 01
(00) Not equipped/not available
____ Code the accident event sequence number that initiated the air bag deployment
(96) Deployed, unknown event
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

39. CDC For Air Bag Deployment Impact 1
(0) Not equipped/not available
(1) Highest delta V
(2) Second highest delta V
(3) Other non-coded delta V (specify):
_____
(6) Deployed, unknown event
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact ~~+996~~ ~~-017~~ -027
(_000) Not equipped/not available
Code the value of the delta V for the impact that initiated the air bag deployment
(_996) Deployment, unknown longitudinal Delta V
(_997) Not deployed
(_998) Unknown if deployed
(_999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? 2
(0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? 1
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

43. Was There Damage To The Air Bag? 01
(00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage
(02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify):
_____
(95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION *continued*

44. Source of Air Bag Damage 01
(00) Not equipped/not available
(01) Not damaged
(02) Object worn by occupant, (specify):
(03) Object carried by occupant, (specify):
(04) Adaptive/assistive controls, (specify):
(05) Fire in vehicle
(06) Thermal burns
(07) Rescue or emergency efforts
(88) Other damage source (specify):
(95) Damaged, unknown source
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

45. Was The Air Bag Tethered? 2
(0) Not equipped/not available
(1) No
(2) Yes (specify number of tether straps): 2
(3) Deployed, unknown if tethered
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

46. Did The Air Bag Have Vent Ports? 2
(0) Not equipped/not available
(1) No
(2) Yes (specify number of vent ports): 2
(3) Deployed, unknown if vent ports present
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? 1
(0) Not equipped/not available
(1) No
(2) Yes (specify):
(3) Deployed, unknown if other occupant contact to air bag
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

48. Was This Occupant Wearing Eye-wear? 1
(0) Not equipped/not available
(1) No
(2) Eyeglasses/sunglasses
(3) Contact lenses
(4) Deployed, unknown if eyewear worn
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION

49. Head Restraint Type/Damage by Occupant at This Occupant Position 1
(0) No head restraints
(1) Integral—no damage
(2) Integral—damaged during accident
(3) Adjustable—no damage
(4) Adjustable—damaged during accident
(5) Add-on—no damage
(6) Add-on—damaged during accident
(8) Other (specify):
(9) Unknown

50. Seat Type (this Occupant Position) 01
(00) Occupant not seated or no seat
(01) Bucket
(02) Bucket with folding back
(03) Bench
(04) Bench with separate back cushions
(05) Bench with folding back(s)
(06) Split bench with separate back cushions
(07) Split bench with folding back(s)
(08) Pedestal (i.e., column supported)
(09) Box mounted seat (i.e., van type)
(10) Other seat type (specify):
(99) Unknown

51. Seat Orientation (this Occupant Position) 1
(0) Occupant not seated or no seat
(1) Forward facing seat
(2) Rear facing seat
(3) Side facing seat (inward)
(4) Side facing seat (outward)
(8) Other (specify):
(9) Unknown

52. Seat Track Adjusted Position Prior To Impact 5
(0) Occupant not seated or no seat
(1) Non-adjustable seat track

Adjustable Seat Track
(2) Seat at forward most track position
(3) Seat between forward most and middle track positions
(4) Seat at middle track position
(5) Seat between middle and rear most track positions
(6) Seat at rear most track position
(9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*

53. Seat Back Incline Prior and Post Impact 23
(00) Occupant not seated or no seat
(01) Not adjustable

Upright prior to impact
(11) Moved to completely rearward position
(12) Moved to rearward midrange position
(13) Moved to slightly rearward position
(14) Retained pre-impact position
(15) Moved to slightly forward position
(16) Moved to forward midrange position
(17) Moved to completely forward position

Slightly reclined prior to impact
(21) Moved to completely rearward position
(22) Moved to rearward midrange position
(23) Retained pre-impact position
(24) Moved to upright position
(25) Moved to slightly forward position
(26) Moved to forward midrange position
(27) Moved to completely forward position

Completely reclined prior to impact
(31) Retained pre-impact position
(32) Moved to rearward midrange position
(33) Moved to slightly rearward position
(34) Moved to upright position
(35) Moved to slightly forward position
(36) Moved to forward midrange position
(37) Moved to completely forward position

(99) Unknown







54. Seat Performance (this Occupant Position) 1
(0) Occupant not seated or no seat
(1) No seat performance failure(s)
(2) Seat adjusters failed
(3) Seat back folding locks or "seat back" failed (specify):_____
(4) Seat track/anchors failed
(5) Deformed by impact of occupant
(6) Deformed by passenger compartment intrusion, (specify):_____
_____
(7) Combination of above (specify):
_____
(8) Other (specify): _____
(9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model 0 0 0
(000) No child safety seat
Applicable codes are found in your NASS CDS Data Collection, Coding and Editing
(950) Built-in child safety seat
(997) Other make/model (specify):
_____
(998) Unknown make/model
(999) Unknown if child safety seat used

56. Type of Child Safety Seat 0
(0) No child safety seat
(1) Infant seat
(2) Toddler seat
(3) Convertible seat
(4) Booster seat - with shield
(5) Booster seat - without shield
(7) Other type child safety seat (specify):
_____
(8) Unknown child safety seat type
(9) Unknown if child safety seat used

57. Child Safety Seat Orientation 0 0
(00) No child safety seat

Designed for Rear Facing for This Age/Weight
(01) Rear facing
(02) Forward facing
(08) Other orientation (specify):
_____
(09) Unknown orientation

Designed For Forward Facing for This Age/Weight
(11) Rear facing
(12) Forward facing
(18) Other orientation (specify):
_____
(19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
(21) Rear facing
(22) Forward facing
(28) Other orientation (specify):
_____
(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage 0 0

59. Child Safety Seat Shield Usage 0 0

60. Child Safety Seat Tether Usage 0 0

Note: Options below applicable to Variables OA58-OA60.
(00) No child safety seat

Not Designed With Harness/Shield/Tether
(01) After market harness/shield/tether added, not used
(02) After market harness/shield/tether used
(03) Child safety seat used, but no after market harness/shield/tether added
(09) Unknown if harness/shield/tether added or used

Designed With Harness/Shield/Tether
(11) Harness/shield/tether not used
(12) Harness/shield/tether used
(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether
(21) Harness/shield/tether not used
(22) Harness/shield/tether used
(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES

61. Injury Severity (Police Rating) 0

(0) O - No injury
(1) C - Possible injury
(2) B - Nonincapacitating injury
(3) A - Incapacitating injury
(4) K - Killed
(5) U - Injury, severity unknown
(6) Died prior to accident
(9) Unknown

62. Treatment - Mortality 0

(0) No treatment
(1) Fatal
(2) Fatal - ruled disease (specify):

_____

Nonfatal
(3) Hospitalization
(4) Transported and released
(5) Treatment at scene - nontransported
(6) Treatment later
(7) Treatment - other (specify):

_____

(8) Transported to a medical facility-unknown if treated
(9) Unknown

63. Type Of Medical Facility (for Initial Treatment) 0

(0) Not treated at a medical facility
(1) Trauma center
(2) Hospital
(3) Medical clinic
(4) Physician's office
(5) Treatment later at medical facility
(8) Other (specify):

_____

(9) Unknown

64. Hospital Stay 0 0

(00) Not Hospitalized
____Code the number of days (up through 60) that the occupant stayed in hospital.
(61) 61 days or more
(99) Unknown

65. Working Days Lost 0 0

____Code the number of days (up through 60) that the occupant lost from work due to the accident
(00) No working days lost
(61) 61 days or more
(62) Fatally injured
(97) Not working prior to accident
(99) Unknown

STOP WORK HERE

VARIABLES 66-74

TO BE CODED BY THE ZONE CENTER

TO BE CODED BY THE ZONE CENTER

INJURY CONSEQUENCES

66. Time to Death — 00
____Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 +n up through 30 days = 60)
(00) Not fatal
(96) Fatal - ruled disease
(99) Unknown

67. 1st Medically Reported Cause of Death — 00

68. 2nd Medically Reported Cause of Death — 00

69. 3rd Medically Reported Cause of Death — 00
____Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death
(00) Not fatal or no additional causes
(96) Mode of death given but specific injuries are not linked to cause of death. (specify):
_____
(97) Other result (includes fatal ruled disease) (specify):
_____
(99) Unknown

70. Number of Recorded Injuries for This Occupant — 00
____Code the actual number of injuries recorded for this occupant.
(00) No recorded injuries
(97) Injured, details unknown
(99) Unknown if injured

TRAUMA DATA

71. Glasgow Coma Scale (GCS) Score (at Medical Facility) — 00
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured

72. Was the Occupant Given Blood? — 1
(1) No - blood not given
(2) Yes - blood given
(specify units):_____
(9) Unknown if blood given

73. Arterial Blood Gases (ABG) – HCO_3 — 00
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported , HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

74. Primary Source of Belt Use Determination — 1
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify):_____
(9) Unknown if belt used

PSU NUMBER 49

CASE NUMBER 120A

VEHICLE NUMBER 02

OCCUPANT NUMBER 01

OCCUPANT INJURY FORM

THE FOLLOWING DATA IS NOT INCLUDED IN THIS CASE:

[✓] ENTIRE FORM

[ ] PAGE NUMBER (S) _____

U.S. Department of Transportation
National Highway Traffic Safety Administration

OCCUPANT ASSESSMENT FORM

Form Approved
O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 49
2. Case Number - Stratum: 120A
3. Vehicle Number: 02
4. Occupant Number: 02

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age: 29
Code actual age at time of accident.
(00) Less than one year old (specify by month): _____
(97) 97 years and older
(99) Unknown

6. Occupant's Sex: 1
(1) Male
(2) Female-not reported pregnant
(3) Female-pregnant-1st trimester(1st-3rd month)
(4) Female-pregnant-2nd trimester(4th-6th month)
(5) Female-pregnant-3rd trimester(7th-9th month)
(6) Female-pregnant-term unknown
(9) Unknown

7. Occupant's Height: 183
Code actual height to the nearest centimeter.
(999) Unknown

72 inches X 2.54 = 182.8 centimeters

8. Occupant's Weight: 073
Code actual weight to the nearest kilogram.
(999)Unknown

160 pounds X .4536 = 72.5 kilograms

9. Occupant's Role: 2
(1) Driver
(2) Passenger
(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position: 13
Front Seat
(11) Left side
(12) Middle
(13) Right side
(14) Other (specify): _____
(15) On or in the lap of another occupant

Second Seat
(21) Left side
(22) Middle
(23) Right side
(24) Other (specify): _____
(25) On or in the lap of another occupant

Third Seat
(31) Left side
(32) Middle
(33) Right side
(34) Other (specify): _____
(35) On or in the lap of another occupant

Fourth Seat
(41) Left side
(42) Middle
(43) Right side
(44) Other (specify): _____
(45) On or in the lap of another occupant

(97) In or on unenclosed area
(98) Other seat (specify): _____
(99) Unknown

11. Occupant's Posture: 0
(0) Normal posture

Abnormal posture
(1) Kneeling or standing on seat
(2) Lying on or across seat
(3) Kneeling, standing or sitting in front of seat
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window
(5) Sitting on a console
(6) Lying back in a reclined seat position
(7) Bracing with feet or hands on a surface in front of seat
(8) Other abnormal posture (specify): _____
(9) Unknown

EJECTION/ENTRAPMENT

12. Ejection 0
    (0) No ejection
    (1) Complete ejection
    (2) Partial ejection
    (3) Ejection, unknown degree
    (9) Unknown

13. Ejection Area 0
    (0) No ejection
    (1) Windshield
    (2) Left front
    (3) Right front
    (4) Left rear
    (5) Right rear
    (6) Rear
    (7) Roof
    (8) Other area (e.g., back of pickup, etc.)
    (specify):_____
    (9) Unknown

14. Ejection Medium 0
    (0) No ejection
    (1) Door/hatch/tailgate
    (2) Nonfixed roof structure
    (3) Fixed glazing
    (4) Nonfixed glazing (specify):
    _____
    (5) Integral structure
    (8) Other medium (specify):
    _____
    (9) Unknown

15. Medium Status (Immediately Prior To Impact) 0
    (0) No ejection
    (1) Open
    (2) Closed
    (3) Integral structure
    (9) Unknown

16. Entrapment 0
    (0) Not entrapped/exit not inhibited
    (1) Entrapped/pinned - mechanically restrained
    (2) Could not exit vehicle due to jammed doors, fire, etc.
    (specify):_____
    _____
    (9) Unknown

17. Occupant Mobility 4
    (0) Occupant fatal before removed from vehicle
    (1) Removed from vehicle while unconscious or disoriented
    (2) Removed from vehicle due to injuries
    (3) Exited vehicle with some assistance
    (4) Exited vehicle under own power
    (5) Occupant fully ejected
    (9) Unknown

BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 4
(0) None available
(1) Belt removed/destroyed
(2) Shoulder belt
(3) Lap belt
(4) Lap and shoulder belt
(5) Belt available—type unknown

Integral Belt Partially Destroyed
(6) Shoulder belt (lap belt destroyed/removed)
(7) Lap belt (shoulder belt destroyed/removed)
(8) Other belt (specify):

(9) Unknown

19. Manual (Active) Belt System Use 04
(00) None used, not available, or belt removed/destroyed
(01) Inoperative (specify):

(02) Shoulder belt
(03) Lap belt
(04) Lap and shoulder belt
(05) Belt used—type unknown
(08) Other belt used (specify):

(12) Shoulder belt used with child safety seat
(13) Lap belt used with child safety seat
(14) Lap and shoulder belt used with child safety seat
(15) Belt used with child safety seat—type unknown
(18) Other belt used with child safety seat (specify):
(99) Unknown if belt used

20. Proper Use of Manual (Active) Belts 1
(0) None used or not available
(1) Belt used properly
(2) Belt used properly with child safety seat

Belt Used Improperly
(3) Shoulder belt worn under arm
(4) Shoulder belt worn behind back or seat
(5) Belt worn around more than one person
(6) Lap belt worn on abdomen
(7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of manual belt system (specify):

(9) Unknown

21. Manual (Active) Belt Failure Modes During Accident 1
(0) No manual belt used or not available
(1) No manual belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify):

(6) Broken retractor
(7) Combination of above (specify):

(8) Other manual belt failure (specify):

(9) Unknown

22. Shoulder Belt Upper Anchorage Adjustment 1
(0) No shoulder belt
(1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage
(2) In full up position
(3) In mid position
(4) In full down position
(5) Position unknown
(9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/ Function 0
(0) Not equipped/not available
(1) 2 point automatic belts
(2) 3 point automatic belts
(3) Automatic belts - type unknown

Non-functional
(4) Automatic belts destroyed or rendered inoperative
(9) Unknown

24. Automatic (Passive) Belt System Use 0
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Automatic belt in use
(2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify):
(3) Automatic belt use unknown
(9) Unknown

25. Automatic (Passive) Belt System Type 0
(0) Not equipped/not available
(1) Non-motorized system
(2) Motorized system
(9) Unknown

26. Proper Use of Automatic (Passive) Belt System 0
(0) Not equipped/not available/not used
(1) Automatic belt used properly
(2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly
(3) Automatic shoulder belt worn under arm
(4) Automatic shoulder belt worn behind back
(5) Automatic belt worn around more than one person
(6) Lap portion of automatic belt worn on abdomen
(7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of automatic belt system (specify):
(9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident 0
(0) Not equipped/not available/not in use
(1) No automatic belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify):

(6) Broken retractor
(7) Combination of above (specify):
(8) Other automatic belt failure (specify):

(9) Unknown

POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use 4
    (0) None used
    (1) Police did not indicate belt use
    (2) Shoulder belt
    (3) Lap belt
    (4) Lap and shoulder belt
    (5) Belt used, type not specified
    (6) Child safety seat
    (7) Automatic belt
    (8) Other type belt, (specify): _____
    (9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 0
    (0) No air bag available
    (1) Police did not indicate air bag availability/function
    (2) Deployed
    (3) Not deployed
    (4) Unknown if deployed
    (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

[ ] Not equipped/not available/destroyed or rendered inoperative
1 [✓] Vehicle inspection
[ ] Official injury data
2 [✓] Driver/occupant interview
[ ] Other (specify): _____
[ ] Unknown if belt used

AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

31. Frontal Air Bag System Deployment (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

32. Other Than First Seat Frontal Air Bag Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

    Specify type of "other" air bag present: _____

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) 0
    (0) Not equipped with an "other" air bag
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

34. Are There Indications of Air Bag System Failure? (This Occupant Position) 0
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify): _____
    (9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? 0
(0) Not equipped/not available
(1) No previous accidents

Yes
(2) Previous accident(s) without deployment(s)
(3) One previous accident with deployment
(4) More than one previous accident with at least one deployment
(8) Previous accidents, unknown deployment status
(9) Unknown

36. Type of Air Bag 0
(0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? 0
(0) Not equipped/not available
(1) No prior maintenance
(2) Yes, prior maintenance (specify): _____
(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number 00
(00) Not equipped/not available
_____ Code the accident event sequence number that initiated the air bag deployment
(96) Deployed, unknown event
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

39. CDC For Air Bag Deployment Impact 0
(0) Not equipped/not available
(1) Highest delta V
(2) Second highest delta V
(3) Other non-coded delta V (specify): _____
(6) Deployed, unknown event
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact ≠0000
(_000) Not equipped/not available
Code the value of the delta V for the impact that initiated the air bag deployment
(_996) Deployment, unknown longitudinal Delta V
(_997) Not deployed
(_998) Unknown if deployed
(_999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? 0
(0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

43. Was There Damage To The Air Bag? 00
(00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage
(02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify): _____
(95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION *continued*

44. Source of Air Bag Damage 0 0
(00) Not equipped/not available
(01) Not damaged
(02) Object worn by occupant, (specify):
_____
(03) Object carried by occupant, (specify):
_____
(04) Adaptive/assistive controls, (specify):
_____
(05) Fire in vehicle
(06) Thermal burns
(07) Rescue or emergency efforts
(88) Other damage source (specify):
_____
(95) Damaged, unknown source
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

45. Was The Air Bag Tethered? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify number of tether straps):
_____
(3) Deployed, unknown if tethered
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

46. Did The Air Bag Have Vent Ports? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify number of vent ports):
_____
(3) Deployed, unknown if vent ports present
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify):
_____
(3) Deployed, unknown if other occupant contact to air bag
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

48. Was This Occupant Wearing Eye-wear? 0
(0) Not equipped/not available
(1) No
(2) Eyeglasses/sunglasses
(3) Contact lenses
(4) Deployed, unknown if eyewear worn
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION

49. Head Restraint Type/Damage by Occupant at This Occupant Position 1
(0) No head restraints
(1) Integral—no damage
(2) Integral—damaged during accident
(3) Adjustable—no damage
(4) Adjustable—damaged during accident
(5) Add-on—no damage
(6) Add-on—damaged during accident
(8) Other (specify):
_____
(9) Unknown

50. Seat Type (this Occupant Position) 0 1
(00) Occupant not seated or no seat
(01) Bucket
(02) Bucket with folding back
(03) Bench
(04) Bench with separate back cushions
(05) Bench with folding back(s)
(06) Split bench with separate back cushions
(07) Split bench with folding back(s)
(08) Pedestal (i.e., column supported)
(09) Box mounted seat (i.e., van type)
(10) Other seat type (specify):
_____
(99) Unknown

51. Seat Orientation (this Occupant Position) 1
(0) Occupant not seated or no seat
(1) Forward facing seat
(2) Rear facing seat
(3) Side facing seat (inward)
(4) Side facing seat (outward)
(8) Other (specify):
_____
(9) Unknown

52. Seat Track Adjusted Position Prior To Impact 5
(0) Occupant not seated or no seat
(1) Non-adjustable seat track

Adjustable Seat Track
(2) Seat at forward most track position
(3) Seat between forward most and middle track positions
(4) Seat at middle track position
(5) Seat between middle and rear most track positions
(6) Seat at rear most track position
(9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*

53. Seat Back Incline Prior and Post Impact 23
    (00) Occupant not seated or no seat
    (01) Not adjustable

    Upright prior to impact
    (11) Moved to completely rearward position
    (12) Moved to rearward midrange position
    (13) Moved to slightly rearward position
    (14) Retained pre-impact position
    (15) Moved to slightly forward position
    (16) Moved to forward midrange position
    (17) Moved to completely forward position

    Slightly reclined prior to impact
    (21) Moved to completely rearward position
    (22) Moved to rearward midrange position
    (23) Retained pre-impact position
    (24) Moved to upright position
    (25) Moved to slightly forward position
    (26) Moved to forward midrange position
    (27) Moved to completely forward position

    Completely reclined prior to impact
    (31) Retained pre-impact position
    (32) Moved to rearward midrange position
    (33) Moved to slightly rearward position
    (34) Moved to upright position
    (35) Moved to slightly forward position
    (36) Moved to forward midrange position
    (37) Moved to completely forward position

    (99) Unknown







54. Seat Performance (this Occupant Position) 1
    (0) Occupant not seated or no seat
    (1) No seat performance failure(s)
    (2) Seat adjusters failed
    (3) Seat back folding locks or "seat back" failed (specify):_____
    (4) Seat track/anchors failed
    (5) Deformed by impact of occupant
    (6) Deformed by passenger compartment intrusion, (specify):_____
    _____
    (7) Combination of above (specify):
    _____
    (8) Other (specify): _____
    (9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model 0 0 0
(000) No child safety seat
Applicable codes are found in your NASS CDS Data Collection, Coding and Editing
(950) Built-in child safety seat
(997) Other make/model (specify):
_____
(998) Unknown make/model
(999) Unknown if child safety seat used

56. Type of Child Safety Seat 0
(0) No child safety seat
(1) Infant seat
(2) Toddler seat
(3) Convertible seat
(4) Booster seat - with shield
(5) Booster seat - without shield
(7) Other type child safety seat (specify):
_____
(8) Unknown child safety seat type
(9) Unknown if child safety seat used

57. Child Safety Seat Orientation 0 0
(00) No child safety seat

Designed for Rear Facing for This Age/Weight
(01) Rear facing
(02) Forward facing
(08) Other orientation (specify):
_____
(09) Unknown orientation

Designed For Forward Facing for This Age/Weight
(11) Rear facing
(12) Forward facing
(18) Other orientation (specify):
_____
(19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
(21) Rear facing
(22) Forward facing
(28) Other orientation (specify):
_____
(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage 0 0

59. Child Safety Seat Shield Usage 0 0

60. Child Safety Seat Tether Usage 0 0

Note: Options below applicable to Variables OA58-OA60.
(00) No child safety seat

Not Designed With Harness/Shield/Tether
(01) After market harness/shield/tether added, not used
(02) After market harness/shield/tether used
(03) Child safety seat used, but no after market harness/shield/tether added
(09) Unknown if harness/shield/tether added or used

Designed With Harness/Shield/Tether
(11) Harness/shield/tether not used
(12) Harness/shield/tether used
(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether
(21) Harness/shield/tether not used
(22) Harness/shield/tether used
(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES

61. Injury Severity (Police Rating) 0

(0) O - No injury
(1) C - Possible injury
(2) B - Nonincapacitating injury
(3) A - Incapacitating injury
(4) K - Killed
(5) U - Injury, severity unknown
(6) Died prior to accident
(9) Unknown

62. Treatment - Mortality 0

(0) No treatment
(1) Fatal
(2) Fatal - ruled disease (specify):

_____

Nonfatal
(3) Hospitalization
(4) Transported and released
(5) Treatment at scene - nontransported
(6) Treatment later
(7) Treatment - other (specify):

_____

(8) Transported to a medical facility-unknown if treated
(9) Unknown

63. Type Of Medical Facility (for Initial Treatment) 0

(0) Not treated at a medical facility
(1) Trauma center
(2) Hospital
(3) Medical clinic
(4) Physician's office
(5) Treatment later at medical facility
(8) Other (specify):

_____

(9) Unknown

64. Hospital Stay 0 0

(00) Not Hospitalized
____Code the number of days (up through 60) that the occupant stayed in hospital.
(61) 61 days or more
(99) Unknown

65. Working Days Lost 0 0

____Code the number of days (up through 60) that the occupant lost from work due to the accident
(00) No working days lost
(61) 61 days or more
(62) Fatally injured
(97) Not working prior to accident
(99) Unknown

STOP WORK HERE

VARIABLES 66-74

TO BE CODED BY THE ZONE CENTER

TO BE CODED BY THE ZONE CENTER

INJURY CONSEQUENCES

66. Time to Death 00
_____Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 +n up through 30 days = 60)
(00) Not fatal
(96) Fatal - ruled disease
(99) Unknown

67. 1st Medically Reported Cause of Death 00

68. 2nd Medically Reported Cause of Death 00

69. 3rd Medically Reported Cause of Death 00
_____Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death
(00) Not fatal or no additional causes
(96) Mode of death given but specific injuries are not linked to cause of death. (specify):
_____
(97) Other result (includes fatal ruled disease) (specify):
_____
(99) Unknown

70. Number of Recorded Injuries for This Occupant 00
_____Code the actual number of injuries recorded for this occupant.
(00) No recorded injuries
(97) Injured, details unknown
(99) Unknown if injured

TRAUMA DATA

71. Glasgow Coma Scale (GCS) Score (at Medical Facility) 00
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured

72. Was the Occupant Given Blood? 1
(1) No - blood not given
(2) Yes - blood given
(specify units):_____
(9) Unknown if blood given

73. Arterial Blood Gases (ABG) – HCO_3 00
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported , HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

74. Primary Source of Belt Use Determination 1
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify):_____
(9) Unknown if belt used

PSU NUMBER 49

CASE NUMBER 120A

VEHICLE NUMBER 02

OCCUPANT NUMBER 02

OCCUPANT INJURY FORM

THE FOLLOWING DATA IS NOT INCLUDED IN THIS CASE:

[✓] ENTIRE FORM

[] PAGE NUMBER (S) _____

PSU 49-120A
V-03

PRECRASH ENVIRONMENTAL DATA

19. Relation To Interchange Or Junction — 2
(0) Non-interchange area and non-junction
(1) Interchange area related

Non-Interchange junctions
(2) Intersection related
(3) Driveway, alley access related
(4) Other junction (specify)
_____
(5) Unknown type of junction

(9) Unknown

20. Trafficway Flow — 1
(0) Not physically divided (two way traffic)
(1) Divided trafficway-median strip without positive barrier
(2) Divided trafficway-median strip with positive barrier
(3) One way traffic
(9) Unknown

21. Number Of Travel Lanes — 4
(1) One
(2) Two
(3) Three
(4) Four
(5) Five
(6) Six
(7) Seven or more
(9) Unknown

22. Roadway Alignment — 1
(1) Straight
(2) Curve right
(3) Curve left
(9) Unknown

23. Roadway Profile — 1
(1) Level
(2) Uphill grade (>2%)
(3) Hill crest
(4) Downhill grade (>2%)
(5) Sag
(9) Unknown

24. Roadway Surface Type — 1
(1) Concrete
(2) Bituminous (asphalt)
(3) Brick or block
(4) Slag, gravel, or stone
(5) Dirt
(8) Other (specify): _____
(9) Unknown

25. Roadway Surface Condition — 1
(1) Dry
(2) Wet
(3) Snow or slush
(4) Ice
(5) Sand, dirt, or oil
(8) Other (specify): _____
(9) Unknown

26. Light Conditions — 1
(1) Daylight
(2) Dark
(3) Dark, but lighted
(4) Dawn
(5) Dusk
(9) Unknown

27. Atmospheric Conditions — 0
(0) No adverse atmospheric-related driving conditions
(1) Rain
(2) Sleet/hail
(3) Snow
(4) Fog
(5) Rain and fog
(6) Sleet and fog
(7) Other (e.g., smog, smoke, blowing sand or dust, etc.) (specify):
_____
(9) Unknown

28. Traffic Control Device — 1
(0) No traffic control(s)
(1) Traffic control signal (not RR crossing)

Regulatory
(2) Stop sign
(3) Yield sign
(4) School zone sign
(5) Other regulatory sign (specify):
_____
(6) Warning sign (not RR crossing)
(7) Unknown sign
(8) Miscellaneous/other controls including RR controls (specify):
_____
(9) Unknown

29. Traffic Control Device Functioning — 2
(0) No traffic control device
(1) Traffic control device not functioning (specify):_____
(2) Traffic control device functioning properly
(9) Unknown

PSU 49-120A V03

OCCUPANT RELATED

37. Driver Presence in Vehicle: 1
(0) Driver not present
(1) Driver present
(9) Unknown

38. Number of Occupants This Vehicle: 01
(00-96) Code actual number of occupants for this vehicle
(97) 97 or more
(99) Unknown

39. Number of Occupant Forms Submitted: 00

AIR BAG RELATED

40. Is this an AOPS Vehicle? 0
(0) No (includes unknown)
(1) Yes - researcher determined
(2) VIN determined air bag system
(3) VIN determined automatic (passive) belts
(4) VIN determined air bag and automatic (passive) belts

41. Air Bag(s) Deployment, First Seat Frontal: 0
(0) Not equipped or not available
(1) No air bags deployed

Single Air Bag Vehicle
(2) Driver air bag deployed
(3) Driver air bag, unknown if deployed

Multiple Air Bag Vehicle
(4) Driver side only deployed
(5) Passenger side only deployed
(6) Driver and passenger side deployed
(7) Driver and passenger side unknown if deployed
(8) Air bag(s) deployed, details unknown
(9) Unknown

42. Air Bag(s) Deployment, Other Than First Seat Frontal: 0
(0) Not equipped with an "other" air bag
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, details unknown
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

Specify type of "other" air bag present: _____

VEHICLE WEIGHT ITEMS

43. Vehicle Curb Weight: 1,090
____ Code weight to nearest 10 kilograms.
(045) Less than 450 kilograms
(610) 6,100 kilograms or more
(999) Unknown
2,404 lbs X .4536 = 1,090 kgs
Source: [redacted]

44. Vehicle Cargo Weight: 0,000
____ Code weight to nearest 10 kilograms.
(000) Less than 5 kilograms
(450) 4,500 kilograms or more
(999) Unknown
___,___ lbs X .4536 = ___,___ kgs
Source: [redacted]

ROLLOVER DATA

45. Rollover: 00
(00) No rollover (no overturning)

Rollover (primarily about the longitudinal axis)
(01-16) Code the number of quarter turns
(17) Rollover, 17 or more quarter turns (specify): _____
(98) Rollover--end-over-end (i.e., primarily about the lateral axis)
(99) Rollover (overturn), details unknown

46. Rollover Initiation Type: 00
(00) No rollover
(01) Trip-over
(02) Flip-over
(03) Turn-over
(04) Climb-over
(05) Fall-over
(06) Bounce-over
(07) Collision with another vehicle
(08) Other rollover initiation type specify): _____
(98) Rollover--end-over-end
(99) Unknown rollover initiation type

47. Location of Rollover Initiation: 0
(0) No rollover
(1) On roadway
(2) On shoulder—paved
(3) On shoulder—unpaved
(4) On roadside or divided trafficway median
(8) Rollover--end-over-end
(9) Unknown

48. Rollover Initiation Object Contacted: 00
(Note: Applicable codes on back of page)

49. Location on Vehicle Where Initial Principal Tripping Force Is Applied: 0
(0) No rollover
(1) Wheels/tires
(2) Side plane
(3) End plane
(4) Undercarriage
(5) Other location on vehicle (specify): _____
(6) Non-contact rollover forces (specify): _____
(8) Rollover--end-over-end
(9) Unknown

50. Direction of Initial Roll: 0
(0) No rollover
(1) Roll right - primarily about the longitudinal axis
(2) Roll left - primarily about the longitudinal axis
(8) Rollover--end-over-end
(9) Unknown roll direction

PSU 49-120A
V-03

CODES FOR ROLLOVER INITIATION OBJECT CONTACTED

(00) No rollover
(01-30) — Vehicle Number

Noncollision
(31) Turn-over — fall-over
(32) No rollover impact initiation (end-over-end)
(34) Jackknife

Collision With Fixed Object
(41) Tree (≤ 10 cm in diameter)
(42) Tree (> 10 cm in diameter)
(43) Shrubbery or bush
(44) Embankment

(45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
(50) Pole or post (≤ 10 cm in diameter)
(51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
(52) Pole or post (> 30 cm in diameter)
(53) Pole or post (diameter unknown)

(54) Concrete traffic barrier
(55) Impact attenuator
(56) Other traffic barrier (includes guardrail) (specify):_____

(57) Fence
(58) Wall
(59) Building
(60) Ditch or culvert
(61) Ground
(62) Fire hydrant
(63) Curb
(64) Bridge
(68) Other fixed object (specify):

(69) Unknown fixed object

Collision with Nonfixed Object
(70) Passenger car, light truck, van, or other vehicle not in-transport
(71) Medium/heavy truck or bus not in-transport
(76) Animal
(77) Train
(78) Trailer, disconnected in transport
(79) Object fell from vehicle in-transport
(88) Other nonfixed object (specify):

(89) Unknown nonfixed object

(98) Other event (specify):

(99) Unknown event or object

U.S. Department of Transportation
National Highway Traffic Safety Administration

EXTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 49
2. Case Number - Stratum: 120A
3. Vehicle Number: 03

VEHICLE IDENTIFICATION

VIN 1G2JB51kXH7[redacted] Model Year 87

Vehicle Make (specify): PONTIAC Vehicle Model (specify): SUNBIRD

LOCATOR

Locate the end of the damage with respect to the vehicle longitudinal center line or bumper corner for end impacts or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L	Location of Max Crush
1	BEGINS 62cm FORWARD LF AXLE	BEGINS 19 cm FORWARD LF AXLE	72cm FORWAR LF AXLE
2	BEGINS 100cm BACK LF AXLE	BEGINS 62cm BACK LF AXLE	120cm BACK LF AXLE

CRUSH PROFILE IN CENTIMETERS

NOTES: Identify the plane at which the C-measurements are taken (e.g., at bumper, above bumper, at sill, above sill, etc.) and label adjustments (e.g., free space).

Measure C1 to C6 from driver to passenger side in front or rear impacts and rear to front in side impacts.

Free space value is defined as the distance between the baseline and the original body contour taken at the individual C locations. This may include the following: bumper lead, bumper taper, side protrusion, side taper, etc. Record the value for each C-measurement and maximum crush.

Use as many lines/columns as necessary to describe each damage profile.

Specific Impact Number	Plane of Impact C-Measurements	Direct Damage Width (CDC)	Direct Damage Max Crush	Field L	C_1	C_2	C_3	C_4	C_5	C_6	±D
1	LEFT (FRONT)	27	C5	72	2	2	4	6	10	12	+205
	FREESPACE				0	1	1	1	2	5	
	RESULTANT				2	1	3	5	8	7	
2	LEFT	60	13	111	7	9	10	12	9	7	-1
	FREESPACE		7		7	7	7	7	7	7	
	RESULTANT		6		0	2	3	5	2	0	
			BETWEEN								
			C3 & C4								

ORIGINAL SPECIFICATIONS WORK SHEET

Wheelbase	101.2	inches	x	2.54	=	257 cm
Overall Length	175.7	inches	x	2.54	=	446 cm
Maximum Width	66.3	inches	x	2.54	=	168 cm
Curb Weight	2,404	pounds	x	.4536	=	1,090 kg
Average Track	55.3	inches	x	2.54	=	140 cm
Front Overhang	___.__	inches	x	2.54	=	___ cm
Rear Overhang	___.__	inches	x	2.54	=	___ cm
Undeformed End Width	___.__	inches	x	2.54	=	___ cm
Engine Size: cyl./displ.	____	cc	x	.001	=	__.__ L
	___	CID	x	.0164	=	__.__ L

VEHICLE DAMAGE SKETCH

TIRE—WHEEL DAMAGE

	a. Rotation physically restricted	b. Tire deflated
RF	2	2
LF	2	2
RR	2	2
LR	2	2

(1) Yes (2) No (8) NA (9) Unk.

TYPE OF TRANSMISSION

☐ Manual ☒ Automatic

END SHIFT ≥ 10 CM

☐ Yes ☒ No

ORIGINAL SPECIFICATIONS

Wheelbase	257	cm
Overall Length	446	cm
Maximum Width	168	cm
Curb Weight	1,090	kg
Average Track	140	cm
Front Overhang	89	cm
Rear Overhang	100	cm
Undeformed End Width	139	cm
Engine Size: cyl./displ.	4cyl/2.0	L

WHEEL STEER ANGLES

(For locked front wheels or displaced rear axles only)

RF ± ___ o
LF ± ___ o
RR ± ___ o
LR ± ___ o

Within ± 5 degrees

DRIVE WHEELS

☒ FWD ☐ RWD ☐ 4WD

Approximate Cargo Weight 0 kg

MEASUREMENTS IN CENTIMETERS



NOTES: Sketch new perimeter and cross hatch direct damage and single hatch induced damage on all views. Annotate observations which might be useful in reconstructing the accident (e.g., grass in tire bead, direction of striations, scuff on sidewalls, etc.). If pulling trailer, sketch type of trailer and damage received on the back of this page.

Annotate any damage caused by extrication such as component removal by torching, prying, or hydraulic shears.

CDC WORKSHEET

CODES FOR OBJECT CONTACTED

(01-30) — Vehicle Number

Noncollision
- (31) Overturn — rollover (excludes end-over-end)
- (32) Rollover—end-over-end
- (33) Fire or explosion
- (34) Jackknife
- (35) Other intraunit damage (specify): _____
- (36) Noncollision injury
- (38) Other noncollision (specify): _____
- (39) Noncollision — details unknown

Collision With Fixed Object
- (41) Tree (≤ 10 cm in diameter)
- (42) Tree (> 10 cm in diameter)
- (43) Shrubbery or bush
- (44) Embankment
- (45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
- (50) Pole or post (≤ 10 cm in diameter)
- (51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
- (52) Pole or post (> 30 cm in diameter)
- (53) Pole or post (diameter unknown)
- (54) Concrete traffic barrier
- (55) Impact attenuator
- (56) Other traffic barrier (includes guardrail) (specify): _____
- (57) Fence
- (58) Wall
- (59) Building
- (60) Ditch or culvert
- (61) Ground
- (62) Fire hydrant
- (63) Curb
- (64) Bridge
- (68) Other fixed object (specify): _____
- (69) Unknown fixed object

Collision with Nonfixed Object
- (70) Passenger car, light truck, van, or other vehicle not in-transport
- (71) Medium/heavy truck or bus not in-transport
- (72) Pedestrian
- (73) Cyclist or cycle
- (74) Other nonmotorist or conveyance _____
- (75) Vehicle occupant
- (76) Animal
- (77) Train
- (78) Trailer, disconnected in transport
- (79) Object fell from vehicle in-transport
- (88) Other nonfixed object (specify): LR TIRE & WHEEL From V1
- (89) Unknown nonfixed object
- (98) Other event (specify): _____
- (99) Unknown event or object

DEFORMATION CLASSIFICATION BY EVENT NUMBER

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force (degrees)	Incremental Value of Shift	(3) Deformation Location	(4) Specific Longitudinal or Lateral Location	(5) Specific Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
02	03	280	00	L	F	E	F	01
03	88	310	00	L	P	E	W	01

COLLISION DEFORMATION CLASSIFICATION

HIGHEST DELTA "V"

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force	(3) Deformation Location	(4) Longitudinal or Lateral Location	(5) Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
4. 02	5. 01	6. 09	7. L	8. F	9. E	10. E	11. 01

Second Highest Delta "V"

12. 03	13. ~~88~~ 79	14. 10	15. L	16. P	17. E	18. W	19. 01

CRUSH PROFILE IN CENTIMETERS

The crush profile for the damage described in the CDC(s) above should be documented in the appropriate space below. (ALL MEASUREMENTS ARE IN CENTIMETERS.)

HIGHEST DELTA "V"

20. L	21. C_1	C_2	C_3	C_4	C_5	C_6	22. ±D
072	002	001	003	005	008	007	⊕205

Second Highest Delta "V"

23. L	24. C_1	C_2	C_3	C_4	C_5	C_6	25. ±D
111	000	002	003	005	002	000	⊖001

26. Undeformed End Width (Coded when highest severity impact is an end plane impact.) 998
- ____ Code to the nearest centimeter
- (250) 250 centimeters or more
- (998) No highest severity end plane impact
- (999) Unknown

27. Direct Damage Width (For highest severity impact) 027
- ____ Code to the nearest centimeter
- (250) 250 centimeters or more
- (999) Unknown

28. Original Wheelbase 257
- ____ Code to the nearest centimeter
- (650) 650 centimeters or more
- (999) Unknown

101.2 inches X 2.54 = 257 centimeters

29. Original Average Track Width 140
- ____ Code to the nearest centimter
- (185) 185 centimeters or more
- (999) Unknown

55.3 inches X 2.54 = 140 centimeters

30. Are CDCs Documented but Not Coded on The Automated File? 0
(0) No
(1) Yes

31. Researcher's Assessment of Vehicle Disposition 0
(0) Not towed due to vehicle damage
(1) Towed due to vehicle damage
(9) Unknown

32. Is This A Multi-Stage Manufactured Vehicle And/Or A Certified Altered Vehicle? 0
(0) No post manufacturer modifications
(1) Yes - post manufacturer modifications (specify): _____
_____
_____
(Include photograph of CERTIFICATION PLACARD in case report)
(9) Unknown if vehicle is modified

FIRE OCCURRENCE

33. Fire Occurrence D
(0) No fire

Yes, fire occurred
(1) Minor
(2) Major
(9) Unknown

34. Origin of Fire 0
(0) No fire
(1) Vehicle exterior (front, side, back, top)
(2) Exhaust system
(3) Fuel tank (and other fuel retention system parts)
(4) Engine compartment
(5) Cargo/trunk compartment
(6) Instrument panel
(7) Passenger compartment area
(8) Other location (specify):
_____
(9) Unknown

FUEL SYSTEM

35. Location of Fuel Tank-1 Filler Cap 3

36. Location of Fuel Tank-2 Filler Cap 0
(0) No fuel tank
(1) On back plane
(2) Aft of center of the rear wheels (rear axle) on left side plane
(3) Aft of center of the rear wheels (rear axle) on right side plane
(4) Forward of center of the rear wheels (rear axle) on left side plane
(5) Forward of center of the rear wheels (rear axle) on right side plane
(6) Over the center of the rear wheels (rear axle) on left side plane
(7) Over the center of the rear wheels (rear axle) on right side plane
(8) Other (specify):_____
(9) Unknown

37. Type of Fuel Tank-1 1

38. Type of Fuel Tank-2 0
(0) No fuel tank (electrical vehicle)
(1) Metallic
(2) Non-metallic
(9) Unknown

39. Location of Fuel Tank-1 4

40. Location of Fuel Tank-2 0
(0) No fuel tank
(1) Aft of center of the rear wheels (rear axle) centered
(2) Aft of center of the rear wheels (rear axle) left side
(3) Aft of center of the rear wheels (rear axle) right side
(4) Forward of center of the rear wheels (rear axle) centered
(5) Forward of center of the rear wheels (rear axle) left side
(6) Forward of center of the rear wheels (rear axle) right side
(7) Over center of the rear wheels (rear axle)
(8) Other (specify):_____
(9) Unknown

41. Damage to Fuel Tank-1 1

42. Damage to Fuel Tank-2 0
(0) No fuel tank
(1) No damage to fuel tank
(2) Deformed, no seam failure
(3) Deformed, with a seam failure
(4) Punctured
(5) Lacerated (ripped)
(6) Abraded (scraped)
(7) Filler neck separation from the fuel tank
(8) Other damage (specify):_____
(9) Unknown

43. Leakage Location of Fuel System-1 1

44. Leakage Location of Fuel System-2 0
(0) No fuel tank
(1) No fuel leakage

Primary Area Of Leakage
(2) Tank
(3) Filler neck
(4) Cap
(5) Lines/pump/filter
(6) Vent/emission recovery
(8) Other (specify):_____
(9) Unknown

45. Fuel Type-1 01

46. Fuel Type-2 00

Single Fuel Type
(00) No fuel tank
(01) Gasoline
(02) Diesel
(03) CNG (Compressed Natural Gas)
(04) LPG (Liquid Petroleum Gas) also known as Propane
(05) LNG (Liquid Natural Gas)
(06) Methanol (M100 or M85)
(07) Ethanol (E100 or E85)
(08) Other (Hydrogen or others) (specify):
_____

Electric Powered or Electric/Solar Powered Vehicles
(10) Lead Acid Battery
(11) Nickel-Iron Battery
(12) Nickel-Cadmium Battery
(13) Sodium Metal Chloride Battery
(14) Sodium Sulfur Battery
(18) Other (Specify):_____

(98) Other Hybrid (specify):
_____

(99) Unknown fuel type

47. Is This Vehicle Equipped With More Than Two Fuel Tanks? 0
(0) No (one or two tanks only)

Yes - More Than Two Tanks
(1) Yes -- no damage to any tank or filler cap and no fuel system leakage
(2) Yes -- no damage to any tank or filler cap but there is fuel system leakage (specify leakage location):
_____
(3) Yes -- damage to an additional tank or filler cap and there is fuel system leakage (specify the following):
Type of tank _____
Tank location _____
Filler cap location _____
Tank damage _____
Location of leakage _____
Type of fuel _____
(9) Unknown if more than two tanks

COMMENTS

_____
_____
_____
_____
_____
_____
_____
_____
_____
_____
_____

*** STOP: IF THE CDS APPLICABLE VEHICLE WAS NOT TOWED ***

(GV10=0)

DO NOT COMPLETE THE INTERIOR VEHICLE FORM.

PSU NUMBER 49

CASE NUMBER 120A

VEHICLE NUMBER 03

INTERIOR VEHICLE FORM

THE FOLLOWING DATA IS NOT INCLUDED IN THIS CASE:

[✓] ENTIRE FORM

[] PAGE NUMBER (S) _____

PSU NUMBER 49

CASE NUMBER 120A

VEHICLE NUMBER 03

OCCUPANT NUMBER N/A

OCCUPANT ASSESSMENT FORM

THE FOLLOWING DATA IS NOT INCLUDED IN THIS CASE:

[✓] ENTIRE FORM

[] PAGE NUMBER (S) _____

PSU NUMBER 49

CASE NUMBER 120A

VEHICLE NUMBER 03

OCCUPANT NUMBER N/A

OCCUPANT INJURY FORM

THE FOLLOWING DATA IS NOT INCLUDED IN THIS CASE:

[✓] ENTIRE FORM

[] PAGE NUMBER (S) _____

U.S. Department of Transportation
National Highway Traffic Safety Administration

SMASH Program Summary 87-93

(All Measurements in Metric)

National Accident Sampling System
Crashworthiness Data System

Identifying Title	49	120 A	01	[redacted] 95
	PSU	Case No. - Stratum	Sequence No.	Date (month, day, year) of Run

General Vehicle Information

	Vehicle 1	Vehicle 2
Year	1992	2
Make	Chevrolet F4	1995
Model	Camaro F4	Ford
Body Style	3Dr Hatchback	Econoline 150 Van
NASS Veh. No.	1	2
CDC	11 L D A W 04	missing
Damaged Side (Missing Veh. Only)		Front
PDOF	-30 °	+50 °
HDG Angle	350 °	90 °

Vehicle Specifications

	Vehicle 1	Vehicle 2
Wheelbase	257 mm	351 mm
OAL	489 mm	538 mm
OAW	184 mm	202 mm
Weight:		
	1408 Curb + 0 Cargo + 61 Occupants = 1469 kg	2121 Curb + 136 Cargo + 155 Occupants = 2412 kg
Engine Displacement	3.1	4.9
Drive System	RWD	RWD
Size	3	7
Stiffness	3	7

Damage Information

	Vehicle 1	Vehicle 2
Damage known?	yes	No
Damage length	292 cm	178 cm
Damage offset	+0 42 cm	+- 0 cm
Crush Depth:		
C1	6 cm	cm
C2	26 cm	cm
C3	54 cm	cm
C4	46 cm	cm
C5	36 cm	cm
C6	4 cm	cm

work

National Accident Sampling System - Crashworthiness Data System: SMASH Program Summary

Scene Information

Vehicle 1		Vehicle 2	
Rest and Impact Positions	[ ]yes [ ]no		
Rest position X	_____m	Rest position X	_____m
Rest position Y	_____m	Rest position Y	_____m
Rest position angle	_____deg	Rest position angle	_____deg
Impact position X	_____m	Impact position X	_____m
Impact position Y	_____m	Impact position Y	_____m
Impact position angel	_____deg	Impact position angel	_____deg
Slip angle	_____deg	Slip angle	_____deg

Vehicle Motion

Vehicle 1		Vehicle 2	
Vehicle Rotation	[ ]yes [ ]no	Vehicle Rotation	[ ]yes [ ]no
Rotation Stop Before Rest	[ ]yes [ ]no	Rotation Stop Before Rest	[ ]yes [ ]no
End of Rotation	X___ ___ ___ . ___m	End of Rotation	X___ ___ ___ . ___m
Position	Y___ ___ ___ . ___m	Position	Y___ ___ ___ . ___m
	PSI ___ ___ . ___m		PSI ___ ___ . ___m
Curved Path	[ ]yes [ ]no	Curved Path	[ ]yes [ ]no
Point on Path	X___ ___ ___ . ___m	Point on Path	X___ ___ ___ . ___m
	Y___ ___ ___ . ___m		Y___ ___ ___ . ___m
Rotation Direction	[ ]None [ ]CW [ ]CCW	Rotation Direction	[ ]None [ ]CW [ ]CCW
Rotation >360 deg	[ ]yes [ ]no	Rotation >360 deg	[ ]yes [ ]no

Friction Information

Coefficient of Friction ___ ___ ___

Rolling Resistance Option ___

Vehicle 1 Rolling Resistance

LF___ . ___ ___ RF___ . ___ ___

LR___ . ___ ___ RR___ . ___ ___

Vehicle 2 Rolling Resistance

LF___ . ___ ___ RF___ . ___ ___

LR___ . ___ ___ RR___ . ___ ___

Trajectory Information

Trajectory Data [ ]yes [ ]no

Vehicle 1 Steer Angle

LF___ ___ ___ RF___ ___ ___

LR___ ___ ___ RR___ ___ ___

Vehicle 2 Steer Angle

LF___ ___ ___ RF___ ___ ___

LR___ ___ ___ RR___ ___ ___

Terrain Boundary [ ]yes [ ]no

First Path

X___ ___ ___ . ___m Y___ ___ ___ . ___m

Second Path

X___ ___ ___ . ___m Y___ ___ ___ . ___m

Coefficient of Friction ___ ___ ___

[redacted], 1995

Summary of Results Using Damage

ROLDMISS Crash

	Speed Change (ROLDMISS)
Vehicle #1	
Total	68 km/h (42 mph)
Longitudinal	-59 km/h (-37 mph)
Latitudinal	34 km/h (21 mph)
PDOF Angle	-30 °
Energy Dissipated	= 433558 Joules (319733 Ft-Lb)
Barrier Equivalent Speed	= 76.0 km/h (47.2 mph)
Calculated using crush coefficients calculated from vehicle parameters.	
Vehicle #2	
Total	41 km/h (26 mph)
Longitudinal	-27 km/h (-17 mph)
Latitudinal	-32 km/h (-20 mph)
PDOF Angle	50 °
Energy Dissipated	= 204192 Joules (150584 Ft-Lb)
Barrier Equivalent Speed	= 34.5 km/h (21.4 mph)
Calculated using crush coefficients calculated from vehicle parameters.	

General Information

	Vehicle #1	Vehicle #2
Year	1992	1995
Make	Chevrolet	Ford
Model	Camaro	Econline 150
CDC	11LDAW4	MISSING
Side Damaged	L	F
PDOF Angle	-30 °	50 °
Heading Angle	350 °	90 °
Calculation method:	Calculated Crush Coeff.	Calculated Crush Coeff.
d0 crush coeff.	63.27 sqrt(N)	86.67 sqrt(N)
d1 crush coeff.	9.27 sqrt(N)/cm	9.32 sqrt(N)/cm

[redacted] 1995

Damage Information

	Vehicle #1	Vehicle #2
Vehicle Damage Known	Yes	No
Crush Length	292.0 cm (115 in)	0.0 cm (0 in)
C1	6.0 cm (2 in)	0.0 cm (0 in)
C2	26.0 cm (10 in)	0.0 cm (0 in)
C3	54.0 cm (21 in)	0.0 cm (0 in)
C4	41.0 cm (16 in)	0.0 cm (0 in)
C5	36.0 cm (14 in)	0.0 cm (0 in)
C6	4.0 cm (2 in)	0.0 cm (0 in)
D	-41.9 cm (-16 in)	0.0 cm (0 in)
D'	-39.6 cm (-16 in)	0.0 cm (0 in)

Vehicle Dimensions

	Vehicle #1	Vehicle #2
Length	4890 mm (193 in)	5380 mm (212 in)
Width	1840 mm (72 in)	2020 mm (80 in)
Wheelbase	2571 mm (101 in)	3510 mm (138 in)
Weight	1470 kgs (3241 lbs)	2412 kgs (5318 lbs)
CG to Front of Veh	2281 mm (90 in)	1920 mm (76 in)
Engine Displacement	3.1 liters	4.9 liters
Moment of Inertia	317566 kgs (28108 lbs)	630726 kgs (55827 lbs)
Vehicle Mass	1470 kgs (8.4 lb-s^2/in)	2412 kgs (13.8 lb-s^2/in)

Impact #2 $V_1 \rightarrow V_3$

U.S. Department of Transportation
National Highway Traffic Safety Administration

CRASHPC PROGRAM SUMMARY

(All Measurements In Metric)

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Identifying Title

49	120A	02	[redacted]95
Primary Sampling Unit	Case No.-Stratum	Accident Event Sequence No.	Date (Month, day, year) of Run

CRASHPC Vehicle Identification

	Year	Make	Model	NASS Veh. No.
Vehicle 1	1992	CHEVROLET	CAMARO	01
Vehicle 2	1987	PONTIAC	SUNBIRD	03

GENERAL INFORMATION

	VEHICLE 1	VEHICLE 2
Size	3	2
Weight	1408 (Curb) + 61 (Occupant(s)) + 0 (Cargo) = 1469 kg	1,090 (Curb) + 78 (Occupant(s)) + 0 (Cargo) = 1168 kg
CDC	10LFEWZX	09LFEE1
PDOF (-180 to +180)	±0060 °	±0080 °
Stiffness	3x	2

SCENE INFORMATION

Rest and Impact Positions [ ] No, *Go To Damage Information* [ ] Yes

		VEHICLE 1	VEHICLE 2
Rest Position	X	___.___ m	___.___ m
	Y	___.___ m	___.___ m
	PSI	___ °	___ °
Impact Position	X	___.___ m	___.___ m
	Y	___.___ m	___.___ m
	PSI	___ °	___ °
Slip Angle(-180 to +180)		___ °	___ °

VEHICLE MOTION

Sustained Contact [ ] No [ ] Yes

		VEHICLE 1	VEHICLE 2
Vehicle Rotation		[ ] No [ ] Yes	[ ] No [ ] Yes
Rotation Stop Before Rest		[ ] No [ ] Yes	[ ] No [ ] Yes
End of Rotation Position	X	___.___ m	___.___ m
	Y	___.___ m	___.___ m
	PSI	___ °	___ °
Curved Path		[ ] No [ ] Yes	[ ] No [ ] Yes
Point on Path	X	___.___ m	___.___ m
	Y	___.___ m	___.___ m
Rotation Direction		[ ] None [ ] CW [ ] CCW	[ ] None [ ] CW [ ] CCW
Rotation >360°		[ ] No [ ] Yes	[ ] No [ ] Yes

National Accident Sampling System-Crashworthiness Data System: CRASHPC Program Summary

FRICTION INFORMATION

Coefficient of Friction . ___ ___ ___

Rolling Resistance Option ___

Vehicle 1 Rolling Resistance

LF ___ . ___ ___ RF ___ . ___ ___

LR ___ . ___ ___ RR ___ . ___ ___

Vehicle 2 Rolling Resistance

LF ___ . ___ ___ RF ___ . ___ ___

LR ___ . ___ ___ RR ___ . ___ ___

TRAJECTORY INFORMATION

Trajectory Data [ ] **No** [ ] **Yes**

If No, Go To Damage Information

Vehicle 1 Steer Angles

LF ___ ___ ___ ° RF ___ ___ ___ °

LR ___ ___ ___ ° RR ___ ___ ___ °

Vehicle 2 Steer Angles

LF ___ ___ ___ ° RF ___ ___ ___ °

LR ___ ___ ___ ° RR ___ ___ ___ °

Terrain Boundary [ ] **No** [ ] **Yes**

First Point

X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m

Second Point

X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m

Secondary Coefficient of Friction . ___ ___ ___

DAMAGE INFORMATION

	VEHICLE 1		VEHICLE 2	
Damage Length	L	064 cm	L	072 cm
Crush Depths	C_1	002 cm	C_1	002 cm
	C_2	008 cm	C_2	001 cm
	C_3	013 cm	C_3	003 cm
	C_4	017 cm	C_4	005 cm
	C_5	011 cm	C_5	008 cm
	C_6	013 cm	C_6	007 cm
Damage Offset	D	⊖199 cm	D	⊖205 cm

IF THIS COMMON IMPACT WAS WITH A MOTOR VEHICLE *NOT IN TRANSPORT*, FILL IN THE INFORMATION BELOW.

Model Year: _____

Make: _____

Model: _____

VIN: _____

The Weight, CDC, Scene Data and Damage Information for this vehicle should be recorded above.

Complete and ATTACH the appropriate vehicle damage sketch and dimensions to the Form.

Impact #2 $V_1 \rightarrow V_3$

SUMMARY OF CRASHPC RESULTS USING DAMAGE

CRASH3 RECONSTRUCTION

	SPEED CHANGE (DAMAGE)
VEHICLE #1	
TOTAL	5 KPH (3 MPH)
LONGITUDINAL	-2 KPH (-2 MPH)
LATITUDINAL	4 KPH (3 MPH)
PDOF ANGLE	-60 DEGREES
ENERGY DISSIPATED =	6311 JOULES (4654 FT-LB)
VEHICLE #2	
TOTAL	6 KPH (4 MPH)
LONGITUDINAL	-1 KPH (-1 MPH)
LATITUDINAL	6 KPH (4 MPH)
PDOF ANGLE	-80 DEGREES
ENERGY DISSIPATED =	1691 JOULES (1247 FT-LB)

DAMAGE DATA

	VEHICLE #1	VEHICLE #2
SIZE CATEGORY	3	2
STIFFNESS CATEGORY	3	2
VEHICLE WEIGHT	1469 KGS (3239 LBS)	1168 KGS (2575 LBS)
CDC	10LFEW2	09LFEE1
PDOF ANGLE	-60 DEGREES	-80 DEGREES
CRUSH LENGTH	64 CM. (25 IN.)	72 CM. (28 IN.)
C1	2 CM. (1 IN.)	2 CM. (1 IN.)
C2	8 CM. (3 IN.)	1 CM. (0 IN.)
C3	13 CM. (5 IN.)	3 CM. (1 IN.)
C4	17 CM. (7 IN.)	5 CM. (2 IN.)
C5	11 CM. (4 IN.)	8 CM. (3 IN.)
C6	13 CM. (5 IN.)	7 CM. (3 IN.)
D	199 CM. (78 IN.)	205 CM. (81 IN.)
D'	203 CM. (80 IN.)	216 CM. (85 IN.)

(* INDICATES DEFAULT VALUE)

DIMENSIONS AND INERTIAL PROPERTIES

	VEHICLE #1	VEHICLE #2
CG TO FRONT AXLE	130 CM. (51 IN.)	118 CM. (46 IN.)
CG TO REAR AXLE	141 CM. (56 IN.)	127 CM. (50 IN.)
TRACK	150 CM. (59 IN.)	139 CM. (55 IN.)
CG TO FRONT OF VEH	228 CM. (90 IN.)	212 CM. (83 IN.)
CG TO REAR OF VEH	-270 CM. (-106 IN.)	-233 CM. (-92 IN.)
CG TO SIDE OF VEH	92 CM. (36 IN.)	85 CM. (34 IN.)
MOMENT OF INERTIA	12696 KGS (27990 LBS)	8962 KGS (19757 LBS)
VEHICLE MASS	4 KGS (8 LBS)	3 KGS (7 LBS)

Printing Picture: 120A



DAMAGE DESCRIPTION

V3 IMPACT #3 BARRIER

U.S. Department of Transportation
National Highway Traffic Safety Administration

CRASHPC PROGRAM SUMMARY

(All Measurements In Metric)

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Identifying Title

49	120A	03	[redacted] 95
Primary Sampling Unit	Case No.-Stratum	Accident Event Sequence No.	Date (Month, day, year) of Run

CRASHPC Vehicle Identification

	Year	Make	Model	NASS Veh. No.
Vehicle 1	1987	PONTIAC	SUNBIRD	03
Vehicle 2				

GENERAL INFORMATION

	VEHICLE 1	VEHICLE 2
Size	2	11
Weight	1090 (Curb) + 78 (Occupant(s)) + 0 (Cargo) = 1168 kg	____ (Curb) + ____ (Occupant(s)) + ____ (Cargo) = ____ kg
CDC	YOLPEW1	
PDOF (-180 to +180)	±050 °	± ____ °
Stiffness	2	

SCENE INFORMATION

Rest and Impact Positions [ ] No, *Go To Damage Information* [ ] Yes

		VEHICLE 1	VEHICLE 2
Rest Position	X	____.____ m	____.____ m
	Y	____.____ m	____.____ m
	PSI	____ °	____ °
Impact Position	X	____.____ m	____.____ m
	Y	____.____ m	____.____ m
	PSI	____ °	____ °
Slip Angle(-180 to +180)		____ °	____ °

VEHICLE MOTION

Sustained Contact [ ] No [ ] Yes

		VEHICLE 1	VEHICLE 2
Vehicle Rotation		[ ] No [ ] Yes	[ ] No [ ] Yes
Rotation Stop Before Rest		[ ] No [ ] Yes	[ ] No [ ] Yes
End of Rotation Position	X	____.____ m	____.____ m
	Y	____.____ m	____.____ m
	PSI	____ °	____ °
Curved Path		[ ] No [ ] Yes	[ ] No [ ] Yes
Point on Path	X	____.____ m	____.____ m
	Y	____.____ m	____.____ m
Rotation Direction		[ ] None [ ] CW [ ] CCW	[ ] None [ ] CW [ ] CCW
Rotation >360°		[ ] No [ ] Yes	[ ] No [ ] Yes

National Accident Sampling System-Crashworthiness Data System: CRASHPC Program Summary

FRICTION INFORMATION

Coefficient of Friction . ___ ___ ___

Rolling Resistance Option ___

Vehicle 1 Rolling Resistance

LF ___ . ___ ___ RF ___ . ___ ___

LR ___ . ___ ___ RR ___ . ___ ___

Vehicle 2 Rolling Resistance

LF ___ . ___ ___ RF ___ . ___ ___

LR ___ . ___ ___ RR ___ . ___ ___

TRAJECTORY INFORMATION

Trajectory Data [ ] **No** [ ] **Yes**

If No, Go To Damage Information

Vehicle 1 Steer Angles

LF ___ ___ ___ ° RF ___ ___ ___ °

LR ___ ___ ___ ° RR ___ ___ ___ °

Vehicle 2 Steer Angles

LF ___ ___ ___ ° RF ___ ___ ___ °

LR ___ ___ ___ ° RR ___ ___ ___ °

Terrain Boundary [ ] **No** [ ] **Yes**

First Point

X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m

Second Point

X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m

Secondary Coefficient of Friction . ___ ___ ___

DAMAGE INFORMATION

	VEHICLE 1		VEHICLE 2	
Damage Length	L	111 cm	L	___ ___ ___ cm
Crush Depths	C_1	000 cm	C_1	___ ___ ___ cm
	C_2	002 cm	C_2	___ ___ ___ cm
	C_3	003 cm	C_3	___ ___ ___ cm
	C_4	005 cm	C_4	___ ___ ___ cm
	C_5	002 cm	C_5	___ ___ ___ cm
	C_6	000 cm	C_6	___ ___ ___ cm
Damage Offset	D	+001 cm	D	± ___ ___ ___ cm

IF THIS COMMON IMPACT WAS WITH A MOTOR VEHICLE *NOT IN TRANSPORT,* FILL IN THE INFORMATION BELOW.

Model Year: _____

Make: _____

Model: _____

VIN: _____

The Weight, CDC, Scene Data and Damage Information for this vehicle should be recorded above.

Complete and ATTACH the appropriate vehicle damage sketch and dimensions to the Form.

V_3 Impact #3 Barrier

SUMMARY OF CRASHPC RESULTS USING DAMAGE

CRASH3 RECONSTRUCTION

	SPEED CHANGE (DAMAGE)
VEHICLE #1	
TOTAL	7 KPH (4 MPH)
LONGITUDINAL	-5 KPH (-3 MPH)
LATITUDINAL	6 KPH (3 MPH)
PDOF ANGLE	-50 DEGREES
ENERGY DISSIPATED =	2693 JOULES (1986 FT-LB)
VEHICLE #2	
TOTAL	0 KPH (0 MPH)
LONGITUDINAL	0 KPH (0 MPH)
LATITUDINAL	0 KPH (0 MPH)
PDOF ANGLE	0 DEGREES
ENERGY DISSIPATED =	0 JOULES (0 FT-LB)

DAMAGE DATA

	VEHICLE #1	VEHICLE #2
SIZE CATEGORY	2	11
STIFFNESS CATEGORY	2	0
VEHICLE WEIGHT	1168 KGS (2575 LBS)	****** KGS (2204586 LBS) *
CDC	10LPEW1	BARRIER
PDOF ANGLE	-50 DEGREES	0 DEGREES *
CRUSH LENGTH	111 CM. (44 IN.)	0 CM. (0 IN.) *
C1	0 CM. (0 IN.)	0 CM. (0 IN.) *
C2	2 CM. (1 IN.)	0 CM. (0 IN.) *
C3	3 CM. (1 IN.)	0 CM. (0 IN.) *
C4	5 CM. (2 IN.)	0 CM. (0 IN.) *
C5	2 CM. (1 IN.)	0 CM. (0 IN.) *
C6	0 CM. (0 IN.)	0 CM. (0 IN.) *
D	-1 CM. (0 IN.)	0 CM. (0 IN.) *
D'	1 CM. (0 IN.)	0 CM. (0 IN.) *

(* INDICATES DEFAULT VALUE)

DIMENSIONS AND INERTIAL PROPERTIES

	VEHICLE #1	VEHICLE #2
CG TO FRONT AXLE	118 CM. (46 IN.)	127 CM. (50 IN.)
CG TO REAR AXLE	127 CM. (50 IN.)	127 CM. (50 IN.)
TRACK	139 CM. (55 IN.)	127 CM. (50 IN.)
CG TO FRONT OF VEH	212 CM. (83 IN.)	127 CM. (50 IN.)
CG TO REAR OF VEH	-233 CM. (-92 IN.)	-127 CM. (-50 IN.)
CG TO SIDE OF VEH	85 CM. (34 IN.)	127 CM. (50 IN.)
MOMENT OF INERTIA	8962 KGS (19757 LBS)	****** KGS (******* LBS)
VEHICLE MASS	3 KGS (7 LBS)	2600 KGS (5732 LBS)

Pr inting Picture: 120A4



DAMAGE DESCRIPTION

V1 IMPACT #2 BARRIER

U.S. Department of Transportation
National Highway Traffic Safety Administration

CRASHPC PROGRAM SUMMARY

(All Measurements In Metric)

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Identifying Title

49	120A	02	[redacted]95
Primary Sampling Unit	Case No.-Stratum	Accident Event Sequence No.	Date (Month, day, year) of Run

CRASHPC Vehicle Identification

	Year	Make	Model	NASS Veh. No.
Vehicle 1	1992	CHEVROLET	CAMARO	01
Vehicle 2				

GENERAL INFORMATION

	VEHICLE 1	VEHICLE 2
Size	3	11
Weight	1408 (Curb) + 61 (Occupant(s)) + 0 (Cargo) = 1469 kg	____ (Curb) + ____ (Occupant(s)) + ____ (Cargo) = ____ kg
CDC	10LFEW2	
PDOF (-180 to +180)	±060°	± ____°
Stiffness	3	

SCENE INFORMATION

Rest and Impact Positions [ ] No, *Go To Damage Information* [ ] Yes

		VEHICLE 1	VEHICLE 2
Rest Position	X	____.___ m	____.___ m
	Y	____.___ m	____.___ m
	PSI	___°	___°
Impact Position	X	____.___ m	____.___ m
	Y	____.___ m	____.___ m
	PSI	___°	___°
Slip Angle(-180 to +180)		___°	___°

VEHICLE MOTION

Sustained Contact [ ] No [ ] Yes

		VEHICLE 1	VEHICLE 2
Vehicle Rotation		[ ] No [ ] Yes	[ ] No [ ] Yes
Rotation Stop Before Rest		[ ] No [ ] Yes	[ ] No [ ] Yes
End of Rotation Position	X	____.___ m	____.___ m
	Y	____.___ m	____.___ m
	PSI	___°	___°
Curved Path		[ ] No [ ] Yes	[ ] No [ ] Yes
Point on Path	X	____.___ m	____.___ m
	Y	____.___ m	____.___ m
Rotation Direction		[ ] None [ ] CW [ ] CCW	[ ] None [ ] CW [ ] CCW
Rotation >360°		[ ] No [ ] Yes	[ ] No [ ] Yes

National Accident Sampling System-Crashworthiness Data System: CRASHPC Program Summary

FRICTION INFORMATION

Coefficient of Friction . ___ ___ ___

Rolling Resistance Option ___

Vehicle 1 Rolling Resistance

LF ___ . ___ ___ RF ___ . ___ ___

LR ___ . ___ ___ RR ___ . ___ ___

Vehicle 2 Rolling Resistance

LF ___ . ___ ___ RF ___ . ___ ___

LR ___ . ___ ___ RR ___ . ___ ___

TRAJECTORY INFORMATION

Trajectory Data [ ] No [ ] Yes

If No, Go To Damage Information

Vehicle 1 Steer Angles

LF ___ ___ ___ ° RF ___ ___ ___ °

LR ___ ___ ___ ° RR ___ ___ ___ °

Vehicle 2 Steer Angles

LF ___ ___ ___ ° RF ___ ___ ___ °

LR ___ ___ ___ ° RR ___ ___ ___ °

Terrain Boundary [ ] No [ ] Yes

First Point

X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m

Second Point

X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m

Secondary Coefficient of Friction . ___ ___ ___

DAMAGE INFORMATION

	VEHICLE 1		VEHICLE 2	
Damage Length	L	064 cm	L	___ ___ ___ cm
Crush Depths	C_1	002 cm	C_1	___ ___ ___ cm
	C_2	008 cm	C_2	___ ___ ___ cm
	C_3	013 cm	C_3	___ ___ ___ cm
	C_4	017 cm	C_4	___ ___ ___ cm
	C_5	011 cm	C_5	___ ___ ___ cm
	C_6	013 cm	C_6	___ ___ ___ cm
Damage Offset	D	⊕ 199 cm	D	± ___ ___ ___ cm

IF THIS COMMON IMPACT WAS WITH A MOTOR VEHICLE *NOT IN TRANSPORT,* FILL IN THE INFORMATION BELOW.

Model Year: _____

Make: _____

Model: _____

VIN: _____

The Weight, CDC, Scene Data and Damage Information for this vehicle should be recorded above.

Complete and ATTACH the appropriate vehicle damage sketch and dimensions to the Form.

V1 Impact #2 Barrier

SUMMARY OF CRASHPC RESULTS USING DAMAGE

CRASH3 RECONSTRUCTION

	SPEED CHANGE (DAMAGE)
VEHICLE #1	
TOTAL	8 KPH (5 MPH)
LONGITUDINAL	-4 KPH (-2 MPH)
LATITUDINAL	7 KPH (4 MPH)
PDOF ANGLE	-60 DEGREES
ENERGY DISSIPATED =	6311 JOULES (4654 FT-LB)
VEHICLE #2	
TOTAL	0 KPH (0 MPH)
LONGITUDINAL	0 KPH (0 MPH)
LATITUDINAL	0 KPH (0 MPH)
PDOF ANGLE	0 DEGREES
ENERGY DISSIPATED =	0 JOULES (0 FT-LB)

DAMAGE DATA

	VEHICLE #1	VEHICLE #2
SIZE CATEGORY	3	11
STIFFNESS CATEGORY	3	0
VEHICLE WEIGHT	1469 KGS (3239 LBS)	****** KGS (2204586 LBS) *
CDC	10LFEW2	BARRIER
PDOF ANGLE	-60 DEGREES	0 DEGREES *
CRUSH LENGTH	64 CM. (25 IN.)	0 CM. (0 IN.) *
C1	2 CM. (1 IN.)	0 CM. (0 IN.) *
C2	8 CM. (3 IN.)	0 CM. (0 IN.) *
C3	13 CM. (5 IN.)	0 CM. (0 IN.) *
C4	17 CM. (7 IN.)	0 CM. (0 IN.) *
C5	11 CM. (4 IN.)	0 CM. (0 IN.) *
C6	13 CM. (5 IN.)	0 CM. (0 IN.) *
D	199 CM. (78 IN.)	0 CM. (0 IN.) *
D'	203 CM. (80 IN.)	0 CM. (0 IN.) *

(* INDICATES DEFAULT VALUE)

DIMENSIONS AND INERTIAL PROPERTIES

	VEHICLE #1	VEHICLE #2
CG TO FRONT AXLE	130 CM. (51 IN.)	127 CM. (50 IN.)
CG TO REAR AXLE	141 CM. (56 IN.)	127 CM. (50 IN.)
TRACK	150 CM. (59 IN.)	127 CM. (50 IN.)
CG TO FRONT OF VEH	228 CM. (90 IN.)	127 CM. (50 IN.)
CG TO REAR OF VEH	-270 CM. (-106 IN.)	-127 CM. (-50 IN.)
CG TO SIDE OF VEH	92 CM. (36 IN.)	127 CM. (50 IN.)
MOMENT OF INERTIA	12696 KGS (27990 LBS)	****** KGS (******* LBS)
VEHICLE MASS	4 KGS (8 LBS)	2600 KGS (5732 LBS)

Printing Picture: 120A2



D AMAGE DESCRIPTION

V3 IMPACT #2 BARRIER

U.S. Department of Transportation
National Highway Traffic Safety Administration

CRASHPC PROGRAM SUMMARY

(All Measurements In Metric)

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Identifying Title			
49	120A	02	[redacted] 95
Primary Sampling Unit	Case No.-Stratum	Accident Event Sequence No.	Date (Month, day, year) of Run

CRASHPC Vehicle Identification

	Year	Make	Model	NASS Veh. No.
Vehicle 1	1987	PONTIAC	SUNBIRD	03
Vehicle 2				

GENERAL INFORMATION

	VEHICLE 1	VEHICLE 2
Size	2	11
Weight	1090 (Curb) + 78 (Occupant(s)) + 0 (Cargo) = 1168 kg	____ (Curb) + ____ (Occupant(s)) + ____ (Cargo) = ____ kg
CDC	09LFEE1	
PDOF (-180 to +180)	±0080 °	± ____ °
Stiffness	2	

SCENE INFORMATION

Rest and Impact Positions [ ] No, *Go To Damage Information* [ ] Yes

		VEHICLE 1	VEHICLE 2
Rest Position	X	____.____ m	____.____ m
	Y	____.____ m	____.____ m
	PSI	____ °	____ °
Impact Position	X	____.____ m	____.____ m
	Y	____.____ m	____.____ m
	PSI	____ °	____ °
Slip Angle(-180 to +180)		____ °	____ °

VEHICLE MOTION

Sustained Contact [ ] No [ ] Yes

	VEHICLE 1	VEHICLE 2
Vehicle Rotation	[ ] No [ ] Yes	[ ] No [ ] Yes
Rotation Stop Before Rest	[ ] No [ ] Yes	[ ] No [ ] Yes
End of Rotation Position X	____.____ m	____.____ m
End of Rotation Position Y	____.____ m	____.____ m
End of Rotation Position PSI	____ °	____ °
Curved Path	[ ] No [ ] Yes	[ ] No [ ] Yes
Point on Path	X ____.____ m Y ____.____ m	X ____.____ m Y ____.____ m
Rotation Direction	[ ] None [ ] CW [ ] CCW	[ ] None [ ] CW [ ] CCW
Rotation >360°	[ ] No [ ] Yes	[ ] No [ ] Yes

National Accident Sampling System-Crashworthiness Data System: CRASHPC Program Summary

FRICTION INFORMATION

Coefficient of Friction . ___ ___ ___

Rolling Resistance Option ___

Vehicle 1 Rolling Resistance

LF ___ . ___ ___ RF ___ . ___ ___

LR ___ . ___ ___ RR ___ . ___ ___

Vehicle 2 Rolling Resistance

LF ___ . ___ ___ RF ___ . ___ ___

LR ___ . ___ ___ RR ___ . ___ ___

TRAJECTORY INFORMATION

Trajectory Data [ ] No [ ] Yes

If No, Go To Damage Information

Vehicle 1 Steer Angles

LF ___ ___ ___ ° RF ___ ___ ___ °

LR ___ ___ ___ ° RR ___ ___ ___ °

Vehicle 2 Steer Angles

LF ___ ___ ___ ° RF ___ ___ ___ °

LR ___ ___ ___ ° RR ___ ___ ___ °

Terrain Boundary [ ] No [ ] Yes

First Point

X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m

Second Point

X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m

Secondary Coefficient of Friction .___ ___ ___

DAMAGE INFORMATION

	VEHICLE 1		VEHICLE 2	
Damage Length	L	072 cm	L	___ ___ ___ cm
Crush Depths	C_1	002 cm	C_1	___ ___ ___ cm
	C_2	00___ cm	C_2	___ ___ ___ cm
	C_3	003 cm	C_3	___ ___ ___ cm
	C_4	005 cm	C_4	___ ___ ___ cm
	C_5	008 cm	C_5	___ ___ ___ cm
	C_6	007 cm	C_6	___ ___ ___ cm
Damage Offset	D	$\oplus$ 205 cm	D	$\pm$ ___ ___ ___ cm

IF THIS COMMON IMPACT WAS WITH A MOTOR VEHICLE *NOT IN TRANSPORT,* FILL IN THE INFORMATION BELOW.

Model Year: _____

Make: _____

Model: _____

VIN: _____

The Weight, CDC, Scene Data and Damage Information for this vehicle should be recorded above.

Complete and ATTACH the appropriate vehicle damage sketch and dimensions to the Form.

Y3 IMPACT # 2 BARRIER

SUMMARY OF CRASHPC RESULTS USING DAMAGE

CRASH3 RECONSTRUCTION

	SPEED CHANGE (DAMAGE)
VEHICLE #1	
TOTAL	3 KPH (2 MPH)
LONGITUDINAL	-1 KPH (0 MPH)
LATITUDINAL	3 KPH (2 MPH)
PDOF ANGLE	-80 DEGREES
ENERGY DISSIPATED =	1691 JOULES (1247 FT-LB)
VEHICLE #2	
TOTAL	0 KPH (0 MPH)
LONGITUDINAL	0 KPH (0 MPH)
LATITUDINAL	0 KPH (0 MPH)
PDOF ANGLE	0 DEGREES
ENERGY DISSIPATED =	0 JOULES (0 FT-LB)

DAMAGE DATA

DIMENSIONS AND INERTIAL PROPERTIES

	VEHICLE #1	VEHICLE #2
CG TO FRONT AXLE	118 CM. (46 IN.)	127 CM. (50 IN.)
CG TO REAR AXLE	127 CM. (50 IN.)	127 CM. (50 IN.)
TRACK	139 CM. (55 IN.)	127 CM. (50 IN.)
CG TO FRONT OF VEH	212 CM. (83 IN.)	127 CM. (50 IN.)
CG TO REAR OF VEH	-233 CM. (-92 IN.)	-127 CM. (-50 IN.)
CG TO SIDE OF VEH	85 CM. (34 IN.)	127 CM. (50 IN.)
MOMENT OF INERTIA	8962 KGS (19757 LBS)	****** KGS (******* LBS)
VEHICLE MASS	3 KGS (7 LBS)	2600 KGS (5732 LBS)

	VEHICLE #1	VEHICLE #2
SIZE CATEGORY	2	11
STIFFNESS CATEGORY	2	0
VEHICLE WEIGHT	1168 KGS (2575 LBS)	****** KGS (2204586 LBS) *
CDC	09LFEE1	BARRIER
PDOF ANGLE	-80 DEGREES	0 DEGREES *
CRUSH LENGTH	72 CM. (28 IN.)	0 CM. (0 IN.) *
C1	2 CM. (1 IN.)	0 CM. (0 IN.) *
C2	1 CM. (0 IN.)	0 CM. (0 IN.) *
C3	3 CM. (1 IN.)	0 CM. (0 IN.) *
C4	5 CM. (2 IN.)	0 CM. (0 IN.) *
C5	8 CM. (3 IN.)	0 CM. (0 IN.) *
C6	7 CM. (3 IN.)	0 CM. (0 IN.) *
D	205 CM. (81 IN.)	0 CM. (0 IN.) *
D'	216 CM. (85 IN.)	0 CM. (0 IN.) *

(* INDICATES DEFAULT VALUE)

Printing Picture: 120A3



DAMAGE DESCRIPTION

Final

49120A0000001[redacted]958.0500000000000307410000004[redacted]95005761000
00215700001242608 0508
49120A0001001[redacted]958.0510000000000102L0221F
49120A0002001[redacted]958.0510000000000102L0302L
49120A0003001[redacted]958.0510000000000302L79000
49120A0004001[redacted]958.0510000000000102L63000
49120A0100002[redacted] 8.05 00000000092200090316IFP23[redacted]0199904B096007522912
13211110129914179911B9
49120A0100002[redacted] 8.05 000000000101011201410000000000000035009000003068-059+03
44336998207603
49120A0100003[redacted] 8.05 00000000010211LDAW0402031OLFEW022920060260540460360O4-
042064002008013017011013+19999825025715411000201040801001000
49120A0100004[redacted] 8.05 000000000983100200002122002001220010026100600111001O0
49120A0100004[redacted] 8.05 000000000111143210733112033212133112533212533113233111 4
331106331118232900000999191900
49120A0101005[redacted] 8.05 000000000312168077111900009940411100000421100111101 1-05
92105881211102152360000000000041100620101000013029011
49120A0101016[redacted] 8.05 000000000142021864051210 1
49120A0101026[redacted] 8.05 000000000144141043051210 1
49120A0101036[redacted] 8.05 000000000145025242051210 1
49120A0101046[redacted] 8.05 000000000119040212203210 8
49120A0101056[redacted] 8.05 000000000129060217514210 0
49120A0101066[redacted] 8.05 000000000129060212514210 0
49120A0101076[redacted] 8.05 000000000139060212152210 0
49120A0101086[redacted] 8.05 000000000179060212514210 0
49120A0101096[redacted] 8.05 000000000129020211701100
49120A0101106[redacted] 8.05 000000000189040212051110 1
49120A0101116[redacted] 8.05 000000000119020212010110 0
49120A0101126[redacted] 8.05 000000000189040211004210 0
49120A0101136[redacted] 8.05 000000000189020212051110 1
49120A0200002[redacted] 8.05 000000000951246121IFTEE1[redacted]999056096007500632
13111110120101660111B8
49120A0200002[redacted] 8.05 000000000102021202120140000000000009035001003041-027-03
22042998403502
49120A0200003[redacted] 8.05 0000000000010199999999
1789993511740110040105010100 1000
49120A0200004[redacted] 8.05 000000000001101100000122022021420110111101101111011 01
49120A0200004[redacted] 8.05 000000000
100000099902100
49120A0201005[redacted] 8.05 000000000181178082111000000440411100000411100111101 1-02
72101012211101152310000000000000000000000000000001001
49120A0202005[redacted] 8.05 000000000291183073213000000440411100000400000000000 00
00000000000101152310000000000000000000000000000001001
49120A0300002[redacted] 8.05 000000000872201604162JB[redacted]0000056096007524412
14111110120105780111 98
49120A0300002[redacted] 8.05 000000000101000001090000000000000027010000001006-001+00
60017998100302
49120A0300003[redacted] 8.05 000000000020109LFEE01037910LPEW0107200200100300500B007+
20511100000200300500200O-0019980272571400000030104010100 1000
49120A0000006[redacted] 8.05 000000000CAR/VAN/CAR - RIGHT ANGLE
49120A0000017[redacted] 8.05 000000000Vehicle 1 was traveling north approaching an i
ntersection. Vehicle 2 was
49120A0000027[redacted] 8.05 000000000traveling east and vehicle 3 was traveling wes
t. At the intersection, the
49120A0000037[redacted] 8.05 000000000front of vehicle 2 impacted the left side of v
ehicle 1. Vehicle 1 continued
49120A0000047[redacted] 8.05 000000000and impacted the left front to the left front
of vehicle 3. The LR tire and
49120A0000057[redacted] 8.05 000000000wheel from vehicle 1 seperated from the vehicl
e and impacted the left side of
49120A0000067[redacted] 8.05 000000000vehicle 3. Then the LR hub of vehicle 1 impac
ted a curb on the
49120A0000077[redacted] 8.05 000000000northeast corner of the intersection and came
to rest. Vehicles 1 & 2 were
49120A0000087[redacted] 8.05 000000000towed andvehicle 3 was driven. The driver of
vehicle 1 was fatally injured.
49120A0000018[redacted] 8.05 00000000001 Compact 1992/Chevrolet/Camaro Left
Severe None
49120A0000028[redacted] 8.05 000000000

49120A0000038[redacted] 8.05 00000000002 Large Van 1995/Ford/Econoline Fron
t Unk None
49120A0000048[redacted] 8.05 000000000

49120A0000058[redacted] 8.05 00000000003 Compact 1987/Pontiac/Sunbird Left
Minor None
49120A0000019[redacted] 8.05 00000000001 Driver LF L&S Aorta T
ransec- 6 Door surface
49120A0000029[redacted] 8.05 000000000 air bag t
ion
49120A0000039[redacted] 8.05 000000000

49120A0000049[redacted] 8.05 00000000002 Driver LF L&S N
one
49120A0000059[redacted] 8.05 000000000 air bag

49120A0000069[redacted] 8.05 000000000 Pass RF L&S N
one
49120A0000079[redacted] 8.05 000000000

49120A0000089[redacted] 8.05 00000000003 Non-tow

49120A9999999900000000000000000000000000000000000010000000010000000010000000020000
00000000000003

```
GENERAL VEHICLE Vehicle: 1
11
INTRA ERRORS

0GG2251  2  If ACCIDENT TYPE GV36 equals 20, 24, 28, 44, 45, 51, 65, 69, 71,
 GG2252     73, 77, 79, 81, 83 or 86-89, then PRE-EVENT MOVEMENT GV31 should
 GG2253     equal 01.

0
EXTERIOR VEHICLE Vehicle: 1
11
INTRA ERRORS

0EE1101  2  If LEAKAGE SYSTEM-1 EV43 equals 1, then DAMAGE TANK-1 EV41
 EE1102     should equal 1, 2 or 6.

0
INTERIOR VEHICLE Vehicle: 1
11
INTRA ERRORS

0CC0531  2  ****** THIS CASE SHOWS A DOOR OR HATCH OR GATE OPENING ******
 CC0532     ****** CHECK YOUR DATA AND IF CORRECT, NOTIFY YOUR ZONE ******
 CC0533     DOOR LEFT FRONT IV05 equals 2 or IV06 equals 2 or IV07 equals 2
 CC0534     or IV08 equals 2 or IV09 equals 2.

0
OCCUPANT ASSESSMENT Vehicle: 1 Occupant: 1
11
INTRA ERRORS

0HH2961  2  If DAMAGE AIR BAG OA43 equals 02-95, then DID AIR BAG FAIL OA34
 HH2962     should equal 2.

HH3691   2  If SEAT BACK INCLINE OA53 equals 14, 23, or 31, then SEAT
HH3692      PERFORMANCE OA54 should equal 1.

011
INTER ERRORS

0GC0361  2  If BODY TYPE GV07 equals 04-06, 14-16, 20, 21 or 24, then TYPE
 GC0362     LEFT REAR IV18 should not equal 0. GV=02

GH0161   2  If TOTAL DELTA V GV59 is greater than or equal to 040, and less
GH0162      than 999, then RECORDED INJURIES OA70 should not equal 00.
GH0163      GV=02 OA=01

GH0161   2  If TOTAL DELTA V GV59 is greater than or equal to 040, and less
GH0162      than 999, then RECORDED INJURIES OA70 should not equal 00.
GH0163      GV=02 OA=02

01
```

PSU49 ERROR SUMMARY SCREEN [redacted]96
CASE 120A
CURRENT VERSION: 8.05

FORM NAME	NUMBER OF DOLLAR SIGNS	NUMBER OF LEVEL 1 ERRORS	NUMBER OF LEVEL 2 ERRORS	VERSION NUMBER CONSISTENT
Accident	0	0	0	Y
General Vehicle	0	0	1	Y
Vehicle Exterior	0	0	1	Y
Vehicle Interior	0	0	1	Y
Occupant Assessment	0	0	2	Y
Occupant Injury	0	0	0	Y
Total Inter Errors		0	3	
Total Case Errors	0	0	8	

U.S. Department of Transportation
National Highway Traffic Safety Administration

SLIDE INDEX

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Primary Sampling Unit Number 4 9 | Case Number—Stratum 120A

Slide No.	Vehicle No.	Direction of Picture	Description of Slide Subject Matter
1-7	1	N	Pre-impact direction of travel for V1.
8	1	N	Impact area of V1 with gouge.
9-10	1	N	Post impact direction of travel.
11-13	1	S	Opposite view pre-impact direction of travel.
14	1	S	Opposite view post-impact direction of travel.
15	1	N	View of LR curb impact from V1 at final rest - other marks on island from previous accident.
16-20	2	E	Pre-impact direction of travel.
21	2	W	Opposite view direction of travel.
22-23	2	E	Post-impact direction of travel to final rest.
24	2	W	Opposite view post-impact direction of travel.
25-26	3	W	Pre-impact direction of travel.
27	3	E	Opposite view direction of travel.
28-53	1		Exteriors of left front and left side damage.
54	1		View of front bumper cover - pavement marks from bumper folding under vehicle.
55	1		View of filler neck.
56	1		View of extrication mark on LF door.
57	1		View of LR tire and wheel.
58	1		View of LR hub - impacted curb.
59-60	1		Views of hatch latch failure.
61-72	1		Interiors.
73	1		Rear view of left side intrusion.
74-78	1		Views of driver air bag.
79-81	1		Views of small tears in drivers bag.
82-83	1		Views of air bag flaps.
84	1		Scuff on left door handle.
85	1		Hair on left roof side rail.
86	1		Scuffs on shoulder belt.

U.S. Department of Transportation
National Highway Traffic Safety Administration

SLIDE INDEX

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Primary Sampling Unit Number 4 9 | Case Number—Stratum 120A

Slide No.	Vehicle No.	Direction of Picture	Description of Slide Subject Matter
87-94	2		Exterior view of V2 under repair.
95-104	2		Interior views of V2.
105-108	2		Views of safety cage and storage shelves.
109-112	2		Views of driver air bag.
113	2		View of tether.
114-115	2		View of air bag flaps.
116	2		View of altered certification label. (missing)
117-131	3		Exterior views of left front and left side damage to V3.
132	3		View of front bumper - from V1 sliding across bumper and the left front impact.
133	3		View of left side damage to V3 from LR tire and wheel of V3.

PSU 49-120A (1995) #1

PSU 49-120A (1995) #2

PSU 49-120A (1995) #3

PSU 49-120A (1995) #4

PSU 49-120A (1995) #5

PSU 49-120A (1995) #6

PSU 49-120A (1995) #7

PSU 49-120A (1995) #8

PSU 49-120A (1995) #9

PSU 49-120A (1995) #10

PSU 49-120A (1995) #11

PSU 49-120A (1995) #12

PSU 49-120A (1995) #13

PSU 49-120A (1995) #14

PSU 49-120A (1995) #15

PSU 49-120A (1995) #16

PSU 49-120A (1995) #17

PSU 49-120A (1995) #18

PSU 49-120A (1995) #19

PSU 49-120A (1995) #20

PSU 49-120A (1995) #21

PSU 49-120A (1995) #22

PSU 49-120A (1995) #23

PSU 49-120A (1995) #24

PSU 49-120A (1995) #25

PSU 49-120A (1995) #26

PSU 49-120A (1995) #27

PSU 49-120A (1995) #28

PSU 49-120A (1995) #29



PSU 49-120A (1995) #30
Best Available



PSU 49-120A (1995) #31



PSU 49-120A (1995) #32



PSU 49-120A (1995) #33

PSU 49-120A (1995) #34

PSU 49-120A (1995) #35
Best Available

PSU 49-120A (1995) #36
Best Available

PSU 49-120A (1995) #37

PSU 49-120A (1995) #38



PSU 49-120A (1995) #39
Best Available

PSU 49-120A (1995) #40
Best Available

PSU 49-120A (1995) #41
Best Available

49-120A (1995) #42

PSU 49-120A (1995) #43

PSU 49-120A (1995) #44



PSU 49-120A (1995) #45

PSU 49-120A (1995) #46

PSU 49-120A (1995) #47

PSU 49-120A (1995) #48

PSU 49-120A (1995) #49

PSU 49-120A (1995) #50

PSU 49-120A (1995) #51

PSU 49-120A (1995) #52

PSU 49-120A (1995) #53

PSU 49-120A (1995) #54

PSU 49-120A (1995) #55
Best Available



PSU 49-120A (1995) #56

PSU 49-120A (1995) #57

PSU 49-120A (1995) #58

PSU 49-120A (1995) #59



PSU 49-120A (1995) #60

PSU 49-120A (1995) #61

PSU 49-120A (1995) #62

PSU 49-120A (1995) #63

PSU 49-120A (1995) #64

PSU 49-120A (1995) #65
Best Available

PSU 49-120A (1995) #66
Best Available

PSU 49-120A (1995) #67
Best Available

PSU 49-120A (1995) #68
Best Available

PSU 49-120A (1995) #69
Best Available

PSU 49-120A (1995) #70
Best Available

PSU 49-120A (1995) #71
Best Available

PSU 49-120A (1995) #72
Best Available

PSU 49-120A (1995) #73
Best Available

PSU 49-120A (1995) #74
Best Available

PSU 49-120A (1995) #75
Best Available

PSU 49-120A (1995) #76
Best Available

PSU 49-120A (1995) #77
Best Available



PSU 49-120A (1995) #78
Best Available



PSU 49-120A (1995) #79
Best Available



PSU 49-120A (1995) #80
Best Available



PSU 49-120A (1995) #81
Best Available

PSU 49-120A (1995) #82
Best Available

PSU 49-120A (1995) #83
Best Available

PSU 49-120A (1995) #84
Best Available

PSU 49-120A (1995) #85
Best Available

PSU 49-120A (1995) #86
Best Available

PSU 49-120A (1995) #87
Best Available

PSU 49-120A (1995) #88
Best Available

PSU 49-120A (1995) #89
Best Available

PSU 49-120A (1995) #90
Best Available

PSU 49-120A (1995) #91
Best Available

PSU 49-120A (1995) #92
Best Available

PSU 49-120A (1995) #93
Best Available

PSU 49-120A (1995) #94
Best Available

PSU 49-120A (1995) #95
Best Available

PSU 49-120A (1995) #96
Best Available

PSU 49-120A (1995) #97
Best Available

PSU 49-120A (1995) #98
Best Available

PSU 49-120A (1995) #99
Best Available

PSU 49-120A (1995) #100
Best Available

PSU 49-120A (1995) #101
Best Available

PSU 49-120A (1995) #102
Best Available

PSU 49-120A (1995) #103
Best Available

PSU 49-120A (1995) #104
Best Available



PSU 49-120A (1995) #105
Best Available

PSU 49-120A (1995) #106
Best Available

PSU 49-120A (1995) #107
Best Available

PSU 49-120A (1995) #108
Best Available



PSU 49-120A (1995) #109
Best Available

PSU 49-120A (1995) #110
Best Available



PSU 49-120A (1995) #111
Best Available

PSU 49-120A (1995) #112
Best Available

PSU 49-120A (1995) #113
Best Available

PSU 49-120A (1995) #114
Best Available

PSU 49-120A (1995) #115
Best Available

PSU NUMBER 49

CASE NUMBER 120A

SLIDES

THE FOLLOWING SLIDES ARE NOT INCLUDED IN THIS CASE:

SLIDE NUMBER (S) #16

PSU 49-120A (1995) #117

PSU 49-120A (1995) #118

PSU 49-120A (1995) #119



PSU 49-120A (1995) #120

PSU 49-120A (1995) #121

PSU 49-120A (1995) #122

PSU 49-120A (1995) #123

PSU 49-120A (1995) #124



PSU 49-120A (1995) #125



PSU 49-120A (1995) #126

PSU 49-120A (1995) #127
Best Available

PSU 49-120A (1995) #128
Best Available

PSU 49-120A (1995) #129
Best Available

PSU 49-120A (1995) #130

PSU 49-120A (1995) #131

PSU 49-120A (1995) #132

PSU 49-120A (1995) #133