GET A HOLD ON WINTER ALER

Remove snow and ice on roads by applying sand and salt.

Apply paint/sand mixtures to walkways, handrails and equipment ladders.

Keep walkways clear of snow and ice.

✓ Watch for highwall freeze and thaw, and thoroughly examine highwalls.

Conduct pre-operational checks of equipment.

Beware of vehicle fumes in enclosed cabs; examine exhaust systems for leaks.

✓ When working in confined spaces, ensure that there is proper ventilation.



Watch for Highwall freeze/thaw

KEEP WALKWAYS CLEAR OF SNOW AND ICE

VENTILATE CONFINED SPACES

www.msha.gov

KEEP ROADS CLEAN