



## SUPPORT AND CONTROL RIBS



## **Best Practices**

- Examine ribs often and whenever unusual rib hazards are encountered take additional measures such as bolting or screening the ribs.
- From a safe location pry down or control loose ribs or loose roof before any other work is performed.
- When mining conditions are not controlled by the current plan, the roof/rib control plan must be revised to protect the miners.



U.S. Dept. of Labor Mine Safety and Health Administration

www.msha.gov