

## UNITED STATES NUCLEAR REGULATORY COMMISSION

## REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-4005

August 30, 2004

Harold B. Ray, Executive Vice President San Onofre, Units 2 and 3 Southern California Edison Co. P.O. Box 128, Mail Stop D-3-F San Clemente, CA 92674-0128

SUBJECT: MIDCYCLE PERFORMANCE REVIEW AND INSPECTION PLAN - SAN ONOFRE NUCLEAR GENERATING STATION

Dear Mr. Rav:

On August 5, 2004, the NRC staff completed its midcycle plant performance assessment of the San Onofre Nuclear Generating Station. The midcycle review for the San Onofre Nuclear Generating Station involved the participation of all technical divisions in evaluating performance for the first half of the calendar year 2004 assessment cycle. The process included a review of performance indicators (PIs) for the most recent quarter and inspection results over the previous 12 months. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility so that you will have an opportunity to prepare for these inspections and to inform us of any planned inspections that may conflict with your plant activities.

This performance review and inspection plan does not include physical protection information. A separate letter designated and marked as "Exempt from Public Disclosure in Accordance with 10 CFR 2.390" will include the physical protection review and resultant inspection plan.

Plant performance for Unit 2 during the most recent quarter was within the Regulatory Response column of the NRC's Action Matrix based on a White performance indicator for Scrams with Loss of Normal Heat Removal (Initiating Events Cornerstone). This resulted from an automatic reactor trip during the second quarter of 2002 because of a main steam isolation signal, an automatic reactor trip during the fourth quarter of 2002 because of a low steam generator water level caused by a feedwater regulating valve failure, and a manual trip during the second quarter of 2004 because of a loss of main feedwater.

We plan to conduct a supplemental inspection during the fourth quarter of 2004 in accordance with NRC Inspection Procedure 95001, "Inspection for One or Two White Inputs in a Strategic Performance Area," to review the actions taken in response to this White performance indicator. The purpose of this supplemental inspection will be to provide assurance that the root and contributing causes for the White performance indicator are understood, to provide assurance that the extent of condition and extent of cause are identified, and to provide assurance that the corrective actions are sufficient to address the root and contributing causes to prevent their recurrence.

The enclosed inspection plan details the inspections, except those related to physical protection, scheduled through March 31, 2006. In addition to the baseline inspection program, Temporary Instruction 2515/150, "Reactor Pressure Vessel Head and Vessel Head Penetration Nozzles (NRC Bulletin 2002-02)," will be performed during this inspection cycle.

The inspection plan is provided to minimize the resource impact on your staff and to allow for scheduling conflicts and personnel availability to be resolved in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last 12 months of the inspection plan are tentative and may be revised at the end-of-cycle review meeting.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <a href="http://www.nrc.gov/reading-rm/adams.html">http://www.nrc.gov/reading-rm/adams.html</a> (the Public Electronic Reading Room).

If circumstances arise which cause us to change the inspection plan, we will contact you to discuss the change as soon as possible. Please contact Mr. Kriss Kennedy, Chief, Branch C, at (817) 860-8144 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

/RA/

Arthur T. Howell III, Director Division of Reactor Projects

Dockets: 50-361, 50-362 Licenses: NPF-10, NPF-15

Enclosure:

San Onofre Nuclear Generating Station Inspection/Activity Plan

CC:

Chairman, Board of Supervisors County of San Diego 1600 Pacific Highway, Room 335 San Diego, CA 92101

Gary L. Nolff
Power Projects/Contracts Manager
Riverside Public Utilities
2911 Adams Street
Riverside, CA 92504

Eileen M. Teichert, Esq. Supervising Deputy City Attorney City of Riverside 3900 Main Street Riverside, CA 92522

Joseph J. Wambold, Vice President Southern California Edison Company San Onofre Nuclear Generating Station P.O. Box 128 San Clemente, CA 92674-0128

David Spath, Chief
Division of Drinking Water and
Environmental Management
California Department of Health Services
P.O. Box 942732
Sacramento, CA 94234-7320

Michael R. Olson San Onofre Liaison San Diego Gas & Electric Company P.O. Box 1831 San Diego, CA 92112-4150

Ed Bailey, Chief Radiologic Health Branch State Department of Health Services P.O. Box 997414 (MS 7610) Sacramento, CA 95899-7414

Mayor City of San Clemente 100 Avenida Presidio San Clemente, CA 92672

James D. Boyd, Commissioner California Energy Commission 1516 Ninth Street (MS 34) Sacramento, CA 95814

Douglas K. Porter, Esq. Southern California Edison Company 2244 Walnut Grove Avenue Rosemead, CA 91770

## Southern California Edison Co.

-4-

Dwight E. Nunn, Vice President Southern California Edison Company San Onofre Nuclear Generating Station P.O. Box 128 San Clemente, CA 92674-0128

Dr. Raymond Waldo Southern California Edison Company San Onofre Nuclear Generating Station P. O. Box 128 San Clemente, CA 92674-0128

A. Edward Scherer Southern California Edison San Onofre Nuclear Generating Station P.O. Box 128 San Clemente, CA 92674-0128

Institute of Nuclear Power Operations (INPO) Records Center 700 Galleria Parkway SE, Suite 100 Atlanta, GA 30339

Southern California Ed	lison Co.	-5-					
Electronic distribution by RIV: Regional Administrator (BSM1) DRP Director (ATH) DRS Director (DDC) Senior Resident Inspector (CCO1) Branch Chief, DRP/C (KMK) Senior Project Engineer, DRP/C (WCW) Staff Chief, DRP/TS (PHH) RITS Coordinator (KEG) RidsNrrDipmLipb V. Dricks, PAO (VLD) W. Maier, RSLO (WAM) C. Gordon (CJG) DRS Branch Chiefs (LJS, MPS1, ATG, JAC) L. Reyes, EDO (LAR1) S. Richards, Chief, NRR/DIPM/IIPB (SAR) R. Frahm, PRR Program Manager, NRR/DIPM/IIPB (RKF) C. Carpenter, Deputy Dir. for Inspection and Programs (CAC) B. Sheron, Associate Dir. for Project Licensing and Technical Analysis (BWS) T. Bergman, Chief, ROPMS, OEDO (TAB) H. Berkow, Director, LPD4, NRR/DLPM (HNB) S. Dembek, Chief, PDIV-2B, NRR/DLPM (SXD) B. Pham, NRR Project Manager (BMP)							
√ Publicly Available □ Non-Publicly Available □ Sensitive √ Non-Sensitive							
S:\DRP\DRPDIR\MIDCYCLE 2004\SONGS.wpd							
RIV:DRP/PE/C	C:DRP/C	D:DRS	D:DRP				
RVAzua;mjs	KMKennedy	DDChamberlain	ATHowell				
/RA/	WCWalker for	VLOrdaz for	/RA/				
8/13/04	8/18/04	8/25/04	8/28/04				

Page 1 of 2 08/27/2004 07:52:13

## San Onofre Inspection / Activity Plan 08/01/2004 - 03/31/2006

Report 22

PEB-05T - TRIENNIAL FIRE PROTECTION INSPECTION   5	Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Start	d Dates End	Inspection Type
Packar   P	Number				Start	Liiu	Туре
ALARA   ALARA PLANNING AND CONTROLS   1				5			
Parameter   Para	2, 3				08/09/2004	08/20/2004	Baseline Inspections
PEB-52   BIENNIAL PIR				1			
P   11   12   I dentification and Resolution of Problems   P   13   13   13   13   13   13   13	2, 3		· ·		08/02/2004	08/06/2004	Baseline Inspections
BB-08				4		00/01/0001	5 "
1	2, 3			_	09/13/2004	09/24/2004	Baseline Inspections
1				2			
Ti-150			·				Baseline Inspections
3	3		·		10/18/2004	10/22/2004	Baseline Inspections
TI-153			AND VESSEL HEAD PENET. NOZZLES	1			
10/08/2004   11/11/2004   11/	3		•		10/05/2004	11/03/2004	Safety Issues
DB-INIT		TI-153 - TEM		1			
2	3				10/08/2004	11/11/2004	Safety Issues
3		OB-INIT - INITIA	AL EXAM	4			
2	2	X02279	SONGS UNIT 2 (11/04) INITIAL EXAM		04/04/2005	04/08/2005	Not Applicable
Note	3	X02280	SONGS UNIT 3 (11/04) - INITIAL EXAM		04/04/2005	04/08/2005	Not Applicable
ALARA2	2	X02279	SONGS UNIT 2 (11/04) INITIAL EXAM		04/25/2005	04/29/2005	Not Applicable
2,3	3	X02280	SONGS UNIT 3 (11/04) - INITIAL EXAM		04/25/2005	04/29/2005	Not Applicable
DB-INIT		ALARA2 - ALAF	RA PLANNING AND CONTROLS	1			
2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/03/2005       10/07/2005       Not Applicable         3       X02290       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/03/2005       10/07/2005       Not Applicable         2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/24/2005       10/28/2005       Not Applicable         2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/31/2005       11/11/2005       Not Applicable         2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/31/2005       11/11/2005       Not Applicable         2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/31/2005       11/11/2005       Not Applicable         2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/31/2005       11/11/2005       Not Applicable         2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/31/2005       11/11/2005       Not Applicable         2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/31/2005       11/11/2005       Not Applicable         2       Y02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/31/2005       03/18/2005       Baseline Inspections         3       IP 7111201       Access Control to Radiologically Significant Areas	2, 3	IP 7112102	ALARA Planning and Controls		01/10/2005	01/14/2005	Baseline Inspections
3       X02290       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/03/2005       10/07/2005       Not Applicable         2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/24/2005       10/28/2005       Not Applicable         3       X02290       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/24/2005       10/28/2005       Not Applicable         2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/31/2005       11/11/2005       Not Applicable         2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/31/2005       11/11/2005       Not Applicable         2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/31/2005       11/11/2005       Not Applicable         2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/31/2005       11/11/2005       Not Applicable         2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       1       10/31/2005       Not Applicable         2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       1       10/31/2005       Baseline Inspections         3       IP 7112101       Access Control S RACESS CONTROLS TO RAD SIGNIFICANT AREAS       3       0       0       0       0       0       0       0       0       0       0       0 <td></td> <td>OB-INIT - INITIA</td> <td>AL EXAM</td> <td>4</td> <td></td> <td></td> <td></td>		OB-INIT - INITIA	AL EXAM	4			
2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/24/2005       10/28/2005       Not Applicable         3       X02290       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/24/2005       10/28/2005       Not Applicable         2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/31/2005       11/11/2005       Not Applicable         ACRSA       - ACCESS CONTROLS TO RAD SIGNIFICANT AREAS       1         2,3       IP 7112101       Access Control to Radiologically Significant Areas       03/14/2005       03/18/2005       Baseline Inspections         0B-EP EX       - EMERGENCY PREPAREDNESS EXERCISE       3         2,3       IP 7111401       Exercise Evaluation       04/11/2005       04/15/2005       Baseline Inspections         2,3       IP 7111404       Emergency Action Level and Emergency Plan Changes       04/11/2005       04/15/2005       Baseline Inspections         2,3       IP 71151       Performance Indicator Verification       04/11/2005       04/15/2005       Baseline Inspections         0B-RQ       - REQUAL INSPECTION       2	2	X02289	SONGS UNIT 2 (07/05) - INITIAL EXAM		10/03/2005	10/07/2005	Not Applicable
3 X02290 SONGS UNIT 2 (07/05) - INITIAL EXAM 2 X02289 SONGS UNIT 2 (07/05) - INITIAL EXAM 4 ACRSA - ACCESS CONTROLS TO RAD SIGNIFICANT AREAS 3 IP 7112101 Access Control to Radiologically Significant Areas 6 OB-EP EX - EMERGENCY PREPAREDNESS EXERCISE 7 SIP 7111401 Exercise Evaluation 7 Service Evaluation 8 Service Evaluation 9 Service Evaluatio	3	X02290	SONGS UNIT 2 (07/05) - INITIAL EXAM		10/03/2005	10/07/2005	Not Applicable
2       X02289       SONGS UNIT 2 (07/05) - INITIAL EXAM       10/31/2005       11/11/2005       Not Applicable         ACRSA       - ACCESS CONTROLS TO RAD SIGNIFICANT AREAS       1         2,3       IP 7112101       Access Control to Radiologically Significant Areas       03/14/2005       03/18/2005       Baseline Inspections         0B-EP EX       - EMERGENCY PREPAREDNESS EXERCISE       3         2,3       IP 7111401       Exercise Evaluation       04/11/2005       04/15/2005       Baseline Inspections         2,3       IP 7111404       Emergency Action Level and Emergency Plan Changes       04/11/2005       04/15/2005       Baseline Inspections         2,3       IP 71151       Performance Indicator Verification       04/11/2005       04/15/2005       Baseline Inspections         0B-RQ       - REQUAL INSPECTION       2	2	X02289	SONGS UNIT 2 (07/05) - INITIAL EXAM		10/24/2005	10/28/2005	Not Applicable
ACRSA - ACCESS CONTROLS TO RAD SIGNIFICANT AREAS  2, 3 IP 7112101 Access Control to Radiologically Significant Areas  OB-EP EX - EMERGENCY PREPAREDNESS EXERCISE  2, 3 IP 7111401 Exercise Evaluation  2, 3 IP 7111404 Emergency Action Level and Emergency Plan Changes  2, 3 IP 71151 Performance Indicator Verification  OB-RQ - REQUAL INSPECTION  1 03/14/2005 03/18/2005 Baseline Inspections  04/11/2005 04/15/2005 Baseline Inspections 04/11/2005 04/15/2005 Baseline Inspections	3	X02290	SONGS UNIT 2 (07/05) - INITIAL EXAM		10/24/2005	10/28/2005	Not Applicable
2,3 IP 7112101 Access Control to Radiologically Significant Areas  OB-EP EX - EMERGENCY PREPAREDNESS EXERCISE  2,3 IP 7111401 Exercise Evaluation  2,3 IP 7111404 Emergency Action Level and Emergency Plan Changes  2,3 IP 71151 Performance Indicator Verification  OB-RQ - REQUAL INSPECTION  O3/14/2005 O3/18/2005 Baseline Inspections  04/11/2005 O4/15/2005 Baseline Inspections  04/11/2005 O4/15/2005 Baseline Inspections	2	X02289	SONGS UNIT 2 (07/05) - INITIAL EXAM		10/31/2005	11/11/2005	Not Applicable
OB-EP EX         - EMERGENCY PREPAREDNESS EXERCISE         3           2,3         IP 7111401         Exercise Evaluation         04/11/2005         04/15/2005         Baseline Inspections           2,3         IP 7111404         Emergency Action Level and Emergency Plan Changes         04/11/2005         04/15/2005         Baseline Inspections           2,3         IP 71151         Performance Indicator Verification         04/11/2005         04/15/2005         Baseline Inspections           OB-RQ         - REQUAL INSPECTION         2		ACRSA - ACCI	ESS CONTROLS TO RAD SIGNIFICANT AREAS	1			
2,3 IP 7111401 Exercise Evaluation 04/11/2005 04/15/2005 Baseline Inspections 2,3 IP 7111404 Emergency Action Level and Emergency Plan Changes 04/11/2005 04/15/2005 Baseline Inspections 04/11/2005 04/15/2005 Baseline Inspections 04/11/2005 04/15/2005 Baseline Inspections 08-RQ - REQUAL INSPECTION	2, 3	IP 7112101	Access Control to Radiologically Significant Areas		03/14/2005	03/18/2005	Baseline Inspections
2,3 IP 7111404 Emergency Action Level and Emergency Plan Changes  2,3 IP 711151 Performance Indicator Verification  OB-RQ - REQUAL INSPECTION  04/11/2005 04/15/2005 Baseline Inspections		OB-EP EX - EMEI	RGENCY PREPAREDNESS EXERCISE	3			
2,3 IP 71151 Performance Indicator Verification 04/11/2005 04/15/2005 Baseline Inspections OB-RQ - REQUAL INSPECTION 2	2, 3	IP 7111401	Exercise Evaluation		04/11/2005	04/15/2005	Baseline Inspections
OB-RQ - REQUAL INSPECTION 2	2, 3	IP 7111404	Emergency Action Level and Emergency Plan Changes		04/11/2005	04/15/2005	Baseline Inspections
OB-RQ - REQUAL INSPECTION 2	2, 3	IP 71151	Performance Indicator Verification		04/11/2005	04/15/2005	Baseline Inspections
		OB-RQ - REQI	UAL INSPECTION	2			·
2,0 ii 7111111 Licensed Operator requalification i rogram	2, 3	IP 7111111B	Licensed Operator Requalification Program		09/26/2005	09/30/2005	Baseline Inspections

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.

Page 2 of 2

08/27/2004

07:52:13

San Onofre Inspection / Activity Plan 08/01/2004 - 03/31/2006

Report 22

Unit				No. of Staff	Planne	d Dates	Inspection
Number	Inspection	Activity	Title	on Site	Start	End	Туре
	PEB-07B	- HX PE	RFORMANCE	1			
2, 3	IP 71111	07B	Heat Sink Performance		10/03/2005	10/07/2005	Baseline Inspections
	EB08P	- ISI U2	- VESS VOL (T1 150/152) AS REQ	1			
2	IP 71111	08P	Inservice Inspection Activities - PWR		11/14/2005	11/18/2005	Baseline Inspections
2	IP 71111	08P	Inservice Inspection Activities - PWR		11/28/2005	12/02/2005	Baseline Inspections
	ALARA3	- ALARA	A PLANNING AND CONTROLS	1			
2, 3	IP 71121	02	ALARA Planning and Controls		12/05/2005	12/09/2005	Baseline Inspections
	EP2	- EMER	G PREPAREDNESS PROGRAM INSPECTION	1			
2, 3	IP 71114	02	Alert and Notification System Testing		02/13/2006	02/17/2006	Baseline Inspections
2, 3	IP 71114	03	Emergency Response Organization Augmentation Testing		02/13/2006	02/17/2006	Baseline Inspections
2, 3	IP 71114	04	Emergency Action Level and Emergency Plan Changes		02/13/2006	02/17/2006	Baseline Inspections
2, 3	IP 71114	05	Correction of Emergency Preparedness Weaknesses and Deficiencies		02/13/2006	02/17/2006	Baseline Inspections
2, 3	IP 71151		Performance Indicator Verification		02/13/2006	02/17/2006	Baseline Inspections