

Non- NASA

ANSI ASQC Q9001-2000, American National Standard, Quality Systems – Model for Quality Assurance in Design and Development, Production, Installation, and Servicing, R2000.

ANSI/ESD S20.20-1999, Protection of Electrical and Electronic Parts, Assemblies and Equipment (Excluding Electrically Initiated Explosive Devices), 08/1999.

ANSI/NCSL Z540-1, General Requirements for Calibration Laboratories and Measuring and Test Equipment, R2002.

ISO/IEC 17025, General requirements for the Competence of Testing and Calibration Laboratories, 12/1999.

ISO 10012, Quality Assurance Requirements for Measuring Equipment, 04/2003.

OSHA TED 8.4, Voluntary Protection Program (VPP) Policies and Procedures Manual, 03/2003.

ISO VIM, International vocabulary of basic and general terms in metrology, 12/1999.

JSC

EM-002.12 General Operating Procedures for Bldg 15, 03/2000.

ES-CWI-006.32 IM&TE User Instructions for MSCL Calibration, 12/2002.

ES-CWI-006.33 IM&TE User Calibration Instructions, 12/2002.

JB15W-20 Management of Controlled Equipment, 06/2002.

JPD 5335.1 Quality Policy, 01/2003.

JPD 5335.3A JSC Quality Manual, 06/2002.

JPD 8800.7 JSC Environmental Policy, 01/1999.

JPG 1440.3 JSC Files and Records Management Procedures, 08/2001.

JPG 1700.1I JSC Safety and Health Handbook, 07/2002.

JHB 1710.13, Design, Inspection, and Certification of Pressure Vessels and Pressurized Systems, 03/1994.

JPD 2800.4 Johnson Space Center Information Technology (IT) Program Management, 03/2001.

JPG 2810.1 Johnson Space Center Information Technology Security Handbook, 10/2001.

JPG 5151.2 JSC Support Contractor Procedures & Guidelines, 07/1998.

JPR 5335.3 Quality Manual, 01/2004.

JHB 8800.6, Asbestos Control Manual, 04/1992.

JSC 05900 JSC Emergency Preparedness Plan, 06/2002.

JSC 26549 Manual for the Control of Program Stock, 02/2001.

JSC-SLP-4.5-1 Document and Data Control, 01/2003.

JSC-SLP-4.5-3 Preparation of Common Work Instructions, 08/1998.

JSC-SLP-4.11 Control of Monitoring and Measuring Devices, 12/2002.

JSC-SLP-4.13 Control of Nonconforming Product, 12/2000.

NT-CWI-003, Quality Assurance Record Center Discrepancy Reporting and Tracking, 03/2002

SOP-002.6 Control of Hazardous Energy (Lockout Tag out), 08/2002.

SOP-002.11 General Operating Procedures for Bldg 343, 07/2002.

SOP-006.31 MSCL Standard Operating Instructions, 01/2003.

SOP-006.35 MSCL Calibration Processes in Clean/Oxygen Environments, 07/2002.

SOP-008.1 Training and Certification of Personnel, 07/2002.

SOP-008.2 Preparation and Revision of Training Instructions (TIs), 07/2002.

NASA Non- JSC

NPR 1441.1 NASA Records Retention Schedule, 02/2003.

NPR 4100.1D NASA Materials Inventory Management Manual, 07/1999.

NPR 4200.1E, NASA Equipment Management Manual, 07/1999.

NPR 4200.2, NASA Equipment Management Manual for Property Custodians, 09/1998.

NPD 2820.1, NASA Software Policies, 05/1998.

NPD 8730.1A, Metrology and Calibration, 08/2003.

NPR 7120.5 Program and Project Management Processes and Requirements, 11/2002.