

Table 8. Movements of Natural Gas by State, 1967-2000
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1967						
Alabama	2,509,299	2,254,258	255,041	0	0	0
Arizona	1,316,669	1,154,223	162,446	0	3,716	-3,716
Arkansas	2,457,182	2,259,392	197,790	0	0	0
California	1,329,287	0	1,329,287	0	0	0
Colorado	218,751	93,325	125,426	0	0	0
Connecticut	135,569	83,826	51,743	0	0	0
D.C.	a	a	a	a	a	a
Delaware	23,389	1,518	21,871	0	0	0
Florida	227,439	0	227,439	0	0	0
Georgia	1,055,687	797,663	258,024	0	0	0
Idaho	69,417	288,469	-219,052	253,707	0	253,707
Illinois	2,163,355	1,152,186	1,011,169	0	0	0
Indiana	1,813,968	1,371,265	442,703	0	0	0
Iowa	1,173,314	882,504	290,810	0	0	0
Kansas	1,693,221	2,083,980	-390,759	0	0	0
Kentucky	3,083,696	2,962,722	120,974	0	0	0
Louisiana ^b	1,237,137	5,383,284	-4,146,147	0	0	0
Maine ^a	6,391	0	6,391	613	0	613
Maryland	693,372	543,626	149,746	0	0	0
Massachusetts	143,318	12,682	130,636	0	0	0
Michigan	698,475	0	698,475	0	40,418	-40,418
Minnesota	304,672	105,102	199,570	83,718	0	83,718
Mississippi	4,980,531	4,833,931	146,600	0	0	0
Missouri	1,661,867	1,291,995	369,872	0	0	0
Montana	35,750	11,389	24,361	30,769	106	30,663
Nebraska	1,156,110	973,066	183,044	0	0	0
Nevada	35,627	0	35,627	0	0	0
New Hampshire	b	b	b	b	b	b
New Jersey	673,228	420,719	252,509	0	0	0
New Mexico	623,090	1,376,027	-752,937	0	0	0
New York	840,028	222,877	617,151	4,020	29,932	-25,912
North Carolina	673,861	574,676	99,185	0	0	0
North Dakota	6,374	9,512	-3,138	0	0	0
Ohio	2,553,517	1,628,374	925,143	0	0	0
Oklahoma	1,054,717	1,936,297	-881,580	0	0	0
Oregon	276,786	205,166	71,620	0	0	0
Pennsylvania	1,826,672	1,209,168	617,504	0	0	0
Rhode Island	88,523	69,418	19,105	0	0	0
South Carolina	778,373	673,861	104,512	0	0	0
South Dakota	28,868	1,004	27,864	0	0	0
Tennessee	3,312,635	3,074,312	238,323	0	0	0
Texas	272,830	3,520,811	-3,247,981	50,971	7,442	43,529
Utah	199,031	138,978	60,053	0	0	0
Vermont	b	b	b	b	b	b
Virginia	795,107	680,254	114,853	0	0	0
Washington	254,223	264,821	-10,598	140,428	0	140,428
West Virginia	1,090,403	1,124,633	-34,230	0	0	0
Wisconsin	267,045	14,142	252,903	0	0	0
Wyoming	77,441	230,789	-153,348	0	0	0
Total	45,916,245	45,916,245	0	564,226	81,614	482,612

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1968						
Alabama	2,929,775	2,641,104	288,671	0	0	0
Arizona	1,377,431	1,197,090	180,341	0	3,891	-3,891
Arkansas	2,505,614	2,329,995	175,619	0	0	0
California	1,416,580	0	1,416,580	0	0	0
Colorado	250,125	105,486	144,639	0	0	0
Connecticut	142,353	87,094	55,259	0	0	0
D.C.	a	a	a	a	a	a
Delaware	26,095	1,750	24,345	0	0	0
Florida	277,626	0	277,626	0	0	0
Georgia	1,208,829	917,165	291,664	0	0	0
Idaho	85,879	337,505	-251,626	291,801	0	291,801
Illinois	2,144,948	1,066,373	1,078,575	0	0	0
Indiana	1,754,225	1,288,462	465,763	0	0	0
Iowa	1,240,460	935,395	305,065	0	0	0
Kansas	1,841,240	2,129,987	-288,747	0	0	0
Kentucky ^b	3,340,555	3,215,291	125,264	0	0	0
Louisiana ^a	1,219,066	5,941,616	-4,722,550	0	0	0
Maine	7,091	1,403	5,688	1,452	0	1,452
Maryland	766,725	610,974	155,751	0	0	0
Massachusetts	150,594	13,703	136,891	0	0	0
Michigan	742,934	1	742,933	0	68,044	-68,044
Minnesota	332,984	142,839	190,145	120,862	0	120,862
Mississippi	5,515,327	5,338,335	176,992	0	0	0
Missouri	1,611,649	1,246,146	365,503	0	0	0
Montana	30,124	12,281	17,843	36,635	104	36,531
Nebraska	1,229,265	1,031,229	198,036	0	0	0
Nevada	37,376	0	37,376	0	0	0
New Hampshire	b	b	b	b	b	b
New Jersey	741,435	460,243	281,192	0	0	0
New Mexico	689,089	1,537,473	-848,384	0	0	0
New York	885,390	228,565	656,825	4,869	13,499	-8,630
North Carolina	763,794	648,101	115,693	0	0	0
North Dakota	7,191	9,350	-2,159	0	0	0
Ohio	2,672,596	1,712,919	959,677	0	0	0
Oklahoma	1,293,066	2,119,168	-826,102	0	0	0
Oregon	320,466	240,631	79,835	0	0	0
Pennsylvania	1,891,020	1,222,364	668,656	0	0	0
Rhode Island	92,031	70,649	21,382	0	0	0
South Carolina	895,084	763,794	131,290	0	0	0
South Dakota	30,409	1,149	29,260	0	0	0
Tennessee	3,574,364	3,332,244	242,120	0	0	0
Texas	388,348	3,750,818	-3,362,470	47,423	8,206	39,217
Utah	229,148	161,188	67,960	0	0	0
Vermont	b	b	b	b	b	b
Virginia	868,322	745,344	122,978	0	0	0
Washington	290,442	298,511	-8,069	148,843	0	148,843
West Virginia	1,299,699	1,345,085	-45,386	0	0	0
Wisconsin	292,179	15,733	276,446	0	0	0
Wyoming	93,424	247,815	-154,391	0	0	0
Total	49,502,367	49,502,367	0	651,885	93,745	558,140

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1969						
Alabama	3,162,432	2,863,081	299,351	0	0	0
Alaska.....	0	0	0	0	2,982	-2,982
Arizona	1,421,296	1,222,800	198,496	0	3,880	-3,880
Arkansas	2,711,753	2,519,758	191,995	0	0	0
California	1,452,623	0	1,452,623	0	0	0
Colorado.....	253,398	89,723	163,675	0	0	0
Connecticut	148,570	89,137	59,433	0	0	0
D.C.	a	a	a	a	a	a
Delaware	27,559	1,922	25,637	0	0	0
Florida	314,216	0	314,216	0	0	0
Georgia.....	1,333,701	1,016,515	317,186	0	0	0
Idaho	90,641	360,618	-269,977	312,096	0	312,096
Illinois	2,230,926	1,073,480	1,157,446	0	0	0
Indiana.....	1,802,014	1,254,114	547,900	0	0	0
Iowa.....	1,296,021	973,565	322,456	0	0	0
Kansas	1,956,738	2,251,021	-294,283	0	0	0
Kentucky ^b	3,658,171	3,480,571	177,600	0	0	0
Louisiana ^a	1,278,995	6,522,705	-5,243,710	0	0	0
Maine.....	9,482	1,887	7,595	2,095	0	2,095
Maryland	830,054	661,936	168,118	0	0	0
Massachusetts	159,908	21,537	138,371	0	0	0
Michigan	776,010	5	776,005	0	29,765	-29,765
Minnesota.....	345,279	156,936	188,343	137,687	0	137,687
Mississippi.....	6,062,845	5,860,437	202,408	0	0	0
Missouri.....	1,706,524	1,308,335	398,189	0	0	0
Montana	31,347	20,677	10,670	39,830	112	39,718
Nebraska	1,276,838	1,073,502	203,336	0	0	0
Nevada.....	44,899	0	44,899	0	0	0
New Hampshire.....	b	b	b	b	b	b
New Jersey	801,428	484,644	316,784	0	0	0
New Mexico.....	745,257	1,564,480	-819,223	0	0	0
New York.....	920,580	229,149	691,431	16,460	5,054	11,406
North Carolina	848,423	710,066	138,357	0	0	0
North Dakota	12,823	8,383	4,440	0	0	0
Ohio.....	2,830,201	1,846,031	984,170	0	0	0
Oklahoma	1,376,159	2,263,047	-886,888	0	0	0
Oregon	350,678	260,308	90,370	0	0	0
Pennsylvania	2,022,425	1,291,854	730,571	0	0	0
Rhode Island	94,348	71,218	23,130	0	0	0
South Carolina	994,488	848,423	146,065	0	0	0
South Dakota	36,258	1,286	34,972	0	0	0
Tennessee	3,921,292	3,657,812	263,480	0	0	0
Texas.....	438,448	3,983,752	-3,545,304	46,845	9,511	37,334
Utah.....	220,174	141,310	78,864	0	0	0
Vermont.....	b	b	b	b	b	b
Virginia	957,370	823,196	134,174	0	0	0
Washington	315,872	341,012	-25,140	171,938	0	171,938
West Virginia	1,356,800	1,408,566	-51,766	0	0	0
Wisconsin.....	336,019	17,888	318,131	0	0	0
Wyoming	74,071	258,667	-184,596	0	0	0
Total	53,035,354	53,035,354	0	726,951	51,304	675,647

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1970						
Alabama	3,331,382	3,036,629	294,753	0	0	0
Alaska.....	0	0	0	0	44,257	-44,257
Arizona	1,501,765	1,303,743	198,022	0	4,044	-4,044
Arkansas	2,875,836	2,658,022	217,814	0	0	0
California	1,566,146	0	1,566,146	0	0	0
Colorado.....	300,071	120,686	179,385	0	0	0
Connecticut	159,916	97,541	62,375	0	0	0
D.C.	a	a	a	a	a	a
Delaware	28,913	2,014	26,899	0	0	0
Florida	335,829	0	335,829	0	0	0
Georgia.....	1,451,528	1,114,192	337,336	0	0	0
Idaho	108,518	414,340	-305,822	353,640	0	353,640
Illinois	2,368,114	1,099,907	1,268,207	0	0	0
Indiana.....	1,905,929	1,344,232	561,697	0	0	0
Iowa.....	1,385,306	1,023,394	361,912	0	0	0
Kansas	2,106,380	2,375,467	-269,087	0	0	0
Kentucky ^b	3,841,778	3,653,585	188,193	0	0	0
Louisiana ^a	1,242,036	6,911,945	-5,669,909	0	0	0
Maine.....	10,269	1,916	8,353	2,532	0	2,532
Maryland	893,459	705,782	187,677	0	0	0
Massachusetts	183,981	36,489	147,492	757	0	757
Michigan	791,773	0	791,773	0	10,643	-10,643
Minnesota.....	354,694	181,757	172,937	172,219	0	172,219
Mississippi.....	6,427,316	6,179,522	247,794	0	0	0
Missouri.....	1,729,750	1,292,000	437,750	0	0	0
Montana	47,619	27,303	20,316	42,560	109	42,451
Nebraska	1,401,041	1,197,396	203,645	0	0	0
Nevada.....	53,293	0	53,293	0	0	0
New Hampshire.....	b	b	b	b	b	b
New Jersey	850,669	516,649	334,020	0	0	0
New Mexico.....	897,381	1,707,781	-810,400	0	0	0
New York.....	946,097	244,902	701,195	33,638	126	33,512
North Carolina	928,285	773,117	155,168	0	0	0
North Dakota	8,899	7,264	1,635	0	0	0
Ohio.....	2,922,669	1,927,523	995,146	0	0	0
Oklahoma.....	1,544,187	2,454,115	-909,928	0	0	0
Oregon	395,557	296,839	98,718	0	0	0
Pennsylvania.....	2,107,804	1,344,650	763,154	0	0	0
Rhode Island	102,880	76,820	26,060	0	0	0
South Carolina	1,092,190	928,285	163,905	0	0	0
South Dakota	46,551	9,392	37,159	0	0	0
Tennessee	4,104,085	3,840,823	263,262	0	0	0
Texas.....	513,070	4,288,792	-3,775,722	41,336	10,634	30,702
Utah.....	261,741	179,333	82,408	0	0	0
Vermont.....	b	b	b	b	b	b
Virginia	1,022,945	883,702	139,243	0	0	0
Washington	359,646	376,204	-16,558	174,098	0	174,098
West Virginia	1,374,977	1,391,586	-16,609	0	0	0
Wisconsin.....	369,637	20,620	349,017	0	0	0
Wyoming	87,625	293,278	-205,653	0	0	0
Total	56,339,537	56,339,537	0	820,780	69,813	750,967

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1971						
Alabama	3,324,993	3,045,698	279,295	0	0	0
Alaska.....	0	0	0	0	50,231	-50,231
Arizona	1,539,074	1,317,932	221,142	0	4,659	-4,659
Arkansas	2,886,765	2,703,083	183,682	0	0	0
California	1,611,970	0	1,611,970	0	0	0
Colorado.....	307,246	119,777	187,469	0	0	0
Connecticut	160,212	97,323	62,889	0	0	0
D.C.	a	a	a	a	a	a
Delaware	28,938	2,006	26,932	0	0	0
Florida	336,912	0	336,912	0	0	0
Georgia.....	1,451,190	1,097,561	353,629	0	0	0
Idaho	99,370	453,035	-353,665	405,219	0	405,219
Illinois	2,537,661	1,199,376	1,338,285	0	0	0
Indiana.....	2,074,282	1,494,970	579,312	0	0	0
Iowa.....	1,377,917	1,022,972	354,945	0	0	0
Kansas	2,148,750	2,370,594	-221,844	0	0	0
Kentucky ^b	4,007,330	3,810,758	196,572	0	0	0
Louisiana ^a	1,140,338	7,050,301	-5,909,963	0	0	0
Maine.....	9,615	0	9,615	2,820	0	2,820
Maryland	887,732	693,404	194,328	0	0	0
Massachusetts	191,598	36,071	155,527	2,933	0	2,933
Michigan	839,385	0	839,385	0	14,236	-14,236
Minnesota.....	350,115	239,456	110,659	249,935	0	249,935
Mississippi.....	6,622,133	6,350,901	271,232	0	0	0
Missouri.....	1,709,375	1,273,536	435,839	0	0	0
Montana	41,167	18,851	22,316	44,647	113	44,534
Nebraska	1,430,865	1,218,806	212,059	0	0	0
Nevada.....	67,965	0	67,965	0	0	0
New Hampshire.....	b	b	b	b	b	b
New Jersey	853,285	511,779	341,506	0	0	0
New Mexico.....	941,843	1,774,348	-832,505	0	0	0
New York.....	985,603	254,365	731,238	19,171	0	19,171
North Carolina	916,766	752,345	164,421	0	0	0
North Dakota	10,540	6,618	3,922	0	0	0
Ohio.....	3,098,756	2,064,911	1,033,845	0	0	0
Oklahoma.....	1,535,753	2,517,696	-981,943	0	0	0
Oregon	443,716	340,884	102,832	0	0	0
Pennsylvania.....	2,155,052	1,390,196	764,856	0	0	0
Rhode Island	102,544	76,838	25,706	0	0	0
South Carolina	1,076,171	916,766	159,405	0	0	0
South Dakota	36,607	4,613	31,994	0	0	0
Tennessee	4,287,786	4,014,046	273,740	0	0	0
Texas.....	546,074	4,206,222	-3,660,148	20,689	10,973	9,716
Utah.....	261,708	176,992	84,716	0	0	0
Vermont.....	b	b	b	b	b	b
Virginia	1,024,162	876,573	147,589	0	0	0
Washington	403,190	431,704	-28,514	189,134	0	189,134
West Virginia	1,456,042	1,491,297	-35,255	0	0	0
Wisconsin.....	409,134	60,039	349,095	0	0	0
Wyoming	97,716	340,703	-242,987	0	0	0
Total	57,825,346	57,825,346	0	934,548	80,212	854,336

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1972						
Alabama	3,280,337	2,999,002	281,335	0	0	0
Alaska.....	0	0	0	0	47,882	-47,882
Arizona	1,697,235	1,460,502	236,733	0	4,521	-4,521
Arkansas	2,862,507	2,687,122	175,385	0	0	0
California	1,778,649	0	1,778,649	0	0	0
Colorado.....	330,661	126,293	204,368	0	0	0
Connecticut	162,824	95,939	66,885	0	0	0
D.C.	a	a	a	a	a	a
Delaware	25,962	1,966	23,996	0	0	0
Florida	287,250	0	287,250	0	0	0
Georgia.....	1,400,727	1,064,294	336,433	0	0	0
Idaho	81,015	455,378	-374,363	434,836	0	434,836
Illinois	2,470,725	1,201,533	1,269,192	0	0	0
Indiana.....	2,106,027	1,517,039	588,988	0	0	0
Iowa.....	1,402,943	1,052,903	350,040	0	0	0
Kansas	2,194,730	2,411,550	-216,820	0	0	0
Kentucky ^b	3,967,250	3,750,891	216,359	0	0	0
Louisiana ^a	1,247,034	7,069,882	-5,822,848	0	0	0
Maine.....	10,282	0	10,282	3,745	0	3,745
Maryland	882,661	670,572	212,089	0	0	0
Massachusetts	189,487	25,033	164,454	2,262	0	2,262
Michigan	823,515	0	823,515	0	15,426	-15,426
Minnesota.....	334,609	235,116	99,493	256,856	0	256,856
Mississippi.....	6,582,428	6,222,130	360,298	0	0	0
Missouri.....	1,717,673	1,282,951	434,722	0	0	0
Montana	18,112	12,363	5,749	48,589	127	48,462
Nebraska	1,458,769	1,220,005	238,764	0	0	0
Nevada.....	71,214	0	71,214	0	0	0
New Hampshire.....	b	b	b	b	b	b
New Jersey	828,129	495,237	332,892	0	0	0
New Mexico.....	1,036,716	1,902,655	-865,939	0	0	0
New York.....	940,149	265,808	674,341	9,571	0	9,571
North Carolina	893,642	725,356	168,286	0	0	0
North Dakota	17,739	9,401	8,338	0	0	0
Ohio.....	2,995,531	1,947,957	1,047,574	0	0	0
Oklahoma	1,422,394	2,531,603	-1,109,209	0	0	0
Oregon	487,064	371,989	115,075	0	0	0
Pennsylvania.....	2,074,454	1,307,827	766,627	0	0	0
Rhode Island	101,359	77,868	23,491	0	0	0
South Carolina	1,044,679	893,642	151,037	0	0	0
South Dakota	36,164	1,351	34,813	0	0	0
Tennessee	4,259,140	3,975,797	283,343	0	0	0
Texas.....	550,684	4,290,834	-3,740,150	8,141	10,057	-1,916
Utah.....	236,460	135,143	101,317	0	0	0
Vermont.....	b	b	b	b	b	b
Virginia	1,028,270	870,773	157,497	0	0	0
Washington	426,649	499,728	-73,079	255,496	0	255,496
West Virginia	1,430,913	1,429,773	1,140	0	0	0
Wisconsin.....	436,534	105,675	330,859	0	0	0
Wyoming	83,781	314,196	-230,415	0	0	0
Total	57,715,077	57,715,077	0	1,019,496	78,013	941,483

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1973						
Alabama	3,157,465	2,898,432	259,033	0	0	0
Alaska.....	0	0	0	0	48,346	-48,346
Arizona	1,533,942	1,313,585	220,357	0	4,477	-4,477
Arkansas	2,701,399	2,519,599	181,800	0	0	0
California	1,636,723	0	1,636,723	0	0	0
Colorado.....	328,439	126,573	201,866	0	0	0
Connecticut	151,382	87,523	63,859	0	0	0
D.C.	a	a	a	a	a	a
Delaware	25,456	1,996	23,460	0	0	0
Florida	282,070	0	282,070	0	0	0
Georgia.....	1,388,683	1,044,611	344,072	0	0	0
Idaho	86,974	469,131	-382,157	437,857	0	437,857
Illinois	2,329,907	1,085,154	1,244,753	0	0	0
Indiana.....	2,047,305	1,487,347	559,958	0	0	0
Iowa.....	1,323,459	937,517	385,942	0	0	0
Kansas	2,079,962	2,314,562	-234,600	0	0	0
Kentucky ^b	4,193,000	3,979,588	213,412	0	0	0
Louisiana ^a	1,256,830	7,162,687	-5,905,857	0	0	0
Maine.....	10,363	0	10,363	3,912	0	3,912
Maryland	862,879	657,919	204,960	0	0	0
Massachusetts	177,177	23,211	153,966	4,055	0	4,055
Michigan	925,952	0	925,952	0	14,736	-14,736
Minnesota.....	341,828	246,767	95,061	262,434	0	262,434
Mississippi.....	6,636,027	6,420,802	215,225	0	0	0
Missouri.....	1,644,311	1,210,425	433,886	0	0	0
Montana	34,727	46,192	-11,465	50,064	88	49,976
Nebraska	1,361,501	1,133,627	227,874	0	0	0
Nevada.....	74,358	0	74,358	0	0	0
New Hampshire.....	b	b	b	b	b	b
New Jersey	779,068	474,736	304,332	0	0	0
New Mexico.....	844,003	1,740,552	-896,549	0	0	0
New York.....	939,403	249,573	689,830	5,546	0	5,546
North Carolina	871,572	710,868	160,704	0	0	0
North Dakota	11,058	4,308	6,750	0	0	0
Ohio.....	2,978,272	1,929,823	1,048,449	0	0	0
Oklahoma	1,268,128	2,333,024	-1,064,896	0	0	0
Oregon	490,611	382,264	108,347	0	0	0
Pennsylvania	2,048,053	1,276,144	771,909	0	0	0
Rhode Island	92,655	71,889	20,766	0	0	0
South Carolina	1,022,225	871,572	150,653	0	0	0
South Dakota	62,663	31,089	31,574	0	0	0
Tennessee	4,503,040	4,202,057	300,983	0	0	0
Texas.....	549,700	3,932,341	-3,382,641	1,632	9,522	-7,890
Utah.....	234,442	147,833	86,609	0	0	0
Vermont.....	b	b	b	b	b	b
Virginia	1,008,381	854,454	153,927	0	0	0
Washington	436,924	502,473	-65,549	267,401	0	267,401
West Virginia	1,543,718	1,515,862	27,856	0	0	0
Wisconsin.....	439,371	81,686	357,685	0	0	0
Wyoming	96,638	332,248	-235,610	0	0	0
Total	56,812,044	56,812,044	0	1,032,901	77,169	955,732

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1974						
Alabama	2,927,510	2,673,216	254,294	0	0	0
Alaska.....	0	0	0	0	50,258	-50,258
Arizona	1,491,149	1,291,148	200,001	0	4,217	-4,217
Arkansas	2,421,412	2,249,394	172,018	0	0	0
California	1,598,378	0	1,598,378	0	0	0
Colorado.....	295,181	118,486	176,695	0	0	0
Connecticut	160,854	94,299	66,555	0	0	0
D.C.	a	a	a	a	a	a
Delaware	22,193	1,457	20,736	0	0	0
Florida	255,493	0	255,493	0	0	0
Georgia.....	1,227,583	892,111	335,472	0	0	0
Idaho	101,380	453,673	-352,293	405,499	0	405,499
Illinois	2,213,790	991,334	1,222,456	0	0	0
Indiana.....	1,967,486	1,435,665	531,821	0	0	0
Iowa.....	1,379,323	995,699	383,624	0	0	0
Kansas	2,100,454	2,345,003	-244,549	0	0	0
Kentucky ^b	3,854,479	3,684,235	170,244	0	0	0
Louisiana ^a	972,873	6,499,158	-5,526,285	0	0	0
Maine.....	12,369	1,934	10,435	4,891	0	4,891
Maryland	752,816	548,930	203,886	0	0	0
Massachusetts	182,472	26,779	155,693	0	0	0
Michigan	869,059	0	869,059	0	13,232	-13,232
Minnesota.....	321,258	223,040	98,218	256,100	0	256,100
Mississippi.....	6,064,296	5,858,875	205,421	0	0	0
Missouri.....	1,603,047	1,184,299	418,748	0	0	0
Montana	22,934	25,183	-2,249	48,111	31	48,080
Nebraska	1,373,156	1,149,267	223,889	0	0	0
Nevada.....	64,593	0	64,593	0	0	0
New Hampshire.....	b	b	b	b	b	b
New Jersey	700,511	426,406	274,105	0	0	0
New Mexico.....	784,918	1,700,380	-915,462	0	0	0
New York.....	883,182	256,725	626,457	5,556	0	5,556
North Carolina	732,669	589,735	142,934	0	0	0
North Dakota	16,053	6,301	9,752	0	0	0
Ohio.....	2,778,124	1,794,255	983,869	0	0	0
Oklahoma	1,451,639	2,367,371	-915,732	0	0	0
Oregon	464,072	359,991	104,081	0	0	0
Pennsylvania.....	1,776,519	1,181,508	595,011	0	0	0
Rhode Island	99,154	75,696	23,458	0	0	0
South Carolina	869,771	732,669	137,102	0	0	0
South Dakota	34,107	1,901	32,206	0	0	0
Tennessee	4,127,109	3,863,265	263,844	0	0	0
Texas.....	536,392	3,757,200	-3,220,808	222	9,051	-8,829
Utah.....	238,164	161,740	76,424	0	0	0
Vermont.....	b	b	b	b	b	b
Virginia	889,360	747,850	141,510	0	0	0
Washington	425,795	477,866	-52,071	238,905	0	238,905
West Virginia	1,295,565	1,300,577	-5,012	0	0	0
Wisconsin.....	465,509	79,739	385,770	0	0	0
Wyoming	97,006	296,797	-199,791	0	0	0
Total	52,921,157	52,921,157	0	959,284	76,789	882,495

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1975						
Alabama	2,716,837	2,476,511	240,326	0	0	0
Alaska.....	0	0	0	0	53,002	-53,002
Arizona	1,388,649	1,231,323	157,326	0	3,223	-3,223
Arkansas	2,365,936	2,218,627	147,309	0	0	0
California	1,569,946	0	1,569,946	0	0	0
Colorado.....	279,070	134,124	144,946	0	0	0
Connecticut	155,741	91,871	63,870	0	0	0
D.C.	a	a	a	a	a	a
Delaware	20,894	1,221	19,673	0	0	0
Florida	246,566	0	246,566	0	0	0
Georgia.....	1,137,354	809,093	328,261	0	0	0
Idaho	100,600	421,876	-321,276	380,232	0	380,232
Illinois	2,112,982	933,892	1,179,090	0	0	0
Indiana.....	1,838,901	1,353,199	485,702	0	0	0
Iowa.....	1,309,669	952,599	357,070	0	0	0
Kansas	1,852,575	2,137,528	-284,953	0	0	0
Kentucky ^b	3,684,713	3,513,056	171,657	0	0	0
Louisiana ^a	1,181,696	6,218,499	-5,036,803	0	0	0
Maine.....	9,799	0	9,799	4,124	0	4,124
Maryland	676,710	508,502	168,208	0	0	0
Massachusetts	178,298	23,271	155,027	4,893	0	4,893
Michigan	826,505	0	826,505	0	10,153	-10,153
Minnesota.....	308,975	224,678	84,297	253,638	0	253,638
Mississippi.....	5,683,382	5,521,131	162,251	0	0	0
Missouri.....	1,535,678	1,158,783	376,895	0	0	0
Montana	14,061	23,587	-9,526	42,180	66	42,114
Nebraska	1,305,434	1,081,138	224,296	0	0	0
Nevada.....	61,463	0	61,463	0	0	0
New Hampshire.....	b	b	b	b	b	b
New Jersey	633,893	384,050	249,843	0	0	0
New Mexico.....	717,762	1,629,530	-911,768	0	0	0
New York.....	821,004	250,455	570,549	5,497	0	5,497
North Carolina	659,826	541,933	117,893	0	0	0
North Dakota	18,655	3,490	15,165	0	0	0
Ohio.....	2,641,647	1,723,553	918,094	0	0	0
Oklahoma	1,220,782	2,090,214	-869,432	0	0	0
Oregon	517,337	403,477	113,860	0	0	0
Pennsylvania	1,721,102	1,097,990	623,112	0	0	0
Rhode Island	97,119	75,886	21,233	0	0	0
South Carolina	786,871	659,826	127,045	0	0	0
South Dakota	34,677	1,428	33,249	0	0	0
Tennessee	3,912,003	3,690,655	221,348	0	0	0
Texas.....	544,730	3,616,338	-3,071,608	0	6,230	-6,230
Utah.....	206,470	131,094	75,376	0	0	0
Vermont.....	b	b	b	b	b	b
Virginia	791,615	672,911	118,704	0	0	0
Washington	389,810	485,271	-95,461	262,443	0	262,443
West Virginia	1,241,589	1,194,850	46,739	0	0	0
Wisconsin.....	464,271	93,154	371,117	0	0	0
Wyoming	104,385	307,368	-202,983	0	0	0
Total	50,087,982	50,087,982	0	953,008	72,675	880,333

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1976						
Alabama	2,686,071	2,496,561	189,510	0	0	0
Alaska.....	0	0	0	0	49,780	-49,780
Arizona	1,265,930	1,093,797	172,133	0	1,665	-1,665
Arkansas	2,349,241	2,192,542	156,699	0	0	0
California	1,474,658	0	1,474,658	0	0	0
Colorado.....	269,218	137,180	132,038	0	0	0
Connecticut	144,040	78,530	65,510	0	0	0
D.C.	a	a	a	0	0	a
Delaware	20,179	1,178	19,001	0	0	0
Florida	259,717	0	259,717	0	0	0
Georgia.....	1,047,507	786,275	261,232	0	0	0
Idaho	94,110	487,023	-392,913	440,276	0	440,276
Illinois	2,140,583	896,971	1,243,612	0	0	0
Indiana.....	1,663,876	1,239,222	424,654	0	0	0
Iowa.....	1,325,699	991,843	333,856	0	0	0
Kansas	1,877,945	2,151,678	-273,733	0	0	0
Kentucky ^b	3,407,936	3,219,540	188,396	0	0	0
Louisiana ^a	985,150	5,770,752	-4,785,602	0	0	0
Maine.....	9,823	0	9,823	4,066	0	4,066
Maryland	634,812	457,011	177,801	0	0	0
Massachusetts	175,739	28,932	146,807	10,155	0	10,155
Michigan	742,482	0	742,482	0	7,461	-7,461
Minnesota.....	308,975	238,474	70,501	254,858	0	254,858
Mississippi.....	5,233,400	5,112,309	121,091	0	0	0
Missouri.....	1,517,775	1,139,598	378,177	0	0	0
Montana	8,189	22,447	-14,258	35,633	45	35,588
Nebraska	1,341,096	1,138,711	202,385	0	0	0
Nevada.....	67,300	0	67,300	0	0	0
New Hampshire.....	b	b	b	b	b	b
New Jersey	705,482	375,966	329,516	0	0	0
New Mexico.....	630,215	1,512,447	-882,232	0	0	0
New York.....	819,575	242,378	577,197	5,537	0	5,537
North Carolina	600,683	495,998	104,685	0	0	0
North Dakota	15,530	1,403	14,127	0	0	0
Ohio.....	2,512,997	1,634,534	878,463	0	0	0
Oklahoma	1,245,596	2,161,079	-915,483	0	0	0
Oregon	546,601	451,649	94,952	0	0	0
Pennsylvania	1,728,941	1,178,012	550,929	0	0	0
Rhode Island	83,390	63,648	19,742	0	0	0
South Carolina	763,722	600,683	163,039	0	0	0
South Dakota	41,498	1,385	40,113	0	0	0
Tennessee	3,631,175	3,415,042	216,133	0	0	0
Texas.....	634,907	3,391,257	-2,756,350	0	5,760	-5,760
Utah.....	220,219	122,503	97,716	0	0	0
Vermont.....	b	b	b	b	b	b
Virginia	755,515	633,272	122,243	0	0	0
Washington	436,144	495,722	-59,578	213,243	0	213,243
West Virginia	1,195,503	1,259,379	-63,876	0	0	0
Wisconsin.....	473,612	157,996	315,616	0	0	0
Wyoming	104,394	322,223	-217,829	0	0	0
Total	48,197,150	48,197,150	0	963,768	64,711	899,057

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1977						
Alabama	2,582,686	2,398,807	183,879	0	0	0
Alaska.....	0	0	0	0	51,655	-51,655
Arizona	1,273,610	1,106,086	167,524	0	672	-672
Arkansas	2,224,850	2,101,603	123,247	0	0	0
California	1,484,303	0	1,484,303	0	0	0
Colorado.....	252,362	155,732	96,630	0	0	0
Connecticut	155,096	89,668	65,428	0	0	0
D.C.	a	a	a	a	a	a
Delaware	17,084	0	17,084	224	0	224
Florida	257,996	0	257,996	0	0	0
Georgia.....	951,567	679,433	272,134	0	0	0
Idaho	99,573	443,519	-343,946	390,095	0	390,095
Illinois	2,134,641	884,741	1,249,900	0	0	0
Indiana.....	1,566,492	1,165,698	400,794	0	0	0
Iowa.....	1,260,124	950,776	309,348	0	0	0
Kansas	1,807,647	2,029,120	-221,473	0	0	0
Kentucky ^b	3,386,909	3,207,686	179,223	0	0	0
Louisiana ^a	1,026,909	5,815,429	-4,788,520	0	0	0
Maine.....	21,982	2,115	19,867	4,263	0	4,263
Maryland	589,471	424,605	164,866	0	0	0
Massachusetts	220,596	60,655	159,941	11,522	0	11,522
Michigan	664,617	0	664,617	0	0	0
Minnesota.....	331,219	306,038	25,181	276,453	0	276,453
Mississippi.....	5,087,125	4,960,512	126,613	0	0	0
Missouri.....	1,520,721	1,153,708	367,013	0	0	0
Montana	15,919	17,587	-1,668	31,619	31	31,588
Nebraska	1,248,780	1,087,828	160,952	0	0	0
Nevada.....	71,052	0	71,052	0	0	0
New Hampshire.....	b	b	b	b	b	b
New Jersey	597,845	362,275	235,570	150	0	150
New Mexico.....	598,738	1,518,098	-919,360	0	0	0
New York.....	741,333	277,228	464,105	7,854	0	7,854
North Carolina	517,264	450,232	67,032	0	0	0
North Dakota	11,388	0	11,388	0	0	0
Ohio.....	2,461,503	1,671,667	789,836	0	0	0
Oklahoma.....	1,181,518	2,045,675	-864,157	0	0	0
Oregon	581,615	514,363	67,252	0	0	0
Pennsylvania.....	1,665,935	1,014,084	651,851	0	0	0
Rhode Island	95,018	63,648	31,370	0	0	0
South Carolina	659,591	517,264	142,327	0	0	0
South Dakota	40,216	3,507	36,709	0	0	0
Tennessee	3,583,552	3,394,257	189,295	0	0	0
Texas.....	812,304	3,246,816	-2,434,512	2,384	3,268	-884
Utah.....	166,523	120,468	46,055	0	0	0
Vermont.....	b	b	b	b	b	b
Virginia	686,485	574,675	111,810	0	0	0
Washington	434,241	572,337	-138,096	286,437	0	286,437
West Virginia	1,274,217	1,182,381	91,836	0	0	0
Wisconsin.....	510,029	124,835	385,194	0	0	0
Wyoming	78,096	255,586	-177,490	0	0	0
Total	46,950,742	46,950,742	0	1,011,002	55,626	955,376

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1978						
Alabama	2,566,115	2,406,395	159,720	0	0	0
Alaska.....	0	0	0	0	48,434	-48,434
Arizona	1,106,300	933,769	172,531	0	0	0
Arkansas	2,346,437	2,224,216	122,221	0	0	0
California	1,252,011	0	1,252,011	0	0	0
Colorado.....	267,866	165,043	102,823	0	0	0
Connecticut	146,892	85,378	61,514	0	0	0
D.C.	a	a	a	a	a	a
Delaware	20,920	0	20,920	0	0	0
Florida	281,170	0	281,170	0	0	0
Georgia.....	943,636	684,739	258,897	22,358	0	22,358
Idaho	59,758	399,341	-339,583	384,536	0	384,536
Illinois	2,245,661	1,037,504	1,208,157	0	0	0
Indiana.....	1,640,895	1,189,675	451,220	0	0	0
Iowa.....	1,220,827	970,927	249,900	0	0	0
Kansas	1,662,386	1,951,995	-289,609	0	0	0
Kentucky ^b	3,437,020	3,276,196	160,824	0	0	0
Louisiana ^a	677,122	5,716,788	-5,039,666	0	0	0
Maine.....	10,570	0	10,570	4,224	0	4,224
Maryland	543,974	415,482	128,492	47,496	0	47,496
Massachusetts	169,023	22,185	146,838	14,568	0	14,568
Michigan	664,144	0	664,144	0	0	0
Minnesota.....	308,975	235,732	73,243	248,453	0	248,453
Mississippi.....	5,102,266	4,994,098	108,168	0	0	0
Missouri.....	1,537,431	1,168,810	368,621	0	0	0
Montana	17,424	18,325	-901	28,102	66	28,036
Nebraska	1,201,335	1,041,156	160,179	0	0	0
Nevada.....	65,507	0	65,507	0	0	0
New Hampshire.....	b	b	b	b	b	b
New Jersey	601,305	371,219	230,086	0	0	0
New Mexico.....	413,935	1,309,836	-895,901	0	0	0
New York.....	793,109	241,313	551,796	6,231	0	6,231
North Carolina	539,601	454,777	84,824	0	0	0
North Dakota	13,155	500	12,655	0	0	0
Ohio.....	2,469,659	1,625,596	844,063	0	0	0
Oklahoma	902,256	1,817,265	-915,009	0	0	0
Oregon	475,712	387,285	88,427	0	0	0
Pennsylvania	1,667,275	1,065,881	601,394	0	0	0
Rhode Island	90,876	69,080	21,796	0	0	0
South Carolina	660,057	539,601	120,456	0	0	0
South Dakota	39,252	1,423	37,829	0	0	0
Tennessee	3,630,187	3,443,194	186,993	0	0	0
Texas.....	673,642	2,523,974	-1,850,332	0	4,032	-4,032
Utah.....	168,495	101,036	67,459	0	0	0
Vermont.....	b	b	b	b	b	b
Virginia	669,776	540,278	129,498	0	0	0
Washington	399,341	475,712	-76,371	209,577	0	209,577
West Virginia	1,250,535	1,216,200	34,335	0	0	0
Wisconsin.....	512,647	132,490	380,157	0	0	0
Wyoming	77,861	289,927	-212,066	0	0	0
Total	45,544,341	45,544,341	0	965,545	52,532	913,013

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1979						
Alabama	2,720,629	2,517,934	202,695	0	0	0
Alaska.....	0	0	0	0	51,289	-51,289
Arizona	1,328,521	1,154,774	173,747	0	706	-706
Arkansas	2,610,559	2,454,689	155,870	0	0	0
California	1,626,812	0	1,626,812	0	0	0
Colorado.....	274,941	149,485	125,456	0	0	0
Connecticut	152,009	82,026	69,983	0	0	0
D.C.	a	a	a	a	a	a
Delaware	26,992	1,684	25,308	0	0	0
Florida	307,587	0	307,587	0	0	0
Georgia.....	1,041,167	810,314	230,853	87,729	0	87,729
Idaho	93,426	470,848	-377,422	431,334	0	431,334
Illinois	2,239,878	1,031,254	1,208,624	0	0	0
Indiana.....	1,776,965	1,259,512	517,453	0	0	0
Iowa.....	1,182,263	874,890	307,373	0	0	0
Kansas	1,753,120	1,899,244	-146,124	0	0	0
Kentucky ^b	3,590,045	3,414,944	175,101	0	0	0
Louisiana ^a	1,290,824	6,397,908	-5,107,084	0	0	0
Maine.....	12,899	1,855	11,044	4,545	0	4,545
Maryland	776,495	707,568	68,927	136,313	0	136,313
Massachusetts	191,662	60,060	131,602	28,566	0	28,566
Michigan	806,346	393	805,953	0	0	0
Minnesota.....	337,592	283,878	53,714	286,290	0	286,290
Mississippi.....	5,459,097	5,355,528	103,569	0	0	0
Missouri.....	1,657,515	1,303,530	353,985	0	0	0
Montana	30,321	34,992	-4,671	30,081	76	30,005
Nebraska	1,129,595	954,368	175,227	0	0	0
Nevada.....	85,313	0	85,313	0	0	0
New Hampshire.....	b	b	b	b	b	b
New Jersey	664,027	390,995	273,032	0	0	0
New Mexico.....	632,203	1,544,893	-912,690	0	0	0
New York.....	938,935	302,390	636,545	9,157	0	9,157
North Carolina	661,536	528,650	132,886	0	0	0
North Dakota	13,548	720	12,828	0	0	0
Ohio.....	2,694,620	1,889,780	804,840	0	0	0
Oklahoma	1,073,641	1,988,047	-914,406	0	0	0
Oregon	513,926	420,930	92,996	0	0	0
Pennsylvania	1,986,465	1,279,419	707,046	0	0	0
Rhode Island	92,800	64,734	28,066	0	0	0
South Carolina	783,573	661,536	122,037	0	0	0
South Dakota	25,609	398	25,211	0	0	0
Tennessee	3,828,223	3,597,245	230,978	0	0	0
Texas.....	815,548	3,584,006	-2,768,458	0	3,602	-3,602
Utah.....	144,159	70,397	73,762	0	0	0
Vermont.....	b	b	b	b	b	b
Virginia	880,271	750,366	129,905	0	0	0
Washington	427,938	505,004	-77,066	239,368	0	239,368
West Virginia	1,277,700	1,236,170	41,530	0	0	0
Wisconsin.....	480,579	112,729	367,850	0	0	0
Wyoming	80,589	368,376	-287,787	0	0	0
Total	50,518,463	50,518,463	0	1,253,383	55,673	1,197,710

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1980						
Alabama	2,901,573	2,703,544	198,029	0	0	0
Alaska.....	0	0	0	0	44,732	-44,732
Arizona	1,398,841	1,215,974	182,867	0	686	-686
Arkansas	2,855,625	2,687,070	168,555	0	0	0
California	1,481,832	0	1,481,832	0	0	0
Colorado.....	207,996	174,197	33,799	0	0	0
Connecticut	166,127	90,101	76,026	0	0	0
D.C.	28,096	0	28,096	0	0	0
Delaware	4,268	1,452	2,816	0	0	0
Florida	276,295	0	276,295	0	0	0
Georgia.....	1,321,780	1,013,310	308,470	24,603	0	24,603
Idaho	75,680	417,488	-341,808	352,015	0	352,015
Illinois	2,312,585	1,031,428	1,281,157	0	0	0
Indiana.....	1,687,205	1,227,308	459,897	0	0	0
Iowa.....	1,160,209	908,461	251,748	0	0	0
Kansas	1,430,150	1,856,216	-426,066	0	0	0
Kentucky	3,377,276	3,214,552	162,724	0	0	0
Louisiana.....	1,246,163	6,181,011	-4,934,848	0	0	0
Maine.....	2,207	0	2,207	0	0	0
Maryland	910,356	787,956	122,400	36,973	0	36,973
Massachusetts	208,470	45,703	162,767	24,274	0	24,274
Michigan	862,303	0	862,303	236	256,152	-255,916
Minnesota.....	282,412	488,173	-205,761	529,676	9,819	519,857
Mississippi.....	5,512,802	5,420,674	92,128	0	0	0
Missouri.....	1,563,023	1,237,618	325,405	0	0	0
Montana	22,777	5,691	17,086	22,350	15,196	7,154
Nebraska	1,336,951	1,175,024	161,927	0	0	0
Nevada.....	59,932	0	59,932	0	0	0
New Hampshire.....	6,807	2,207	4,600	0	0	0
New Jersey	859,553	384,175	475,378	0	0	0
New Mexico.....	816,621	1,583,501	-766,880	0	0	0
New York.....	918,815	328,201	590,614	14,867	295	14,572
North Carolina	868,660	725,642	143,018	0	0	0
North Dakota	5,218	6,349	-1,131	0	0	0
Ohio.....	2,388,034	1,680,895	707,139	0	0	0
Oklahoma.....	1,009,941	1,713,727	-703,786	0	0	0
Oregon	387,393	308,551	78,842	0	0	0
Pennsylvania.....	2,112,132	1,429,770	682,362	0	0	0
Rhode Island	96,336	69,928	26,408	0	0	0
South Carolina	987,633	868,660	118,973	0	0	0
South Dakota	23,990	906	23,084	0	0	0
Tennessee	3,638,105	3,385,302	252,803	0	0	0
Texas.....	880,500	3,658,707	-2,778,207	102,410	3,200	99,210
Utah.....	160,420	80,264	80,156	0	0	0
Vermont.....	0	0	0	4,221	0	4,221
Virginia	1,045,465	908,811	136,654	0	0	0
Washington	349,580	340,115	9,465	154,488	0	154,488
West Virginia	1,261,669	1,229,175	32,494	0	0	0
Wisconsin.....	725,678	364,181	361,497	0	0	0
Wyoming	90,465	373,927	-283,462	0	0	0
Total	51,325,948	51,325,948	0	1,266,116	330,080	936,036

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1981						
Alabama	2,904,870	2,726,721	178,149	0	0	0
Alaska.....	0	0	0	0	55,929	-55,929
Arizona	1,497,434	1,300,640	196,794	0	904	-904
Arkansas	2,852,414	2,679,339	173,075	0	0	0
California	1,512,595	0	1,512,595	0	0	0
Colorado.....	281,075	241,968	39,107	0	0	0
Connecticut	161,068	82,021	79,047	0	0	0
D.C.	29,299	0	29,299	0	0	0
Delaware	32,310	1,769	30,541	0	0	0
Florida	291,318	0	291,318	0	0	0
Georgia.....	1,387,833	1,043,121	344,712	0	0	0
Idaho	92,572	386,605	-294,033	303,936	0	303,936
Illinois	2,264,715	1,138,477	1,126,238	0	0	0
Indiana.....	1,743,506	1,089,140	654,366	0	0	0
Iowa.....	1,082,708	865,684	217,024	0	0	0
Kansas	1,617,860	1,792,482	-174,622	0	0	0
Kentucky	3,391,713	3,243,894	147,819	0	0	0
Louisiana	1,465,289	6,188,796	-4,723,507	0	0	0
Maine.....	2,267	0	2,267	0	0	0
Maryland	905,278	731,363	173,915	0	0	0
Massachusetts	170,128	28,301	141,827	36,824	32	36,792
Michigan	728,736	27,046	701,690	10,440	283,347	-272,907
Minnesota.....	266,470	504,359	-237,889	566,516	8,904	557,612
Mississippi.....	5,566,506	5,480,593	85,913	0	0	0
Missouri.....	1,421,730	1,130,012	291,718	0	0	0
Montana	16,924	7,523	9,401	20,865	13,175	7,690
Nebraska	1,238,716	1,095,943	142,773	0	0	0
Nevada.....	75,667	0	75,667	0	0	0
New Hampshire.....	6,859	2,133	4,726	6	0	6
New Jersey	891,285	408,951	482,334	0	0	0
New Mexico.....	849,033	1,680,770	-831,737	0	0	0
New York.....	891,449	260,901	630,548	26,983	0	26,983
North Carolina	901,437	755,544	145,893	0	0	0
North Dakota	4,701	6,630	-1,929	0	0	0
Ohio.....	2,318,930	1,637,760	681,170	0	0	0
Oklahoma.....	801,924	1,882,457	-1,080,533	0	0	0
Oregon	332,716	258,831	73,885	0	0	0
Pennsylvania.....	2,176,824	1,441,152	735,672	0	0	0
Rhode Island	90,272	61,253	29,019	0	0	0
South Carolina	1,019,156	901,437	117,719	0	0	0
South Dakota	21,723	858	20,865	0	0	0
Tennessee	3,634,770	3,399,600	235,170	0	0	0
Texas.....	819,919	3,565,013	-2,745,094	105,013	2,433	102,580
Utah.....	140,716	74,701	66,015	0	0	0
Vermont.....	0	0	0	4,589	0	4,589
Virginia	1,053,672	902,638	151,034	0	0	0
Washington	302,502	281,646	20,856	134,322	0	134,322
West Virginia	1,396,558	1,364,807	31,751	0	0	0
Wisconsin.....	723,161	391,211	331,950	0	0	0
Wyoming	86,025	400,543	-314,518	0	0	0
Total	51,464,633	51,464,633	0	1,209,493	364,724	844,769

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1982						
Alabama	2,792,147	2,639,141	153,006	0	0	0
Alaska.....	0	0	0	0	49,861	-49,861
Arizona	1,289,708	1,167,774	121,934	0	1,694	-1,694
Arkansas	2,731,040	2,617,671	113,369	0	0	0
California	1,410,366	0	1,410,366	0	0	0
Colorado.....	278,284	275,904	2,380	0	0	0
Connecticut	165,157	87,972	77,185	0	0	0
D.C.	29,299	0	29,299	0	0	0
Delaware	31,562	1,890	29,672	0	0	0
Florida	292,417	0	292,417	0	0	0
Georgia.....	1,343,109	1,050,184	292,925	0	0	0
Idaho	77,475	374,751	-297,276	338,147	0	338,147
Illinois	2,326,052	1,177,114	1,148,938	0	0	0
Indiana.....	1,796,559	1,325,168	471,391	0	0	0
Iowa.....	999,293	772,274	227,019	0	0	0
Kansas	1,537,130	1,531,396	5,734	0	0	0
Kentucky	3,382,236	3,229,328	152,908	0	0	0
Louisiana	1,521,833	6,053,706	-4,531,873	23,114	0	23,114
Maine.....	2,672	0	2,672	0	0	0
Maryland	886,722	731,799	154,923	0	0	0
Massachusetts	185,711	34,106	151,605	32,022	0	32,022
Michigan	829,747	0	829,747	10,027	251,634	-241,607
Minnesota.....	253,895	495,415	-241,520	513,616	8,260	505,356
Mississippi.....	5,475,869	5,381,281	94,588	0	0	0
Missouri.....	1,314,736	1,030,553	284,183	0	0	0
Montana	18,725	74,957	-56,232	70,647	10,151	60,496
Nebraska	1,086,512	952,242	134,270	0	0	0
Nevada.....	50,225	2,393	47,832	0	0	0
New Hampshire.....	12,438	2,417	10,021	0	0	0
New Jersey	915,301	529,486	385,815	0	0	0
New Mexico.....	814,677	1,485,634	-670,957	0	0	0
New York.....	1,026,699	275,000	751,699	24,139	0	24,139
North Carolina	931,428	784,137	147,291	0	0	0
North Dakota	62,464	63,721	-1,257	0	0	0
Ohio.....	2,185,567	1,537,796	647,771	0	0	0
Oklahoma.....	801,580	1,827,898	-1,026,318	0	0	0
Oregon	338,866	271,331	67,535	0	0	0
Pennsylvania	2,133,874	1,473,452	660,422	0	0	0
Rhode Island	96,064	68,657	27,407	0	0	0
South Carolina	1,028,337	931,428	96,909	0	0	0
South Dakota	78,537	54,149	24,388	0	0	0
Tennessee	3,606,129	3,386,785	219,344	0	0	0
Texas.....	846,744	3,541,391	-2,694,647	94,794	11	94,783
Utah.....	142,268	104,038	38,230	0	0	0
Vermont.....	0	0	0	4,519	0	4,519
Virginia	1,038,422	894,597	143,825	0	0	0
Washington	337,068	323,453	13,615	92,027	0	92,027
West Virginia	1,279,463	1,297,206	-17,743	0	0	0
Wisconsin.....	698,335	366,048	332,287	0	0	0
Wyoming	141,972	399,067	-257,095	0	0	0
Total	50,624,713	50,624,713	0	1,203,052	321,611	881,441

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1983						
Alabama	2,730,841	2,579,069	151,772	0	0	0
Alaska.....	0	0	0	0	52,857	-52,857
Arizona	1,130,306	1,011,375	118,931	0	1,646	-1,646
Arkansas	2,221,118	2,115,459	105,659	0	0	0
California	1,238,601	0	1,238,601	0	0	0
Colorado.....	378,709	320,339	58,370	0	0	0
Connecticut	181,304	104,468	76,836	0	0	0
D.C.	29,566	0	29,566	0	0	0
Delaware	38,782	2,063	36,719	0	0	0
Florida	293,075	977	292,098	0	0	0
Georgia.....	1,269,604	965,347	304,257	0	0	0
Idaho	77,305	353,270	-275,965	310,811	0	310,811
Illinois	1,854,416	920,448	933,968	0	0	0
Indiana.....	1,464,094	1,056,485	407,609	0	0	0
Iowa.....	1,001,729	804,228	197,501	0	0	0
Kansas	1,249,165	1,336,973	-87,808	0	0	0
Kentucky	2,763,767	2,626,651	137,116	0	0	0
Louisiana	1,430,057	5,247,893	-3,817,836	96,945	0	96,945
Maine.....	2,397	0	2,397	0	0	0
Maryland	783,232	628,291	154,941	0	0	0
Massachusetts	191,701	29,533	162,168	34,178	0	34,178
Michigan	625,986	0	625,986	6,951	218,264	-211,313
Minnesota.....	383,185	510,430	-127,246	381,039	8,705	372,335
Mississippi.....	4,775,876	4,712,056	63,820	0	0	0
Missouri.....	1,183,703	920,322	263,381	0	0	0
Montana	41,239	145,266	-104,027	136,508	9,255	127,253
Nebraska	1,068,515	945,695	122,820	0	0	0
Nevada.....	41,093	2,327	38,766	0	0	0
New Hampshire.....	11,978	2,287	9,691	0	0	0
New Jersey	924,060	514,435	409,625	0	0	0
New Mexico.....	592,185	1,284,703	-692,518	0	0	0
New York.....	998,082	295,242	702,840	22,348	0	22,348
North Carolina	857,732	717,080	140,652	0	0	0
North Dakota	138,101	162,743	-24,642	0	0	0
Ohio.....	1,974,508	1,390,020	584,488	0	0	0
Oklahoma.....	641,333	1,601,634	-960,301	0	0	0
Oregon	315,215	268,603	46,612	0	0	0
Pennsylvania.....	1,957,169	1,472,641	484,528	0	0	0
Rhode Island	111,470	81,855	29,615	0	0	0
South Carolina	960,964	857,732	103,232	0	0	0
South Dakota	154,136	132,093	22,043	0	0	0
Tennessee	2,996,742	2,770,062	226,680	0	0	0
Texas.....	737,616	3,057,348	-2,319,732	75,361	0	75,361
Utah.....	104,760	59,568	45,192	0	0	0
Vermont.....	0	0	0	4,610	0	4,610
Virginia	944,050	798,296	145,754	0	0	0
Washington	329,645	291,317	38,328	87,242	666	86,576
West Virginia	1,173,584	1,278,569	-104,985	0	0	0
Wisconsin.....	605,634	286,829	318,805	0	0	0
Wyoming	167,530	483,838	-316,308	0	0	0
Total	45,145,860	45,145,860	0	1,155,993	291,393	864,600

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1984						
Alabama	2,791,263	2,649,691	141,572	0	0	0
Alaska.....	0	0	0	0	52,840	-52,840
Arizona	1,205,626	1,071,352	134,274	0	1,757	-1,757
Arkansas	2,285,386	2,185,420	99,966	0	0	0
California	1,277,119	0	1,277,119	0	0	0
Colorado.....	395,292	332,406	62,886	0	0	0
Connecticut	196,625	115,489	81,136	0	0	0
D.C.	30,214	0	30,214	0	0	0
Delaware	44,886	2,071	42,815	0	0	0
Florida	299,632	960	298,672	0	0	0
Georgia.....	1,274,720	970,146	304,574	0	0	0
Idaho	106,622	367,032	-260,410	299,360	0	299,360
Illinois	2,024,163	1,016,321	1,007,842	0	0	0
Indiana.....	1,588,849	1,155,902	432,947	0	0	0
Iowa.....	1,072,542	840,337	232,205	0	0	0
Kansas	1,362,932	1,465,318	-102,386	0	0	0
Kentucky	2,999,015	2,808,010	191,005	0	0	0
Louisiana	1,459,954	5,537,465	-4,077,511	0	0	0
Maine.....	2,537	0	2,537	0	0	0
Maryland	768,952	617,953	150,999	0	0	0
Massachusetts	213,871	34,388	179,483	36,191	0	36,191
Michigan	833,598	0	833,598	3,683	265,904	-262,221
Minnesota.....	332,380	571,221	-238,841	475,985	8,011	467,974
Mississippi.....	5,077,761	4,924,788	152,973	0	0	0
Missouri.....	1,375,373	1,101,511	273,862	0	0	0
Montana	42,182	149,287	-107,105	137,661	11,946	125,715
Nebraska	1,165,283	1,032,214	133,069	0	0	0
Nevada.....	42,309	2,311	39,997	0	0	0
New Hampshire.....	12,709	2,343	10,365	0	0	0
New Jersey	994,404	558,792	435,612	0	0	0
New Mexico.....	660,003	1,356,584	-696,581	0	0	0
New York.....	1,031,511	320,448	711,063	29,326	0	29,326
North Carolina	856,551	713,188	143,363	0	0	0
North Dakota	136,005	168,575	-32,570	0	0	0
Ohio.....	2,215,520	1,615,523	599,997	0	0	0
Oklahoma.....	573,477	1,735,343	-1,161,866	0	0	0
Oregon	328,291	251,745	76,546	0	0	0
Pennsylvania	2,132,930	1,535,162	597,769	0	0	0
Rhode Island	124,053	91,838	32,215	0	0	0
South Carolina	963,059	856,551	106,508	0	0	0
South Dakota	157,776	134,433	23,343	0	0	0
Tennessee	3,206,817	3,004,360	202,456	0	0	0
Texas.....	725,220	3,135,482	-2,410,262	51,502	29	51,473
Utah.....	68,944	83,569	-14,625	0	0	0
Vermont.....	0	0	0	4,994	0	4,994
Virginia	926,054	785,589	140,466	0	0	0
Washington	320,846	278,422	42,424	91,003	1,002	90,001
West Virginia	1,311,136	1,419,611	-108,474	0	0	0
Wisconsin.....	668,112	362,907	305,205	0	0	0
Wyoming	189,264	509,711	-320,447	0	0	0
Total	47,871,766	47,871,766	0	1,129,705	341,489	788,216

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1985						
Alabama	2,476,383	2,336,142	140,241	0	0	0
Alaska.....	0	0	0	0	52,883	-52,883
Arizona	1,249,968	1,066,147	183,821	0	1,813	-1,813
Arkansas	2,099,656	2,041,747	57,909	0	0	0
California	1,340,239	0	1,340,239	0	0	0
Colorado.....	427,666	387,305	40,361	0	0	0
Connecticut	203,446	131,499	71,947	0	0	0
D.C.	29,344	0	29,344	0	0	0
Delaware	40,802	2,035	38,767	0	0	0
Florida	273,348	297	273,051	0	0	0
Georgia.....	1,222,557	926,049	296,508	0	0	0
Idaho	68,640	440,434	-371,794	411,380	0	411,380
Illinois	1,959,775	970,738	989,037	0	0	0
Indiana.....	1,437,123	989,109	448,014	0	0	0
Iowa.....	1,143,876	897,378	246,498	0	0	0
Kansas	1,334,222	1,498,697	-164,475	0	0	0
Kentucky	2,670,242	2,531,793	138,449	0	0	0
Louisiana	1,297,299	4,836,028	-3,538,729	0	0	0
Maine.....	2,664	0	2,664	0	0	0
Maryland	810,397	664,606	145,791	0	0	0
Massachusetts	243,676	47,050	196,626	23,659	0	23,659
Michigan	764,145	0	764,145	467	249,918	-249,451
Minnesota.....	394,368	613,634	-219,266	474,353	6,063	468,290
Mississippi.....	4,542,097	4,488,750	53,347	0	0	0
Missouri.....	1,297,658	1,023,757	273,901	0	0	0
Montana	38,734	172,755	-134,021	155,377	12,148	143,229
Nebraska	1,208,753	1,077,085	131,668	0	0	0
Nevada.....	42,181	2,334	39,847	0	0	0
New Hampshire.....	12,589	2,354	10,235	0	0	0
New Jersey	953,145	590,915	362,230	0	0	0
New Mexico.....	697,489	1,392,041	-694,554	0	0	0
New York.....	1,087,340	324,177	763,163	47,677	0	47,677
North Carolina	819,112	681,309	137,803	0	0	0
North Dakota	157,948	224,131	-66,183	0	0	0
Ohio.....	1,948,185	1,384,582	563,603	0	0	0
Oklahoma.....	596,415	1,778,481	-1,182,066	0	0	0
Oregon	402,173	321,928	80,245	0	0	0
Pennsylvania	1,950,891	1,525,409	425,482	0	0	0
Rhode Island	139,610	108,552	31,058	0	0	0
South Carolina	920,594	819,112	101,482	0	0	0
South Dakota	214,468	190,758	23,710	0	0	0
Tennessee	2,859,222	2,672,435	186,787	0	0	0
Texas.....	667,141	2,920,140	-2,252,999	0	394	-394
Utah.....	56,766	43,794	12,972	0	0	0
Vermont.....	0	0	0	5,213	0	5,213
Virginia	927,392	803,990	123,402	0	0	0
Washington	433,168	390,991	42,177	101,337	2,157	99,180
West Virginia	1,212,710	1,326,139	-113,429	0	0	0
Wisconsin.....	652,627	335,237	317,390	0	0	0
Wyoming	170,208	516,606	-346,398	0	0	0
Total	45,498,452	45,498,452	0	1,219,463	325,376	894,087

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1986						
Alabama	2,446,444	2,328,949	117,495	0	0	0
Alaska.....	0	0	0	0	50,172	-50,172
Arizona	1,043,759	943,306	100,453	0	1,525	-1,525
Arkansas	2,107,365	2,058,532	48,833	0	0	0
California	1,170,859	0	1,170,859	0	0	0
Colorado.....	414,997	319,531	95,466	0	0	0
Connecticut	189,519	110,207	79,312	0	0	0
D.C.	29,956	0	29,956	0	0	0
Delaware	34,394	1,926	32,468	0	0	0
Florida	275,182	287	274,895	0	0	0
Georgia.....	1,217,373	942,159	275,214	0	0	0
Idaho	49,531	362,124	-312,593	348,307	0	348,307
Illinois	1,935,509	1,047,869	887,640	0	0	0
Indiana.....	1,626,913	1,222,332	404,582	0	0	0
Iowa.....	957,733	745,415	212,318	0	0	0
Kansas	1,232,696	1,380,015	-147,319	0	0	0
Kentucky	2,865,860	2,762,789	103,071	0	0	0
Louisiana	1,498,208	4,850,695	-3,352,487	0	0	0
Maine.....	2,562	0	2,562	0	0	0
Maryland	829,464	669,729	159,735	0	0	0
Massachusetts	211,244	22,430	188,814	1,669	0	1,669
Michigan	907,933	0	907,933	0	321,194	-321,194
Minnesota.....	336,917	571,718	-234,801	485,505	6,183	479,322
Mississippi.....	4,689,745	4,668,235	21,510	0	0	0
Missouri.....	1,171,668	925,412	246,256	0	0	0
Montana	39,479	114,214	-74,735	95,958	9,524	86,434
Nebraska	1,022,406	911,908	110,498	0	0	0
Nevada.....	32,709	2,203	30,506	0	0	0
New Hampshire.....	12,584	2,435	10,149	0	0	0
New Jersey	940,391	570,213	370,178	0	0	0
New Mexico.....	781,653	1,157,115	-375,462	0	0	0
New York.....	1,003,593	316,105	687,488	35,720	0	35,720
North Carolina	844,801	708,279	136,522	0	0	0
North Dakota	97,599	172,405	-74,806	0	0	0
Ohio.....	1,963,447	1,375,756	587,691	0	0	0
Oklahoma	542,020	1,724,092	-1,182,072	0	0	0
Oregon	344,001	278,055	65,946	0	0	0
Pennsylvania	1,966,448	1,440,738	525,710	0	0	0
Rhode Island	116,107	89,471	26,636	0	0	0
South Carolina	943,995	844,801	99,194	0	0	0
South Dakota	159,809	137,631	22,178	0	0	0
Tennessee	3,058,204	2,868,649	189,555	0	0	0
Texas.....	615,297	3,093,141	-2,477,844	0	372	-372
Utah.....	119,557	80,968	38,589	0	0	0
Vermont.....	0	0	0	5,137	0	5,137
Virginia	945,391	830,616	114,775	0	0	0
Washington	346,128	344,001	2,127	107,212	61	107,151
West Virginia	1,292,550	1,389,831	-97,281	0	0	0
Wisconsin.....	698,900	397,527	301,373	0	0	0
Wyoming	115,297	464,379	-349,082	0	0	0
Total	45,248,194	45,248,194	0	1,079,508	389,030	690,478

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1987						
Alabama	2,537,793	2,423,579	114,214	0	0	0
Alaska.....	0	0	0	0	48,599	-48,599
Arizona	1,320,262	1,204,302	115,960	0	1,757	-1,757
Arkansas	2,060,704	2,007,028	53,676	0	0	0
California	1,553,144	0	1,553,144	0	0	0
Colorado.....	437,073	381,721	55,353	0	0	0
Connecticut	234,298	140,079	94,219	0	0	0
D.C.	31,907	0	31,907	0	0	0
Delaware	38,426	2,531	35,895	0	0	0
Florida	308,955	1,165	307,790	0	0	0
Georgia.....	1,280,796	957,516	323,279	0	0	0
Idaho	52,138	499,704	-447,566	483,547	0	483,547
Illinois	1,829,079	952,376	876,703	0	0	0
Indiana.....	1,587,276	1,204,207	383,069	0	0	0
Iowa.....	1,079,859	871,808	208,051	0	0	0
Kansas	1,348,168	1,463,576	-115,409	0	0	0
Kentucky	3,014,749	2,822,957	191,792	0	0	0
Louisiana	1,502,000	5,036,474	-3,534,474	0	0	0
Maine.....	2,758	0	2,758	0	0	0
Maryland	840,250	648,022	192,228	0	0	0
Massachusetts	265,324	27,826	237,497	0	0	0
Michigan	941,957	374	941,583	136	306,724	-306,588
Minnesota.....	413,730	630,410	-216,679	454,180	6,079	448,101
Mississippi.....	4,907,867	4,891,035	16,832	0	0	0
Missouri.....	1,121,724	884,569	237,155	0	0	0
Montana	42,435	196,665	-154,230	178,262	10,938	167,324
Nebraska	1,048,843	931,739	117,104	0	0	0
Nevada.....	43,709	2,350	41,359	0	0	0
New Hampshire.....	15,440	2,495	12,945	0	0	0
New Jersey	1,028,386	635,106	393,279	0	0	0
New Mexico.....	850,344	1,407,542	-557,197	0	0	0
New York.....	1,126,174	390,995	735,178	52,013	0	52,013
North Carolina	839,769	689,638	150,131	0	0	0
North Dakota	177,986	258,647	-80,661	0	0	0
Ohio.....	2,143,475	1,590,135	553,339	0	0	0
Oklahoma	477,426	1,853,323	-1,375,897	0	0	0
Oregon	485,741	403,639	82,102	0	0	0
Pennsylvania	2,104,595	1,592,245	512,349	0	0	0
Rhode Island	149,839	114,336	35,503	0	0	0
South Carolina	952,856	839,769	113,087	0	0	0
South Dakota	241,032	221,432	19,600	0	0	0
Tennessee	3,197,553	3,019,976	177,577	0	0	0
Texas.....	570,819	2,929,521	-2,358,702	0	368	-368
Utah.....	131,513	76,388	55,125	0	0	0
Vermont.....	0	233	-233	5,453	0	5,453
Virginia	963,316	846,246	117,070	0	0	0
Washington	480,668	485,741	-5,073	139,021	0	139,021
West Virginia	1,347,578	1,469,624	-122,045	0	0	0
Wisconsin.....	666,957	396,280	270,677	0	0	0
Wyoming	102,011	493,375	-391,364	0	0	0
Total	47,898,699	47,898,699	0	1,312,612	374,464	938,148

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1988						
Alabama	2,633,500	2,476,584	156,915	0	0	0
Alaska.....	0	0	0	0	51,573	-51,573
Arizona	1,287,035	1,141,767	145,268	0	1,905	-1,905
Arkansas	2,250,040	2,198,705	51,335	0	0	0
California	1,495,049	0	1,495,049	0	0	0
Colorado.....	466,630	408,688	57,942	0	0	0
Connecticut	211,099	119,268	91,830	0	0	0
D.C.	33,587	0	33,587	0	0	0
Delaware	24,698	2,762	21,936	0	0	0
Florida	290,973	33	290,940	0	0	0
Georgia.....	1,303,774	985,384	318,390	0	0	0
Idaho	60,696	522,973	-462,277	503,451	0	503,451
Illinois	1,637,380	747,413	889,967	0	0	0
Indiana.....	1,404,557	1,066,977	337,580	0	0	0
Iowa.....	1,238,879	999,000	239,879	0	0	0
Kansas	1,029,701	1,129,686	-99,985	0	0	0
Kentucky	3,055,726	2,853,063	202,663	0	0	0
Louisiana	1,525,303	5,292,062	-3,766,758	0	0	0
Maine.....	3,324	0	3,324	0	0	0
Maryland	857,050	682,447	174,603	0	0	0
Massachusetts	243,528	27,697	215,832	17,490	0	17,490
Michigan.....	975,993	1,300	974,693	997	349,054	-348,057
Minnesota.....	578,243	876,813	-298,570	586,097	7,116	578,982
Mississippi.....	5,147,232	5,023,162	124,070	0	0	0
Missouri.....	900,081	655,619	244,462	0	0	0
Montana	31,092	344,845	-313,753	318,618	15,119	303,500
Nebraska	1,091,860	962,058	129,802	0	0	0
Nevada.....	45,301	2,422	42,879	0	0	0
New Hampshire.....	16,711	3,167	13,545	0	0	0
New Jersey	1,009,154	607,748	401,406	0	0	0
New Mexico.....	879,379	1,368,584	-489,206	0	0	0
New York.....	1,075,859	362,242	713,617	70,993	1,800	69,193
North Carolina	863,186	707,786	155,399	0	0	0
North Dakota	324,701	391,683	-66,982	0	0	0
Ohio.....	2,040,012	1,459,639	580,373	0	0	0
Oklahoma.....	422,822	1,602,593	-1,179,771	0	0	0
Oregon	489,376	402,366	87,010	0	0	0
Pennsylvania	2,101,771	1,554,266	547,505	0	0	0
Rhode Island	128,474	96,574	31,900	0	0	0
South Carolina	975,127	863,186	111,942	0	0	0
South Dakota	386,118	363,676	22,442	0	0	0
Tennessee	3,282,888	3,061,224	221,664	0	0	0
Texas.....	581,388	2,949,238	-2,367,850	0	422	-422
Utah.....	158,711	91,943	66,769	0	0	0
Vermont.....	0	2,240	-2,240	8,105	0	8,105
Virginia	994,838	848,322	146,516	0	0	0
Washington	499,706	489,376	10,329	140,826	0	140,826
West Virginia	1,371,002	1,517,502	-146,500	0	0	0
Wisconsin.....	755,753	481,650	274,103	0	0	0
Wyoming	110,032	543,606	-433,574	0	0	0
Total	48,289,338	48,289,338	0	1,646,579	426,988	1,219,590

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1989						
Alabama	2,682,687	2,538,496	144,191	0	0	0
Alaska.....	0	0	0	0	51,424	-51,424
Arizona	1,443,075	1,275,692	167,384	0	1,469	-1,469
Arkansas	2,393,404	2,334,761	58,643	0	0	0
California	1,627,420	0	1,627,420	0	0	0
Colorado.....	473,834	433,066	40,768	0	0	0
Connecticut	234,593	137,224	97,369	0	0	0
D.C.	34,598	0	34,598	0	0	0
Delaware	39,248	3,005	36,242	0	0	0
Florida	322,798	32	322,766	0	0	0
Georgia.....	1,320,609	1,007,074	313,535	0	0	0
Idaho	78,911	534,497	-455,586	501,477	0	501,477
Illinois	2,071,383	1,048,895	1,022,488	0	0	0
Indiana.....	1,607,719	1,182,560	425,159	0	0	0
Iowa.....	1,168,434	946,728	221,706	0	0	0
Kansas	1,136,401	1,426,927	-290,526	0	0	0
Kentucky	3,208,031	2,948,517	259,514	0	0	0
Louisiana	1,632,234	5,482,027	-3,849,793	3,934	0	3,934
Maine.....	3,686	0	3,686	0	0	0
Maryland	893,124	681,700	211,424	0	0	0
Massachusetts	248,715	23,294	225,422	38,229	0	38,229
Michigan	972,991	1,495	971,496	0	363,680	-363,680
Minnesota.....	581,545	895,058	-313,513	609,215	7,119	602,096
Mississippi.....	5,299,819	5,172,100	127,719	0	0	0
Missouri.....	1,333,176	1,069,819	263,357	0	0	0
Montana	22,259	358,128	-335,869	323,538	14,454	309,084
Nebraska	1,011,038	888,303	122,736	0	0	0
Nevada.....	65,715	2,556	63,158	0	0	0
New Hampshire.....	17,736	3,657	14,079	0	0	0
New Jersey	1,039,568	615,094	424,475	0	0	0
New Mexico.....	846,451	1,523,896	-677,445	0	0	0
New York.....	1,066,665	375,695	690,969	67,956	0	67,956
North Carolina	878,416	711,800	166,617	0	0	0
North Dakota	338,072	402,546	-64,474	0	0	0
Ohio.....	2,198,268	1,550,668	647,600	0	0	0
Oklahoma	320,324	1,655,455	-1,335,130	0	0	0
Oregon	510,333	390,029	120,304	0	0	0
Pennsylvania	2,141,761	1,586,513	555,248	0	0	0
Rhode Island	146,218	111,986	34,232	0	0	0
South Carolina	993,292	876,596	116,696	0	0	0
South Dakota	408,928	384,461	24,467	0	0	0
Tennessee	3,399,413	3,212,302	187,111	0	0	0
Texas.....	531,621	2,922,632	-2,391,011	0	15,535	-15,535
Utah.....	126,786	84,990	41,796	0	0	0
Vermont.....	0	6,872	-6,872	13,152	0	13,152
Virginia	1,029,161	880,831	148,330	0	0	0
Washington	497,794	510,333	-12,539	170,832	0	170,832
West Virginia	1,411,412	1,470,635	-59,222	0	0	0
Wisconsin.....	775,925	465,397	310,528	0	0	0
Wyoming	111,823	563,073	-451,250	0	0	0
Total	50,697,415	50,697,415	0	1,728,333	453,682	1,274,651

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1990						
Alabama	2,818,949	2,688,474	130,475	0	0	0
Alaska.....	0	0	0	0	52,546	-52,546
Arizona	1,428,400	1,270,461	157,939	0	1,676	-1,676
Arkansas	2,223,388	2,179,835	43,553	0	0	0
California	1,620,132	0	1,620,132	0	0	0
Colorado.....	497,558	490,561	6,997	0	0	0
Connecticut	227,723	131,255	96,469	0	0	0
D.C.	29,321	0	29,321	0	0	0
Delaware	37,742	2,730	35,012	0	0	0
Florida	325,897	34	325,863	0	0	0
Georgia.....	1,361,415	1,057,288	304,127	0	0	0
Idaho	80,926	546,339	-465,413	514,597	0	514,597
Illinois	2,051,448	1,023,874	1,027,573	0	0	0
Indiana.....	1,596,047	1,159,628	436,420	0	0	0
Iowa.....	1,135,682	895,053	240,629	0	0	0
Kansas	1,036,161	1,330,368	-294,207	0	0	0
Kentucky	3,303,547	2,963,545	340,002	0	0	0
Louisiana	1,718,218	5,388,681	-3,670,463	30,750	0	30,750
Maine.....	4,471	0	4,471	0	0	0
Maryland	931,632	749,836	181,796	0	0	0
Massachusetts	232,459	22,950	209,509	53,443	0	53,443
Michigan	993,264	3,088	990,176	0	349,146	-349,146
Minnesota.....	584,815	958,389	-373,575	664,982	7,813	657,169
Mississippi	5,349,228	5,204,455	144,773	0	0	0
Missouri.....	1,236,536	996,135	240,401	0	0	0
Montana	28,628	368,321	-339,694	343,716	16,088	327,628
Nebraska	970,896	845,834	125,062	0	0	0
Nevada.....	68,994	2,548	66,446	0	0	0
New Hampshire.....	18,090	4,457	13,634	0	0	0
New Jersey	1,036,853	631,471	405,382	0	0	0
New Mexico.....	780,741	1,519,563	-738,821	0	0	0
New York.....	1,039,598	360,693	678,905	98,217	0	98,217
North Carolina	931,485	765,691	165,794	0	0	0
North Dakota	351,741	416,428	-64,687	0	0	0
Ohio.....	2,154,654	1,622,075	532,579	0	0	0
Oklahoma	313,884	1,758,270	-1,444,386	0	0	0
Oregon	500,269	387,778	112,491	0	0	0
Pennsylvania.....	2,245,534	1,538,925	706,609	0	0	0
Rhode Island	140,431	103,518	36,912	0	0	0
South Carolina	1,042,099	926,742	115,357	0	0	0
South Dakota	417,567	393,476	24,092	0	0	0
Tennessee	3,403,840	3,299,107	104,733	0	0	0
Texas.....	653,332	2,883,075	-2,229,743	0	13,983	-13,983
Utah.....	156,942	72,020	84,922	0	0	0
Vermont.....	0	7,887	-7,887	14,512	0	14,512
Virginia	1,059,259	914,223	145,036	0	0	0
Washington	508,705	500,269	8,436	168,441	0	168,441
West Virginia	1,463,155	1,513,864	-50,709	0	0	0
Wisconsin.....	788,801	489,196	299,606	0	0	0
Wyoming	122,436	634,485	-512,049	0	0	0
Total	51,022,894	51,022,894	0	1,888,660	441,253	1,447,407

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1991						
Alabama	2,782,487	2,674,828	107,659	0	0	0
Alaska.....	0	0	0	0	54,005	-54,005
Arizona	1,430,709	1,279,952	150,756	0	1,597	-1,597
Arkansas	2,263,622	2,199,198	64,424	0	0	0
California	1,623,693	0	1,623,693	0	0	0
Colorado.....	576,054	580,145	-4,091	0	0	0
Connecticut	239,690	138,751	100,939	0	0	0
D.C.	31,872	0	31,872	0	0	0
Delaware	41,760	2,894	38,866	0	0	0
Florida	335,763	29	335,734	0	0	0
Georgia.....	1,397,050	1,070,813	326,237	0	0	0
Idaho	87,575	532,277	-444,702	496,967	0	496,967
Illinois	1,991,216	981,904	1,009,311	0	0	0
Indiana.....	1,467,559	1,018,361	449,198	0	0	0
Iowa.....	1,075,376	867,098	208,278	0	0	0
Kansas	906,394	1,182,773	-276,379	0	0	0
Kentucky	3,030,350	2,826,802	203,548	0	0	0
Louisiana.....	1,654,594	5,181,474	-3,526,880	33,284	0	33,284
Maine.....	4,839	0	4,839	0	0	0
Maryland	931,110	738,910	192,200	0	0	0
Massachusetts	272,029	41,353	230,676	30,312	0	30,312
Michigan.....	942,159	2,506	939,653	1,151	361,041	-359,890
Minnesota.....	638,534	1,065,366	-426,832	741,353	0	741,353
Mississippi.....	5,193,842	5,069,990	123,852	0	0	0
Missouri.....	1,221,675	965,344	256,332	0	0	0
Montana	22,128	408,507	-386,379	393,463	16,338	377,125
Nebraska.....	924,993	786,554	138,439	0	0	0
Nevada.....	69,164	2,230	66,934	0	0	0
New Hampshire.....	19,494	4,815	14,680	0	0	0
New Jersey	1,049,018	662,376	386,642	0	0	0
New Mexico.....	707,737	1,517,997	-810,260	0	0	0
New York.....	1,105,278	414,155	691,123	188,233	0	188,233
North Carolina.....	928,505	751,862	176,643	0	0	0
North Dakota	394,319	454,014	-59,695	0	0	0
Ohio.....	1,889,579	1,295,980	593,599	0	0	0
Oklahoma.....	330,531	1,756,711	-1,426,181	0	0	0
Oregon	488,666	405,163	83,503	0	0	0
Pennsylvania.....	2,032,791	1,591,144	441,647	0	0	0
Rhode Island.....	166,305	110,202	56,103	0	0	0
South Carolina	1,050,481	923,920	126,562	0	0	0
South Dakota	459,068	434,073	24,995	0	0	0
Tennessee	3,210,927	3,025,125	185,802	0	0	0
Texas.....	709,907	2,742,234	-2,032,327	0	58,851	-58,851
Utah.....	85,735	48,664	37,071	0	0	0
Vermont.....	0	8,651	-8,651	15,796	0	15,796
Virginia	1,077,858	916,463	161,395	0	0	0
Washington	493,474	488,666	4,807	235,614	0	235,614
West Virginia	1,322,383	1,354,722	-32,339	0	0	0
Wisconsin.....	872,520	549,079	323,441	0	0	0
Wyoming	157,598	634,337	-476,738	0	0	0
Total	49,708,414	49,708,414	0	2,136,174	491,832	1,644,341

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1992						
Alabama	2,792,910	2,833,444	-40,535	0	0	0
Alaska.....	0	0	0	0	52,532	-52,532
Arizona	1,244,223	1,117,497	126,726	0	2,565	-2,565
Arkansas	2,235,546	2,193,258	42,289	0	0	0
California	1,610,708	0	1,610,708	0	0	0
Colorado.....	523,124	573,771	-50,647	0	0	0
Connecticut	336,972	218,371	118,601	0	0	0
D.C.	33,422	0	33,422	0	0	0
Delaware	40,864	3,230	37,634	0	0	0
Florida	341,354	29	341,325	0	0	0
Georgia.....	1,418,312	1,085,345	332,967	0	0	0
Idaho	103,589	543,842	-440,253	496,451	0	496,451
Illinois	2,134,256	1,112,815	1,021,441	0	0	0
Indiana.....	1,563,152	1,082,783	480,369	0	0	0
Iowa.....	1,270,083	1,027,408	242,675	0	0	0
Kansas	1,047,474	1,305,142	-257,668	0	0	0
Kentucky	3,197,882	3,023,149	174,733	0	0	0
Louisiana.....	1,870,183	5,165,877	-3,295,694	12,637	0	12,637
Maine.....	5,161	0	5,161	0	0	0
Maryland	959,084	766,661	192,423	0	0	0
Massachusetts	334,816	62,194	272,622	30,479	0	30,479
Michigan.....	1,135,780	6,268	1,129,512	38,568	539,369	-500,801
Minnesota.....	706,629	1,288,392	-581,763	855,300	0	855,300
Mississippi.....	5,198,262	5,103,156	95,107	0	0	0
Missouri.....	1,219,024	974,394	244,630	0	0	0
Montana	21,791	478,815	-457,024	467,036	14,569	452,467
Nebraska.....	1,021,817	898,635	123,182	0	0	0
Nevada.....	259,899	180,832	79,067	0	0	0
New Hampshire.....	24,110	5,135	18,975	0	0	0
New Jersey	1,108,758	628,131	480,627	0	0	0
New Mexico.....	436,787	1,348,520	-911,733	0	0	0
New York.....	1,121,178	559,844	561,333	435,470	0	435,470
North Carolina.....	943,723	752,237	191,486	0	0	0
North Dakota	465,592	528,330	-62,738	0	0	0
Ohio.....	2,125,670	1,481,800	643,869	0	0	0
Oklahoma.....	545,863	1,812,379	-1,266,516	0	0	0
Oregon	541,201	450,261	90,940	0	0	0
Pennsylvania.....	2,240,904	1,661,664	579,240	0	0	0
Rhode Island.....	205,808	132,486	73,322	0	0	0
South Carolina	1,065,954	937,086	128,868	0	0	0
South Dakota	532,549	506,324	26,225	0	0	0
Tennessee	3,361,934	3,193,074	168,860	0	0	0
Texas.....	566,789	2,748,086	-2,181,297	0	93,408	-93,408
Utah.....	333,653	273,310	60,343	0	0	0
Vermont.....	0	9,653	-9,653	17,248	0	17,248
Virginia	1,119,418	930,018	189,401	0	0	0
Washington	491,200	542,972	-51,772	270,477	0	270,477
West Virginia	1,466,319	1,543,220	-76,901	0	0	0
Wisconsin.....	1,057,942	706,270	351,672	0	0	0
Wyoming	193,125	778,686	-585,561	0	0	0
Total	52,574,795	52,574,795	0	2,623,667	702,442	1,921,225

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1993						
Alabama	2,849,645	2,904,162	-54,517	0	0	0
Alaska.....	0	0	0	0	55,989	-55,989
Arizona	1,270,649	1,069,293	201,356	0	3,253	-3,253
Arkansas	2,384,562	2,353,378	31,184	0	0	0
California	1,654,143	0	1,654,143	0	0	0
Colorado.....	503,217	636,724	-133,507	0	0	0
Connecticut	302,126	188,443	113,682	0	0	0
D.C.	33,373	0	33,373	0	0	0
Delaware	43,788	2,963	40,826	0	0	0
Florida	336,185	30	336,155	0	0	0
Georgia.....	1,371,442	1,041,851	329,591	0	0	0
Idaho	91,967	554,834	-462,867	511,727	0	511,727
Illinois	2,269,660	1,234,731	1,034,929	0	0	0
Indiana.....	1,751,885	1,239,776	512,110	0	0	0
Iowa.....	1,232,578	935,411	297,167	0	0	0
Kansas	974,939	1,246,045	-271,105	0	0	0
Kentucky	3,314,559	3,143,992	170,567	0	0	0
Louisiana	1,831,797	5,336,593	-3,504,796	30,790	0	30,790
Maine.....	4,989	0	4,989	0	0	0
Maryland	855,001	697,939	157,062	0	0	0
Massachusetts	278,925	60,665	218,261	50,895	0	50,895
Michigan.....	1,042,778	431	1,042,347	34,874	368,505	-333,631
Minnesota.....	756,282	1,335,315	-579,033	707,795	0	707,795
Mississippi.....	5,279,804	5,157,115	122,689	0	0	0
Missouri.....	1,306,977	1,036,225	270,752	0	0	0
Montana	19,293	530,201	-510,908	511,294	106	511,188
Nebraska.....	933,217	809,216	124,001	0	0	0
Nevada.....	329,846	241,471	88,376	0	0	0
New Hampshire.....	24,232	4,962	19,270	0	0	0
New Jersey	1,018,950	552,903	466,047	0	0	0
New Mexico.....	289,001	1,362,958	-1,073,957	0	0	0
New York.....	881,247	495,010	386,236	502,701	0	502,701
North Carolina.....	902,203	700,015	202,188	0	0	0
North Dakota	517,897	581,442	-63,545	0	0	0
Ohio.....	2,226,113	1,369,698	856,415	0	0	0
Oklahoma.....	511,429	1,670,651	-1,159,222	0	0	0
Oregon	540,702	435,002	105,699	0	0	0
Pennsylvania.....	2,167,583	1,370,888	796,695	0	0	0
Rhode Island.....	159,848	96,034	63,814	0	0	0
South Carolina	1,024,140	893,469	130,670	0	0	0
South Dakota	592,248	561,602	30,646	0	0	0
Tennessee	3,510,786	3,310,172	200,614	0	0	0
Texas.....	538,183	2,571,929	-2,033,746	1,678	36,423	-34,745
Utah.....	393,269	361,042	32,227	0	0	0
Vermont.....	0	9,097	-9,097	16,424	0	16,424
Virginia	1,035,590	851,890	183,700	0	0	0
Washington	515,637	540,711	-25,073	306,030	0	306,030
West Virginia	1,517,304	1,656,271	-138,967	0	0	0
Wisconsin.....	1,101,129	688,237	412,892	0	0	0
Wyoming	182,933	833,269	-650,336	0	0	0
Total	52,674,053	52,674,053	0	2,674,207	464,276	2,209,931

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1994						
Alabama	2,715,849	2,888,962	-173,112	0	0	0
Alaska.....	0	0	0	0	62,682	-62,682
Arizona	1,234,695	1,119,548	115,147	0	2,459	-2,459
Arkansas	2,865,799	2,801,918	63,880	0	0	0
California	1,887,149	0	1,887,149	0	0	0
Colorado.....	585,207	798,437	-213,230	0	0	0
Connecticut	324,576	214,098	110,478	0	0	0
D.C.	29,806	0	29,806	0	0	0
Delaware	52,304	2,896	49,408	0	0	0
Florida	359,172	30	359,143	0	0	0
Georgia.....	1,371,651	1,039,839	331,812	0	0	0
Idaho	98,230	759,717	-661,486	723,071	0	723,071
Illinois	2,489,443	1,328,116	1,161,327	0	0	0
Indiana.....	2,233,089	1,632,229	600,860	0	0	0
Iowa.....	1,443,469	1,156,188	287,281	0	0	0
Kansas	1,127,799	1,390,051	-262,252	0	0	0
Kentucky	3,663,838	3,577,873	85,965	0	0	0
Louisiana.....	1,844,714	5,649,614	-3,804,900	17,887	0	17,887
Maine.....	4,928	0	4,928	0	0	0
Maryland	883,179	656,585	226,594	0	0	0
Massachusetts	292,161	48,281	243,880	32,891	0	32,891
Michigan.....	1,495,917	0	1,495,917	17,320	521,969	-504,649
Minnesota.....	814,096	1,377,432	-563,335	875,226	0	875,226
Mississippi.....	5,660,877	5,493,256	167,621	0	0	0
Missouri.....	1,442,661	1,196,675	245,985	0	0	0
Montana	20,408	551,660	-531,252	535,855	3,087	532,768
Nebraska.....	1,170,211	1,019,871	150,340	0	0	0
Nevada.....	348,147	245,519	102,628	0	0	0
New Hampshire.....	20,249	4,884	15,365	0	0	0
New Jersey	1,119,949	589,632	530,317	0	0	0
New Mexico.....	334,650	1,417,608	-1,082,958	0	0	0
New York.....	926,727	549,862	376,865	562,267	0	562,267
North Carolina.....	901,123	702,517	198,606	0	0	0
North Dakota.....	543,543	607,129	-63,586	1,617	0	1,617
Ohio.....	2,617,648	1,838,402	779,245	0	0	0
Oklahoma.....	543,679	1,785,764	-1,242,085	0	0	0
Oregon	765,764	628,931	136,833	0	0	0
Pennsylvania.....	2,165,861	1,476,943	688,918	0	0	0
Rhode Island.....	184,516	125,766	58,749	0	0	0
South Carolina.....	1,025,779	896,007	129,772	0	0	0
South Dakota	613,908	583,653	30,255	0	0	0
Tennessee	3,878,897	3,658,815	220,081	0	0	0
Texas.....	603,826	2,672,096	-2,068,270	7,013	44,041	-37,029
Utah.....	444,646	440,415	4,231	0	0	0
Vermont.....	0	10,789	-10,789	18,091	0	18,091
Virginia	1,025,827	885,104	140,723	0	0	0
Washington	713,101	765,840	-52,739	320,362	0	320,362
West Virginia.....	1,620,921	1,725,985	-105,063	0	0	0
Wisconsin.....	1,179,011	698,586	480,425	0	0	0
Wyoming.....	280,941	956,416	-675,475	0	0	0
Total	57,969,941	57,969,941	0	3,111,599	634,238	2,477,361

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1995						
Alabama	3,253,871	3,389,137	-135,266	0	0	0
Alaska.....	0	0	0	0	65,283	-65,283
Arizona	994,103	879,159	114,944	0	42	-42
Arkansas	2,614,855	2,546,781	68,073	0	0	0
California	1,690,530	0	1,690,530	0	0	0
Colorado.....	699,431	844,388	-144,957	0	0	0
Connecticut	410,639	259,486	151,154	0	0	0
D.C.	29,860	0	29,860	0	0	0
Delaware	54,864	3,030	51,834	0	0	0
Florida	523,721	34	523,687	0	0	0
Georgia.....	1,439,907	1,075,834	364,073	0	0	0
Idaho	139,483	887,158	-747,675	823,478	0	823,478
Illinois	2,446,381	1,388,479	1,057,902	0	0	0
Indiana.....	2,041,013	1,475,557	565,456	0	0	0
Iowa.....	1,444,142	1,188,548	255,594	0	0	0
Kansas	1,140,230	1,458,930	-318,699	0	0	0
Kentucky	3,689,277	3,507,584	181,693	0	0	0
Louisiana	2,164,567	5,553,146	-3,388,579	5,149	0	5,149
Maine.....	5,533	0	5,533	0	0	0
Maryland	864,322	652,253	212,069	0	0	0
Massachusetts	541,527	98,974	442,554	12,769	0	12,769
Michigan	1,355,745	196,589	1,159,156	26,475	519,430	-492,955
Minnesota.....	863,304	1,434,132	-570,828	899,364	0	899,364
Mississippi	5,623,521	5,832,741	-209,220	0	0	0
Missouri.....	1,544,992	1,274,401	270,591	0	0	0
Montana	20,207	569,852	-549,645	570,396	0	570,396
Nebraska	1,030,750	1,054,114	-23,364	0	0	0
Nevada.....	355,804	247,692	108,112	0	0	0
New Hampshire.....	31,742	5,521	26,221	0	0	0
New Jersey	1,296,464	712,420	584,045	0	0	0
New Mexico.....	343,196	1,470,532	-1,127,337	0	0	0
New York.....	1,376,638	886,014	490,624	630,321	0	630,321
North Carolina	913,692	696,000	217,693	0	0	0
North Dakota	574,766	636,351	-61,585	4,559	0	4,559
Ohio.....	2,817,908	1,975,801	842,107	0	0	0
Oklahoma	810,112	1,872,345	-1,062,232	0	0	0
Oregon	882,385	741,523	140,861	0	0	0
Pennsylvania.....	2,718,075	1,982,831	735,243	0	0	0
Rhode Island	251,800	151,700	100,100	0	0	0
South Carolina	1,053,357	906,316	147,041	0	0	0
South Dakota	638,002	604,039	33,963	0	0	0
Tennessee	4,027,113	3,758,529	268,584	0	0	0
Texas.....	853,812	3,203,828	-2,350,016	6,722	61,241	-54,519
Utah.....	431,245	388,831	42,414	0	0	0
Vermont.....	0	9,335	-9,335	18,429	0	18,429
Virginia	1,055,691	850,457	205,235	0	0	0
Washington	804,621	882,385	-77,764	335,866	605	335,261
West Virginia	1,724,557	1,777,613	-53,057	0	0	0
Wisconsin.....	1,195,087	811,591	383,496	0	0	0
Wyoming	384,208	1,025,093	-640,884	0	0	0
Total	61,167,051	61,167,051	0	3,333,530	646,600	2,686,929

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1996						
Alabama	3,231,927	3,395,153	-163,227	0	0	0
Alaska.....	0	0	0	0	67,648	-67,648
Arizona	883,918	740,632	143,286	0	3,405	-3,405
Arkansas	2,810,961	2,737,292	73,669	0	0	0
California	1,547,503	0	1,547,503	0	0	0
Colorado.....	744,096	750,810	-6,713	0	0	0
Connecticut	388,927	254,633	134,294	0	0	0
D.C.	29,693	0	29,693	0	0	0
Delaware	46,232	3,252	42,980	0	0	0
Florida	483,085	33	483,052	0	0	0
Georgia.....	1,502,968	1,124,962	378,006	0	0	0
Idaho	126,244	899,611	-773,368	842,114	0	842,114
Illinois	2,607,330	1,498,747	1,108,583	0	0	0
Indiana.....	2,305,253	1,680,509	624,743	0	0	0
Iowa.....	1,497,972	1,206,074	291,899	0	0	0
Kansas	1,219,027	1,529,940	-310,913	0	0	0
Kentucky	3,956,093	3,878,714	77,379	0	0	0
Louisiana.....	2,373,002	5,922,946	-3,549,945	7,042	0	7,042
Maine.....	5,907	0	5,907	0	0	0
Maryland	882,473	672,257	210,215	0	0	0
Massachusetts	462,643	83,924	378,718	33,232	0	33,232
Michigan.....	1,516,628	139,929	1,376,700	29,043	586,696	-557,653
Minnesota.....	892,727	1,443,843	-551,116	937,806	0	937,806
Mississippi.....	5,880,172	6,073,530	-193,358	0	0	0
Missouri.....	1,556,791	1,270,306	286,485	0	0	0
Montana	27,448	590,475	-563,027	576,511	91	576,420
Nebraska.....	1,091,152	1,103,916	-12,764	0	0	0
Nevada.....	356,416	243,866	112,550	0	0	0
New Hampshire.....	27,435	5,888	21,548	0	0	0
New Jersey	1,217,278	637,254	580,023	0	0	0
New Mexico.....	316,153	1,452,364	-1,136,212	0	0	0
New York.....	1,194,754	798,572	396,182	652,578	0	652,578
North Carolina.....	970,866	744,068	226,797	0	0	0
North Dakota.....	598,044	653,690	-55,646	6,110	0	6,110
Ohio.....	2,997,400	1,929,760	1,067,640	0	0	0
Oklahoma.....	848,589	1,928,829	-1,080,240	0	0	0
Oregon	906,506	728,952	177,554	0	0	0
Pennsylvania.....	2,650,265	1,804,267	845,998	0	0	0
Rhode Island.....	243,047	136,456	106,591	0	0	0
South Carolina.....	1,102,786	965,420	137,366	0	0	0
South Dakota	656,552	620,225	36,327	0	0	0
Tennessee	4,272,871	3,951,222	321,649	0	0	0
Texas.....	941,088	3,413,156	-2,472,067	13,862	30,435	-16,573
Utah.....	420,103	390,959	29,144	0	0	0
Vermont.....	0	7,937	-7,937	18,736	0	18,736
Virginia	1,074,350	867,600	206,750	0	0	0
Washington	823,997	906,604	-82,608	356,711	1,451	355,260
West Virginia.....	1,776,833	1,899,227	-122,393	0	0	0
Wisconsin.....	1,194,236	796,522	397,714	0	0	0
Wyoming.....	294,140	1,069,550	-775,410	0	0	0
Total	62,953,877	62,953,877	0	3,473,745	689,725	2,784,020

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1997						
Alabama	3,063,122	3,248,827	-185,706	0	0	0
Alaska.....	0	0	0	0	62,187	-62,187
Arizona	969,669	844,452	125,217	0	3,901	-3,901
Arkansas	2,872,118	2,799,272	72,846	0	0	0
California	1,671,128	0	1,671,128	0	308	-308
Colorado.....	751,517	834,780	-83,263	0	0	0
Connecticut	396,610	259,700	136,910	0	0	0
D.C.	35,144	0	35,144	0	0	0
Delaware	47,619	3,405	44,214	0	0	0
Florida	503,155	28	503,126	0	0	0
Georgia.....	1,498,880	1,129,650	369,230	0	0	0
Idaho	145,009	950,876	-805,867	856,503	0	856,503
Illinois	2,495,356	1,475,069	1,020,287	0	0	0
Indiana.....	2,255,729	1,628,553	627,176	0	0	0
Iowa.....	1,436,026	1,144,445	291,581	0	0	0
Kansas	1,201,629	1,449,894	-248,265	0	0	0
Kentucky	3,576,553	3,433,137	143,416	0	0	0
Louisiana	2,106,229	5,787,452	-3,681,223	30,596	0	30,596
Maine.....	6,444	0	6,444	0	0	0
Maryland	932,773	681,017	251,756	0	0	0
Massachusetts	387,349	71,558	315,791	47,183	0	47,183
Michigan	1,452,628	146,328	1,306,300	23,356	573,066	-549,710
Minnesota.....	849,959	1,429,306	-579,348	950,706	0	950,706
Mississippi	5,701,467	5,660,658	40,809	0	0	0
Missouri.....	1,508,139	1,234,476	273,663	0	0	0
Montana	19,054	587,923	-568,869	572,977	0	572,977
Nebraska	1,082,729	1,065,103	17,627	0	0	0
Nevada.....	343,785	229,779	114,006	0	0	0
New Hampshire.....	27,720	6,433	21,287	0	0	0
New Jersey	1,274,307	706,829	567,479	0	0	0
New Mexico.....	303,455	1,441,218	-1,137,763	0	0	0
New York.....	1,196,768	746,689	450,079	656,332	0	656,332
North Carolina	976,910	737,497	239,413	0	0	0
North Dakota	596,337	642,906	-46,569	7,672	0	7,672
Ohio.....	2,662,578	1,835,811	826,767	0	0	0
Oklahoma	827,475	1,815,627	-988,152	0	0	0
Oregon	954,325	773,152	181,173	0	0	0
Pennsylvania.....	2,477,537	1,788,650	688,887	0	0	0
Rhode Island	221,909	123,040	98,868	0	0	0
South Carolina	1,105,842	971,634	134,208	0	0	0
South Dakota	648,098	611,611	36,487	0	0	0
Tennessee	3,868,295	3,571,683	296,613	0	0	0
Texas.....	824,731	3,172,315	-2,347,584	17,243	34,163	-16,920
Utah.....	443,318	494,909	-51,590	0	0	0
Vermont.....	0	8,134	-8,134	19,343	0	19,343
Virginia	1,120,061	906,833	213,228	0	0	0
Washington	867,820	954,325	-86,505	360,261	0	360,261
West Virginia	1,790,175	1,890,522	-100,347	0	0	0
Wisconsin.....	1,185,145	792,086	393,058	0	0	0
Wyoming	516,922	1,111,955	-595,034	0	0	0
Total	61,199,549	61,199,549	0	3,542,173	673,625	2,868,547

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1998						
Alabama	2,868,989	3,069,942	-200,953	0	0	0
Alaska.....	0	0	0	0	65,951	-65,951
Arizona	1,069,361	982,517	86,844	0	4,166	-4,166
Arkansas	2,510,822	2,414,107	96,715	0	0	0
California	1,820,433	0	1,820,433	0	2,067	-2,067
Colorado.....	732,416	929,026	-196,610	0	0	0
Connecticut	342,482	227,644	114,837	0	0	0
D.C.	31,164	0	31,164	0	0	0
Delaware	40,057	3,308	36,749	0	0	0
Florida	472,632	0	472,632	0	0	0
Georgia.....	1,511,671	1,116,847	394,824	0	0	0
Idaho	103,464	935,098	-831,635	879,840	0	879,840
Illinois	2,161,831	1,221,336	940,495	0	0	0
Indiana.....	1,869,111	1,328,356	540,755	0	0	0
Iowa.....	1,292,698	1,024,700	267,998	0	0	0
Kansas	1,070,930	1,151,812	-80,882	0	0	0
Kentucky	3,062,969	2,876,176	186,793	0	0	0
Louisiana	1,672,280	5,214,945	-3,542,665	42,922	0	42,922
Maine.....	5,734	0	5,734	0	0	0
Maryland	894,531	714,077	180,453	0	0	0
Massachusetts	350,148	72,360	277,789	42,531	0	42,531
Michigan	1,306,417	150,741	1,155,676	47,343	499,144	-451,801
Minnesota.....	791,117	1,417,230	-626,113	956,733	0	956,733
Mississippi	5,098,105	5,086,484	11,621	0	0	0
Missouri.....	1,290,478	1,052,273	238,205	0	0	0
Montana	16,410	572,643	-556,233	580,548	0	580,548
Nebraska	1,141,508	987,971	153,537	0	0	0
Nevada.....	357,695	236,624	121,071	0	0	0
New Hampshire.....	30,093	5,728	24,365	0	0	0
New Jersey	1,154,761	630,054	524,708	0	0	0
New Mexico.....	292,297	1,459,182	-1,166,885	0	0	0
New York.....	1,042,286	686,882	355,404	666,256	0	666,256
North Carolina	962,544	721,564	240,980	0	0	0
North Dakota	578,285	627,044	-48,759	9,268	0	9,268
Ohio.....	2,108,289	1,341,561	766,728	0	0	0
Oklahoma	657,304	1,538,619	-881,316	0	0	0
Oregon	957,810	740,433	217,378	0	0	0
Pennsylvania.....	2,203,403	1,591,154	612,248	0	0	0
Rhode Island	201,303	106,096	95,207	0	0	0
South Carolina	1,091,920	957,525	134,395	0	0	0
South Dakota	633,863	598,472	35,390	0	0	0
Tennessee	3,328,150	3,059,985	268,165	0	0	0
Texas.....	734,541	2,562,270	-1,827,728	14,532	46,933	-32,401
Utah.....	420,012	376,224	43,788	0	0	0
Vermont.....	0	11,319	-11,319	18,998	0	18,998
Virginia	1,091,838	872,552	219,286	0	0	0
Washington	892,082	957,886	-65,804	374,666	208	374,458
West Virginia	1,437,472	1,570,388	-132,917	0	0	0
Wisconsin.....	1,168,021	805,893	362,128	0	0	0
Wyoming	267,950	1,132,626	-864,676	0	0	0
Total	55,139,674	55,139,674	0	3,633,638	618,468	3,015,170

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
1999						
Alabama	2,865,624	3,118,673	-253,049	0	0	0
Alaska.....	0	0	0	0	63,607	-63,607
Arizona	1,076,545	977,041	99,504	0	4,279	-4,279
Arkansas	2,529,375	2,449,383	79,993	0	0	0
California	1,795,215	0	1,795,215	0	3,761	-3,761
Colorado.....	722,120	921,601	-199,481	0	0	0
Connecticut	383,598	222,593	161,005	0	0	0
D.C.	33,635	0	33,635	0	0	0
Delaware	45,009	3,666	41,343	0	0	0
Florida	508,613	0	508,613	0	0	0
Georgia.....	1,631,329	1,233,464	397,865	0	0	0
Idaho	105,368	844,465	-739,097	800,345	0	800,345
Illinois	2,302,647	1,325,077	977,570	0	0	0
Indiana.....	1,957,592	1,370,379	587,213	0	0	0
Iowa.....	1,542,212	1,151,305	390,907	0	0	0
Kansas	1,062,570	1,291,955	-229,385	0	0	0
Kentucky	3,072,091	2,879,517	192,574	0	0	0
Louisiana.....	1,584,311	5,283,607	-3,699,296	R64,786	0	R64,786
Maine.....	6,597	0	6,597	0	0	0
Maryland	1,010,107	802,650	207,457	0	0	0
Massachusetts	295,928	62,228	233,700	96,068	0	96,068
Michigan.....	1,384,456	207,115	1,177,341	41,194	531,542	-490,348
Minnesota.....	1,032,755	1,665,731	-632,977	998,603	0	998,603
Mississippi.....	5,203,246	5,221,834	-18,588	0	0	0
Missouri.....	1,350,606	1,078,929	271,677	0	0	0
Montana	23,871	806,377	-782,506	807,124	1,510	805,614
Nebraska.....	1,232,471	1,027,378	205,093	0	0	0
Nevada.....	354,582	225,138	129,443	0	0	0
New Hampshire.....	17,072	6,597	10,475	22,820	0	22,820
New Jersey	1,357,384	793,190	564,195	0	0	0
New Mexico.....	276,296	1,449,390	-1,173,095	0	0	0
New York.....	1,173,917	690,146	483,771	754,484	0	754,484
North Carolina.....	1,073,958	818,593	255,366	0	0	0
North Dakota.....	808,102	851,305	-43,203	3,416	0	3,416
Ohio.....	2,213,648	1,393,984	819,664	0	0	0
Oklahoma.....	630,269	1,369,337	-739,067	0	0	0
Oregon	838,607	628,608	209,999	0	0	0
Pennsylvania.....	2,386,329	1,767,868	618,461	0	0	0
Rhode Island.....	170,823	84,335	86,487	0	0	0
South Carolina.....	1,210,330	1,069,291	141,038	0	0	0
South Dakota	866,666	828,874	37,792	0	0	0
Tennessee.....	3,366,178	3,070,410	295,768	0	0	0
Texas.....	497,937	2,374,107	-1,876,170	54,530	53,260	1,270
Utah.....	359,246	381,416	-22,170	0	0	0
Vermont.....	0	3,248	-3,248	10,391	0	10,391
Virginia	1,215,366	997,134	218,232	0	0	0
Washington	803,073	837,942	-34,869	415,636	0	415,636
West Virginia.....	1,468,619	1,705,207	-236,588	0	0	0
Wisconsin.....	1,189,182	824,124	365,058	0	0	0
Wyoming.....	291,248	1,211,506	-920,258	0	0	0
Total	57,326,720	57,326,720	0	R4,069,397	657,959	R3,411,439

See footnotes at end of table.

Table 8. Movements of Natural Gas by State, 1967-2000 (Continued)
(Million Cubic Feet)

State	Interstate Movements			Movements Across U.S. Borders		
	Receipts	Deliveries	Net	Receipts	Deliveries	Net
2000						
Alabama	2,913,210	3,112,028	-198,818	0	0	0
Alaska.....	0	0	0	0	65,610	-65,610
Arizona	1,262,272	1,084,195	178,077	0	9,099	-9,099
Arkansas	2,361,147	2,251,967	109,180	0	0	0
California	1,903,159	0	1,903,159	0	13,152	-13,152
Colorado.....	811,997	1,007,044	-195,047	0	0	0
Connecticut	427,221	209,454	217,766	0	0	0
D.C.	34,120	0	34,120	0	0	0
Delaware	47,052	3,945	43,107	0	0	0
Florida	523,997	0	523,997	0	0	0
Georgia.....	1,640,769	1,198,383	442,386	0	0	0
Idaho	156,481	917,141	-760,660	830,351	0	830,351
Illinois	2,464,994	1,391,241	1,073,753	0	0	0
Indiana.....	2,033,397	1,471,765	561,632	0	0	0
Iowa.....	1,682,214	1,394,266	287,948	0	0	0
Kansas	1,130,728	1,344,919	-214,192	0	0	0
Kentucky	2,948,301	2,731,304	216,996	0	0	0
Louisiana.....	1,613,101	5,284,190	-3,671,089	127,198	0	127,198
Maine.....	30,858	110,225	-79,367	123,521	0	123,521
Maryland	1,003,523	789,414	214,110	0	0	0
Massachusetts	321,352	72,584	248,768	98,838	0	98,838
Michigan.....	1,409,122	296,922	1,112,200	23,369	587,546	-564,177
Minnesota.....	1,125,830	1,730,499	-604,669	928,332	0	928,332
Mississippi.....	5,180,831	5,184,326	-3,496	0	0	0
Missouri.....	1,288,185	1,011,266	276,919	0	0	0
Montana	39,386	831,482	-792,097	800,026	1,606	798,420
Nebraska.....	1,323,148	1,110,777	212,371	0	0	0
Nevada.....	366,304	209,242	157,063	0	0	0
New Hampshire.....	125,384	139,958	-14,574	38,289	0	38,289
New Jersey	1,322,670	746,510	576,160	0	0	0
New Mexico.....	294,745	1,517,702	-1,222,957	0	0	0
New York.....	1,262,403	646,212	616,190	832,762	0	832,762
North Carolina.....	1,051,425	813,121	238,304	0	0	0
North Dakota	831,330	940,713	-109,382	60,718	0	60,718
Ohio.....	2,204,658	1,536,300	668,358	0	0	0
Oklahoma.....	608,121	1,453,327	-845,206	0	0	0
Oregon	887,461	653,155	234,306	0	0	0
Pennsylvania.....	2,385,051	1,868,831	516,220	0	0	0
Rhode Island.....	170,561	83,200	87,362	0	0	0
South Carolina.....	1,212,184	1,046,316	165,868	0	0	0
South Dakota	886,757	844,771	41,986	0	0	0
Tennessee.....	3,242,619	2,946,327	296,292	0	0	0
Texas.....	417,392	2,330,517	-1,913,125	11,601	83,268	-71,667
Utah.....	356,690	384,473	-27,783	0	0	0
Vermont.....	0	0	0	9,980	0	9,980
Virginia	1,209,209	976,629	232,580	0	0	0
Washington	831,267	841,630	-10,363	347,992	0	347,992
West Virginia.....	1,434,186	1,588,838	-154,652	0	0	0
Wisconsin.....	1,185,803	805,903	379,900	0	0	0
Wyoming	323,006	1,372,609	-1,049,603	0	0	0
Total	58,285,622	58,285,622	0	4,232,977	760,281	3,472,695

^a Data for the District of Columbia are included with data for Maryland.

^b Data for New Hampshire and Vermont are included with data for Maine.

Note: Totals may not equal sum of components due to independent rounding.

Source: Energy Information Administration (EIA), Form EIA-176, "Annual Report of Natural and Supplemental Gas Supply and Disposition."