

Table 11. Changes in Natural Gas Storage by State, 1980-2000
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
1980							
Alabama.....	0	0	0	655	470	185	185
Arkansas.....	1,107	1,853	-746	14	0	14	-732
California.....	93,556	90,870	2,686	0	916	-916	1,770
Colorado.....	32,974	18,155	14,819	0	3	-3	14,816
Connecticut.....	0	0	0	1,336	2,156	-820	-820
Delaware.....	0	0	0	113	0	113	113
Georgia.....	0	0	0	20,484	19,950	534	534
Illinois.....	197,385	180,764	16,621	277	318	-41	16,580
Indiana.....	24,509	25,773	-1,264	1,107	1,236	-129	-1,393
Iowa.....	61,413	57,949	3,464	3,063	3,672	-609	2,855
Kansas.....	87,788	78,485	9,303	0	0	0	9,303
Kentucky.....	49,142	65,689	-16,547	0	0	0	-16,547
Louisiana.....	134,386	144,014	-9,628	0	0	0	-9,628
Maryland.....	16,907	20,919	-4,012	443	2,851	-2,408	-6,420
Massachusetts.....	0	0	0	7,885	11,268	-3,383	-3,383
Michigan.....	290,497	317,830	-27,333	0	0	0	-27,333
Minnesota.....	1,217	626	591	4,838	5,427	-589	2
Mississippi.....	59,653	57,898	1,755	0	0	0	1,755
Missouri.....	5,305	6,409	-1,104	0	0	0	-1,104
Montana.....	29,751	15,635	14,116	0	0	0	14,116
Nebraska.....	6,557	803	5,754	225	130	95	5,849
New Hampshire.....	0	0	0	5	27	-22	-22
New Jersey.....	0	0	0	3,617	3,300	317	317
New Mexico.....	2,871	3,989	-1,118	0	8	-8	-1,126
New York.....	41,857	45,520	-3,663	432	150	282	-3,381
North Carolina.....	0	0	0	597	0	597	597
Ohio.....	169,268	166,361	2,907	0	0	0	2,907
Oklahoma.....	112,403	101,688	10,715	0	0	0	10,715
Oregon.....	0	0	0	251	264	-13	-13
Pennsylvania.....	212,048	260,087	-48,039	4,046	4,915	-869	-48,908
Rhode Island.....	0	0	0	61	316	-255	-255
South Carolina.....	0	0	0	345	342	3	3
Tennessee.....	0	0	0	1,222	2,865	-1,643	-1,643
Texas.....	109,242	92,184	17,058	0	0	0	17,058
Utah.....	2,381	1,190	1,191	0	0	0	1,191
Virginia.....	22	0	22	1,626	1,633	-7	15
Washington.....	14,408	11,573	2,835	0	0	0	2,835
West Virginia.....	128,443	137,474	-9,031	0	0	0	-9,031
Wisconsin.....	0	0	0	136	212	-76	-76
Wyoming.....	11,194	6,163	5,031	0	0	0	5,031
Total.....	1,896,284	1,909,902	-13,618	52,780	62,431	-9,651	-23,269
1981							
Alabama.....	0	0	0	908	878	30	30
Arkansas.....	1,690	1,171	519	5	24	-19	500
California.....	99,397	92,214	7,183	371	476	-105	7,078
Colorado.....	25,291	25,932	-641	0	0	0	-641
Connecticut.....	0	0	0	2,160	1,459	701	701
Delaware.....	0	0	0	99	102	-3	-3
Georgia.....	0	0	0	1,508	3,106	-1,598	-1,598
Idaho.....	0	0	0	110	91	19	19
Illinois.....	141,824	169,502	-27,678	327	305	22	-27,656
Indiana.....	24,301	22,949	1,352	1,966	1,762	204	1,556
Iowa.....	48,918	48,971	-53	2,576	2,835	-259	-312
Kansas.....	101,892	87,629	14,263	0	0	0	14,263
Kentucky.....	67,518	57,603	9,915	0	0	0	9,915
Louisiana.....	212,267	110,544	101,723	0	0	0	101,723

See footnotes at end of table.

Table 11. Changes in Natural Gas Storage by State, 1980-2000 (Continued)
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
1981							
Maine	0	0	0	0	86	-86	-86
Maryland	18,753	14,673	4,080	714	623	91	4,171
Massachusetts	0	0	0	15,234	12,649	2,585	2,585
Michigan	354,911	347,592	7,319	0	0	0	7,319
Minnesota	1,125	477	648	4,402	3,663	739	1,387
Mississippi	42,916	40,688	2,228	0	0	0	2,228
Missouri	4,727	5,004	-277	7	33	-26	-303
Montana	30,147	13,008	17,139	0	0	0	17,139
Nebraska	7,198	809	6,389	119	173	-54	6,335
New Hampshire	0	0	0	0	11	-11	-11
New Jersey	0	0	0	4,658	3,541	1,117	1,117
New Mexico	2,801	1,980	821	0	0	0	821
New York	57,610	40,250	17,360	1,240	878	362	17,722
North Carolina	0	0	0	1,497	1,591	-94	-94
Ohio	177,387	162,268	15,119	0	0	0	15,119
Oklahoma	111,148	83,696	27,452	0	0	0	27,452
Oregon	0	0	0	265	268	-3	-3
Pennsylvania	360,752	311,051	49,701	4,051	3,084	967	50,668
Rhode Island	0	0	0	265	192	73	73
South Carolina	0	0	0	736	546	190	190
Tennessee	0	0	0	2,508	2,742	-234	-234
Texas	124,439	96,961	27,478	0	0	0	27,478
Utah	11,107	10,910	197	0	0	0	197
Virginia	0	0	0	1,876	1,881	-5	-5
Washington	11,083	11,243	-160	0	0	0	-160
West Virginia	127,788	125,753	2,035	0	0	0	2,035
Wisconsin	0	0	0	238	151	87	87
Wyoming	12,695	4,060	8,635	0	0	0	8,635
Total	2,179,683	1,886,940	292,743	47,839	43,152	4,687	297,430
1982							
Alabama	0	0	0	754	688	66	66
Arkansas	1,854	1,440	414	21	32	-11	403
California	112,916	145,654	-32,738	514	495	19	-32,719
Colorado	32,861	25,198	7,663	0	0	0	7,663
Connecticut	0	0	0	1,766	3,122	-1,356	-1,356
Delaware	0	0	0	118	121	-3	-3
Georgia	0	0	0	1,555	2,914	-1,359	-1,359
Idaho	0	0	0	361	229	132	132
Illinois	217,536	193,480	24,056	524	477	47	24,103
Indiana	25,489	23,284	2,205	4,352	2,361	1,991	4,196
Iowa	61,121	49,187	11,934	5,243	4,517	726	12,660
Kansas	128,737	84,877	43,860	0	0	0	43,860
Kentucky	64,789	56,611	8,178	0	0	0	8,178
Louisiana	177,194	149,813	27,381	22,711	18,720	3,991	31,372
Maine	0	0	0	364	349	15	15
Maryland	19,476	19,096	380	676	581	95	475
Massachusetts	0	0	0	14,021	15,639	-1,618	-1,618
Michigan	371,216	342,046	29,170	0	0	0	29,170
Minnesota	1,601	1,232	369	4,505	4,800	-295	74
Mississippi	43,834	47,306	-3,472	0	0	0	-3,472
Missouri	4,407	4,251	156	26	39	-13	143
Montana	25,180	18,721	6,459	0	0	0	6,459
Nebraska	7,455	3,693	3,762	7	293	-286	3,476
Nevada	0	0	0	294	5	289	289
New Hampshire	0	0	0	21	21	0	0
New Jersey	0	0	0	4,518	4,329	189	189

See footnotes at end of table.

Table 11. Changes in Natural Gas Storage by State, 1980-2000 (Continued)
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
1982							
New Mexico	19,894	2,483	17,411	0	0	0	17,411
New York	55,213	42,991	12,222	1,124	1,170	-46	12,176
North Carolina.....	0	0	0	1,372	1,483	-111	-111
Ohio	193,275	150,195	43,080	0	0	0	43,080
Oklahoma.....	104,572	87,048	17,524	0	0	0	17,524
Oregon	0	0	0	28	29	-1	-1
Pennsylvania	405,477	370,581	34,896	3,234	3,526	-292	34,604
Rhode Island.....	0	0	0	243	260	-17	-17
South Carolina	0	0	0	35	401	-366	-366
Tennessee	0	0	0	2,491	1,850	641	641
Texas	141,811	120,665	21,146	0	0	0	21,146
Utah	12,089	24,369	-12,280	0	0	0	-12,280
Virginia.....	0	0	0	1,865	1,879	-14	-14
Washington	5,344	6,433	-1,089	0	0	0	-1,089
West Virginia.....	144,153	119,103	25,050	0	0	0	25,050
Wisconsin.....	0	0	0	283	207	76	76
Wyoming.....	21,860	3,887	17,973	0	0	0	17,973
Total	2,399,355	2,093,644	305,711	73,028	70,540	2,488	308,199
1983							
Alabama.....	0	0	0	353	933	-580	-580
Arkansas.....	241	997	-756	0	34	-34	-790
California.....	97,424	86,157	11,267	66	496	-430	10,837
Colorado	26,361	30,288	-3,927	0	0	0	-3,927
Connecticut.....	0	0	0	980	1,365	-385	-385
Delaware.....	0	0	0	94	123	-29	-29
Georgia	0	0	0	1,024	1,193	-169	-169
Idaho	0	0	0	110	126	-16	-16
Illinois	122,620	165,746	-43,126	338	868	-530	-43,656
Indiana	20,160	25,165	-5,005	785	1,283	-498	-5,503
Iowa	49,523	74,291	-24,768	256	1,476	-1,220	-25,988
Kansas.....	70,412	95,404	-24,992	0	0	0	-24,992
Kentucky	42,090	59,633	-17,543	0	0	0	-17,543
Louisiana.....	148,679	192,973	-44,294	96,945	94,323	2,622	-41,672
Maine	0	0	0	166	251	-85	-85
Maryland	16,298	16,871	-573	235	394	-159	-732
Massachusetts	0	0	0	6,599	7,299	-700	-700
Michigan.....	227,107	327,954	-100,847	0	0	0	-100,847
Minnesota	646	559	87	1,277	1,770	-493	-406
Mississippi.....	44,467	51,910	-7,443	0	0	0	-7,443
Missouri.....	924	3,537	-2,613	29	43	-14	-2,627
Montana.....	33,262	13,221	20,041	0	0	0	20,041
Nebraska.....	3,869	4,949	-1,080	283	121	162	-918
Nevada.....	0	0	0	241	92	149	149
New Hampshire	0	0	0	0	84	-84	-84
New Jersey	0	0	0	4,770	4,979	-209	-209
New Mexico	2,500	4,887	-2,387	0	0	0	-2,387
New York	43,106	53,205	-10,099	1,174	1,050	124	-9,975
North Carolina.....	0	0	0	1,145	1,427	-282	-282
Ohio	129,541	156,531	-26,990	0	0	0	-26,990
Oklahoma.....	75,872	111,292	-35,420	0	0	0	-35,420
Oregon	0	0	0	649	773	-124	-124
Pennsylvania	284,948	342,623	-57,675	1,970	3,090	-1,120	-58,795
Rhode Island.....	0	0	0	47	55	-8	-8
South Carolina	0	0	0	132	292	-160	-160
Tennessee	0	0	0	977	2,222	-1,245	-1,245
Texas	135,309	181,770	-46,461	0	0	0	-46,461
Utah	19,948	17,824	2,124	0	0	0	2,124

See footnotes at end of table.

Table 11. Changes in Natural Gas Storage by State, 1980-2000 (Continued)
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
1983							
Virginia.....	0	0	0	1,223	1,310	-87	-87
Washington.....	6,218	8,481	-2,263	0	0	0	-2,263
West Virginia.....	87,355	106,200	-18,845	0	0	0	-18,845
Wisconsin.....	0	0	0	60	153	-93	-93
Wyoming.....	11,546	9,560	1,986	0	0	0	1,986
Total.....	1,700,426	2,142,027	-441,602	121,928	127,627	-5,699	-447,301
1984							
Alabama.....	0	0	0	838	379	459	459
Arkansas.....	1,817	1,817	0	44	8	36	36
California.....	103,983	112,525	-8,542	191	526	-335	-8,877
Colorado.....	26,228	21,531	4,697	0	0	0	4,697
Connecticut.....	0	0	0	1,673	1,129	544	544
Delaware.....	0	0	0	149	110	39	40
Georgia.....	0	0	0	678	881	-203	-203
Idaho.....	0	0	0	230	282	-52	-52
Illinois.....	194,327	173,305	21,022	1,034	381	653	21,675
Indiana.....	22,069	17,597	4,472	2,714	836	1,878	6,350
Iowa.....	44,355	56,503	-12,148	3,089	2,074	1,015	-11,133
Kansas.....	104,782	81,635	23,147	0	0	0	23,147
Kentucky.....	63,617	50,776	12,841	0	0	0	12,841
Louisiana.....	193,096	174,405	18,691	0	3,556	-3,556	15,134
Maine.....	0	0	0	203	198	5	5
Maryland.....	16,154	16,886	-732	650	500	150	-582
Massachusetts.....	0	0	0	9,844	7,110	2,734	2,733
Michigan.....	379,036	357,896	21,140	0	0	0	21,140
Minnesota.....	1,113	416	696	4,954	4,523	431	1,127
Mississippi.....	54,186	36,551	17,635	0	0	0	17,635
Missouri.....	4,431	1,992	2,438	57	10	47	2,485
Montana.....	39,814	23,577	16,237	0	0	0	16,237
Nebraska.....	5,628	5,453	175	65	135	-70	106
Nevada.....	0	0	0	133	65	68	68
New Jersey.....	0	0	0	4,781	3,313	1,468	1,469
New Mexico.....	4,033	9,102	-5,069	0	0	0	-5,069
New York.....	59,702	47,907	11,795	1,017	836	181	11,977
North Carolina.....	0	0	0	1,511	1,063	448	448
Ohio.....	156,006	177,388	-21,382	0	0	0	-21,382
Oklahoma.....	105,055	78,919	26,137	0	0	0	26,137
Oregon.....	0	0	0	304	272	32	32
Pennsylvania.....	362,878	323,951	38,927	3,714	2,266	1,448	40,376
Rhode Island.....	0	0	0	97	66	31	31
South Carolina.....	0	0	0	362	258	104	104
Tennessee.....	0	0	0	2,376	1,303	1,073	1,073
Texas.....	145,916	149,642	-3,726	0	0	0	-3,726
Utah.....	17,291	20,988	-3,697	0	0	0	-3,697
Virginia.....	0	0	0	1,812	1,771	41	41
Washington.....	12,002	10,747	1,255	0	0	0	1,255
West Virginia.....	128,717	106,758	21,959	0	0	0	21,959
Wisconsin.....	0	0	0	272	162	110	110
Wyoming.....	6,110	6,024	86	0	0	0	86
Total.....	2,252,347	2,064,292	188,055	42,791	34,011	8,780	196,835

See footnotes at end of table.

Table 11. Changes in Natural Gas Storage by State, 1980-2000 (Continued)
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
1985							
Alabama.....	0	0	0	512	971	-459	-459
Arkansas.....	4,359	1,427	2,932	18	26	-8	2,924
California.....	124,099	145,492	-21,393	20	227	-207	-21,600
Colorado.....	26,722	28,711	-1,989	0	0	0	-1,989
Connecticut.....	0	0	0	1,466	1,653	-187	-187
Delaware.....	0	0	0	133	126	7	7
Georgia.....	0	0	0	1,834	2,359	-525	-525
Idaho.....	0	0	0	287	921	-634	-634
Illinois.....	165,688	183,650	-17,962	653	858	-205	-18,167
Indiana.....	21,885	23,537	-1,652	923	494	429	-1,223
Iowa.....	64,993	63,117	1,876	289	1,102	-813	1,063
Kansas.....	96,153	114,502	-18,349	0	0	0	-18,349
Kentucky.....	62,202	57,307	4,895	0	0	0	4,895
Louisiana.....	184,351	212,372	-28,021	0	0	0	-28,021
Maine.....	0	0	0	308	296	12	12
Maryland.....	17,362	18,551	-1,189	786	867	-81	-1,270
Massachusetts.....	0	0	0	9,261	9,216	45	45
Michigan.....	325,729	338,737	-13,008	0	0	0	-13,008
Minnesota.....	1,640	2,050	-410	3,190	3,424	-234	-644
Mississippi.....	54,105	42,682	11,423	0	0	0	11,423
Missouri.....	4,537	5,018	-481	21	31	-10	-491
Montana.....	36,786	27,361	9,425	0	0	0	9,425
Nebraska.....	6,848	5,920	928	4	140	-136	792
Nevada.....	0	0	0	419	330	89	89
New Jersey.....	0	0	0	4,317	4,064	253	253
New Mexico.....	14,552	13,872	680	0	0	0	680
New York.....	48,748	53,515	-4,767	1,312	1,073	239	-4,528
North Carolina.....	0	0	0	1,164	1,397	-233	-233
Ohio.....	138,801	169,453	-30,652	0	0	0	-30,652
Oklahoma.....	87,860	106,914	-19,054	0	0	0	-19,054
Oregon.....	0	0	0	461	283	178	178
Pennsylvania.....	350,022	400,420	-50,398	2,309	2,936	-627	-51,025
Rhode Island.....	0	0	0	147	120	27	27
South Carolina.....	0	0	0	484	293	191	191
Tennessee.....	0	0	0	2,105	2,477	-372	-372
Texas.....	125,560	154,554	-28,994	0	0	0	-28,994
Utah.....	20,386	22,453	-2,067	0	0	0	-2,067
Virginia.....	0	0	0	2,117	2,120	-3	-3
Washington.....	7,847	7,162	685	0	0	0	685
West Virginia.....	129,134	149,952	-20,818	0	0	0	-20,818
Wisconsin.....	0	0	0	131	151	-20	-20
Wyoming.....	7,565	10,676	-3,111	0	0	0	-3,111
Total.....	2,127,932	2,359,405	-231,473	34,671	37,954	-3,283	-234,756
1986							
Alabama.....	0	0	0	581	449	132	132
Arkansas.....	1,871	789	1,082	22	18	4	1,086
California.....	89,891	89,527	364	18	23	-5	359
Colorado.....	24,313	21,743	2,570	0	0	0	2,570
Connecticut.....	0	0	0	1,035	837	198	198
Delaware.....	0	0	0	0	71	-71	-71
Georgia.....	0	0	0	1,942	1,346	596	596
Idaho.....	0	0	0	93	1,025	-932	-932
Illinois.....	156,754	140,510	16,244	199	469	-270	15,974
Indiana.....	22,118	18,981	3,137	777	162	615	3,752
Iowa.....	52,084	49,133	2,951	154	650	-496	2,455

See footnotes at end of table.

Table 11. Changes in Natural Gas Storage by State, 1980-2000 (Continued)
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
1986							
Kansas	97,214	85,306	11,908	0	0	0	11,908
Kentucky	43,698	41,420	2,278	0	0	0	2,278
Louisiana	174,222	192,473	-18,251	0	0	0	-18,251
Maine	0	0	0	127	121	6	6
Maryland	16,330	17,080	-750	769	616	153	-597
Massachusetts	0	0	0	6,184	5,591	593	593
Michigan	366,672	317,743	48,929	0	0	0	48,929
Minnesota	1,146	646	500	4,679	1,043	3,636	4,136
Mississippi	38,678	41,779	-3,101	0	0	0	-3,101
Missouri	2,835	2,084	751	28	23	5	756
Montana	22,084	11,220	10,864	0	0	0	10,864
Nebraska	5,748	3,468	2,280	81	129	-48	2,232
Nevada	0	0	0	217	107	110	110
New Hampshire	0	0	0	0	100	-100	-100
New Jersey	0	0	0	5,384	3,468	1,916	1,916
New Mexico	11,531	15,729	-4,198	0	0	0	-4,198
New York	49,185	44,696	4,489	647	777	-130	4,359
North Carolina	0	0	0	1,663	977	686	686
Ohio	163,093	142,235	20,858	0	0	0	20,858
Oklahoma	84,072	84,943	-871	0	0	0	-871
Oregon	0	0	0	0	346	-346	-346
Pennsylvania	249,028	239,233	9,795	2,657	2,398	259	10,054
Rhode Island	0	0	0	20	36	-16	-16
South Carolina	0	0	0	403	342	61	61
Tennessee	0	0	0	1,766	1,695	71	71
Texas	121,631	113,331	8,300	0	0	0	8,300
Utah	9,542	7,688	1,854	0	0	0	1,854
Virginia	0	0	0	1,989	2,038	-49	-49
Washington	6,269	3,217	3,052	0	0	0	3,052
West Virginia	134,394	114,872	19,522	0	0	0	19,522
Wisconsin	0	0	0	64	138	-74	-74
Wyoming	7,701	11,849	-4,148	0	0	0	-4,148
Total	1,952,103	1,811,697	140,406	31,500	24,996	6,504	146,910
1987							
Alabama	0	0	0	465	511	-46	-46
Arkansas	398	332	67	52	43	9	76
California	130,990	159,681	-28,692	18	19	0	-28,692
Colorado	24,083	25,601	-1,518	0	0	0	-1,518
Connecticut	0	0	0	1,281	1,160	121	121
Delaware	0	0	0	6	66	-60	-60
Georgia	0	0	0	1,150	1,001	149	149
Idaho	0	0	0	0	86	-86	-86
Illinois	125,066	124,889	177	223	320	-96	81
Indiana	15,844	16,317	-473	806	265	541	68
Iowa	45,128	41,856	3,272	670	878	-208	3,064
Kansas	87,570	92,360	-4,790	0	0	0	-4,790
Kentucky	42,388	38,780	3,608	0	0	0	3,608
Louisiana	188,110	175,623	12,486	0	0	0	12,486
Maine	0	0	0	226	227	0	0
Maryland	16,539	17,081	-543	482	480	2	-541
Massachusetts	0	0	0	5,732	7,775	-2,043	-2,043
Michigan	268,325	268,785	-461	0	0	0	-461
Minnesota	476	369	107	3,109	2,488	621	728
Mississippi	43,550	35,520	8,029	0	0	0	8,029
Missouri	1,337	1,019	318	58	48	10	328
Montana	22,894	8,596	14,297	0	0	0	14,297
Nebraska	6,241	4,575	1,666	130	115	14	1,681

See footnotes at end of table.

Table 11. Changes in Natural Gas Storage by State, 1980-2000 (Continued)
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
1987							
Nevada.....	0	0	0	441	185	256	256
New Hampshire	0	0	0	0	91	-91	-91
New Jersey	0	0	0	3,236	3,422	-185	-185
New Mexico	14,892	15,769	-877	0	0	0	-877
New York	42,616	43,252	-636	1,188	892	296	-341
North Carolina.....	0	0	0	1,609	1,571	39	39
Ohio	143,588	143,827	-239	0	0	0	-239
Oklahoma.....	84,031	75,151	8,880	0	0	0	8,880
Oregon.....	4,148	0	4,148	183	305	-122	4,026
Pennsylvania	335,166	335,670	-504	1,381	247	1,135	631
Rhode Island.....	0	0	0	65	295	-230	-230
South Carolina.....	0	0	0	545	481	64	64
Tennessee	0	0	0	1,135	1,228	-93	-93
Texas	121,245	114,434	6,811	0	0	0	6,811
Utah	14,359	14,905	-547	0	0	0	-547
Virginia.....	0	0	0	112	108	4	4
Washington.....	6,884	7,787	-903	0	0	0	-903
West Virginia.....	98,311	104,225	-5,914	0	0	0	-5,914
Wisconsin.....	0	0	0	74	164	-90	-90
Wyoming.....	2,932	14,545	-11,613	0	0	0	-11,613
Total	1,887,110	1,880,951	6,159	24,379	24,468	-89	6,070
1988							
Alabama.....	0	0	0	607	444	164	164
Arkansas.....	1,522	974	548	42	54	-12	536
California.....	120,167	104,375	15,792	9	20	-11	15,781
Colorado.....	25,898	26,380	-481	0	0	0	-481
Connecticut.....	0	0	0	1,229	1,154	75	75
Delaware.....	0	0	0	93	89	4	4
Georgia.....	0	0	0	1,702	1,157	545	545
Idaho.....	0	0	0	528	194	334	334
Illinois.....	166,713	157,954	8,759	393	325	69	8,827
Indiana.....	24,423	23,199	1,224	6,321	244	6,077	7,301
Iowa.....	55,076	54,659	417	477	648	-171	246
Kansas.....	107,182	90,238	16,944	0	0	0	16,944
Kentucky.....	55,774	68,676	-12,902	0	0	0	-12,902
Louisiana.....	194,251	156,364	37,886	0	0	0	37,886
Maine.....	0	0	0	157	157	0	0
Maryland.....	14,653	19,397	-4,744	764	771	-7	-4,751
Massachusetts.....	0	0	0	5,782	7,427	-1,644	-1,644
Michigan.....	341,649	342,472	-823	0	0	0	-823
Minnesota.....	1,142	5,210	-4,068	5,391	949	4,442	374
Mississippi.....	41,780	42,348	-567	0	0	0	-567
Missouri.....	4,240	4,054	186	0	0	0	186
Montana.....	13,782	20,351	-6,570	0	0	0	-6,570
Nebraska.....	7,615	7,567	48	299	167	132	180
Nevada.....	0	0	0	213	383	-170	-170
New Hampshire	0	0	0	0	142	-142	-142
New Jersey.....	0	0	0	3,243	3,202	40	40
New Mexico.....	19,407	14,411	4,996	0	0	0	4,996
New York.....	56,332	52,735	3,598	449	370	80	3,677
North Carolina.....	0	0	0	2,151	1,890	261	261
Ohio.....	162,801	336,351	-173,550	0	0	0	-173,550
Oklahoma.....	95,241	81,021	14,220	0	0	0	14,220
Oregon.....	0	0	0	803	243	560	560
Pennsylvania.....	377,046	368,481	8,565	3,023	3,186	-163	8,402
Rhode Island.....	0	0	0	174	143	31	31
South Carolina.....	0	0	0	503	547	-44	-44

See footnotes at end of table.

Table 11. Changes in Natural Gas Storage by State, 1980-2000 (Continued)
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
1988							
Tennessee	0	0	0	2,109	2,053	56	56
Texas	146,758	107,769	38,989	0	0	0	38,989
Utah	19,426	19,959	-533	0	0	0	-533
Virginia	0	0	0	231	260	-29	-29
Washington	5,415	6,014	-600	0	0	0	-600
West Virginia	106,318	127,909	-21,591	0	0	0	-21,591
Wisconsin	0	0	0	253	172	81	81
Wyoming	9,719	4,753	4,965	0	0	0	4,965
Total	2,174,328	2,243,621	-69,293	36,949	26,390	10,559	-58,734
1989							
Alabama	0	0	0	512	934	-422	-422
Arkansas	1,299	1,252	47	30	62	-32	15
California	140,933	151,488	-10,554	19	18	0	-10,554
Colorado	28,165	26,942	1,223	0	0	0	1,223
Connecticut	0	0	0	1,115	1,720	-604	-604
Delaware	0	0	0	39	76	-38	-38
Georgia	0	0	0	2,930	2,586	343	343
Idaho	0	0	0	258	93	165	165
Illinois	199,165	216,543	-17,378	0	579	-579	-17,957
Indiana	24,816	26,700	-1,884	737	393	344	-1,540
Iowa	58,386	67,421	-9,035	1,008	715	292	-8,743
Kansas	104,735	121,895	-17,160	0	0	0	-17,160
Kentucky	55,277	69,423	-14,147	0	0	0	-14,147
Louisiana	178,222	242,403	-64,181	0	0	0	-64,181
Maine	0	0	0	29	25	4	4
Maryland	18,548	19,166	-619	697	760	-62	-681
Massachusetts	0	0	0	10,004	16,450	-6,447	-6,447
Michigan	414,819	436,508	-21,688	0	0	0	-21,688
Minnesota	1,226	1,555	-330	6,453	6,916	-462	-792
Mississippi	50,478	63,872	-13,394	0	0	0	-13,394
Missouri	2,911	4,557	-1,647	0	0	0	-1,647
Montana	10,479	32,537	-22,058	0	0	0	-22,058
Nebraska	6,952	8,309	-1,357	210	414	-204	-1,561
Nevada	0	0	0	696	491	205	205
New Hampshire	0	0	0	0	213	-213	-213
New Jersey	0	0	0	1,433	2,444	-1,011	-1,011
New Mexico	14,036	17,774	-3,739	0	0	0	-3,739
New York	53,490	64,708	-11,218	564	595	-31	-11,249
North Carolina	0	0	0	1,597	2,803	-1,205	-1,205
Ohio	132,898	144,607	-11,709	0	0	0	-11,709
Oklahoma	98,370	112,700	-14,331	0	0	0	-14,331
Oregon	4,944	2,223	2,721	940	890	49	2,770
Pennsylvania	572,180	631,258	-59,078	2,268	4,242	-1,974	-61,052
Rhode Island	0	0	0	164	202	-38	-38
South Carolina	0	0	0	490	547	-57	-57
Tennessee	0	0	0	1,879	3,757	-1,879	-1,879
Texas	161,181	177,116	-15,935	0	0	0	-15,935
Utah	16,885	18,869	-1,984	0	0	0	-1,984
Virginia	0	0	0	2,167	2,173	-6	-6
Washington	12,921	12,081	840	0	0	0	840
West Virginia	115,421	125,796	-10,375	0	0	0	-10,375
Wisconsin	0	0	0	228	174	54	54
Wyoming	12,546	6,081	6,465	0	0	0	6,465
Total	2,491,283	2,803,787	-312,505	36,467	50,274	-13,807	-326,312

See footnotes at end of table.

Table 11. Changes in Natural Gas Storage by State, 1980-2000 (Continued)
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
1990							
Alabama.....	0	0	0	893	437	456	456
Arkansas.....	1,938	472	1,466	128	23	106	1,572
California.....	147,074	137,752	9,322	14	15	0	9,322
Colorado.....	27,674	31,174	-3,500	0	0	0	-3,500
Connecticut.....	0	0	0	1,696	874	822	822
Delaware.....	0	0	0	88	81	6	6
Georgia.....	0	0	0	2,779	1,435	1,345	1,345
Idaho.....	0	0	0	291	268	23	23
Illinois.....	213,076	197,150	15,926	883	302	580	16,506
Indiana.....	23,054	19,644	3,410	1,027	796	230	3,641
Iowa.....	44,471	47,770	-3,299	1,196	655	541	-2,758
Kansas.....	108,143	95,377	12,766	0	0	0	12,766
Kentucky.....	66,195	45,078	21,117	0	0	0	21,117
Louisiana.....	200,183	127,294	72,890	27,903	26,206	1,697	74,587
Maine.....	0	0	0	18	22	-4	-4
Maryland.....	19,431	14,074	5,357	769	377	392	5,748
Massachusetts.....	0	0	0	6,586	6,279	308	308
Michigan.....	415,309	314,461	100,848	0	0	0	100,848
Minnesota.....	1,256	1,077	179	4,714	4,670	44	223
Mississippi.....	53,161	33,655	19,505	0	0	0	19,505
Missouri.....	5,316	3,992	1,324	0	0	0	1,324
Montana.....	14,648	21,786	-7,138	0	0	0	-7,138
Nebraska.....	7,395	9,772	-2,376	493	155	339	-2,038
Nevada.....	0	0	0	356	904	-548	-548
New Jersey.....	0	0	0	3,740	2,298	1,442	1,442
New Mexico.....	22,352	13,126	9,226	0	0	0	9,226
New York.....	63,690	49,842	13,848	1,205	303	902	14,749
North Carolina.....	0	0	0	2,023	578	1,445	1,445
Ohio.....	154,452	119,117	35,334	0	0	0	35,334
Oklahoma.....	95,274	80,976	14,298	0	0	0	14,298
Oregon.....	5,894	4,531	1,363	754	1,003	-249	1,114
Pennsylvania.....	388,569	287,053	101,516	4,311	1,679	2,632	104,147
Rhode Island.....	0	0	0	142	188	-46	-46
South Carolina.....	0	0	0	394	247	147	147
Tennessee.....	0	0	0	3,008	2,377	631	631
Texas.....	175,039	150,250	24,789	0	0	0	24,789
Utah.....	27,196	22,000	5,196	0	0	0	5,196
Virginia.....	0	0	0	190	142	48	48
Washington.....	14,296	15,622	-1,325	96	104	-8	-1,334
West Virginia.....	126,217	82,558	43,659	0	0	0	43,659
Wisconsin.....	0	0	0	116	126	-10	-10
Wyoming.....	12,146	8,183	3,962	0	0	0	3,962
Total.....	2,433,450	1,933,786	499,663	65,814	52,544	13,271	512,934
1991							
Alabama.....	0	0	0	511	530	-19	-19
Arkansas.....	1,044	3,010	-1,966	38	49	-11	-1,976
California.....	136,433	124,156	12,276	50	19	32	12,308
Colorado.....	30,584	23,214	7,370	0	0	0	7,370
Connecticut.....	0	0	0	1,010	1,112	-103	-103
Delaware.....	0	0	0	79	72	7	7
Georgia.....	0	0	0	1,969	1,579	390	390
Idaho.....	0	0	0	340	227	113	113
Illinois.....	212,232	213,210	-978	115	344	-229	-1,207
Indiana.....	23,654	24,580	-926	1,517	922	595	-331
Iowa.....	57,278	62,486	-5,207	2,012	669	1,343	-3,864

See footnotes at end of table.

Table 11. Changes in Natural Gas Storage by State, 1980-2000 (Continued)
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
1991							
Kansas	109,627	98,805	10,822	0	0	0	10,822
Kentucky	47,425	48,822	-1,397	0	0	0	-1,397
Louisiana	178,002	202,991	-24,989	33,284	32,726	558	-24,432
Maine	0	0	0	25	23	1	1
Maryland	22,508	20,656	1,852	657	531	126	1,978
Massachusetts	0	0	0	4,399	8,366	-3,967	-3,967
Michigan	354,996	394,196	-39,200	0	0	0	-39,200
Minnesota	1,285	1,018	267	5,974	6,044	-70	197
Mississippi	48,054	53,938	-5,884	0	0	0	-5,884
Missouri	4,972	3,855	1,117	0	0	0	1,117
Montana	12,392	22,129	-9,737	0	0	0	-9,737
Nebraska	8,916	8,687	229	92	211	-119	110
Nevada	0	0	0	767	39	728	728
New Jersey	0	0	0	2,683	2,221	461	461
New Mexico	21,563	17,868	3,694	0	0	0	3,694
New York	63,411	51,792	11,619	559	309	250	11,869
North Carolina	0	0	0	1,219	1,232	-13	-13
Ohio	134,060	133,629	431	0	0	0	431
Oklahoma	94,221	106,360	-12,139	0	0	0	-12,139
Oregon	5,853	5,288	566	609	389	220	786
Pennsylvania	707,371	718,706	-11,335	2,390	2,412	-22	-11,357
Rhode Island	0	0	0	749	355	393	393
South Carolina	0	0	0	346	396	-50	-50
South Dakota	0	0	0	0	15	-15	-15
Tennessee	0	0	0	1,522	1,923	-401	-401
Texas	170,908	164,510	6,398	0	0	0	6,398
Utah	32,248	42,224	-9,976	0	0	0	-9,976
Virginia	0	0	0	173	243	-71	-71
Washington	14,214	11,013	3,200	2	0	2	3,203
West Virginia	104,251	121,139	-16,888	0	0	0	-16,888
Wisconsin	0	0	0	167	131	35	35
Wyoming	10,872	10,446	426	0	0	0	426
Total	2,608,373	2,688,728	-80,355	63,259	63,090	169	-80,186
1992							
Alabama	0	0	0	501	262	239	239
Arkansas	2,461	2,975	-514	50	51	-1	-515
California	148,039	176,158	-28,120	13	51	-38	-28,158
Colorado	23,061	27,921	-4,860	0	0	0	-4,860
Connecticut	0	0	0	359	714	-355	-355
Delaware	0	0	0	61	66	-5	-5
Georgia	0	0	0	1,573	1,557	16	16
Idaho	0	0	0	1,338	1,385	-47	-47
Illinois	214,404	223,012	-8,608	570	348	222	-8,387
Indiana	25,770	26,611	-840	849	1,188	-339	-1,179
Iowa	65,818	70,077	-4,259	4,659	4,247	412	-3,846
Kansas	84,249	102,735	-18,486	0	0	0	-18,486
Kentucky	49,367	42,795	6,573	0	0	0	6,573
Louisiana	193,051	207,010	-13,958	12,545	12,097	448	-13,511
Maine	0	0	0	26	22	4	4
Maryland	19,502	19,169	333	804	715	89	422
Massachusetts	0	0	0	5,147	6,990	-1,844	-1,844
Michigan	390,465	392,716	-2,251	0	0	0	-2,251
Minnesota	1,372	1,329	43	3,594	3,380	213	256
Mississippi	55,105	53,373	1,732	0	0	0	1,732
Missouri	3,080	3,094	-15	0	0	0	-15
Montana	11,708	24,310	-12,602	0	0	0	-12,602
Nebraska	10,254	9,848	407	283	173	111	517

See footnotes at end of table.

Table 11. Changes in Natural Gas Storage by State, 1980-2000 (Continued)
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
1992							
Nevada.....	0	0	0	83	155	-71	-71
New Jersey	0	0	0	2,422	2,471	-49	-49
New Mexico	18,963	21,421	-2,458	0	2,599	-2,599	-5,057
New York	62,265	60,693	1,572	732	363	370	1,942
North Carolina.....	0	0	0	1,030	1,122	-92	-92
Ohio	160,009	175,682	-15,672	0	0	0	-15,672
Oklahoma.....	97,468	107,526	-10,058	0	0	0	-10,058
Oregon	6,114	6,985	-872	376	409	-33	-904
Pennsylvania	383,762	377,889	5,873	2,869	2,797	72	5,945
Rhode Island.....	0	0	0	796	1,216	-420	-420
South Carolina	0	0	0	339	323	16	16
South Dakota.....	0	0	0	24	13	11	11
Tennessee	0	0	0	2,759	3,065	-306	-306
Texas	340,602	384,042	-43,441	0	0	0	-43,441
Utah	31,222	26,740	4,482	0	0	0	4,482
Virginia.....	0	0	0	173	168	6	6
Washington.....	13,294	18,960	-5,667	0	471	-471	-6,137
West Virginia.....	138,647	146,827	-8,180	0	0	0	-8,180
Wisconsin.....	0	0	0	57	117	-59	-59
Wyoming.....	5,340	13,876	-8,536	0	0	0	-8,536
Total	2,555,393	2,723,774	-168,381	44,033	48,534	-4,501	-172,882
1993							
Alabama.....	0	0	0	612	396	215	215
Arkansas.....	272	8,481	-8,208	53	44	9	-8,199
California.....	155,135	135,442	19,693	13	37	-24	19,668
Colorado.....	51,132	54,294	-3,162	0	0	0	-3,162
Connecticut.....	0	0	0	610	640	-29	-29
Delaware.....	0	0	0	99	95	3	3
Georgia	0	0	0	1,855	1,896	-42	-42
Idaho	0	0	0	1,389	1,339	51	51
Illinois.....	240,515	228,319	12,196	417	448	-31	12,165
Indiana	25,928	25,332	596	2,320	1,582	738	1,334
Iowa	64,184	61,007	3,176	5,671	5,597	75	3,251
Kansas.....	116,284	109,475	6,809	0	0	0	6,809
Kentucky	48,117	59,742	-11,625	0	0	0	-11,625
Louisiana.....	229,568	221,931	7,638	30,677	32,033	-1,356	6,282
Maine.....	0	0	0	16	19	-2	-2
Maryland.....	15,314	20,420	-5,106	696	610	85	-5,021
Massachusetts.....	0	0	0	5,531	7,900	-2,368	-2,368
Michigan.....	476,312	437,280	39,033	0	0	0	39,033
Minnesota.....	1,762	1,834	-72	6,330	5,864	466	394
Mississippi.....	55,903	55,786	117	0	0	0	117
Missouri.....	4,711	4,779	-68	0	0	0	-68
Montana.....	10,894	32,202	-21,308	0	0	0	-21,308
Nebraska.....	14,485	11,718	2,767	287	222	65	2,832
Nevada.....	0	0	0	253	244	9	9
New Jersey.....	0	0	0	2,620	2,313	307	307
New Mexico.....	16,369	24,794	-8,426	0	0	0	-8,426
New York.....	68,532	67,643	889	810	440	371	1,259
North Carolina.....	0	0	0	1,681	1,823	-142	-142
Ohio	175,630	188,899	-13,269	0	0	0	-13,269
Oklahoma.....	151,249	136,715	14,535	0	0	0	14,535
Oregon.....	6,202	6,302	-100	1,137	1,360	-222	-323
Pennsylvania.....	381,711	381,060	650	4,329	4,534	-204	446
Rhode Island.....	0	0	0	462	800	-337	-337
South Carolina.....	0	0	0	1,231	752	478	478
Tennessee.....	0	0	0	2,663	2,931	-268	-268

See footnotes at end of table.

Table 11. Changes in Natural Gas Storage by State, 1980-2000 (Continued)
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
1993							
Texas	221,412	232,070	-10,658	0	0	0	-10,658
Utah	34,488	27,216	7,271	0	0	0	7,271
Virginia	0	0	0	173	274	-102	-102
Washington	19,575	17,661	1,915	3,167	7,886	-4,718	-2,804
West Virginia	160,450	151,836	8,614	0	0	0	8,614
Wisconsin	0	0	0	112	110	2	2
Wyoming	13,605	14,826	-1,221	0	0	0	-1,221
Total	2,759,738	2,717,064	42,674	75,217	82,189	-6,972	35,701
1994							
Alabama	694	55	639	944	497	448	1,087
Arkansas	3,249	5,731	-2,482	73	68	5	-2,478
California	155,910	150,844	5,066	13	94	-80	4,985
Colorado	31,185	30,085	1,100	0	0	0	1,100
Connecticut	0	0	0	1,435	1,497	-61	-61
Delaware	0	0	0	225	202	23	23
Georgia	0	0	0	3,788	3,881	-94	-94
Idaho	0	0	0	554	373	182	182
Illinois	235,778	222,871	12,907	1,326	1,317	9	12,916
Indiana	24,656	21,081	3,576	2,638	2,733	-95	3,481
Iowa	70,926	68,162	2,764	3,867	3,521	346	3,109
Kansas	106,069	99,851	6,218	0	0	0	6,218
Kentucky	59,831	54,986	4,845	0	0	0	4,845
Louisiana	224,525	184,731	39,794	17,823	18,252	-429	39,364
Maine	0	0	0	27	22	5	5
Maryland	15,316	17,406	-2,090	939	529	410	-1,680
Massachusetts	0	0	0	5,550	12,369	-6,820	-6,820
Michigan	470,220	389,224	80,996	0	0	0	80,996
Minnesota	1,556	1,192	365	6,167	5,537	630	994
Mississippi	64,972	50,526	14,446	0	0	0	14,446
Missouri	4,997	5,082	-85	0	0	0	-85
Montana	14,690	22,509	-7,819	0	0	0	-7,819
Nebraska	12,524	10,052	2,471	393	367	26	2,497
Nevada	0	0	0	241	271	-30	-30
New Jersey	0	0	0	4,835	3,565	1,270	1,270
New Mexico	18,551	17,172	1,379	0	0	0	1,379
New York	66,627	64,803	1,824	1,125	835	290	2,115
North Carolina	0	0	0	2,118	1,802	316	316
Ohio	191,660	163,084	28,576	0	0	0	28,576
Oklahoma	123,576	104,738	18,838	0	0	0	18,838
Oregon	5,956	5,237	720	860	1,117	-257	463
Pennsylvania	339,512	340,334	-823	5,826	5,030	797	-26
Rhode Island	0	0	0	1,156	996	160	160
South Carolina	0	0	0	847	682	165	165
Tennessee	0	0	0	2,985	2,879	106	106
Texas	310,273	274,046	36,228	0	0	0	36,228
Utah	42,508	22,921	19,587	0	0	0	19,587
Virginia	0	0	0	116	236	-121	-121
Washington	18,705	17,133	1,572	2,340	1,701	640	2,212
West Virginia	171,216	156,284	14,932	0	0	0	14,932
Wisconsin	0	0	0	266	316	-50	-50
Wyoming	10,596	8,012	2,584	0	0	0	2,584
Total	2,796,279	2,508,151	288,127	68,478	70,689	-2,211	285,916

See footnotes at end of table.

Table 11. Changes in Natural Gas Storage by State, 1980-2000 (Continued)
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
1995							
Alabama.....	1,375	1,448	-73	524	688	-164	-237
Arkansas.....	5,368	6,076	-709	29	56	-27	-736
California.....	144,312	116,954	27,358	39	72	-33	27,325
Colorado.....	39,717	36,565	3,152	0	0	0	3,152
Connecticut.....	0	0	0	736	1,109	-373	-373
Delaware.....	0	0	0	103	103	-1	-1
Georgia.....	0	0	0	3,746	5,210	-1,464	-1,464
Idaho.....	0	0	0	405	434	-29	-29
Illinois.....	263,409	286,390	-22,981	370	382	-12	-22,993
Indiana.....	24,335	25,046	-711	1,316	1,554	-239	-950
Iowa.....	70,785	77,228	-6,443	2,346	2,996	-651	-7,094
Kansas.....	105,693	110,567	-4,875	0	0	0	-4,875
Kentucky.....	58,561	65,739	-7,178	0	0	0	-7,178
Louisiana.....	209,575	262,328	-52,753	5,032	4,723	308	-52,445
Maine.....	0	0	0	19	16	3	3
Maryland.....	15,610	19,658	-4,049	1,831	540	1,291	-2,757
Massachusetts.....	0	0	0	5,898	9,033	-3,134	-3,134
Michigan.....	377,121	494,531	-117,409	0	0	0	-117,409
Minnesota.....	1,478	1,582	-104	3,746	4,731	-985	-1,090
Mississippi.....	74,821	82,604	-7,783	0	0	0	-7,783
Missouri.....	2,777	2,580	197	0	0	0	197
Montana.....	18,054	21,653	-3,599	0	0	0	-3,599
Nebraska.....	3,872	9,716	-5,844	115	248	-134	-5,978
Nevada.....	0	0	0	259	228	31	31
New Jersey.....	0	0	0	3,055	2,982	73	73
New Mexico.....	14,712	16,986	-2,273	0	0	0	-2,273
New York.....	60,947	75,692	-14,746	926	886	40	-14,706
North Carolina.....	0	0	0	1,572	1,710	-138	-138
Ohio.....	161,350	200,211	-38,862	0	0	0	-38,862
Oklahoma.....	94,809	114,073	-19,264	0	0	0	-19,264
Oregon.....	4,447	3,567	880	790	675	114	994
Pennsylvania.....	332,608	396,393	-63,786	3,523	3,921	-398	-64,183
Rhode Island.....	0	0	0	857	908	-51	-51
South Carolina.....	0	0	0	927	754	173	173
Tennessee.....	0	0	0	2,414	3,035	-621	-621
Texas.....	274,724	300,889	-26,165	0	0	0	-26,165
Utah.....	32,201	32,084	118	0	0	0	118
Virginia.....	0	0	0	1,214	1,276	-62	-62
Washington.....	17,815	15,452	2,363	1,902	2,055	-153	2,210
West Virginia.....	145,958	187,088	-41,129	0	0	0	-41,129
Wisconsin.....	0	0	0	206	120	85	85
Wyoming.....	9,448	11,000	-1,552	0	0	0	-1,552
Total.....	2,565,882	2,974,102	-408,220	43,897	50,446	-6,549	-414,768
1996							
Alabama.....	3,349	2,125	1,224	979	1,282	-303	921
Arkansas.....	7,152	7,216	-64	0	85	-85	-150
California.....	104,238	155,530	-51,292	37	50	-13	-51,305
Colorado.....	37,808	36,804	1,004	0	0	0	1,004
Connecticut.....	0	0	0	2,265	1,585	680	680
Delaware.....	0	0	0	237	226	11	11
Georgia.....	0	0	0	6,523	6,712	-189	-189
Idaho.....	0	0	0	636	661	-25	-25
Illinois.....	241,129	226,020	15,109	971	1,259	-289	14,820
Indiana.....	27,263	25,462	1,801	4,337	4,571	-234	1,567
Iowa.....	61,060	59,831	1,229	5,262	3,284	1,978	3,207

See footnotes at end of table.

Table 11. Changes in Natural Gas Storage by State, 1980-2000 (Continued)
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
1996							
Kansas	104,871	116,989	-12,118	0	0	0	-12,118
Kentucky	69,498	61,968	7,530	0	0	0	7,530
Louisiana	249,153	260,117	-10,964	7,016	7,056	-39	-11,003
Maine	0	0	0	26	22	4	4
Maryland	17,448	17,472	-24	4,881	691	4,190	4,166
Massachusetts	0	0	0	6,107	11,471	-5,364	-5,364
Michigan	503,138	471,467	31,671	0	0	0	31,671
Minnesota	1,655	1,625	30	7,990	5,861	2,128	2,158
Mississippi	88,684	75,926	12,758	0	0	0	12,758
Missouri	6,570	6,522	48	0	0	0	48
Montana	19,871	31,595	-11,725	0	0	0	-11,725
Nebraska	8,423	6,933	1,489	915	788	127	1,617
Nevada	0	0	0	180	109	72	72
New Jersey	0	0	0	5,033	3,219	1,814	1,814
New Mexico	11,953	17,290	-5,338	0	0	0	-5,338
New York	76,475	63,108	13,367	1,853	1,262	591	13,958
North Carolina	0	0	0	2,708	2,490	218	218
Ohio	198,642	187,798	10,844	0	0	0	10,844
Oklahoma	117,067	140,028	-22,961	0	0	0	-22,961
Oregon	4,416	5,199	-783	693	939	-246	-1,029
Pennsylvania	376,290	316,757	59,533	5,590	4,722	867	60,400
Rhode Island	0	0	0	850	1,603	-753	-753
South Carolina	0	0	0	976	910	65	65
South Dakota	0	0	0	0	143	-143	-143
Tennessee	0	0	0	2,809	3,985	-1,175	-1,175
Texas	305,914	369,783	-63,869	0	0	0	-63,869
Utah	32,368	45,323	-12,955	0	0	0	-12,955
Virginia	0	0	0	1,631	1,614	17	17
Washington	20,124	22,192	-2,067	2,284	2,356	-72	-2,140
West Virginia	200,612	164,768	35,844	0	0	0	35,844
Wisconsin	0	0	0	269	329	-60	-60
Wyoming	10,422	15,478	-5,056	0	0	0	-5,056
Total	2,905,592	2,911,327	-5,735	73,057	69,287	3,770	-1,965
1997							
Alabama	2,022	1,860	162	960	535	425	587
Arkansas	6,665	6,915	-250	57	68	-11	-261
California	145,511	161,852	-16,340	51	109	-58	-16,398
Colorado	39,389	38,864	525	0	0	0	525
Connecticut	0	0	0	832	737	94	94
Delaware	0	0	0	112	121	-8	-8
Georgia	0	0	0	3,221	3,374	-153	-153
Idaho	0	0	0	868	836	32	32
Illinois	227,785	217,632	10,153	283	483	-200	9,952
Indiana	23,403	24,388	-984	2,520	1,867	653	-331
Iowa	61,132	54,877	6,255	2,134	1,893	241	6,496
Kansas	114,848	103,475	11,372	0	0	0	11,372
Kentucky	57,073	60,086	-3,013	0	0	0	-3,013
Louisiana	302,324	293,076	9,248	30,419	28,245	2,174	11,422
Maine	0	0	0	11	13	-2	-2
Maryland	15,510	14,966	544	1,439	252	1,186	1,730
Massachusetts	0	0	0	5,049	8,565	-3,517	-3,517
Michigan	424,651	421,264	3,388	0	0	0	3,388
Minnesota	1,417	1,044	373	1,686	1,715	-29	344
Mississippi	63,216	66,979	-3,763	0	0	0	-3,763
Missouri	5,081	4,629	453	0	0	0	453
Montana	18,219	30,181	-11,962	0	0	0	-11,962
Nebraska	6,659	5,069	1,590	505	383	122	1,712

See footnotes at end of table.

Table 11. Changes in Natural Gas Storage by State, 1980-2000 (Continued)
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
1997							
Nevada.....	0	0	0	276	214	61	61
New Jersey	0	0	0	3,926	3,330	596	596
New Mexico	12,936	15,001	-2,065	0	0	0	-2,065
New York	67,135	67,438	-304	1,625	760	865	561
North Carolina.....	0	0	0	2,016	1,686	330	330
Ohio	200,327	192,991	7,336	0	0	0	7,336
Oklahoma.....	132,489	123,008	9,482	0	0	0	9,482
Oregon	6,259	4,943	1,316	889	841	48	1,364
Pennsylvania	312,787	341,168	-28,381	4,615	5,852	-1,237	-29,618
Rhode Island.....	0	0	0	1,056	1,533	-476	-476
South Carolina	0	0	0	6	461	-455	-455
Tennessee.....	0	0	0	1,875	2,416	-541	-541
Texas	312,254	322,289	-10,035	0	0	0	-10,035
Utah	42,803	35,231	7,571	0	0	0	7,571
Virginia.....	0	0	0	1,096	988	108	108
Washington.....	20,018	19,015	1,003	2,193	2,145	48	1,051
West Virginia.....	164,299	181,015	-16,716	0	0	0	-16,716
Wisconsin.....	0	0	0	143	92	51	51
Wyoming.....	14,080	14,989	-908	0	0	0	-908
Total.....	2,800,294	2,824,245	-23,950	69,865	69,517	348	-23,603
1998							
Alabama.....	2,220	1,774	447	501	469	32	478
Arkansas.....	6,951	5,178	1,774	64	62	2	1,776
California.....	172,343	131,374	40,969	37	150	-114	40,855
Colorado	39,789	34,717	5,072	0	0	0	5,072
Connecticut.....	0	0	0	447	381	66	66
Delaware.....	0	0	0	77	70	8	8
Georgia	0	0	0	1,760	2,458	-698	-698
Idaho	0	0	0	776	1,236	-460	-460
Illinois.....	225,089	215,309	9,780	60	410	-351	9,430
Indiana	22,034	21,113	921	1,589	1,102	486	1,407
Iowa	70,001	67,047	2,954	1,269	989	280	3,234
Kansas.....	117,235	98,402	18,833	0	0	0	18,833
Kentucky	65,267	53,567	11,700	0	0	0	11,700
Louisiana.....	321,681	238,821	82,860	30,385	16,515	13,871	96,731
Maine.....	0	0	0	61	44	17	17
Maryland.....	14,627	13,751	876	813	29	785	1,660
Massachusetts.....	0	0	0	2,712	9,955	-7,243	-7,243
Michigan.....	391,041	316,201	74,840	0	0	0	74,840
Minnesota.....	1,291	1,663	-372	1,233	1,269	-36	-408
Mississippi.....	69,268	59,083	10,185	0	0	0	10,185
Missouri.....	2,670	2,843	-173	0	0	0	-173
Montana.....	23,876	23,476	400	0	0	0	400
Nebraska.....	5,264	6,730	-1,466	0	351	-351	-1,817
Nevada.....	0	0	0	92	124	-31	-31
New Jersey	0	0	0	4,922	4,305	617	617
New Mexico	16,821	10,342	6,479	0	0	0	6,479
New York	63,298	52,642	10,656	318	260	58	10,715
North Carolina.....	0	0	0	1,286	1,083	203	203
Ohio	191,831	165,159	26,672	0	0	0	26,672
Oklahoma.....	165,631	117,623	48,008	0	0	0	48,008
Oregon.....	5,673	4,395	1,278	757	1,014	-256	1,022
Pennsylvania	328,118	288,109	40,009	5,092	4,559	533	40,541
Rhode Island.....	0	0	0	102	851	-749	-749
South Carolina	0	0	0	56	406	-350	-350
South Dakota.....	0	0	0	44	53	-9	-9

See footnotes at end of table.

Table 11. Changes in Natural Gas Storage by State, 1980-2000 (Continued)
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
1998							
Tennessee	453	391	62	1,816	3,562	-1,746	-1,684
Texas	344,461	242,343	102,118	0	0	0	102,118
Utah	23,744	24,420	-676	0	0	0	-676
Virginia	2,369	1,859	510	632	774	-142	368
Washington	23,136	22,597	539	902	1,779	-877	-338
West Virginia.....	172,191	143,924	28,267	0	0	0	28,267
Wisconsin.....	0	0	0	85	106	-21	-21
Wyoming.....	15,212	12,493	2,719	0	0	0	2,719
Total	2,903,585	2,377,344	526,241	57,887	54,365	3,522	529,763
1999							
Alabama.....	2,646	2,482	164	564	783	-219	-55
Arkansas.....	5,784	6,017	-233	52	53	-1	-234
California.....	128,420	136,614	-8,194	58	117	-59	-8,253
Colorado	37,828	36,325	1,502	0	0	0	1,502
Connecticut.....	0	0	0	334	400	-66	-66
Delaware.....	0	0	0	83	52	31	31
Georgia.....	0	0	0	607	2,010	-1,403	-1,403
Idaho.....	0	0	0	720	228	492	492
Illinois.....	238,325	235,609	2,715	650	409	241	2,956
Indiana.....	21,533	21,289	244	2,000	R1,418	R582	R826
Iowa.....	73,398	75,843	-2,445	1,697	1,624	72	-2,372
Kansas.....	103,396	118,964	-15,568	0	0	0	-15,568
Kentucky.....	55,134	57,859	-2,725	0	0	0	-2,725
Louisiana.....	261,763	271,293	-9,530	R0	R0	R0	R-9,530
Maine.....	0	0	0	83	68	15	15
Maryland.....	18,802	18,740	63	715	221	494	556
Massachusetts.....	0	0	0	3,934	6,381	-2,447	-2,447
Michigan.....	343,675	376,613	-32,938	0	0	0	-32,938
Minnesota.....	1,384	1,131	253	1,295	983	312	565
Mississippi.....	48,217	62,719	-14,502	0	0	0	-14,502
Missouri.....	3,159	2,592	567	0	0	0	567
Montana.....	20,232	28,116	-7,884	0	0	0	-7,884
Nebraska.....	5,802	6,276	-473	377	201	176	-297
Nevada.....	0	0	0	206	235	-29	-29
New Jersey.....	0	0	0	7,035	6,752	283	283
New Mexico.....	17,459	15,170	2,289	0	0	0	2,289
New York.....	57,442	65,267	-7,825	651	454	197	-7,628
North Carolina.....	0	0	0	4,086	2,089	1,997	1,997
Ohio.....	182,142	198,161	-16,019	0	0	0	-16,019
Oklahoma.....	121,312	114,609	6,703	0	0	0	6,703
Oregon.....	7,605	7,017	589	540	468	73	661
Pennsylvania.....	319,041	342,238	R-23,197	5,146	4,477	669	-22,528
Rhode Island.....	0	0	0	162	139	24	24
South Carolina.....	0	0	0	1,204	493	711	711
South Dakota.....	0	0	0	83	74	9	9
Tennessee.....	599	565	34	2,181	3,005	-824	-789
Texas.....	291,802	297,787	-5,985	0	0	0	-5,985
Utah.....	37,380	46,573	-9,193	0	0	0	-9,193
Virginia.....	2,378	2,470	-92	1,318	1,192	126	33
Washington.....	19,227	18,014	1,213	2,502	1,741	761	1,974
West Virginia.....	160,166	194,788	-34,622	0	0	0	-34,622
Wisconsin.....	0	0	0	53	114	-61	-61
Wyoming.....	11,458	10,395	1,063	0	0	0	1,063
Total.....	2,597,509	R2,771,535	-174,025	R38,333	R36,179	R2,154	R-171,871

See footnotes at end of table.

Table 11. Changes in Natural Gas Storage by State, 1980-2000 (Continued)
(Million Cubic Feet)

State	Underground Storage			LNG Storage ^a			Net Change in Storage
	Injections	Withdrawals	Net	Additions	Withdrawals	Net	
2000							
Alabama.....	2,022	2,452	-430	729	1,014	-285	-714
Arkansas.....	3,943	6,975	-3,033	52	52	-1	-3,033
California.....	110,172	158,132	-47,960	270	36	234	-47,726
Colorado.....	31,601	40,215	-8,613	0	0	0	-8,613
Connecticut.....	0	0	0	707	1,178	-471	-471
Delaware.....	0	0	0	182	99	83	83
Georgia.....	0	0	0	3,241	4,367	-1,126	-1,126
Idaho.....	0	0	0	29	390	-361	-361
Illinois.....	225,524	249,688	-24,165	97	467	-370	-24,535
Indiana.....	19,486	23,378	-3,892	795	1,275	-480	-4,373
Iowa.....	69,893	83,453	-13,560	1,226	1,279	-53	-13,613
Kansas.....	104,007	138,055	-34,047	0	0	0	-34,047
Kentucky.....	55,348	85,546	-30,198	0	0	0	-30,198
Louisiana.....	242,566	338,767	-96,201	0	0	0	-96,201
Maine.....	0	0	0	45	33	12	12
Maryland.....	15,341	19,723	-4,383	684	1,023	-339	-4,722
Massachusetts.....	0	0	0	4,480	11,959	-7,480	-7,480
Michigan.....	402,150	548,738	-146,588	0	0	0	-146,588
Minnesota.....	1,375	1,681	-306	376	1,340	-964	-1,270
Mississippi.....	63,917	65,771	-1,853	0	0	0	-1,853
Missouri.....	2,619	3,186	-567	0	0	0	-567
Montana.....	15,571	29,483	-13,911	0	0	0	-13,911
Nebraska.....	3,763	8,129	-4,366	288	421	-132	-4,499
Nevada.....	0	0	0	153	170	-17	-17
New Hampshire.....	0	0	0	0	102	-102	-102
New Jersey.....	0	0	0	7,507	7,501	7	7
New Mexico.....	16,529	15,967	561	0	0	0	561
New York.....	61,763	71,587	-9,824	1,176	938	238	-9,586
North Carolina.....	0	0	0	4,168	4,891	-722	-722
Ohio.....	179,728	228,058	-48,330	0	0	0	-48,330
Oklahoma.....	136,287	224,641	-88,353	0	0	0	-88,353
Oregon.....	8,892	9,104	-212	997	789	208	-4
Pennsylvania.....	370,957	418,161	-47,204	4,918	5,124	-206	-47,411
Rhode Island.....	0	0	0	174	986	-812	-812
South Carolina.....	0	0	0	1,131	1,194	-63	-63
South Dakota.....	0	0	0	70	66	4	4
Tennessee.....	273	332	-59	884	2,664	-1,780	-1,839
Texas.....	311,995	439,245	-127,251	0	0	0	-127,251
Utah.....	40,179	46,716	-6,537	0	0	0	-6,537
Virginia.....	2,455	2,926	-471	972	826	146	-324
Washington.....	24,424	26,356	-1,932	1,268	1,178	90	-1,842
West Virginia.....	155,359	197,530	-42,171	0	0	0	-42,171
Wisconsin.....	0	0	0	71	111	-40	-40
Wyoming.....	6,144	14,208	-8,063	0	0	0	-8,063
Total.....	2,684,285	3,498,205	-813,920	36,689	51,473	-14,784	-828,704

^a Data on liquefied natural gas (LNG) was not collected prior to 1980.

Note: Totals may not equal sum of components due to independent rounding.

Source: Energy Information Administration (EIA), Form EIA-176, "Annual Report of Natural and Supplemental Gas Supply and Disposition."