Actions	Compliance	Procedures
(2) If the airplane records show that an MIL-H-6000B fuel hose has been replaced, inspect the airplane fuel hoses for a 3.8-inch-wide red or orange-red, length-wise stripe, with manufacturer's code, 94519, printed periodically along the line in red letters on one side. The hoses have a spiral or diagonal outer wrap with a fabric-type texture on the rubber surface.	For all affected airplanes other than the Models 99, 99A, A99, A99A, B99, and C99: Within 200 hours time-in-service (TIS) after August 28, 1998 (the effective date of AD 98–15–13). For all affected Models 99, 99A, A99, A99A, B99, and C99 airplanes: Within the next 200 hours TIS after the effective date of this AD.	Documented compliance with AD 98–15–13 or follow PART II of the ACCOMPLISH-MENT INSTRUCTIONS section in Raytheon Aircraft Mandatory Service Bulletin SB 2718, Revision 1, dated June 1997; or Revision 2, dated April 2000.
(3) Replace any fuel hose that matches the description in paragraph (e)(2) of this AD with an FAA-approved MIL-H-6000B fuel hose that has a criss-cross or braided external wrap.	For all affected airplanes other than the Models 99, 99A, A99, A99A, B99, and C99: Within 200 hours time-in-service (TIS) after August 28, 1998 (the effective date of AD 98–15–13). For all affected Models 99, 99A, A99, A99A, B99, and C99 airplanes: Within the next 200 hours TIS after the effective date of this AD.	Documented compliance with AD 98–15–13 or follow PART II of the ACCOMPLISH-MENT INSTRUCTIONS section in Raytheon Aircraft Mandatory Service Bulletin SB 2718, Revision 1, dated June 1997; or Revision 2, dated April 2000.
(4) For Raytheon Models C90A, B200, and B300 airplanes that were manufactured on January 1, 1994, and after, replace the MIL-H-6000B fuel hoses.	Within 200 hours time-in-service (TIS) after August 28, 1998 (the effective date of AD 98–15–13).	Documented compliance with AD 98–15–13 or follow PART I of the ACCOMPLISH-MENT INSTRUCTIONS section in Raytheon Aircraft Mandatory Service Bulletin SB 2718, Revision 1, dated June 1997; or Revision 2, dated April 2000.
(5) No one shall install a rubber fuel hose having spiral or diagonal external wrap with a 3/8-inch-wide red or orange-red, length-wise stripe running down the side of the hose, with the manufacturer's code, 94519, printed periodically along the line in red letters on any of the affected airplanes.	As of the effective date of this AD	Not applicable.

May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Standards Office, Small Airplane Directorate, FAA. For information on any already approved alternative methods of compliance, contact Jeffrey A. Pretz, Aerospace Engineer, ACE–116W, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946–4153; facsimile: (316) 946–4407.

May I Get Copies of the Documents Referenced in This AD?

(g) To get copies of the documents referenced in this AD, contact Raytheon Aircraft Company, P.O. Box 85, Wichita, Kansas 67201–0085; telephone: (800) 625–7043. To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL–401, Washington, DC, or on the Internet at http://dms.dot.gov. The docket number is FAA–2004–19089.

Issued in Kansas City, Missouri, on October 5, 2004.

Dorenda D. Baker,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04–23028 Filed 10–13–04; 8:45 am]

BILLING CODE 4910-13-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[CA 307-0464b; FRL-7818-7]

Revisions to the California State Implementation Plan, San Joaquin Valley Unified Air Pollution Control District

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

Act).

SUMMARY: EPA is proposing to approve revisions to the San Joaquin Valley Unified Air Pollution Control District (SJVUAPCD) portion of the California State Implementation Plan (SIP). These revisions concern volatile organic compound (VOC) emissions from glass coating operations. We are proposing to approve a local rule to regulate these emission sources under the Clean Air Act as amended in 1990 (CAA or the

DATES: Any comments on this proposal must arrive by November 15, 2004.

ADDRESSES: Send comments to Andy Steckel, Rulemaking Office Chief (AIR–4), U.S. Environmental Protection Agency, Region IX, 75 Hawthorne Street, San Francisco, CA 94105–3901, or e-mail to steckel.andrew@epa.gov, or submit comments at http://www.regulations.gov.

You can inspect copies of the submitted SIP revision, EPA's technical support document (TSD), and other materials relevant to this action at our Region IX office during normal business hours by appointment. You may also see copies of the submitted SIP revisions by appointment at the following locations:

California Air Resources Board, Stationary Source Division, Rule Evaluation Section, 1001 "I" Street, Sacramento, CA 95814.

San Joaquin Valley APCD, 1990 E. Gettysburg, Fresno, CA 93726.

A copy of the rule may also be available via the Internet at http://www.arb.ca.gov/drdb/drdbltxt.htm.

Please be advised that this is not an EPA Web site and may not contain the same version of the rule that was submitted to EPA.

FOR FURTHER INFORMATION CONTACT:

Francisco Dóñez, EPA Region IX, (415) 972–3956, Donez.Francisco@epa.gov.

SUPPLEMENTARY INFORMATION: This proposal addresses the following local rule: SJVUAPCD 4610. In the Rules and Regulations section of this Federal Register, we are approving this local rule in a direct final action without prior proposal because we believe these SIP revisions are not controversial. If we receive adverse comments, however, we will publish a timely withdrawal of the direct final rule and address the

comments in subsequent action based on this proposed rule.

We do not plan to open a second comment period, so anyone interested in commenting should do so at this time. If we do not receive adverse comments, no further activity is planned. For further information, please see the direct final action.

Dated: September 10, 2004.

Laura Yoshii,

Acting Regional Administrator, Region IX. [FR Doc. 04–22957 Filed 10–13–04; 8:45 am] BILLING CODE 6560–50–P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 271

[FRL-7825-7]

Florida: Final Authorization of State Hazardous Waste Management Program Revision

AGENCY: Environmental Protection

Agency (EPA).

ACTION: Proposed rule.

SUMMARY: Florida has applied to EPA for Final authorization of the changes to its hazardous waste program under the Resource Conservation and Recovery Act (RCRA). EPA proposes to grant final

authorization to Florida. In the "Rules and Regulations" section of this Federal **Register**, EPA is authorizing the changes by an immediate final rule. EPA did not make a proposal prior to the immediate final rule because we believe this action is not controversial and do not expect comments that oppose it. We have explained the reasons for this authorization in the preamble to the immediate final rule. Unless we get written comments which oppose this authorization during the comment period, the immediate final rule will become effective on the date it establishes, and we will not take further action on this proposal. If we get comments that oppose this action, we will withdraw the immediate final rule and it will not take effect. We will then respond to public comments in a later final rule based on this proposal. You may not have another opportunity for comment. If you want to comment on this action, you must do so at this time. DATES: Send your written comments by November 15, 2004.

ADDRESSES: Send written comments to Audrey E. Baker, Florida Authorizations Coordinator, RCRA Programs Branch, Waste Management Division, U.S. Environmental Protection Agency, The Sam Nunn Atlanta Federal Center, 61 Forsyth Street, SW., Atlanta, Georgia 30303–8960; (404) 562–8483. You may also e-mail your comments to *Baker.Audrey@epa.gov* or submit your comments at *http://www.regulations.gov*. You can examine copies of the materials submitted by Florida during normal business hours at the following locations: EPA, Region 4 Library, The Sam Nunn Atlanta Federal Center, 61 Forsyth Street, SW., Atlanta, Georgia 30303–8960, Phone number: (404) 562–8190, Patricia Strougal, Librarian; or The Florida Department of Environmental Protection, Twin Towers Office Building, 2600 Blair Stone Road, Tallahassee, Florida 32399–2400.

FOR FURTHER INFORMATION CONTACT:

Audrey E. Baker, Florida Authorizations Coordinator, RCRA Programs Branch, Waste Management Division, U.S. Environmental Protection Agency, The Sam Nunn Atlanta Federal Center, 61 Forsyth Street, SW., Atlanta, Georgia 30303–8960; (404) 562–8483.

SUPPLEMENTARY INFORMATION: For additional information, please see the immediate final rule published in the "Rules and Regulations" section of this **Federal Register**.

Dated: March 26, 2004.

A. Stanley Meiburg,

Acting Regional Administrator, Region 4. [FR Doc. 04–22591 Filed 10–13–04; 8:45 am] BILLING CODE 6560–50–P