

ABATED FALL HAZARD IN AIRCRAFT MAINTENANCE BUILDING

ACTIVITY: NORTH ISLAND NAVAL AIR STATION

CONDITION: Maintenance personnel were at risk of falling when they climbed onto and walked along the unguarded main fuselage of aircraft in order to perform required routine aircraft maintenance every 28 days.



C-9 aircraft without fall protection for personnel who work on top of fuselage.

CORRECTION: Install three horizontal three dimensional fall protection systems without swing fall

HAZARD SEVERITY: 1 **HAZARD PROBABILITY:** B **RAC:** 1

PEOPLE EXPOSED: 650