

Cover Photos: View of the Ipswich River between Russell Street and the South Middleton Dam. Normal streamflow in this reach is shown in the bottom left photo. Dry riverbed photo taken during the summer drought of 1999.

Photo courtesy of David Armstrong and Timothy Driskell, U.S. Geological Survey, Northborough, Mass.

**U.S. Department of Interior
U.S. Geological Survey**

A Precipitation-Runoff Model for Analysis of the Effects of Water Withdrawals on Streamflow, Ipswich River Basin, Massachusetts

By PHILLIP J. ZARRIELLO and KERNELL G. RIES, III

Water-Resources Investigation Report 00-4029

Prepared in cooperation with the
MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL MANAGEMENT and the
MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL PROTECTION

Northborough, Massachusetts
2000

U.S. DEPARTMENT OF THE INTERIOR
BRUCE BABBITT, Secretary

U.S. GEOLOGICAL SURVEY
Charles G. Groat, Director

The use of trade or product names in this report is for identification purposes only and does not constitute endorsement by the U.S. Geological Survey.

For additional information write to:

Chief, Massachusetts–Rhode Island District
U.S. Geological Survey
Water Resources Division
10 Bearfoot Road
Northborough, MA 01532

Copies of this report can be purchased from:

U.S. Geological Survey
Information Services
Box 25286
Denver, CO 80225-0286