

Cover Photo: Aerial view of Hobbs Brook Reservoir, eastern Massachusetts, looking north, with Winter Street in the foreground and Route 128/Interstate 95 to the right of the reservoir.

Photo by Joseph R. Melanson, Aero Photo, Inc., Wareham, Mass.

U.S. Department of the Interior
U.S. Geological Survey

Factors Affecting Reservoir and Stream-Water Quality in the Cambridge, Massachusetts, Drinking-Water Source Area and Implications for Source-Water Protection

By MARCUS C. WALDRON and GARDNER C. BENT

Water-Resources Investigations Report 00-4262

Prepared in cooperation with the
CITY OF CAMBRIDGE, MASSACHUSETTS, WATER DEPARTMENT

Northborough, Massachusetts
2001

U.S. DEPARTMENT OF THE INTERIOR
GALE A. NORTON, Secretary

U.S. GEOLOGICAL SURVEY
Charles G. Groat, Director

The use of trade or product names in this report is for identification purposes only and does not constitute endorsement by the U.S. Government.

For additional information write to:

Chief, Massachusetts-Rhode Island District
U.S. Geological Survey
Water Resources Division
10 Bearfoot Road
Northborough, MA 01532

or visit our web site at

<http://ma.water.usgs.gov>

Copies of this report can be purchased from:

U.S. Geological Survey
Branch of Information Services
Box 25286
Denver, CO 80225-0286